VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2018-01-09	CEVA	ORGIN	2018-01-11

## **CONTAINER 80110 DETAILS**

PO#	TOTAL A	DESCRIPTION	VPART NO.	SHIP QTY	LOCATION	FOB	EXT COST
	ITEM	DESCRIPTION	MAKE				
3358 <b>1119D</b>	60-66 FRONT BED PANEL		_ 2	M91	\$168.00	\$175.98	
3336	3336 1119D	FLEETSIDE	CHEVY PU	2	NISI	\$106.00	\$175.90
3351	3351 <b>1120WT</b>	RADIATOR SUPPORT 55-57			F158	\$166.26	\$171.98
3331	1120 ( ) 1	CHEVY ONLY *WTP*	CHEVY ONLY *WTP* CHEVY PU		1136	\$100.20	φ1/1.90
3351	3351 <b>1121X</b>	47-54 HOOD LATCH PANEL		_ 2	A56	\$239.40	\$242.54
3331	11217	STAINLESS	CHEVY PU				
3320	1128	FRONT BUMPER GUARD 63-66PR	CHEVY PU	1	G102	\$50.32	\$50.77
		67-72 FRONT BUMPER GUARDS	CHEVITO		G102	\$134.40	\$134.90
3355	1129	PR	CHEVY PU	2			
		DOOR WEATHER STRIP 73-91	15522764		C33	\$22.56	\$23.44
3352	3352 <b>1143A</b>	(ON CAB)	2	2			
		FRNT DOOR TOP	14016511	1	C33	\$14.42	\$14.84
3352	1143C	WEATHERSTRIP LH 73-80	CHEVY PU	2			
	11.51.0	47-72 ROUND MIRROR		_	F164	\$60.76	\$61.46
3314	3314 <b>1151C</b>	STAINLESS 5-5 / 8"SMOOTH	CHEVY PU	7			
2225	3335 <b>1153M</b>	67-72 EXTERIOR MIRROR ARM		1	F164	\$14.28	\$14.38
3333		LH STAINLESS	CHEVY PU	1			
3357	3357 <b>1158</b>	60-72 TRAILING ARM RH 1 / 2		3	F91	\$294.33	\$298.44
3337	1150	AND 3 / 4 TON	CHEVY PU				
3357	1158A	60-72 TRAILING ARM LH 1 / 2		3	F92	\$294.21	\$298.32
3331	1136A	AND 3 / 4 TON	CHEVY PU	3	F 74	φ294.21	φ <b>∠90.3</b> 2
3351	3351 <b>1160LA</b>	67 BEDSIDE RH 8' FLEETSIDE		1	S41	\$355.69	\$355.79
3331		BED	CHEVY PU		541	φυυυ.09	ψυυυ.19
3351	3351 <b>1160MA</b>	67 BEDSIDE LH 8' FLEETSIDE		1	S41	\$354.17	\$354.27
3331	HOUNTA	BED	CHEVY PU		541	Ψυυπ.17	ψυυπ.Δ1
3350	1170	TAILGATE 55-87 STEPSIDE W /			M91	\$603.75	\$622.70
	11/0	CHEVROLET	CHEVY PU		1,171	Ψ003.73	Ψ022.70
		55-87 TAILGATE HINGE			F162	\$16.80	\$16.90
3355	1172B	TRUNNIONS STEPSIDE, POLYURETHANE	CHEVY PU	1			
		TOLTOKETHANE	DACE-9				

PAGE:8