GOLDEN LEAF AUTOMOTIVE

INVOICE 62897

GOLDEN LEAF AUTOMOTIVE

170 ZENWAY BLVD UNIT#2 WOODBRIDGE, ONTARIO L4H 2Y7 TELEPHONE 905/850-3433

BILL TO: COUNTER SALES UNUSED PART EXCHANGE/RETURN WITHIN 30 DAYS W/ORIGINAL INV.

TELEPHONE: / -

INVOICE DATE 2017-08-25

PAGE: 2

SHIP TO: DONNA LEWIS 78 VICTORIA ST SAINT JOHN NB E2K-1L4 506-663-8740,

*** INVOICE ***

CUSTOMER		SHIP VIA		F.O.B	TERMS	PO NUMBER	SALES	DATE	OUR ORDER #
CSALE		BEST		ORIGIN	PREPAID	E-MAIL	M	2017-08-24	51067
ODDED	CITT		D.O.	ITEM	WEEN DESCRIPTION		PRICE	EVE PRICE	
ORDER	SHIP		B.O.	MAKE	ITEM DESCRIPTION			DIS%	EXT.PRICE
1	1		0	1154C	60-71 INTERIOR REAR VIEW		\$ 29.00	\$ 29.00	
1	1		0	CHEVY PU	MIRRORSTAINLESS 58-62 IMPALA		0 %	\$ 29.00	
1	1		0	1155D	60-71 INTERIOR REAR VIEW MIRROR BKT		\$ 29.00	\$ 29.00	
	1			CHEVY PU	00-71 INTERIOR REAR VIEW MIRROR BRT		0 %	\$ 29.00	
2	2		0	LP26	67-72 TAIL LAMP LENS RED FLEETSIDE		\$ 10.00	\$ 20.00	
			U	CHEVY PU			0 %	\$ 20.00	
1	1		0	LP33	67-72 BACK UP LENS FLEETSIDE RH		\$ 5.00	\$ 5.00	
				CHEVY PU			0 %	\$ 5.00	
1	1		0	LP34	67-72 BACK UP LENS FLEETSIDE LH		\$ 5.00	\$ 5.00	
				CHEVY PU			0 %	ф 3.00	
2	2		0	M1118B	67-72 DOOR SCUFF PLATE W / BOWTIESTAINLESS		\$ 39.00	\$ 78.00	
2			0	CHEVY PU			0 %	φ / δ.00	
1	1		0	1106BC	67-72 OUTER CAB FLOOR / INNER ROCKERPATCH RH		\$ 110.00	\$ 110.00	
			0	CHEVY PU			0 %	\$ 110.00	
1	1		0	1106BD	67-72 OUTER CAB FLOOR / INNER ROCKERPATCH LH		\$ 110.00	\$ 110.00	
		·		CHEVY PU			0 %	\$ 110.00	
2	2		0	1106AL	67-72 FRONT CAB FLOOR SUPPORT MOUNTRH=LH		\$ 19.00	\$ 38.00	
			0	CHEVY PU			0 %	\$ 36.00	
1	1	1 (0	1106AY	67-72 CAB FLOOR LH		\$ 49.00	\$ 49.00	
				CHEVY PU			0 %	\$ 47.00	
1	1	1	0	G1159	67-72 WINDSHIELD TINTED GREEN		\$ 227.00	\$ 227.00	
				CHEVY PU			0 %	\$ 227.00	
1	0	•	1	1114E	CAB CORNER RH 67-72		\$ 24.00	\$ 0.00	
				CHEVY PU			0 %	Ψ 0.00	
									CONTINUE