VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-25	1	ORGIN	2017-08-25

## **CONTAINER TEST3298 DETAILS**

PO# ITEM	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT COST
	IIEM	DESCRIPTION	MAKE				
3298 <b>1068R</b>	1068R	68-69 FLOOR PAN FRAME RAIL		4	E101	\$180.00	\$180.00
3296	1000K	RH	CAMARO	<b>4</b>			
		68-69 FLOOR PAN FRAME RAIL					
3298	3298 <b>1068RXWT</b>	RH6" WIDER WHEELHOUSE *WTP *	CAMARO	2	E101	\$181.62	\$181.62
		68-69 FLOOR PAN FRAME RAIL		1			
3298	3298 <b>1068SXWT</b>	LH6" WIDER WHEELHOUSE *WTP *	CAMARO		E101	\$90.70	\$90.70
3298	1096A	BUMPER FILLER 47-53	CHEVY PU	5	E114	\$181.80	\$181.80
3298	1103IB	60-63 DOOR RELAY LH	CHEVY PU	2	В93	\$21.00	\$21.00
3298	1104A	ROCKER PANEL RH 60-66	CHEVY PU	3	C124	\$58.05	\$58.05
3298	1104B	ROCKER PANEL LH 60-66	CHEVY PU	3	C124	\$56.28	\$56.28
3298	1104W	47-54 RUNNING BOARD RH	CHEVY PU	3	F107	\$294.81	\$294.81
3298	1104X	47-54 RUNNING BOARD LH	CHEVY PU	3	F107	\$294.90	\$294.90
3298	1106AK	60-66 FRONT CAB FLOOR SUPPORTRH=LH * 1.60 MM *	CHEVY PU	4	B75	\$36.72	\$36.72
3298	1106AL	67-72 FRONT CAB FLOOR SUPPORT MOUNTRH=LH	CHEVY PU	- 6	B75	\$35.28	\$35.28
		47-53 FRONT BED PANEL	CHEVIFU	3			*.=
3298	1119A		CHEVY PU		M91	\$170.04	\$170.04
3298	1160P	60-66 BEDSIDE PANEL RH		1	S41	\$174.17	\$174.17
	11001	SHORTBEDSTEPSIDE	CHEVY PU	1	541	Ψ1/7.1/	Ψ1/7.1/
3298 <b>1160Q</b>	1160Q	60-66 BEDSIDE PANEL LH		1	S41	\$179.08	\$179.08
	11000	SHORTBEDSTEPSIDE	CHEVY PU		ļ	72.7.00	Ψ177.00
3298	1512	HOOD 65-67 GTO	GTO	2	D21	\$280.00	\$280.00

PAGE:1