VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-12-13	CEVA	ORGIN	2017-12-15

CONTAINER 71215 DETAILS

PO# ITEM	DESCRIPTION	VPART NO.	SHID OTV	LOCATION	FOB	EXT COST	
	DESCRIPTION	MAKE	Shir Q11				
3346 1076E	DOOR SHELL RH 69 *FIT			F22	\$288.56	\$305.08	
	FIREBIRD 69*	CAMARO					
3346 1076F	DOOR SHELL LH 69 *FIT		_ 2	F22	\$288.54	\$305.06	
	FIREBIRD 69*	CAMARO	2	F 22	\$200.34	\$303.00	
3346	1076FA	69 DOOR HINGE UPPER RH 69-74			A126	\$109.80	\$110.30
3340 10/0FA	NOVA	CAMARO	3	A120	\$109.80	\$110.50	
3316	3346 1076FB	69 DOOR HINGE UPPER LH 69-74		6	A126	\$131.76	\$132.36
3340		NOVA	CAMARO		A120	\$131.70	\$132.30
3346	1076FC	69 DOOR HINGE LOWER RH	CAMARO	6	A126	\$131.76	\$132.36
3346	3346 1076FD	69 DOOR HINGE LOWER LH		11	A126	\$241.01	\$242.11
3340			CAMARO		A120	Ψ2-11.01	Ψ2-72.11
3342	1076FW	68-69 DOOR GLASS LH CP /	TP	1	N131 / G1	\$46.75	\$46.87
		CONVT CLEAR	CAMARO				
3341	3341 1096Н	55-56 FRONT BUMPER FILLER W		_ 2	E104	\$83.22	\$86.06
		/ BRACKET	CHEVY PU				
3346	3346 1097QC	47-53 FENDER LOWER REAR		_ 2	D82	\$106.18	\$109.82
		PANEL RH	CHEVY PU				
3341 1097QC	47-53 FENDER LOWER REAR		1	D82	\$53.09	\$54.91	
	1037 QC	PANEL RH	CHEVY PU			, / -	, - , -
3341 1097QD	47-53 FENDER LOWER REAR		1	D82	\$54.65	\$56.47	
	PANEL LH	CHEVY PU		-		44	
3345	1099G	INNER FENDER RH 67-72	CHEVY PU	3	J161	\$81.96	\$82.26
22.45	2017 1000-	1 11 15 15 15 15 15 15 15 15 15 15 15 15	CHEVIIO	 	74.64	#O1 0 5	402.2 5
3345	1099H INNER FENDER LH 67-72		CHEVY PU	3	J161	\$81.96	\$82.26
3348 1099S	57 STD HOOD	CHEAN DIT	1	D31	\$227.33	\$260.66	
	20,70		CHEVY PU		_		
3345	1100E	BATTERY HOLD DOWN 55-57	CHEVY PU	2	F151	\$8.86	\$9.08

PAGE:7