VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

CONTAINER 3312TEST DETAILS

PO# ITEM	DESCRIPTION	VPART NO.	SHID OTV	LOCATION	FOB	EXT COST	
	DESCRIPTION	MAKE	Shir Q11				
3312 1006M	77-81 FRONT DISC BRAKE		4	D83	\$83.72	\$83.72	
3312 1000WI		BRACKET PR	CAMARO				<u> </u>
3312	3312 1049W	67-73 BUMPER BOLT BULK		8	D91	\$164.00	\$164.00
3312		PACK50 PCS(3 / 8" X 1")	CAMARO		D71	\$104.00	\$104.00
3312	3312 1067QA	70-81 CROSS MEMBER TRANNY		4	G143	\$110.68	\$110.68
3312		SUPPORTTURBO 400 TRAN.	CAMARO	ļ ·	0143	Ψ110.00	Ψ110.00
3312	3312 1068G	HOOD HINGE RH 67 / 9		20	A91	\$442.20	\$442.20
3312	10000	CAMARO,65 / 7 IMPA	CAMARO		A)I	ψττ2.20	Ψ112.20
3312	3312 1068H	HOOD HINGE LH 67 / 9		20	A91	\$442.20	\$442.20
3312	100011	CAMARO,65 / 7 IMPA	CAMARO		A	Ψ-1-2.20	Ψ-1-2.20
3312	3312 1068Q	67-73 HOOD SAFETY LATCH		6	A133	\$71.28	\$71.28
0012		BLACK	CAMARO		11100	Ψ/1.20	Ψ71.20
3312	1071	HOOD COWL VENT GRILLE70-73	CAMARO	4	E105	\$266.44	\$266.44
		47-54 GMC BUMPER FILLERGMC		_			
3312 1096	ONLY	CHEVY PU	6	F135	\$284.52	\$284.52	
2212		GRILLE UPPER BAR 57 CHEVY			1.65	Φ50.66	Φ52.55
3312 1096E	ONLY	CHEVY PU	2	A65	\$52.66	\$52.66	
2212	2212 10070	68-72 REAR FENDER STEPSIDE			N22	¢1.720.00	¢1 720 00
3312 1097G	RH	CHEVY PU	6	N33	\$1,738.80	\$1,738.80	
3312 1097Н	68-72 REAR FENDER STEPSIDE		6	N32	\$1,750.02	\$1,750.02	
	LH	CHEVY PU	0	1434	\$1,730.02	\$1,730.02	
3312	1099G	INNER FENDER RH 67-72	CHEVY PU	8	J161	\$218.48	\$218.48
			CHEVYPU	1		,	
3312	1099H	INNER FENDER LH 67-72	CHEVY PU	7 4	J161	\$109.40	\$109.40
3312 1103DJ	1102DT	55-59 ROOF FRONT FILLER		12	C74	\$281.76	\$201.76
	BRACE	CHEVY PU	12	C/4	φ201./0	\$281.76	
3312	1103M	DOOR LATCH LH 47-51	CHEWA DA	4	B32	\$88.44	\$88.44
3312 110311		CHEVY PU	_		Ψ00.11	Ψ00.11	

PAGE:1