Flair Log gauge marker

Print at 100 % (actual size, not "fit to page"). The ruler must measure 50 mm.

16 mm - start with this one

12 mm - phone close to the machine, or little room on the gauge

20 mm - phone far away (gauge small in the picture)



How to use it

1. Cut one marker out along the dashed circle. Keep the white border: the app needs it to see the edge of the black ring.
2. Stick it on the gauge, lower right, facing the phone: on the glass over the logo (keep the 0-11 bar scale free) or on the rubber guard. On the gauge it moves with it and the app finds the dial from the marker alone.
3. It must stay in view during the whole shot: not under the lever or your hand, and without glare (plain paper; no glossy tape over it).
4. The wedge may point any way, but the marker must not move afterwards.
5. Calibrate again (Brew > target icon). The app says "Marker found". Not found: use a bigger size, or bring the phone a little closer.