

Introduction to Breadboards

1. Illustration of a breadboard:



Schematic



Internal Anatomy

Instructions:

As shown in the figure above, three colored lines are used on the breadboard to represent the relationship between holes and holes. The holes on a connecting line indicate that they are connected, and the holes between different lines are not connected.