

Lesson 9 Test the LCD1602 display

Table

1. Introduction of 1602 LCD	1
2. What do you need to prepare	3
3. Wiring	3
4. Upload the code and test	5
5. Code	7
6. Any questions and suggestions are welcome	8


1. Introduction of 1602 LCD


I2C communication

I2C (Inter-Integrated Circuit) is a two-wire serial communication mode, which can be used for the connection of micro controllers and their peripheral equipment. Devices using I2C communication must be connected to the serial data (SDA) line, and serial clock (SCL) line (called I2C bus). Each device has a unique address and can be used as a transmitter or receiver to communicate with devices connected to the bus.

LCD1602 communication

The LCD1602 Display Screen can display 2 lines of characters in 16 columns. It is capable of displaying numbers, letters, symbols, ASCII code and so on. As shown below is a monochrome







LCD1602 Display Screen along with its circuit pin diagram.


I2C LCD1602 Display Screen integrates an I2C chip, which connects the serial-input & parallel-output circuit to the LCD1602 Display Screen. This allows us to use only 4 lines to the operate the LCD1602.





The serial-to-parallel IC chip used in this module is PCF8574T (PCF8574AT), and its default I2C address is 0x27(0x3F).

PCF8574 chippindiagram:



PCF8574 chip pin and LCD1602 pin are corresponding to each other and connected with each other: So we only need 4 pins to control the 16 pins of the LCD1602 Display Screen through the I2C connector. In this project, we will use the I2C LCD1602 to display some static characters.




2. What do you need to prepare

Components	Quantity	Picture	Remark
USB Cable	1		
Control board	1	X1 OFF C1330B C2 SCL X4 A SDAA SSDAA	
LCD1602 Display Module	1	1 VSS VDD VORSRW E DO D1 D2 D3 D4 D5 D6 D7 A K SDA SCL	Not included in this Kit, just for example. you can prepared what you want. Thanks
Dupont wires	1		

3. Circuit Connection

Use a 4pin cable to connect the interface of the 1602 LCD module to the X3 interface on the control board, and then use a USB cable to connect the control board. You don't need to connect the 18650 battery for external power supply.





Wiring between the LCD1602display and the control board			
Connector of LCD1602 display	X3 Connector of the control board		
GND	GND		
VCC	5V		
SDA	SDA		
SCL	SCL		




4. Upload the code and test

The code used in this lesson is placed in this folder: "E:\CKK0019-main\Tutorial\sketches"

4.1 Double-click the Arduino IDE shortcut on the desktop to open it



4.2 Click "File" --- "open"



4.3 Select the code in the folder named 7 1 LCD dispaly:

E:\CKK0019-main\Tutorial\sketches\7 1 LCD dispaly, Click "open"

4.4 Select the board "Arduino UNO" and Port "COM3" (COM port is commonly known as an input output port for a device normally PC which enables communication between Arduino



and PC. You can check your arduino com number in device manager, the com port of our arduino board is recognized as COM3 in this tutorial)

```
2.1.1 Transplay | Arduino IDE 2.1.1
     Edit Sketch Tools Help
                     Arduino Uno
                     Unknown
        7_1_LCD_c
                     COM1
           6
           7
                      Arduino Uno
           8
           9
          10
                  Select other board and port...
          11
               LiquidCrystal I2C lcd(0x27,16,2); // set the LCD ad
          12
          13
                void setup()
          15
                 lcd.init(); // initialize the lcd
          16
                 lcd.backlight();
          17
                 lcd.clear();
          18
          19
          20
               void loop()
          21
          22
          23
                 lcd.setCursor(2,0);//set the line and the char be
                 lcd.print("Hello World!");
          24
                 lcd.setCursor(1,1);
          25
                 lcd.print("Hello Cokoino!");
          26
```

4.5 Install LiquidCrystal libraries

For the installation method, please refer to the method of installing the library file Servo.h in Lesson 4

- 4.6 Click compile button successfully compiled the code will display "Done compiling"
- 4.7 Click upload button, successfully uploading the code will display "Done uploading". When code is uploaded successfully, the program starts to run.
- 4.8 After the code is uploaded successfully, you can see two lines of text "Hello World!", "Hello Cokoino" displayed on the LCD display.





5. Code

7_1_LCD_display.ino

```
#include <Wire.h>
#include <LiquidCrystal_I2C.h>
LiquidCrystal_I2C lcd(0x27,16,2); // set the LCD address to 0x27 for a 16 chars and 2
line display
void setup()
 lcd.init(); // initialize the lcd
 lcd.backlight();
 lcd.clear();
}
void loop()
{
 lcd.setCursor(2,0);//set the line and the char begaining for the print information
 lcd.print("Hello World!");
 lcd.setCursor(1,1);
 lcd.print("Hello Cokoino!");
}
```



6. Any questions and suggestions are welcome

THANK YOU for participating in this learning experience!

If you find any errors, omissions or you have suggestions and/or questions about this lesson, please feel free to contact us:

cokoino@outlook.com

We will make every effort to make changes and correct errors as soon as feasibly possible and publish a revised version.

If you want to learn more about Arduino, Raspberry Pi, Smart Cars, Robotics and other interesting products in science and technology, please continue to visit our Amazon Store by search for "LK COKOINO" on Amazon. We will continue to launch fun, cost-effective, innovative and exciting products.