

How to replace the ink in the printer

SOP-002: Replacing the ink in the printer (HP OfficeJet 3830)

This guide provides users with steps on how to replace an empty or low ink cartridge in the HP OfficeJet 3830 printer.

Please ensure you have gone through this guide intended for non-technical users before contacting IT Support.

1. Issue

Printer displays a Low Ink or Replace Ink Cartridge message, or print quality has significantly decreased.


2. Solution

1. Ensure the printer is powered on.
2. Close the output tray.
3. Open the front access door of the printer.




3.a)

4. Open the ink cartridge access door and wait for the cartridge carriage to move to the center of the printer.



4.a)

5. Press down gently on the ink cartridge to release it, then pull it straight out of the slot.



5.a)



5.b)

6. Remove the protective plastic tape from the ink cartridge.



6.a)

Caution: Do not touch the copper-colored electrical contacts or ink nozzles.

7. Insert the new ink cartridge into the correct slot and push firmly until it clicks into place.



7.a)

8. Close the ink cartridge access door and the front access door.



8.a)



8.b)

9. Close the output tray.

10. **Verify** that the issue is resolved:

- Printer no longer displays an ink cartridge error.
- Printer recognizes the new cartridge.
- Test page prints successfully with good print quality.

3. Prevention Best Practices

- Store replacement ink cartridges in their original packaging until needed.
- Avoid touching the electrical contacts or ink nozzles.
- Replace cartridges promptly when low to maintain print quality.
- Use genuine or approved replacement cartridges compatible with the HP OfficeJet 3830.

Contact HP business or IT Support if:

- Hardware damage is visible
- The printer continues to display an ink cartridge error after reinstalling the cartridge.
- The cartridge carriage does not move to the center of the printer.
- Print quality issues persist after cleaning and alignment.
- Physical damage to the printer or ink cartridge is visible.

Version	Date	Author	Changes
1.0	June 2026	Coleton Vowles	Initial release