

Sustainable Communication Networks

Prof. Dr. Anna Förster

USB meter – Introduction and Usage

Prof. Dr. Anna Förster Saurabh Band Dr. Jens Dede





Specifications

The AT-34 is a small but multifunctional USB multimeter. By supporting current Quick Charge standards, it can also be easily used in conjunction with current handheld hardware.

Voltage measurement range: 3,7 - 30 V

Voltage resolution: 0,01 V

Voltage accuracy: ±0,8 %(+4 digits)

Current measurement Range: 0 - 4 A

• Current resolution: 0,001 A

• Current accuracy: ±1 %(+4 digits)

Power measurement range: 0 - 120 W


Capacity accumulation Range: 0 - 99999 mAh

Energy accumulation range: 0-99'999mWh (999,99Wh)













Toggle Menu

- Use this button on the back to toggle between different options
- Long press the button to toggle. Release the button to select the particular option
- Short press will put the meter in Quick Charge detection mode. Short press again to switch to main screen.





Turn display ON/OFF

Toggle Temperature Unit

Switch Log Mode (channel)

Clear the Readings on Selected Log Mode

Flip the display

