
StrainN Facet1
Strain
Time [s]
ABQ
OAS
Chrono
StressN Facet 1
Stress [MPa]
Time [s]
ABQ
OAS
Chrono
StrainT Facet1
×10^-17
Strain
Time [s]
ABQ
OAS
Chrono
StressT Facet1
×10^-14
Stress [MPa]
Time [s]
ABQ
OAS
Chrono
StressN-StrainN Facet 1
Stress [MPa]
Strain
ABQ
OAS
Chrono
StressT-StrainT Facet1
×10^-14
Stress [MPa]
Strain
×10^-17
ABQ
OAS
Chrono


StrainN Facet2
Strain
Time [s]
ABQ
OAS
Chrono
StressN Facet 2
Stress [MPa]
Time [s]
ABQ
OAS
Chrono
StrainT Facet2
×10^-17
Strain
Time [s]
ABQ
OAS
Chrono
StressT Facet2
×10^-14
Stress [MPa]
Time [s]
ABQ
OAS
Chrono
StressN-StrainN Facet 2
Stress [MPa]
Strain
ABQ
OAS
Chrono
StressT-StrainT Facet2
×10^-14
Stress [MPa]
Strain
×10^-17
ABQ
OAS
Chrono


StrainN Facet3
Strain
Time [s]
StressN Facet 3
Stress [MPa]
Time [s]
StrainT Facet3
×10^-11
Strain
Time [s]
StressT Facet3
×10^-7
Stress [MPa]
Time [s]
StressN-StrainN Facet 3
Stress [MPa]
Strain
StressT-StrainT Facet3
×10^-7
Stress [MPa]
Strain
×10^-11
ABQ
OAS
Chrono


StrainN Facet4
Strain
Time [s]
StressN Facet 4
Stress [MPa]
Time [s]
StrainT Facet4
×10^-11
Strain
Time [s]
StressT Facet4
×10^-8
Stress [MPa]
Time [s]
StressN-StrainN Facet 4
Stress [MPa]
Strain
StressT-StrainT Facet4
×10^-8
Stress [MPa]
Strain
×10^-11
ABQ
OAS
Chrono


StrainN Facet5
Strain
Time [s]
StressN Facet 5
Stress [MPa]
Time [s]
StrainT Facet5
×10^-11
Strain
Time [s]
StressT Facet5
×10^-7
Stress [MPa]
Time [s]
StressN-StrainN Facet 5
Stress [MPa]
Strain
StressT-StrainT Facet5
×10^-7
Stress [MPa]
Strain
×10^-11
ABQ
OAS
Chrono


StrainN Facet6
Strain
Time [s]
StressN Facet 6
Stress [MPa]
Time [s]
StrainT Facet6
×10^-11
Strain
Time [s]
StressT Facet6
×10^-7
Stress [MPa]
Time [s]
StressN-StrainN Facet 6
Stress [MPa]
Strain
StressT-StrainT Facet6
×10^-7
Stress [MPa]
Strain
×10^-11
ABQ
OAS
Chrono


StrainN Facet7
Strain
Time [s]
StressN Facet 7
Stress [MPa]
Time [s]
StrainT Facet7
×10^-11
Strain
Time [s]
StressT Facet7
×10^-7
Stress [MPa]
Time [s]
StressN-StrainN Facet 7
Stress [MPa]
Strain
StressT-StrainT Facet7
×10^-7
Stress [MPa]
Strain
×10^-11
ABQ
OAS
Chrono


StrainN Facet8
Strain
Time [s]
ABQ
OAS
Chrono
StressN Facet 8
Stress [MPa]
Time [s]
ABQ
OAS
Chrono
StrainT Facet8
×10^-11
Strain
Time [s]
ABQ
OAS
Chrono
StressT Facet8
×10^-7
Stress [MPa]
Time [s]
ABQ
OAS
Chrono
StressN-StrainN Facet 8
Stress [MPa]
Strain
ABQ
OAS
Chrono
StressT-StrainT Facet8
×10^-7
Stress [MPa]
Strain
×10^-11
ABQ
OAS
Chrono


StrainN Facet9
Strain
Time [s]
StressN Facet 9
Stress [MPa]
Time [s]
StrainT Facet9
×10^-11
Strain
Time [s]
StressT Facet9
×10^-7
Stress [MPa]
Time [s]
StressN-StrainN Facet 9
Stress [MPa]
Strain
StressT-StrainT Facet9
×10^-7
Stress [MPa]
Strain
×10^-11
ABQ
OAS
Chrono


StrainN Facet10
Strain
Time [s]
ABQ
OAS
Chrono
StressN Facet 10
Stress [MPa]
Time [s]
ABQ
OAS
Chrono
StrainT Facet10
×10^-11
Strain
Time [s]
ABQ
OAS
Chrono
StressT Facet10
×10^-7
Stress [MPa]
Time [s]
ABQ
OAS
Chrono
StressN-StrainN Facet 10
Stress [MPa]
Strain
ABQ
OAS
Chrono
StressT-StrainT Facet10
×10^-7
Stress [MPa]
Strain
×10^-11
ABQ
OAS
Chrono


StrainN Facet11
Strain
Time [s]
StressN Facet 11
Stress [MPa]
Time [s]
StrainT Facet11
×10^-11
Strain
Time [s]
StressT Facet11
×10^-7
Stress [MPa]
Time [s]
StressN-StrainN Facet 11
Stress [MPa]
Strain
StressT-StrainT Facet11
×10^-7
Stress [MPa]
Strain
×10^-11
ABQ
OAS
Chrono


StrainN Facet12
Strain
Time [s]
StressN Facet 12
Stress [MPa]
Time [s]
StrainT Facet12
×10^-11
Strain
Time [s]
StressT Facet12
×10^-7
Stress [MPa]
Time [s]
StressN-StrainN Facet 12
Stress [MPa]
Strain
StressT-StrainT Facet12
×10^-7
Stress [MPa]
Strain
×10^-11
ABQ
OAS
Chrono