
StrainN Facet1
StressN Facet 1
StrainT Facet1
StressT Facet1
StressN-StrainN Facet 1
StressT-StrainT Facet1
ABQ
OAS
Chrono
JAX
Strain
Stress [MPa]
Time [s]
1
0.5
0
-0.5
-1
0
0.2
0.4
0.6
0.8


StrainN Facet2
Strain
Time [s]
StressN Facet 2
Stress [MPa]
Time [s]
StrainT Facet2
Strain
Time [s]
StressT Facet2
Stress [MPa]
Time [s]
StressN-StrainN Facet 2
Stress [MPa]
Strain
StressT-StrainT Facet2
Stress [MPa]
Strain
ABQ
OAS
Chrono
JAX


StrainN Facet3
StressN Facet 3
StrainT Facet3
StressT Facet3
StressN-StrainN Facet 3
StressT-StrainT Facet3
ABQ
OAS
Chrono
JAX
Strain
Stress [MPa]
Time [s]
1
0.5
0
-0.5
-1
0
0.2
0.4
0.6
0.8


StrainN Facet4
StressN Facet 4
StrainT Facet4
StressT Facet4
StressN-StrainN Facet 4
StressT-StrainT Facet4
ABQ
OAS
Chrono
JAX
Strain
Stress [MPa]
Time [s]
1
0.5
0
-0.5
-1
0
0.2
0.4
0.6
0.8


StrainN Facet5
×10^-3
Strain
Time [s]
StressN Facet 5
Stress [MPa]
Time [s]
StrainT Facet5
Strain
Time [s]
StressT Facet5
Stress [MPa]
Time [s]
StressN-StrainN Facet 5
Stress [MPa]
Strain
×10^-3
StressT-StrainT Facet5
Stress [MPa]
Strain
ABQ
OAS
Chrono
JAX


StrainN Facet6
×10^-3
Strain
Time [s]
StressN Facet 6
Stress [MPa]
Time [s]
StrainT Facet6
Strain
Time [s]
StressT Facet6
Stress [MPa]
Time [s]
StressN-StrainN Facet 6
Stress [MPa]
Strain
×10^-3
StressT-StrainT Facet6
Stress [MPa]
Strain
ABQ
OAS
Chrono
JAX


StrainN Facet7
StressN Facet 7
StrainT Facet7
StressT Facet7
StressN-StrainN Facet 7
StressT-StrainT Facet7
ABQ
OAS
Chrono
JAX
Strain
Stress [MPa]
Time [s]
1
0.5
0
-0.5
-1
0
0.2
0.4
0.6
0.8


StrainN Facet8
StressN Facet 8
StrainT Facet8
StressT Facet8
StressN-StrainN Facet 8
StressT-StrainT Facet8
ABQ
OAS
Chrono
JAX
Strain
Stress [MPa]
Time [s]
1
0.5
0
-0.5
-1
0
0.2
0.4
0.6
0.8


StrainN Facet9
×10^-3
Strain
Time [s]
StressN Facet 9
Stress [MPa]
Time [s]
StrainT Facet9
Strain
Time [s]
StressT Facet9
Stress [MPa]
Time [s]
StressN-StrainN Facet 9
Stress [MPa]
Strain
×10^-3
StressT-StrainT Facet9
Stress [MPa]
Strain
ABQ
OAS
Chrono
JAX


StrainN Facet10
×10^-3
Strain
Time [s]
StressN Facet 10
Stress [MPa]
Time [s]
StrainT Facet10
Strain
Time [s]
StressT Facet10
Stress [MPa]
Time [s]
StressN-StrainN Facet 10
Stress [MPa]
Strain
×10^-3
StressT-StrainT Facet10
Stress [MPa]
Strain
ABQ
OAS
Chrono
JAX


StrainN Facet11
×10^-3
Strain
Time [s]
StressN Facet 11
Stress [MPa]
Time [s]
StrainT Facet11
Strain
Time [s]
StressT Facet11
Stress [MPa]
Time [s]
StressN-StrainN Facet 11
Stress [MPa]
Strain
×10^-3
StressT-StrainT Facet11
Stress [MPa]
Strain
ABQ
OAS
Chrono
JAX


StrainN Facet12
×10^-3
Strain
Time [s]
ABQ
OAS
Chrono
JAX
StressN Facet 12
Stress [MPa]
Time [s]
StrainT Facet12
Strain
Time [s]
StressT Facet12
Stress [MPa]
Time [s]
StressN-StrainN Facet 12
Stress [MPa]
Strain
×10^-3
StressT-StrainT Facet12
Stress [MPa]
Strain