
StrainN Facet1
Strain
Time [s]
StressN Facet 1
Stress [MPa]
Time [s]
StrainT Facet1
Strain
Time [s]
StressT Facet1
Stress [MPa]
Time [s]
StressN-StrainN Facet 1
Stress [MPa]
Strain
StressT-StrainT Facet1
Stress [MPa]
Strain
ABQ
OAS
Chrono
JAX


StrainN Facet2
Strain
Time [s]
StressN Facet 2
Stress [MPa]
Time [s]
StrainT Facet2
Strain
Time [s]
StressT Facet2
Stress [MPa]
Time [s]
StressN-StrainN Facet 2
Stress [MPa]
Strain
StressT-StrainT Facet2
Stress [MPa]
Strain
ABQ
OAS
Chrono
JAX


StrainN Facet3
StressN Facet 3
StrainT Facet3
StressT Facet3
StressN-StrainN Facet 3
StressT-StrainT Facet3
ABQ
OAS
Chrono
JAX
Strain
Stress [MPa]
Time [s]
1
0.5
0
-0.5
-1
0
0.2
0.4
0.6
0.8


StrainN Facet4
StressN Facet 4
StrainT Facet4
StressT Facet4
StressN-StrainN Facet 4
StressT-StrainT Facet4
ABQ
OAS
Chrono
JAX
Strain
Stress [MPa]
Time [s]
1
0.5
0
-0.5
-1
0
0.2
0.4
0.6
0.8


StrainN Facet5
StressN Facet 5
StrainT Facet5
StressT Facet5
StressN-StrainN Facet 5
StressT-StrainT Facet5
ABQ
OAS
Chrono
JAX
Strain
Stress [MPa]
Time [s]
1
0.5
0
-0.5
-1
0
0.2
0.4
0.6
0.8


StrainN Facet6
StressN Facet 6
StrainT Facet6
StressT Facet6
StressN-StrainN Facet 6
StressT-StrainT Facet6
ABQ
OAS
Chrono
JAX
Strain
Stress [MPa]
Time [s]
1
0.5
0
-0.5
-1
0
0.2
0.4
0.6
0.8


StrainN Facet7
Strain
Time [s]
StressN Facet 7
Stress [MPa]
Time [s]
StrainT Facet7
Strain
Time [s]
StressT Facet7
Stress [MPa]
Time [s]
StressN-StrainN Facet 7
Stress [MPa]
Strain
StressT-StrainT Facet7
Stress [MPa]
Strain
ABQ
OAS
Chrono
JAX


StrainN Facet8
Strain
Time [s]
StressN Facet 8
Stress [MPa]
Time [s]
StrainT Facet8
Strain
Time [s]
StressT Facet8
Stress [MPa]
Time [s]
StressN-StrainN Facet 8
Stress [MPa]
Strain
StressT-StrainT Facet8
Stress [MPa]
Strain
ABQ
OAS
Chrono
JAX


StrainN Facet9
Strain
Time [s]
StressN Facet 9
Stress [MPa]
Time [s]
StrainT Facet9
Strain
Time [s]
StressT Facet9
Stress [MPa]
Time [s]
StressN-StrainN Facet 9
Stress [MPa]
Strain
StressT-StrainT Facet9
Stress [MPa]
Strain
ABQ
OAS
Chrono
JAX


StrainN Facet10
Strain
Time [s]
StressN Facet 10
Stress [MPa]
Time [s]
StrainT Facet10
Strain
Time [s]
StressT Facet10
Stress [MPa]
Time [s]
StressN-StrainN Facet 10
Stress [MPa]
Strain
StressT-StrainT Facet10
Stress [MPa]
Strain
ABQ
OAS
Chrono
JAX


StrainN Facet11
StressN Facet 11
StrainT Facet11
StressT Facet11
StressN-StrainN Facet 11
StressT-StrainT Facet11
ABQ
OAS
Chrono
JAX
Strain
Stress [MPa]
Time [s]
1
0.5
0
-0.5
-1
0
0.2
0.4
0.6
0.8


StrainN Facet12
Strain
Time [s]
StressN Facet 12
Stress [MPa]
Time [s]
StrainT Facet12
Strain
Time [s]
StressT Facet12
Stress [MPa]
Time [s]
StressN-StrainN Facet 12
Stress [MPa]
Strain
StressT-StrainT Facet12
Stress [MPa]
Strain
ABQ
OAS
Chrono
JAX