



Yarn-feeder

Use 2 x 200mm beam 2 x 60mm beam 1 x 40mm beam made out of makerbeam


here will be mounted all the machine parts







4 x Z-shape


keeps the surfaces down and doesn't allow to move them up




Box of electronics













2 x Yarn holder2

Attach a metal piece for passing the yarn











Curated by

David Cuartielles

20th December 2014 - 31th July 2015

Commissioned by



More info

www.knitic.com - www.var-mar.info