

CONTROL AUTOMATICO

CONSTANTE DE ERROR

Profesor: Erick Salas Chaverri.



FUNCION DE TRANSFERENCIA

Limite s
$$\frac{1}{1+H(s)*F(s)}$$
 * I(s)

1 Limite 1 S S--->0 1+ 1

S

1 Limite S

1 1+ 1 S S--->0

1 = 0 1+ 1



$$\frac{1}{1 + \frac{1}{0}} * \frac{1}{0} = \infty$$