

PICTORIAL VIEW

NOTES:

- 1. ALL THE DIMENSIONS ARE IN INCHES AND SHOWN IN [] ARE MILLIMETERS
- 2. BREAK ALL SHARP EDGES.
- 3. INSPECTION: 100% VT, MT ON JOINT 4. IDENTIFICATION: PART NUMBER TO BE STAMPED ON RING