

NOTE 32/

1 MACHINE TALL OVER EXCEPT WHERE SHOWN OTHERWISE.

2 ALLOW FOR GRINDING WHERE SHOWN THUS %

3 HARDEN & TEMPER TO 55 ROCKWELL COMIN AFTER

4 REMOVE ALL BURRS & SHARP EDGES

5 RUBBER STAMP WARMAN RVO77* * AFTER INSPECTION. APPROPRIATE WARMAN MATERIAL CODE

6 'GLOSS COAT' PROTECTIVE COVERING

MATERIAL. WARMAN CODE C21' UNLESS OTHERWISE SPECIFIED.

DATE SCALE	12-7-79	DRN.	RE.	WARMAN PUMP SHAFT SLEEVE EJECTOR RI	/077
WARMAN INTERNATIONAL LIMITED OFFICE OF ORIGIN : SYDNEY				A4 -110 -0-19494	REV.

- 6 mm - 1 -

W