



## NOTA:

- MAQUINAR EN BASE A MODELO 3D
- **A:**  $3X \emptyset 11.00 \text{ THRU} \bigsqcup \emptyset 17.00 \ \text{$\pi$} 13.00$
- **B:** 3X ROSCAS M10 X 1.5 THRU
- **C:** 2X Ø 16.00 THRU
- **D:** 2X  $\emptyset$  10.00 THRU  $\square$   $\emptyset$  11.00  $\vee$  12.00

maquinados <b>aeme</b>	<b>DESCRIPCION:</b> HTA 40206 PORTA#6 SCAN COMPLETO <b>CANTIDAD:</b> 1 PIEZA								
CLIENTE: METALSA	<b>ESCALA:</b> 1 : 1.5	<b>OT:</b> 2	DIMENSIONES: mm		1	MATERIAL: 4140T			
USUARIO: MARKO SANMIGUEL			DIBUJÓ:	STEVEN MORA	FE	<b>CHA:</b> 01/11/2021	<b>HOJA:</b> 1 - 2		





maquinadosaeme	<b>DESCRIPCION:</b> HTA 40206 PORTA#6 SCAN COMPLETO <b>CANTIDAD:</b> 1 PIEZA								
CLIENTE: METALSA	<b>ESCALA:</b> 1 : 1	<b>OT:</b> 2110 12010		DIMENSIONES: mm	MATERIAL: 4140T				
USUARIO: MARKO SANMIGUEL			DIBUJÓ:	STEVEN MORA	<b>FECHA:</b> 01/11/2021	<b>HOJA:</b> 2 - 2			