



1. DIE COLOR LINE CLEARANCE: +0.08(SID 2. CUTTING DIES TO HAVE 5 MM LAND & 1°

MODE	X-POS	Y-POS	
A: 3/8" A 1 A 2	TAP DP25 -181. 2 -181. 2	5 242. 0 394. 3	
B: 1/2" B 1 B 2	TAP -172. 7 -17. 8	74. 9 415. 3	
C 1 C 2	TAP DP15 -120. 8 -174. 3	34. 2 478. 8	
n 1 -	520-8.005 (3/ -172, 72 -181, 20 -181, 20 -17, 78	'8" REM) 49, 53 266, 77 369, 51 440, 69	Through
E: 014. E 1 2 3 4 5 6 7 8	O (Dr;) Ø22 DP15. -172. 7 -172. 7 -172. 7 -17. 7 -17. 8 -17. 8 -17. 8 -17. 8	4 17. 8 170. 2 320. 0 447. 0 17. 8 170. 2 320. 0 472. 4	
F: Ø3. C	(Drill) -151.9	Through 253, 0	1
G: Ø5. C G 1	(Drill) -128.7	Through 256, 8	n
H: Ø15. H 1 H 2	O (C/B) I -172.7 -17.8	0P15, 4 74, 9 415, 3	
I: Ø26. I 1 I 2	10 (WIRE, -139,82 -155,26	Borr) 28, 97 473, 58	Through