





TOOL NAME				
2 STATION	PIER	С	E DIE	Ξ
PART NAME ARM	SCALE		SHT. NO.	NO. OF SHTS
STANDARD ADJUSTABLE	FULL		1	12
DES. BY	DATE	P	ART NO.	
D. BARBOUR	3/13		330	8400.XXX
CHKD. BY	DATE	TC	OL NO. 330	8400,XXX
APP. BY	DATE	RS	EV.	
E Don	aeti	E	mar.	A




INVERTED PUNCH RETAINER

60 59		CRS	X 2 1/4 X 4 1/2 12 X 2 1/4 X 11 1
58		CRS	1 X 2 1/4 X 11 1 1 X 2 1/4 X 2 1/2 1
57		CRS	1/2 X 2 X 25 1/2 1
56	Ė	0.10	1/2 × 2 × 20 1/2 1
55	1	CRS	1 3/4 X 2 1/2 X 2 3/4 1
54		CRS	2 X 2 3/4 X 3 1/4 1
53	1	CRS	2 X 2 3/4 X 12 3/4
52	8	PUR	DAYHJX50D300 P=.375 M2
51		PUR	DAY.HJX50D287 P=.375 M2
50	6	PUR	DAY. HJX50D275 P=.375 M2
49		PUR	DAYHJX50C262 P=.375 M2
48			REID DS-7 SPR. STOP 3
47		CRS	1 X 1 1/4 X 1 1/2 10
46 45		PUR PUR	1/2-13 X 1/2 S.S. SCR
44		A-2	DAY. VNX75-100 P=.217 M2 3/4 X 2 1/2 X 2 3/4
43		PUR	DAY.VUXP400 P=.201 M2
42		PUR	10-32 X 1 1/2 SHCS
41		PUR	1/2-13 X 2 3/4 SHCS
40	17	PUR	5/8-11 X 2 1/2 SHCS
39	1	CRS	2 X2 X 29 10
38	12	PUR	5/8 DIA. X 2 DOWEL 3
37		PUR	1/4-20 X 1 1/4 SHCS
36		PUR	1/4-20 X 3/4 SHCS
35	2	CRS	2 X 2 X 29 10
34		PUR	1/2 DIA. X 2 DOWEL 3 DAYHJXC250 P=.375 M2 DTR
33 32		PUR	3/8-16 Y 2 SHCS
31		CRS	3/8-16 X 2 SHCS 1 X 1 X 2 13/16 1
30		PUR	1/4-20 X 2 1/2 SHCS
29		PUR	1/2-13 X 4 SHCS 3
28		A-2	3/8 X 2 X 14 1
27	1	A-2	1 1/4 X 2 X 14
26	1	A-2	3/8 X 2 X 12 1
25		A-2	1 1/4 X 2 X 12
24	1	A-2	1 5/8 X 2 1/2 X 2 3/4 7
23		A-2	3/8 X 3 X 9 3/4 11
22	1	A-2	1 1/4 X 3 X 9 3/4 7 3/8 X 3 X 9 5/8 1
20	1	A-2	
19		A-2 4142	1 1/4 X 3 X 9 5/8 2 X 3 X 10 6
18		A-2	5/8 X 1 1/2 X 10
17		4142	2 X 3 X 8 6
16	1	A-2	5/8 X 1 1/2 X 8
15	2	PUR	1/2 DIA. X 2 DOWEL 3
14	2	PUR	1/2-13 X 2 1/4 SHCS
13	2	PUR	5/16-18 X 1 1/4 SHCS
12	1	A-2	5/8 X 1 X 3 6
11		CRS	2 X 2 X 12 6
10		4142	2 X 3 X 8 5/8 5
9	1	A-2	5/8 X 1 1/2 X 8 1/2 5
7	1	4142	2 X 3 X 7 5/8 5 5/8 X 1 1/2 X 7 1/2 5
6		A-2 NYLON	1/2 X 3/4 X 1 10
5			ANLEY CROWDER# 9-90-6
4		CRS	2" DIA. X 4 3/4 6
3		S-7	2 X 3 X 5 5
2		A-2	5/8 X 1 1/2 X 5 5
1	1	PLIE	DANLY DIE SET SEE DATA 9
DET. NO.	NO. RECO	MATL	FINISH STOCK SIZE
TOOL	NAME OF		ION PIERCE DIE
PART	NAM	ARM	SCALE SHT. NO. NO. OF
STAN	DARD	ADJUST/	ABLE FULL 2 12

Dometic ****







HOLE TABLE						
HOLE	ø	QTY	DESCRIPTION			
A	ø2.0000	1	PICK UP			
В	ø.5000	10	BORE PF X 1* DP.			
D	ø.3073	28	DRILL AND TAP 3/8-16 X 7/8 DP.			
E	ø.1959	8	SPOT ONLY FOR 1/4-20 TAP DRILL AT ASSY.			


		LIST OF	COORDINA	
HOLE	Х	Y	ø	DESCRIPTION
A1 B1	.0000	.0000	\$2,0000 \$,5000	
	-1.125 0	-2.192 0		
B2	-4.625	-2.192	ø.5000	
B3	-14.37	-2.192	ø.5000	
R4	50 -2.625	-4.192	ø.5000	
	0	0		
B5	-11.37 50	-4.442 0	ø.5000	
B6	-21.12 50	-4.442 0	ø.5000	
B7	-2.280	-8.221	ø.5000	
88	-12.25	-8.221	ø.5000	
B9	-16.25	-8.221	4.5000	
	-16.25 -24.25	0		
B10	-24.25 00	-8.221 0	ø.5000	
	- 00	, i		
	0.005	0.400	- 7077	
D1	-2.625 0	-2.192 0	ø.3073	
D2	-3.875 0	-2.192 0	ø.3073	
D3	-6.125	-2.192	ø.3073	
D4	-9.125	-2,192	ø.3073	
D5	-12.12	-2.192	ø.3073	
	50	0		
D6	-13.62 50	-2.192 0	ø.3073	
D7	-15.87	-2.192	ø.3073	
DB	50 -18,87	-2.192	ø.3073	
D9	50 -22.00	-2.192	ø.3073	
	00	0 1		
D10	-1.125 0	-4.192 0	ø.3073	
D11	-3.875	-4.442 0	ø.3073	
D12	-6.125	-4.442	ø.3073	
D13	-9.125	-4.442	ø.3073	
D14	-12.12	-4.442	ø.3073	
	50	0		
D15	-13.62 50	-4.442 0	ø.3073	
D16	-15.87	-4.442	ø.3073	
D17	_50 -18.87	-4.442	ø.3073	
D18	-22.00	-4,442	ø.3073	
	-2.280	0		
D19	0	-7.221 0	ø.3073	
D20	-8.280	-7.221	ø.3073	
D21	-12.25	-7.221	ø.3073	
D22	-16,25	-7,221	ø.3073	
	00	0		
D23	-20.25 00	0	ø.3073	
D24	-24.25	-7.221	ø.3073	
D25	-4.280	-8.221	ø.3073	
D26	-10.25	-8.221	ø.3073	
D27	00 -18.25	-8.221	ø.3073	
	-18.25 00 -22.25	0 0		
D28	-22.25 00	-8.221	ø.3073	
E1	-6.594	6270	ø.1959	
E2	-20.59	6270	ø.1959	
E3	54 -4.404	-1.007	ø.1959	
	6	0 1		
E4	-18.40 54	-1.007 0	ø.1959	
E5	-6.594	-9.781	ø.1959	
E6	-20.59	-9.781	ø.1959	
E7	54 -4,404	-10,161	ø.1959	
E8	-18.40	-10.161	ø.1959	

INVERTED PUNCH RETAINER





TOOL MAKE			
2 STATION	PIER	CE D	ΙE
PART NAME ARM STANDARD ADJUSTABLE	SCALE FULL	SHT. N 4	10. NO. OF 5
DES. BY D. BARBOUR	3/13	PART NO	308400.X
CHKD. BY	DATE		308400.X
APP. BY	DATE	REV.	1








TOOL NAME				
2 STATION	PIER	C	E DIE	
PART NAME ARM STANDARD ADJUSTABLE	SCALE FULL		SHT. NO. 5	NO. OF SHT:
DES. BY D. BARBOUR	3/13	P	ART NO. 330	8400.XXX
CHKD. BY	DATE	11		8400.XXX
APP. BY	DATE	R	īv.	
III Dei	meti	E	aur.	A.
















DATE PART NO. 3308400.XXX
DATE TOOL NO. 3308400.XXX
DATE REV.

III Dometic ****





TOOL HAME 2 STATION	I DIE	CE DI	F
PART NAME ARM	SCALE	SHT. NO	
STANDARD ADJUSTABLE	FULL	7	12
DES. BY D. BARBOUR	3/13	PART NO.	08400
CHKD. BY	DATE		08400
APP. BY	DATE	REV.	












HOLE		Y	8	DESCRIPTION
A1	10.0000	-1.500 0	ø.5005	
A2	2.0000	-1.500 0	ø.5005	
B1	11.0000	-1.250 0	ø.5000	
B2	9.0000	-1.250 0	ø.5000	
В3	7.0000	-1.250 0	ø.5000	
B4	5.0000	-1.250 0	ø.5000	
B5	3.0000	-1.250 0	ø.5000	
B6	1.0000	-1.250 0	ø.5000	
C1	10.0000	5000	ø.4060	
C2	6.0000	5000	ø.4060	
C3	2.0000	5000	ø.4060	
C4	8.0000	-1.500 0	ø.4060	
C5	4.0000	-1.500 0	ø.4060	
D1	8.0000	5000	Ø.1959	
D2	4.0000	5000	ø.1959	
D3	11.5950	-1.500 0	ø.1959	
D4	6.0000	-1.500 0	ø.1959	
D5	.3750	-1.500 0	ø.1959	
E1		8130	ø.1400	
E2		8130	ø.1400	
E3	7.0000	8130		
E4	5.0000	8130	ø.1400	
E5	3.0000	8130	ø.1400	
E6	1.0000	8130	ø.1400	


	HOLE TABLE					
HOLE		QTY	DESCRIPTION			
A	ø.5005	2	THRU SF. JGR/WIRE BURN			
В	ø.5000	6	RING FIT FOR 1/2 HD BALL LOCK PUNCH			
С	ø.4060	5	DRILL AND C,BORE FOR 3/8 SHCS			
D	ø.1959	5	DRILL THRU 1/4-20 TAP X 3/4 DP. OPP. SIDE			
E	ø.1400	6	SPOT ONLY, DRILL IN DRILL PRESS AFTER			
			DITTING IN ANCHIAD HOLE ODD SIDE			

HOLE	X	Y	8	DESCRIPTION
A1	11.9400	-1.500 0	ø.5005	
A2	1.9700	-1.500 0	ø.5005	
B1	12.9700	-1.250 0	ø.5000	
B2	10.9700	-1.250 0	ø.5000	
B3	8.9700	-1.250 0	ø.5000	
B4	6.9700	-1.250 0	ø.5000	
B5	4.9700	-1.250 0	ø.5000	
86	2.9700	-1.250 0	ø.5000	
B7	.9700	-1.250 0	ø.5000	
C1	11.9400	5000	ø.4060	
C2	5.9400	5000	ø.4060	
C3	1.9700	5000	ø.4060	
C4	9.9400	-1.500 0	ø.4060	
C5	3.9700	-1.500 0	ø.4060	
D1	9.9400	5000	ø.1959	
D2	3.9700	5000	ø.1959	
D3	13.5950	-1.500 0	ø.1959	
D4	7.9700	-1.500 0	ø.1959	
D5	.3750	-1.500 0	ø.1959	
E1	12.9700	8130	ø.1400	
E2	10.9700	8130	ø.1400	
E3	8.9700	8130	p.1400	
E4	6.9700	8130	ø.1400	
E5	4.9700	8130	ø.1400	
E6	2.9700	8130	ø.1400	
E7	.9700	8130	ø.1400	

			HOLE TABLE
IOLE	ø	QTY	DESCRIPTION
Α	ø.5005	2	THRU SF. JGR/WIRE BURN
В	ø.5000	7	RING FIT FOR 1/2 HD BALL LOCK PUNCH
С	ø.4060	5	DRILL AND C,BORE FOR 3/8 SHCS
D	ø.1959	5	DRILL THRU 1/4-20 TAP X 3/4 DP. OPP. SIDE
E	ø.1400	7	SPOT ONLY, DRILL IN DRILL PRESS AFTER
			PUTTING IN ANGULAR HOLE OPP. SIDE

TOOL NAME				
2 STATION	PIER	C	E DIE	Ξ
PART NAME ARM STANDARD ADJUSTABLE	SCALE FULL		SHT. NO. 8	NO. 0
DES. BY D. BARBOUR	3/13	P	ART NO. 330	8400
CHKD. BY	DATE	11		8400
APP. BY	DATE	RI	īv.	









HOLE	X	LIST OF	COORDINA	DESCRIPTION
A1 B1	.0000	.0000	\$2.0000 \$.7500	
B1	25.2500	-7.971 0 -7.971	¢.7500 ¢.7500	
B2 B3	23.2500	-7.971 -7.971	¢.7500 ¢.7500	
B3 B4	21.2500	0	ø.7500 ø.7500	
B4 B5	17,2500	-7.9/1	\$.7500 \$.7500	
B5 B6	15,2500	-7.971 0 -7.971 0 -7.971	\$.7500 \$.7500	
B6 B7	15.2500	-7.9/1	¢.7500	
		-7.971 -7.971		
B8	11.2500	-7.971 0	ø.7500	
B9	9.2500	-7.971 0 -7.971	ø.7500	
B10	7.2500	-7.971 -7.971	ø.7500	
B11	5.2500	-7.971 0 -7.971	ø.7500	
B12	3.2500	-7.971 0 -7.971	ø.7500	
B13	1.2500	-7.971 0	ø.7500	
C1	2.8150	-7.971 0 -2.725 0 -4.644	¢.7496	
D1	20.6250	-4.644 0 -4.644	ø.6250	
D2	15.1250	-4.644 0 -4.644	Ø.6250	
D3	12.1250	-4.644 0	ø.6250	
D4	7.6250	-4.644 0	ø.6250	
D5	4.6250	-4 644	¢.6250	
D6	2.6250	-4.644 0	ø.6250	
D7	24.5000	-4.644 0 -6.144 0	ø.6250	
D8	20.0000		ø.6250	
D9	16.5000		ø.6250	
D10	10.0000		ø.6250	
D11	6.5000	-6 144	ø.6250	
D12	2.0000		ø.6250	
E1	21.5000	-4.644	ø.5312	
E2	17.8750	-4 644	ø.5312	
E3	14,2500	-4.644	ø.5312	
E4	13.0000	4 6 4 4	ø.5312	
E5	9.8750	-4.644	¢.5312	
E6	6.7500	-4.644	ø.5312	
E7	5.5000	-4 644	ø.5312	
EB	1.7500	-4 644	ø.5312	
F9	25,5000		0.5312	
E10	22,2500		Ø.5312 Ø.5312	
F11	19.0000		#.5312 #.5312	
E11	17.5000	6 144	#.5312 #.5312	
E12	17.5000	0 144	ø.5312 ø.5312	
	9.0000		ø.5312 ø.5312	
E14	7.5000	-6.144 0 -6.144		
E15			ø.5312	
E16	4.2500	-6.144 -6.144	ø.5312	
E17	1.0000	-6.144 0	¢.5312	
F1	23.5000 12.5000	1.0000	¢.5300 ¢.5300	
F3 F4	1.5000	1.0000	ø.5300	
	26.0000	-4.894 0	ø.5300	
F5	-1.000 0	-4.894 0	ø.5300	
F6	11.6250	-5.894 0	ø.5300	
F7	23.5000	-12.00 -12.00 -12.00 -12.00	ø.5300	
F8	12.5000	-12.00	ø.5300	
F9	1.5000	-12.00	ø.5300	
G1	2500	-5.894	ø.5000	
G2	-1.500	-6.894	ø.5000	
Н1	-1.500 0 22.0000 3.0000 -1.500	0 -6.894 0 1.0000	¢.4167	
H2 H3	3.0000		Ø.4167 Ø.4167	
H4	2500	-6.894	ø.4167	
H5	22.0000		Ø.4167	
H6	3,0000	- 00	¢.4167	
J1	18,4379		Ø.4167 Ø.1959	
J1 J2	4.4371	-1.100	Ø.1959 Ø.1959	
J2	4.4371	-1.199 -1.579	ø.1959 ø.1959	
J4	6.5621		ø.1959	
J5	18.4369	-9.209 0	ø.1959	
J6	4.4371	-9.209 -9.209 0 -9.589	ø.1959	
J7	20.5619	-9.589	ø.1959	
J8	6.5621	-9.589 0	ø.1959	
K1	3.3780	-1.440 0	ø.1562	THREADED BLIND
K2	2.2520	-1.440 0	ø.1562	THREADED BLIND
К3	3.3780	-9.348 -9.348	ø.1562	THREADED BLIND
K4	2.2520	-9.348 0	Ø.1562	THREADED BLIND


TOOL NAME				
2 STATION	PIER	C	E DIE	Ξ
PART NAME ARM STANDARD ADJUSTABLE	SCALE FULL		9 9	NO. OF S 12
DES. BY D. BARBOUR	3/13	P	ART NO. 330	8400.X
CHKD. BY	DATE	П		8400.X
APP. BY	DATE	T	EV.	





DET 47 CRS 2 REQ,D.





DET 31 CRS 4 REQ,D.



















LIST OF COORDINATES							
HOLE	X	Y	ø	DESCRIPTION			
A1	9.2500	-1.655 0	ø.6250				
A2	8.5000	-1.655	ø.6250				
A3	7.7500	-1.655	ø.6250				
A4	7.0000	-1.655 0	ø.6250				
A5	6.2500	-1.655	ø.6250				
A6	5.5000	-1.655	ø.6250				
A7	4.7500	-1.655	ø.6250				
A8	4.0000	-1.655	ø.6250				
A9	3.2500	-1.655	ø.6250				
A10	2.5000	-1.655	ø.6250				
A11	1.7500	-1.655	ø.6250				
A12	1.0000	-1.655 0	ø.6250				
B1	8.1250	3750	ø.5010				
B2	1.3750	-2.625	ø.5010				
C1	8.8750	3750	ø.4060				
C2	6.6250	3750	ø.4060				
C3	3.6250	3750	ø.4060				
C4	.5000	3750	ø.4060				
C5	8.8750	-2.625	ø.4060				
C6	6.6250	-2.625 0	ø.4060				
C7	3.6250	-2.625 0	ø.4060				
C8	.5000	-2.625 0	ø.4060				
D1	7.3750	3750	ø.2800				
D2	4.3900	3750	ø.2800				
D3	1.3750	3750	ø.2800				
D4	8.1250	-2.625 0	ø.2800				
D5	5.1400	-2.625 0	ø.2800				
D6	2.1250	-2.625	ø.2800				

	HOLE TABLE							
HOLE	0	QTY	DESCRIPTION					
A	ø.6250	12	5/8 DIA X .31 DP. END MILL FOR SPRING					
B	ø.5010	2	J.GR. THRU					
С	ø.4060	8	DRILL THRU					
D	ø.2800	6	DRILL THRU C,BORE OPP. SIDE FOR 1/4 SHCS					






			COORDINAT	
HOLE	X	Y	ø	DESCRIPTION
A1	9.3450	-1.655 0	Ø.6250	
A2	8.5950	-1.655 0	Ø.6250	
A3	7.8450	-1.655 0	Ø.6250	
A4	7.0950	-1.655 0	ø.6250	
A5	6.3450	-1.655 0	Ø.6250	
A6	5.5950	-1.655 0	ø.6250	
A7	4.8450	-1.655 0	Ø.6250	
AB	4.0950	-1.655 0	ø.6250	
A9	3.3450	-1.655 0	ø.6250	
A10	2.5950	-1.655 0	Ø.6250	
A11	1.8450	-1.655 0	Ø.6250	
A12	1.0950	-1.655 0	ø.6250	
A13	.3450	-1.655 0	Ø.6250	
B1	8.2200	3750	Ø.5010	
B2	1.4700	-2.625 0	ø.5010	
C1	8.9700	3750	Ø.4060	
C2	6.7200	3750	ø.4060	
C3	3.7200	3750	Ø.4060	
C4	.7200	3750	Ø.4060	
C5	8.9700	-2.625 0	ø.4060	
C6	6.7200	-2.625 0	ø.4060	
C7	3.7200	-2.625 0	Ø.4060	
CB	.7200	-2.625 0	ø.4060	
D1	7.4700	3750	ø.2800	
D2	4.4850	3750	ø.2800	
D3	1.4700	3750	ø.2800	
D4	8.2200	-2.625 0	ø.2800	
D5	5.2350	-2.625 0	ø.2800	
D6	2.2200	-2.625	ø.2800	

HOLE TABLE							
HOLE	ø	QTY	DESCRIPTION				
A	ø.6250	13	5/8 DIA X .31 DP. END MILL FOR SPRING				
В	ø.5010	2	J.GR. THRU				
С	ø.4060	8	DRILL THRU				
D	ø.2800	6	DRILL THRU C,BORE OPP. SIDE FOR 1/4 SHCS				
		_					

	M Dor	neti	Ļ	- 222.0%	A .
APP. BY		DATE	R	EV.	
CHKD. BY		DATE	П		8400.X
DES. BY D. B.	ARBOUR	3/13	P	ART NO. 330	8400.XX
PART NA STANDAR	ME ARM D ADJUSTABLE	SCALE FULL		SHT. NO. 11	NO. OF S
	STATION		-		



TOOL NAME

PART NAME ARM

2 STATION PIERCE DIE

Dometic sava

SCALE SHT. NO. NO. OF SHTS

DATE PART NO. 3308400.XXX

DATE TOOL NO. 3308400.XXX

DATE REV.