

DRAWING NUMBER OIS-108-540 change letter G

CHANGE DESCRIPTION & REASON

- REDRAWN IN 3-D.
- REMOVED "ASSEMBLE PART NO. 01S-108-542 AND PEEN IN PLACE" NOTE.
- REMOVED "THIS PART IS NOT COMPLETE UNTIL PART NO. 01S-108-542 IS ASSEMBLED IN PLACE - 2 PLACES' NOTE.
- UPDATED SPECIFICATIONS FOR HELI-COIL INSERT HOLE. "USED ON: " CHANGED FROM 01S-0739 TO 01S-108-540-0
- ADDED ISOMETRIC VIEW.

4 - FINISH 8 - OTHER NEXT MANUFACTURED LOT IN PROCESS UP 10 AFFECTED OPERATION + 'F' UNASSEMBLED PARTS - IN PROCESS, STORES, ASSEMBLY FLOOR + 'P' PARTS IN ASSEMBLIES + 'U' PARTS OR ASSEMBLIES IN MACHINES + 'A' SPECIAL INSTRUCTIONS FOR HARD PARTS, MACHINE NO.'S, ETC. PECORD ONLY E.C.N. 7778

CODE

AUTORIZADO FECHA DE IMPRESIÓN: 15/12/2021 MINISTRACIÓN DE DIBUJOS NETWORK

Impresión generada por: Jesus Angel Garcia Saldwere Moved to New Assembly Drawing 01s-108-542 LOCATING PINS