



7000146230 780197

GENERAL TOLERANCES ACCORDING TO DIN ISO 2768 - mK

Table 1 - Linear Dimensions

Permissible deviations in mm	Tolerar	ice Class Desi	Tolerance Class Designation (Description)	iption)
for ranges in nominal lengths	f (fine)	m (medium)	c (coarse)	v (very coarse)
0.5 up to 3	±0.05	±0.1	±0.2	:
over 3 up to 6	±0.05	±0.1	±0.3	±0.5
over 6 up to 30	±0.1	±0.2	±0.5	±1.0
over 30 up to 120	±0.15	±0.3	±0.8	±1.5
over 120 up to 400	±0.2	±0.5	±1.2	±2.5
over 400 up to 1000	±0.3	±0.8	±2.0	±4.0
over 1000 up to 2000	±0.5	±1.2	±3.0	±6.0
over 2000 up to 4000	:	±2.0	±4.0	±8.0

For nominal sizes below 0.5 mm, the deviations shall be indicated adjacent to the relevant nominal size(s).

Table 4 - General Tolerances on Straightness and Flatness

	above 1000 to 3000	above 300 to 1000	above 100 to 300	above 30 to 100	above 10 to 30	up to 10	an Bos or round on Briss	Panges of nominal lengths in mm
	0.4	0.3	0.2	0.1	0.05	0.02	I	
								호
	0.8	0.6	0.4	0.2	0.1	0.05	~	Tolerance Class
٦								SS
	1.6	1.2	0.8	0.4	0.2	0.1	F	

VITRO

NOTA:
PIEZAS SERAN LIBERADAS SI
CUMPLEN CON TODOS LOS
PUNTOS DEL ARCHIVO DE

ESPECIFICACIONES DE DIBUJO

DIN ISO 1302

SET PAMAY YELDERGOM A SU USO ES PROPEIRAD ENCUSIAN DE FABRICIONN DE MODUNAS, S. A. DE C. W., EL USO INDEBIO Y LA WOLLCHIA IL ICONPEDIRADAD DEL MISMO SERA OSTRIBOZIO CORPENIRA LA LEY, DESPUES DE UTILIZARIO PARA LO QUE FUE PRESTADO DEBERA DE PAMA LO DE FUE INVEDIRADO CUANDO "FAMA" LO SOLICITE.

								. <
							Surface	DIN ISO : metal cas values.
	3.2/ V	Q	3.2/	A	3.2/	<	Surface Roughness Symbols	IIN ISO 130 1302 and DIN titings. The foll
							nbols)2, DIN 4768 ar
	Symbol with additional indications. Made without removal of material (non-cutting), with specified roughness.	Symbol without additional indications. Removal of material is not permitted (surface remains in state as supplied).	Symbol with additional indications. Removal of material by machining, with specified roughness.	Symbol without additional indications. Removal of material by machining, without specified roughness.	Symbol with additional indications. Any production method, with specified roughness.	Symbol without additional indications. Basic symbol. The meaning must be explained by additional indications.	Explanation	SURFACE FINISH DIN ISO 1302 DIN ISO 1302, DIN 4768 - Comparison of Surface Roughness Values DIN ISO 1302 and DIN 4768 are the Germany standards for surface roughness for various areas, including metal castings. The followings are some explanation to the symbols and comparison to surface roughness values.
				F	ECHĄ [DE IMP	RE	SIÓN: 26/05/2022
alo	daña	ADI	V - ADN	ЛINISTI	RACIO	N DE D	IBL	JJOS NETWORK

Comparison of Roughness Values

Roug	Roughness Values Ra (um)	0.025	0.05 0.1	0.1	0.2	0.4	0.2 0.4 0.8	1.6	1.6 3.2 6.3 12.5	6.3	12.5	25	
Roug	Roughness Values Ra (uin)		2	4	00	16	32	63	63 125 250 500	250	500	1000	200
Roug	Jhness Grade Numbers	N ₁	N2	N3	4 4	N5	N3 N4 N5 N6	N7	N7 N8 N9 N10 N11	N9	N10		N12
		_	AL,OH	$\bar{\geq}\mid$	7	_ l	구	\ \ \ 	ĺ	j			i
		-	0	,	(,	ſ	(

213F202318				
213F202318 REVISO: FECHA: E.VALADEZ 11-MAY-22	R.CERVANTES 11-MAY-22	2/E DZ 100F 21EEF	ESCALA: MATERIAL:	NOMBRE:
S.A. DE C. V. MONTERREY, N.L. MEXICO	FABRICACI	LEL NUMERO 7000146230	NUMERO 780197	WEAR PLATE
Ħ	Jamaño:	C	CAMBIO:	