Pico Radar Speed Sign Wiring Guide v0.1.0

pantsforbirds.com

= solder bridge

1A **1B** **1F** **1G** **1E** **1C** **1D**

2A **2B** **2F** **2G** **2E** **2C** **2D**

Connect to HB100X

Wire segment ON pins (just one per segment) to corresponding pins on controller.

12VDC FROM POWER SUPPLY

12VDC Power Distribution Board (not included)

Only power one segment per digit: power is shared.