Trip Kit Index
Printed on 12 Sep 2021
Page 1
(c) JEPPESEN SANDERSON, INC., 2021, ALL RIGHTS RESERVED



List of pages in this Trip Kit

Trip Kit Index Airport Information For OAKN Terminal Charts For OAKN Revision Letter For Cycle 18-2021 Change Notices Notebook

JEPPESEN JeppView for Windows

General Information

Location: KANDAHAR AFG ICAO/IATA: OAKN / KDH

Lat/Long: N31° 30.35', E065° 50.87'

Elevation: 3338 ft

Airport Use: Military

Daylight Savings: Not Observed UTC Conversion: -4:30 = UTC Magnetic Variation: 2.0° E

Customs: No Airport Type: IFR Landing Fee: No Control Tower: No Jet Start Unit: No LLWS Alert: No Beacon: Yes

Sunrise: 0119 Z Sunset: 1348 Z

Runway Information

Runway: 05

Length x Width: 10497 ft x 180 ft

Surface Type: asphalt TDZ-Elev: 3314 ft Lighting: Edge, REIL


Runway: 23


Length x Width: 10497 ft x 180 ft


Surface Type: asphalt TDZ-Elev: 3338 ft

Lighting: Edge, ALS, REIL

Communication Information







airport at or above 7300' MSL before proceeding on course.

TAKE-OFF OBSTACLES: Rwy 05, Pylon 2698' from DER 784' right of centerline, 35' AGL/3369' MSL. Pylon 2650' from DER 1187' right of centerline, 35' AGL/3365' MSL. Pylon 2848' from DER 772' left of centerline, 35' AGL/3372' MSL. Pylon 2906' from DER 1201' left of centerline, 35' AGL/3379' MSL. Rwy 23, Tower 3770' from DER 1105' left of centerline, 115' AGL/3412' MSL. Antenna mast 3765' from DER 1152' left of centerline, 107' AGL/3427' MSL. Building 23' from DER 456' left of centerline, 23' AGL/3309' MSL. West bypass road 162' from DER 419' right of centerline, 0' AGL/3312' MSL. OAKN/KDH



KANDAHAR, AFGHANISTAN KANDAHAR

STRAIGHT-IN RWY		Α	В	С	D
05	LNAV ①	3820 ′(506 ′) 1600m	3820 ′(506 ′) 1600m	3820 ′(506 ′) 2400m	3820 ′(506′) 2400 m
23	LNAV ①	3840′(502′) 1500m	3840′(502′) 1500m	3840′(502′) 1600m	3840′(502′) 1600m
	ALS out	1600m	1600m	2400m	2400m

1 Continuous Descent Final Approach.

CIRCLE-TO-LAND	90 KT 120 KT		140 KT	165 KT
• After RNAV (GPS) 23	3840 ′(502′)	3860 ′(522′)		NOT AUTHORIZED
	1600m	1600m	NOT AUTHORIZED	
② After RNAV (GPS) 05	3820 ′(482')	3860 ′(522')	NOT AUTHORIZED	NOT AUTHORIZED
	1 1600m	1600m	NOT AUTHORIZED	


[•] Or higher minimums of preceding straight-in approach.


2 Not authorized southeast of Rwy 05-23.

800m

TAKE-OFF									
	Rwy 05		Rwy 23						
	Adequate Vis Ref	STD	Adequate Vis Ref	STD	For Climb in Visual Conditions				
1 & 2 Eng	400m	1600m	400m	1600m	ceil 4100'-4800m				
			400111		Cell 4100 -4000III				

800m





Revision Letter For Cycle 18-2021
Printed on 12 Sep 2021
Page 1
(c) JEPPESEN SANDERSON, INC., 2021, ALL RIGHTS RESERVED



Chart changes since cycle 17-2021

ADD = added chart, REV = revised chart, DEL = deleted chart.

ACT PROCEDURE IDENT INDEX REV DATE EFF DATE

KANDAHAR, (KANDAHAR - OAKN)

Terminal Chart Change Notices
Page 1 - Printed on 12 Sep 2021
Notice: After 16 Sep 2021, 0000Z, this data may no longer be valid
(c) JEPPESEN SANDERSON, INC., 2021, ALL RIGHTS RESERVED



TERMINAL CHART CHANGE NOTICES

No Chart Change Notices for Airport OAKN