Example values under each block: 40 min after a truck door was left open. Steps 2–5 run on the logger.



Done once, offline: fit b, T_{min}, lag and starting load to ComBase and published data; store the table (step 3) and the 80 parameter sets (step 5) on the logger