NOTICE OF INACTIVATION
FOR NEW DESIGN

TOP 06-2-562
NOTICE 1
14 August 2025

TEST OPERATIONS PROCEDURE
Ratemeter Directional Dependence, Radiac

TOP 06-2-562, dated 19 November 1980, is inactive for new design. This does not preclude use of a document for legal reasons. Use of the latest, actively maintained, document is highly recommended.

CAUTION: The supersession information is valid as of the date of this notice and may be superseded by subsequent revisions of the superseding document.

(Copies of Department of Defense specifications are available from https://quicksearch.dla.mil.)

CONCLUDING MATERIAL

Lead Agent:

Army – TE

AMCS N/A

AREA ENVR

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.dla.mil.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:51Z
Check the source to verify that this is the current version before use.