MIL-C-14700A(PA)
20 November 1974
SUPERSEDING
MIL-C-14700
9 June 1971

MILITARY SPECIFICATION

CHARGE PROPELLING, M80 FOR 8 INCH HOWITZER, M2 CANNON

This specification is mandatory for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification covers the loading, assembling and packing for one type of propelling charge designated as Charge, Propelling M80 for 8 inch Howitzer Projectiles M422 and M424A1 for the 8 Inch Howitzer, M2 Cannon (see 6.4).

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposal, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-P-223	- Black Powder
MIL-A-48078	- Ammunition, Standard Quality Assurance Provisions, General Specification for.

STANDARDS

MILITARY

MIL-STD-105	- Sampling Procedures and Tables for Inspection by Attributes.
MIL-STD-414	- Sampling Procedures and Tables for Inspection by Variables for Percent Defective.
MIL-STD-1167	- Ammunition Data Cards.

FSC: 1110

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.

DRAWINGS

PICATINNY ARSENAL

PRODUCT DRAWINGS

7548187	- Packing and Marking of Metal Containers for Propelling Charges.
8787274	- End.
8787277	- Igniter, Inner.
8787278	- Strap, Tying.
8787283	- Igniter Outer.
8787286	- Body.
8787288	- Increment Charge Assembly.
8787289	- Base Charge 1 Loading Assembly.
8787290	- Charge, Propelling, M80, for 8 Inch Howitzer M2.
8847549	- Cap, Igniter, Protector Assembly, Type A.
8849910	- Cap, Igniter, Protector (Shipping Diagram).
8849912	- Cap, Igniter, Protector (Paper) Assembly.
9289333	- Igniter Assembly.

(Copies of specifications, standards, drawings, and publications required by contractors in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

3. REQUIREMENTS

3.1 Materials. The contractor shall furnish objective evidence (see 3.3) that the material complies with the specifications listed on the applicable drawing.

3.2 Assembly. The propelling charge shall comply with all requirements specified on Drawing (dwg) 8787290, with all requirements specified herein, and with the requirements of all applicable specifications to the extent specified on the drawing and herein.

3.3 Objective evidence.

3.3.1 General. Records of contractor quality control and inspections which can be verified. When test data (see 6.1.2) is required, the data shall be submitted in accordance with DI-T-1906 specified on DD Form 1423 incorporated in the contract.

3.3.2 Material. Certificate of conformance certifying that material complies with drawing and specification requirements.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.

3.4 Moisture content of black powder. The moisture content of the black powder at the loading plant shall not exceed the amount specified in MIL-P-223, when tested as specified. (See 4.5.1).

3.5 Increment loading assembly weight. The net weight of propellant shall comply with the weights specified in the loading authorization within the following tolerance.

Increment Number	Tolerance Ounce
1	± .10
2	± .10
3	± .30

3.5.1 Charge, propelling assembly weight. The charge propelling assembly weight shall not differ by more than ± 1.0 ounces from the total of the amount specified in the loading authorization, plus tare weight of the increments and igniter assembly (see 6.3).

3.6 Chamber gage. The completed propelling charge shall freely enter the prescribed chamber gage.

3.7 Proving ground.

3.7.1 Muzzle velocity. At 70 degrees fahrenheit (F) the muzzle velocity shall be 1745 feet per second (fps) minimum, and 1845 fps maximum, and the velocity standard deviation shall not exceed 8.0 fps.

3.7.2 Pressure. The maximum individual pressure at 70 degrees fahrenheit shall not exceed 42,000 pounds per square inch (psi).

3.8 Test plug assembly torque. The test plug shall be assembled to withstand subsequent application of the minimum assembly torque specified on the applicable drawing, without moving (see 4.4.2.8).

3.9 Data cards. See Data cards, section 6 of MIL-A-48078.

3.10 Workmanship.

3.10.1 Plastic and metal characteristics. All components shall be free from cracks, splits, cold flow, shrinkage, cold shuts, inclusions, porosity, or any similar characteristic.

3.10.2 Threads. Threads shall be full and undamaged for the entire minimum length or depth as required on the applicable drawing.

3.10.3 Burrs. Parts shall be free from burrs.

3.10.4 Foreign matter. Parts shall be free from chips, dirt, grease, rust, corrosion, or any embedded foreign material.

3.10.5 Cleaning. The cleaning method shall not be injurious to any of the parts, nor shall the parts be contaminated by the cleaning agent.

Source: https://assist.dla.mil -- Downloaded: 202610-18T04:36Z
Check the source to verify that this is the current version before use.

3.10.6 Stitching. Stitching shall not be missing where required. Stitching shall be free from any breaks or skipped areas. Tight stitching which breaks when the material is pulled to a flat surface or specified contour, shall be rejected.

3.11 First article inspection. This specification contains technical provisions for first article inspection (see 4.3). Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection and standard quality assurance provisions. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of inspections. The inspection requirements specified herein are classified as follows:

1. First Article Inspection (see 3.11)
2. Quality Conformance Inspection (see 4.4)

4.3 First Article Inspection.

4.3.1 Submission. The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated.

Part Description	Drawings	Quantity
Charge, Propelling, M80, for 8 Inch, M2 Howitzer Assembly	8787290	10

4.3.2 Inspections to be performed. The first article parts submitted in accordance with 4.3.1 shall be subjected by the Government to any or all the requirements of the applicable drawings and to the inspections of Table I. Parts may be used for subassemblies, and subassemblies may be used for assemblies if the inspections required by Table I are verified by a representative of the Government designated by the Contracting Officer.

Source: https://assist.dla.mil -- Downloaded: 202610-18T04:36Z
Check the source to verify that this is the current version before use.

Table I

FIRST ARTICLE INSPECTION
CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.3.2	Charge, Propelling, M80				8787290
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major B	Classification of Defects and tests on all parts, subassemblies and assembly	10		4.4.2.1 thru 4.4.2.8	4.5
Major B	Muzzle velocity	10		3.7.1	4.5.4.1
Major B	Pressure	10		3.7.2	4.5.4.2

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.

4.3.3 Rejection. See MIL-A-48078.

4.4 Quality conformance inspection.

4.4.1 Lot Formation. The term "lot" as used throughout this specification refers to an inspection lot, which is defined as an essentially homogeneous collection of units of product from which a representative sample is drawn and inspected to determine conformance of the lot with applicable requirements. The sample selected shall represent only that quantity of units from which the sample was drawn and shall not be construed to represent any prior or subsequent quantities presented for inspection. Homogeneity shall be considered to exist provided the lot has been produced by one manufacturer, in one unchanged process, in accordance with the same drawing, same drawing revision, same specification. and same specification revision. Changes to the process, specification, or drawing not affecting safety, performance, interchangeability, or storage, as determined by the Government, shall not be deemed to alter the homogeneity of the lot. Inspection lots shall comply with MIL-STD-105 and shall be numbered in accordance with provisions of MIL-A-48078. Unless otherwise approved by the contracting office, the inspection lot size of end items deliverable under the contract shall not be less than the smallest weekly estimate of quantities contractually scheduled for production during the contract period nor more than the largest monthly quantity contractually scheduled for delivery during the contract period. Inspection lots for components or subassemblies, other than the items of delivery, shall be homogeneous and of a size mutually convenient to both the contractor and the government inspection. Each lot shall contain:

a. Propellant from not more than one set of lots.

b. Black Powder of one interfix lot number from one manufacturer.

4.4.2 Examination. See MIL-A-48078.

a. Critical and Special Defects. See MIL-A-48078.

b. Major A and Major B defects sampling plans. Unless otherwise specified, inspection for Major A and Major B defects shall be sampled in accordance with Table II.

c. Minor defects sampling plans. Unless otherwise specified, inspection for minor defects shall be sampled in accordance with Table III.

d. Production tests sampling plans. Unless otherwise specified production tests shall be sampled in accordance with the tables specified in the Quality Conformance Inspection, Classification of Defects and Tests sheets.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.

Table II
Major Defects
LQ = .01 Acceptance No = 0 Consumers Risk = .05

Lot Size	Sample Size	Lot Size	Sample Size	Lot Size	Sample Size	Lot Size	Sample Size
1-72	all	140-141	124	256-259	177	541-549	230
73	72	142	125	260-262	178	550-559	231
74	73	143-144	126	263-265	179	560-569	232
75	74	145	127	266-268	180	570-579	233
76	75	146-147	128	269-271	181	580-590	234
77	76	148-149	129	272-275	182	591-601	235
78	77	150	130	276-278	183	602-613	236
79	78	151-152	131	279-282	184	614-625	237
80	79	153-154	132	283-285	185	626-637	238
81-82	80	155-156	133	286-289	186	638-649	239
83	81	157	134	290-293	187	650-662	240
84	82	158-159	135	294-296	188	663-676	241
85	83	160-161	136	297-300	189	677-690	242
86	84	162-163	137	301-304	190	691-704	243
87	85	164-165	138	305-308	191	705-719	244
88-89	86	166-167	139	309-312	192	720-735	245
90	87	168	140	313-316	193	736-751	246
91	88	169-170	141	317-320	194	752-768	247
92	89	171-172	142	321-324	195	769-785	248
93	90	173-174	143	325-329	196	786-804	249
94-95	91	175-176	144	330-333	197	805-823	250
96	92	177-178	145	334-338	198	824-842	251
97	93	179-180	146	339-342	199	843-863	252
98	94	181-182	147	343-347	200	864-884	253
99-100	95	183-184	148	348-352	201	885-907	254
101	96	185-187	149	353-356	202	908-930	255
102	97	188-189	150	357-361	203	931-955	256
103	98	190-191	151	362-366	204	956-981	257
104-105	99	192-193	152	367-372	205	982-1008	258
106	100	194-195	153	373-377	206	1009-1036	259
107	101	196-197	154	378-382	207	1037-1066	260
108-109	102	198-200	155	383-388	208	1067-1098	261
110	103	201-202	156	389-393	209	1099-1131	262
111	104	203-204	157	394-399	210	1132-1166	263
112-113	105	205-207	158	400-405	211	1167-1204	264
114	106	208-209	159	406-411	212	1205-1243	265
115	107	210-212	160	412-417	213	1244-1285	266
116-117	108	213-214	161	418-424	214	1286-1330	267
118	109	215-217	162	425-430	215	1331-1378	268
119	110	218-219	163	431-437	216	1379-1429	269
120-121	111	220-222	164	438-443	217	1430-1483	270
122	112	223-224	165	444-450	218	1484-1542	271
123-124	113	225-227	166	451-457	219	1543-1605	272
125	114	228-230	167	458-465	220	1606-1673	273
126-127	115	231-232	168	466-472	221	1674-1747	274
128	116	233-235	169	473-480	222	1748-1827	275
129-130	117	236-238	170	481-488	223	1828-1914	276
131	118	239-241	171	489-496	224	1915-2010	277
132-133	119	242-243	172	497-504	225	2011-2115	278
134	120	244-246	173	505-513	226	2116-2232	279
135-136	121	247-249	174	514-521	227	2233-2361	280
137	122	250-252	175	522-530	228	over 2361	298
138-139	123	253-255	176	531-540	229		

Source: https://assist.dla.mil -- Downloaded: 202640-18T04:36Z
Check the source to verify that this is the current version before use.

Table III
Minor Defects

LQ = .05 Acceptance No = 0 Consumers Risk = .10

Lot Size	Sample Size	Lot Size	Sample Size	Lot Size	Sample Size	Lot Size	Sample Size
1-16	all	28-29	23	52-56	31	132-156	39
17	16	30-31	24	57-62	32	157-191	40
18	17	32-34	25	63-69	33	192-244	41
19-20	18	35-36	26	70-76	34	245-334	42
21	19	37-40	27	77-86	35	335-519	43
22-23	20	41-43	28	87-97	36	520-1120	44
24-25	21	44-47	29	98-112	37	over 1120	45
26-27	22	48-51	30	113-131	38		

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.1	Igniter Inner (dwg. 8787277); Igniter, Outer (dwg. 8787283); strap tying (dwg. 8787278) and end (dwg. 8787274) covering details of dwgs. 8787288 and 8787289.		NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major B					
131.	Material			3.1	Visual
Minor					
201.	Marking legible and complete		Table III	3.2	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.2	Body, (dwg. 8787286); covering details of dwgs, 8787288 and 8787289 as applicable.				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major B					
131.	Material			3.1	Visual
132.	Seams lock stitched		Table II	3.2	Visual
Minor					
201.	Marking legible and complete		Table III	3.2	Visual
202.	Workmanship		Table III	3.10	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

10

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9289333
4.4.2.3	Igniter Assembly (dwg. 9289333)				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major B					
131.	No stitching defects such as broken or loose threads and skipped or missed areas.		Table II	3.10.6	Visual/Manual
132.	No hole, tear or other visible damage.		Table II	3.2	Visual
133.	Moisture content of black powder.		Table II	3.4	4.5.1
Minor					
201.	Marking legible and complete		Table III	3.2	Visual
202.	Workmanship		Table III	3.10	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-14700A(PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.4	Increment charge assembly (dwg. 8787288) Covering details of dwg. 8787290.				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major B					
131.	No stitching defects such as broken or loose threads and skipped or missed areas.		Table II	3.10.6	Visual/Manual
132.	Filling opening securely single stitched shut.		Table II	3.2	Visual/Manual
133.	No hole, tear or other visible damage.		Table II	3.2	Visual
134.	Weight of propellant correct		Table II	3.5	4.5.2
Minor					
201.	Marking legible and complete		Table III	3.2	Visual
202.	Workmanship		Table III	3.10	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

12

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.5	Base charge 1 loading assembly (dwg. 8787289) covering a detail of dwg. 8787290.		NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	Igniter charge assembly present and not damaged to the extent that black powder can escape without force.		100%		Visual
Major B					
131.	Igniter opening securely double stitched shut.		Table II	3.2	Visual
132.	Base opening securely single stitched shut.		Table II	3.2	Visual
133.	No stitching defects such as broken or loose threads and skipped or missed areas.		Table II	3.10.6	Visual
134.	No hole, tear or other visible damage.		Table II	3.2	Visual
135.	Proper location and number of tie straps.		Table II	3.2	Visual
136.	Weight of propellant correct.		Table II	3.5	4.5.2
Minor					
201.	Workmanship		Table III	3.10	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.6	Charge propelling M80, for 8 inch, M2 assembly				8787290
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	Igniter charge assembly present and not damaged to the extent that black powder can escape without force.		100%		Visual
Major B					
131.	Igniter protector cap present on igniter end of charge.		Table II	3.2	Visual
132.	Proper assembly of charge		Table II	3.2	Visual
133.	Total length, max		Table II	3.6	Measure*
134.	Outside diameter, max		Table II	3.6	Measure*
135.	No hole, tear, or other visible damage		Table II	3.2	Visual
136.	Weight of charge assembly		Table II	3.5.1	Scale
137.	Velocity	5		3.7.1	4.5.4.1
138.	Pressure	5		3.7.2	4.5.4.2
Minor					
201.	Marking illegible, incomplete, missing		Table III	3.2	Visual
202.	Pad present on igniter protector		Table III	3.2	Manual
203.	Handle present on igniter protector cap		Table III	3.2	Visual
204.	Workmanship		Table III	3.10	Visual/Manual
205.	Tie straps properly assembled		Table III	3.2	Visual

NOTES: *Measure with chamber gage.

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION
CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.7	Packing and marking of metal containers for propelling charges before closing cover.		7548187
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major B					
131.	Charge wrapped		Table II	3.2	Visual
132.	Charge correctly positioned in container		Table II	3.2	Visual
133.	Charge tight in container		Table II	3.2	Manual
134.	Material			3.1	Visual
Minor					
201.	Charge can be removed by hand		Table III		Manual
202.	Cover can be removed by hand		Table III		Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

MIL-C-14700A(PA)

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.8	Packing and marking of metal containers for propellant charges				7548187
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major B					
131.	Proper torque on cover		Table II	3.2	Gage
132.	Lead wire seal properly assembled, and not cracked		Table II	3.2	Visual
133.	Plug greased and seated in place, after pressure test, with proper torque.		Table II	3.8	Gage
134.	Air pressure test		Table II	3.2	4.5.3
Minor					
201.	Exterior coating damaged		Table III	3.2	Visual
202.	Marking legible and complete		Table III	3.2	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.

4.4.3 Testing. Testing is described in the first article and quality conformance inspection tables.

4.4.4 Inspection equipment. The inspection equipment required to perform the examinations and tests prescribed herein is described in the "Paragraph Reference/Inspection Method column in the tables starting with 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See section 6 of MIL-A-48078.

4.4.4.1 Tolerances. The tolerances specified herein are absolute with no allowances for test equipment accuracy. The tolerances used by the manufacturer shall be equal to the absolute tolerances less the accuracy tolerances of the test equipment used.

4.5 Test methods and procedures. Unless otherwise specified, the tests shall be conducted at room temperature 77 ± 10 Degrees Fahrenheit (°F) or 25 + 5 Degrees Centigrade (°C).

4.5.1 Moisture Content of black powder (see 3.4). The moisture content shall be determined in accordance with MIL-P-223.

4.5.2 Increment loading assembly weight (see 3.5). The check weighing shall be performed independently of the original weighing and if performed manually shall be performed by another operator utilizing a different balance.

4.5.3 Air test of packed and sealed container (see 4.4.2.8). Each sealed container shall be tested as follows. The closing plug shall be removed from the cover of the container. Assemble air test hose and adapter and turn on air pressure until a pressure of 3 pounds per square inch minimum is obtained. Turn off air pressure and hold for a minimum of one minute. If the air pressure reading changes in the one minute interval the container shall be rejected and removed from the lot. After completion of the test release pressure, remove test adapter and replace coated plug with the correct torque.

4.5.4 Proving Ground (see 3.7). These tests shall be conducted at a Government Proving Ground in accordance with applicable acceptance test procedures. The sample charges shall be fired in an 8 Inch Howitzer, M2 Cannon for which the charge is standard and observation shall be made for conformance to all applicable requirements. The charges shall be conditioned at 70 degrees fahrenheit + 5 degrees for 24 hours and fired at Zone 3 using M424 projectiles of the standard weight zone and dummy fuzes.

4.5.4.1 Muzzle Velocity (see 3.7.1). Muzzle velocity and muzzle velocity standard deviation. The sampling plan for this test shall be in accordance with MIL-STD-414, Section B, Table B3, Code Letter D, and an AQL of 0.65 percent. In addition, if the standard deviation of the sample multiplied by the factor 0.65 exceeds the applicable requirement, the lot shall be rejected. For first article sample, the factor shall be 0.73.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.

4.5.4.2 Pressure (see 3.7.2). The sample fired for velocity shall also be observed for pressure. If any charge fails to meet the applicable requirement, the lot shall be rejected.

4.5.4.3 Retest. If for any reason the proving ground considers that the test conditions have detrimentally affected the test results, they shall declare the results invalid and perform a new test on additional sample charges as required.

4.5.5 Charge, Propelling, Assembly Weight (see 3.5.1). The assembly shall be weighed 100 percent. Any assembly which fails to comply with the applicable requirement shall be classified defective and removed from the lot.

5. PREPARATION FOR DELIVERY

5.1 Packing.

5.1.1 Level A. The propellant charge shall be packed in a container complying with drawing 8880531. The container shall be closed, sealed, tested and marked in accordance with the requirements of drawing 7548187.

6. NOTES

6.1 Intended use. The components covered by this specification are intended for use on M80 Propelling Charge.

6.2 Ordering data. See MIL-A-48078.

6.2.1 Procurement requirements. See MIL-A-48078.

6.2.2 Contract data requirements.

6.2.2.1 Inspection equipment designs. (See MIL-A-48078).

6.2.2.2 Other requirements. Data specified in 3.3, 3.9, and 4.4.4 will be listed directly on DD Form 1423 incorporated in the contract.

6.3 Charge, Propelling Assembly Weight. This requirement applies to the load plant only due to change in tare weight of the bags because of variation in bag material and moisture content.

6.4 Weapon Application. The M2 Cannon is used in the 8 Inch Howitzer, Towed, M115 and the 8 Inch Howitzer, Self-Propelled, M110.

Custodian:

Army-PA

Preparing Activity

Army-PA

Project No. 1110-A046

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.