MIL-D-14707 (AR)
Amendment 1
22 September 1981

MILITARY SPECIFICATION

DISCRIMINATOR, ANTI-TANK MINE,
M2 AND SPOOL ASSEMBLY

This amendment forms a part of Military Specification MIL-D-14707 (MU), dated 23 Feb 1968 and is approved by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

Add the following preamble underneath the title:

"This specification is approved by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense."

PAGE 9

4.3.2.6, Minor Category:

Delete "1.50 percent" and substitute "1.00 percent.

Delete defects 202 and 203 in their entirety.

2.1, STANDARDS, FEDERAL: Add the following standard:

"FED-STD-151 -Metals; Test Methods."

PAGE 10

4.3.2.11: Add the following new paragraph:

"4.3.2.11 Cable, corrugated, prior to corrugation (see dwg. 9231954 covering a detail of dwg. 9221336).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			

FSC: 1345

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.

Categories	Defects	Method of Inspection	Code No.
Major:	AQL 0.65 percent		
101.	More than one solder joint per discriminator	Visual	11001
102.	Conductor overlap less than min	Scale	11002
103.	Tape does not insulate conductor cables	Visual	11003

Minor: None defined."

PAGE 13

4.3.3.7: Delete and substitute as follows:

"4.3.3.7 Heat treatment of discriminator contact material (see dwg. 9231950) - Major defect - Code No. 18001. A test specimen twelve (12) inches long shall be taken from the beginning and end of each continuous spool of material used in the fabrication of upper and lower contacts. Failure of either specimen to comply with the drawing requirement, when tested as specified in 4.4.7, shall be cause for rejection of the spool from which the specimens were taken."

4.3.3.8: Add the following new paragraph:

"4.3.3.8 Load test, Male Connector (see dwg. 9207416) - Major defect - Code No. 19001. The sampling plan for this test shall be in accordance with Special Inspection Level S-4 of MIL-STD-105 using an AQL of 0.40 percent. Any connector which fails to comply with the applicable drawing requirement shall be classed defective, when tested in accordance with 4.4.7."

PAGE 16

4.4.7: Add the following new paragraph:

"4.4.7 Load Test, Male Connector. Sample connectors shall be prepared for test by cutting away the dust cover, strap and a portion of the connector plug to a depth flush with the bottom of the electrical contact cavity. The

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.

sample shall be assembled to the test fixture in accordance with 4.3.4 and the applicable load applied separately to each contact in a smooth gradual manner. Observation shall be made for conformance with the applicable drawing requirement. Following the completion of the load test, the two-conductor wire may be salvaged by separating from the connector and holding for subsequent molding into new electrical cables per dwg. 9207416, provided the wire length is still within the drawing limits."

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project No. 1345-A192

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:36Z
Check the source to verify that this is the current version before use.