MILITARY SPECIFICATION

CARTRIDGE 106MM, HEAT, M344A1
LOADING, ASSEMBLING AND PACKING

* This amendment forms a part of Military Specification MIL-C-13473C (MU), dated 5 May 1965, and is approved by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

* Add the following preamble underneath the title:

"This specification is approved by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense."

Paragraph 2.1:

Specifications, Military: Add "MIL-I-45607 - Inspection Equipment Supply and Maintenance".

Standards, Military: Add "MIL-STD-1168 - Lot Numbering of Ammunition:

Drawings, Army:

7549097 - delete "M509A1" and substitute "M509A2"

7548962 - delete "M509" and substitute "M509A1, M509A1E1 or M509A2"

7548963 - delete "Box, Packing ... and Packing" and substitute "Box, Packing, Ammunition for Cartridge 106MM: Heat, M344A1, with fuze PIBD, M509A1, M509A1E1 or M509A2 and Practice M344A1 w/inert Projectile w/o fuze for Rifle M40A1 in fiber container M316."

FSC: 1315

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T00:36Z
Check the source to verify that this is the current version before use.

PAGE 6

4.2.2.4: Delete 101 in its entirety and substitute:

"101 Fuze screw and lock washer fails to withstand minimum assembly torque (see 3.8)."

PAGE 7

* 4.2.2.10, Minor: Delete "AQL 0.65 percent" and substitute "AQL 1.0 percent".

Add Minor defect:

"202. Threads and slot of fin and chamber assembly not coated with sealing compound ... Visual 10005".

PAGE 8

4.2.2.14 Cartridge Assembly: Delete Major Defects 101 and 102 in their entirety and substitite:

"Major Defect 101 - Liner not cemented in conformance with adhesive zone area ... Visual 14017".

"Major Defect 102 - Liner loose or insecure ... Visual 14018".

PAGE 9

Add paragraph 4.2.2.18 as follows:

"4.2.2.18 Screw self-locking (see Dwg. 9323855 covering a detail of Dwg. 7549096).

Categories	Defects	Method of Inspection
Critical: None		
Major	AQL 0.65%	
101	Nylon patch missing	Visual
102	Length under head over max.	Gage
103	Pitch Diameter, min.	Gage
104	Major Diameter, min.	Gage

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T00:36Z
Check the source to verify that this is the current version before use.

Categories	Defects	Method of Inspection
Minor	AQL 0.65%	
201	Protective finish incomplete	Visual"

PAGE 12

4.3.5.1: Delete this paragraph in its entirety and substitute the following:

"4.3.5.1 Penetration. The cartridges tested in paragraph 4.2.3.7.2.1 shall be fired at 6 inch homogeneous armor plate. The cartridges tested in paragraph 4.2.3.7.2.2 shall be fired at 3 to 4 inch homogeneous armor plate except that every tenth lot shall be fired at 6 inch plate. The plate shall be placed at 60 degree position from the vertical at approximately 400 feet from the muzzle of the rifle. Observation shall be made for penetration by jet action (see 6.5)."

PAGE 15

6.9: Submission of test data and ammunition data cards:

Delete SMUPA-ND2 and substitute DRDAR-LCU.

Delete SMUPA-DC8 and substitute DRDAR-QAR-E.

Delete Picatinny Arsenal and substitute US Army Armament Research and Development Command.

Add Figures 1 and 2 to MIL-C-13473C (MU) dated 5 May 1965.

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project No.: 1315-A457

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T00:36Z
Check the source to verify that this is the current version before use.





FIGURE 1

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T00:36Z
Check the source to verify that this is the current version before use.



NOMOGRAPH FOR DETERMINING PENETRAMETER THICKNESS FOR RADIOGRAPHY OF LOADED STEEL SHELL

FIG. 2

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T00:36Z
Check the source to verify that this is the current version before use.