MIL-W-50219A (AR)
Amendment 5
19 September 1979
SUPERSEDING
AMENDMENT 4
21 August 1979

MILITARY SPECIFICATION

WARHEAD SECTION, GUIDED MISSILE, HE, M225
ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-W-50219A (AR) dated 13 February 1978

PAGE 3

3.3.4, line 3: Delete "be recorded for information only" and substitute "be 78 plus or minus (±) 15 picofarads.

PAGE 4

3.3.5.2, delete in its entirety.

Table 1, under "Examination or Test", delete "Continuity of red wire terminal to insulated S&A terminal, 10, 3.3.5.2 and 4.5.7.2".

PAGE 11

4.4.2.1 Major Defect 106, under "AQL" or 100%"

Was: "* each 4.0%"
Now: "*"

Under "NOTES:" at bottom of page.

Was: "*In accordance with MIL-STD-105, Inspection Level 1".
Now: "*Six (6) samples, two (2), at beginning of 8 hour shift, two (2) at middle of 8 hour shift and two (2) at end of 8 hour shift."

4.4.2.3, Major Defect 104, under "Examination or Test":

Was: "Turn part 360°, end-over-end to detect any loose parts, 100%, 3.2, and Visual/Manual".

FSC: 1336

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:17Z
Check the source to verify that this is the current version before use.

Now: "Turn warhead nose down and then rotate to nose up and back to nose down to detect any rattle, 100%, 3.2 and Visual/Manual".

PAGE 13

Delete "Major Defect 110," "Continuity of red wire terminal to insulated S&A terminal, 100%, 3.3.5.2 and 4.5.7.2."

Add: "Major Defect 112, Shorting disc screw torqued, 0.40%, 3.2, and Gage".

**4.4.2.3, Examination or Test Major 102 - Delete in its entirety and substitute:

"S&A terminal screw torqued"

**4.4.2.3, Add the following major defect:

"113 - Adhesive coating missing on terminal - 100% 3.2 Visual screw head, exposed metal of wire terminal and exposed portion of insulated terminal post after assembly and inspection operations".

PAGE 15

4.4.2.5, Add major defects 103, 104, and 105 as follows:

*"103	pitch diameter of thread	0.40%	3.2	Gage
* 104	Major diameter of thread	0.40%	3.2	Gage
* 105	Length of threads	0.40%	3.2	Gage"

* Note: These inspections shall be performed before inserting locking element.

PAGE 18

4.4.2.8: Delete "Major Defect 103, Sleeve missing, 0.40%, 3.2, and Visual".

PAGE 21

4.4.2.11, Delete "Major Defect 101", "DOD symbol missing, incorrect or illegible, 0.40%, 3.2, and Visual".

PAGE 23

4.5.3.3, at end of line 5: Add "any assembly not conforming to the specified requirements shall be classed defective and remove from the lot."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:17Z
Check the source to verify that this is the current version before use.

4.5.7.2, delete in its entirety.

5.1, Change as follows:

Was: 5.1 Preservation and Packaging"
Now: 5.2 Packaging Requirements. The warhead section shall be packed in accordance with dwg. 9226389.

5.1.1, Delete in its entirety.

5.2, Change as follows:

Was: 5.2 Packing.
Now: 5.2 Packing. The warhead section shall be packed in accordance with dwg. 9226390.

5.2.1, Delete in its entirety.

NOTE: The margins of this amendment are marked with two asterisks to indicate where changes from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Costodian:
ARMY - AR

Preparing activity:
Army - AR

Project Number; 1336-A332

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:17Z
Check the source to verify that this is the current version before use.