QUALIFICATIONS CERTIFIED
EVERY 2 YEARS

QPL-39029-32
12 December 1995
SUPERSEDING
QPL-39029-31
2 December 1994

**QUALIFIED PRODUCTS LIST**

**FSC** 5935

OF

**PRODUCTS QUALIFIED UNDER MILITARY SPECIFICATION**

MIL-C-39029

CONTACTS, ELECTRICAL CONNECTOR, GENERAL **SPECIFICATION FOR**

This list has been prepared for use by or for the **Government in the acquisition** of **products covered by the subject** specification and such listing of a product is not intended to and does not connote endorsement of the product by the Department of Defense. All products listed herein have been qualified under the requirements **for** the product as specified in the latest effective issue of the applicable specification. This list is subject to change without notice; revision or amendment of this list will be issued as necessary. The listing of a product does **not release the supplier from compliance with the specification requirements.**

THE ACTIVITY RESPONSIBLE FOR THIS QUALIFIED PRODUCTS LIST IS THE NAVAL AIR SYSTEMS COMMAND (ATTENTION: COMMANDING OFFICER, NAVAL AIR WARFARE CENTER AIRCRAFT DIVISION INDIANAPOLIS, 4.5.6.3/MS-60, INDIANAPOLIS, IN 46219-2189)

Questions concerning the QPL for MIL-C-39029/l-/26, /29-/33, /44-/47, /69, /70, /90, /91, /106, and /107 may be directed to the Naval Air Warfare Center, Aircraft Division (4.5.6.3/MS-60), 6000 E. 21st Street, Indianapolis, IN 46219-2189, Mr. Milton Smeltz, ,(317) 306-4560 or DSN 369-4560.

The activity responsible for all other slash sheets is AFALD/PTSP, Passive Components Division, Wright-Patterson AFB, OH 45433. Questions concerning the QPL for these slash sheets may be directed to the Defense Electronic Supply Center (DESC-ELS), Dayton, OH 45444-5285*

See the end of this QPL for full name, address and plant location of listed manufacturers.

AMSC N/A

**Distribution** Statement A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/1-100<br>-101<br>-102<br>-103<br>-507 | 3-592404-1<br>2-5924.04-1<br>1-592404-1<br>592404-1<br>592413-1 | AMP Inc.<br>(1)<br>NAC F04.60/08-31-93 |
| M39029/1-100<br>-101<br>-102<br>-103<br>-507 | 315-1622-500<br>315-1620-501<br>315-1416-502<br>315-1212-503<br>315-2022-600 | Tri-Star Electronics International, Inc.<br><br>NAC E04.81/08-31-93 |
| M39029/4-110<br>-111<br>-113 | 10-497006-205 **or** LP-497006-205<br>10-497006-165 or LP-497006-165<br>10-807300-125 or LP-807300-125 | Amphenol Aerospace Bendix Connectors<br><br>NAC K04.56/05-31-94 |
| M39029/4-110<br>-111<br>-113 | BA4020-36LD<br>BA4016-36LD<br>BA4012-36LD | Amphenol Aerospace Pyle-National Connectors<br><br>NAC E04.54/05-31-94 |
| M39029/4-110<br>-111<br>-112<br>-113<br>-114 | 0641-1-2031<br>0641-2-1631<br>109026-31<br>0641-3-1231<br>109028-31 | Deutsch Engineered Connecting Devices<br><br>NAC G04.74/05-31-94 |
| M39029/4-110<br>-111<br>-113 | 030-9173-006<br>030-9205-007<br>030-9185-003 | ITT Cannon<br>(1)<br>NAC K04.57/05-31-94 |
| M39029/4-110<br>-111<br>-112<br>-113<br>-114 | 5000-054-0020 **or** 5000-054-O020SP<br>5000-054-0016<br>5000-054-1620<br>5000-054-0012<br>5000-054-1216 | Matrix Science Connectors<br><br>NAC H04.59/05-31-94 |
| M39029/4-110<br>-111<br>-113 | 8522-2253A<br>8522-330A<br>8522-331A | Framatome Connectors<br><br>NAC H04.101/07-31-94 |
| M39029/4-110<br>-111<br>-112<br>-113<br>-114 | 315-2020-088 or 315-2020-088L<br>315-1616-089 or 315-1616-089L<br>315-1620-123 or 315-1620-123L<br>31S-1212-090 or 315-1212-090L<br>315-1216-124 or 315-1216-124L | Tri-Star Electronics International, Inc.<br><br>NAC G04.71/05-31-94 |


Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/5-115<br>-115<br>-116<br>-118 | LP-597805-355<br>10-497007-205 or LP-497007-205<br>10-497007-165 OK LP-497007-165<br>10-807301-125 or LP-807301-125 | Amphenol Aerospace<br>Bendix Connectors<br><br>NAC K04.56/05-31-94 |
| M39029/5-115<br>-116<br>-118 | BA4120-36LD<br>BA4116-36LD<br>BA4112-36LD | Amphenol Aerospace<br>Pyle-National Connectors<br><br>NAC E04.54/05-31-94 |
| M39029/5-115<br>-116<br>-117<br>-118<br>-119 | 100503<br>100504<br>109027<br>100505<br>109029 | Deutsch Engineered<br>Connecting Devices<br><br>NAC G04.74/05-31-94 |
| M39029/5-115<br>-116<br>-118 | 031-9174-004 or 031-9174-031<br>031-9206-006<br>031-9186-003 | ITT Cannon<br>(1)<br>NAC K04.57/05-31-94 |
| M39029/5-115<br>-116<br>-117<br>-118<br>-119 | 5100-001-0020 or 5100-001-0020SP<br>5100-001-0016<br>5100-001-1620<br>5100-001-0012<br>5100-001-1216 | Matrix Science<br>Connectors<br><br>NAC H04.59/05-31-94 |
| M39029/5-115<br>-116<br>-118 | 8520-289<br>8522-486A<br>8522-487B | Framatome Connectors<br><br>NAC H04.101/07-31-94 |
| M39029/5-115<br>-116<br>-117<br>-118<br>-119 | 316-2020-088 or 316-2020-088L<br>316-1616-089 or 316-1616-089L<br>316-1620-123 or 316-1620-123L<br>316-1212-090 or 316-1212-090L<br>316-1216-124 or 316-1216-124L | Tri-Star Electronics<br>International, Inc.<br><br>NAC G04.71/05-31-94 |
| M39029/9-133<br>-134<br>-135 | 5000-070-0420<br>5000-070-0120<br>5000-070-0220 | Matrix Science<br>Connectors<br><br>NAC F04.82/02-28-94 |
| M39029/9-132<br>-133<br>-134<br>-135<br>-136 | PM088-2020-M12-615<br>PM088-2020-M16-015<br>PM088-2020-M14-015<br>PM088-2020-M15-015<br>PM088-2020-M17-415 | Precision Technology<br><br>NAC B04.165/02-28-94 |

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| -514 | PM089-1616-M12-615 | Precision Technology (con' t) |
| -515 | PM089-1616-M16-015 | |
| -516 | PM089-1616-M14-015 | |
| -517 | PM089-1616-M15-015 | |
| -518 | PM089-1616-M17-415 | |
| M39029/9-132 | 615-2020-088D | Tri-Star Electronics International, Inc. |
| -133 | 015-2020-088K | |
| -134 | 015-2020-088A | NAC 04.176/04-30-95 |
| -135 | 015-2020-088C | |
| -136 | 415-2020-0881 | |
| - 5 1 4 | 615-1616-089D | |
| -515 | 015-1616-089K | |
| -516 | 015-1616-089A | |
| -517 | 016-1616-089C | |
| -518 | 415-1616-0891 | |
| M39029/10-139 | 5100-108-0420 | Matrix Science Connectors |
| -140 | 5100-108-0120 | |
| -141 | 5100-108-0220 | NAC F04.82/02-28-94 |
| M39029/10-138 | PM088-2020-M 12-616 | Precision Technology |
| -139 | PM088-2020-M 16-016 | |
| -140 | PM088-2020-M 14-016 | NAC B04.165/02-28-94 |
| -141 | PM088-2020-M 15-016 | |
| -142 | PM088-2020-M 17-416 | |
| -519 | PM089-1616-M 12-636 | |
| -520 | PM089-1616-M 16-016 | |
| -521 | PM089-1616-M 14-016 | |
| -522 | PM089-1616-M 15-016 | |
| -523 | PM089-1616-M 17-416 | |
| M39029/10-138 | 616-2020-088D | Tri-Star Electronics International, Inc. |
| -139 | 016-2020-088K | |
| -140 | 016-2020-088A | NAC 04.176/04-30-95 |
| -141 | 016-2020-088C | |
| -142 | 416-2020-088I | |
| -519 | 616-1616-089D | |
| -520 | 016-1616-089K | |
| -521 | 016-1616-089A | |
| -522 | 016-1616-089C | |
| -523 | 416-1616-089I | |
| M39029/11-144 | 204873-3 or 204873-4 | AMP Inc. (1) NAC L04.53/02-28-93 |
| -145 | 204938-3 or 204938-4 | |
| -146 | 204978-3 or 204978-4 | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT **DESIGNATION** | MANUFACTURER'S **DESIGNATION** | MANUFACTURER'S NAME **AND TEST REFERENCE** |
|---|---|---|
| M39029/11-144<br>-145<br>-146<br>-147 | 030-1975-008<br>030-1892-004<br>030-9083-012<br>030-1909-002 | ITT Cannon<br>(1)<br>NAC G04.78/02-28-95 |
| M39029/11-144<br>-145<br>-146<br>-147 | 616-200<br>616-210<br>616-230<br>616-240 | Radian S.A.<br><br>NAC A04.172/02-28-95 |
| M39029/11-144<br>-145<br>-146<br>-147 | 315-2222-079<br>315-2020-081 or 315-2020-081L<br>315-1616-076 or 315-1616-076L<br>315-1212-078 or 315-1212-078L | Tri-Star Electronics International, Inc.<br><br>NAC G04.47/02-28-93 |
| M39029/12-148<br>-149<br>-150 | 205103-3 or 205103-4<br>205116-1 *OK* 205116-2<br>205117-1 or 205117-2 | AMP Inc.<br>(1)<br>NAC L04.53/02-28-93 |
| M39029/12-148<br>-149<br>-150<br>-151 | 031-1113-008<br>031-1047-003<br>031-1271-000<br>031-1059-003 | ITT Cannon<br>(1)<br>NAC G04.78/02-28-95 |
| M39029/12-148<br>-149<br>-150<br>-151 | 616-300<br>616-310<br>616-330<br>616-340 | Radian S.A.<br><br>NAC A04.172/02-28-95 |
| M39029/12-148<br>-149<br>-150<br>-151 | 316-2222-079<br>316-2020-081 or 316-2020-081L<br>316-1616-076 or 316-1616-076L<br>316-1212-078 or 316-1212-078L | Tri-Star Electronics<br><br>NAC G04.47/02-28-93 |
| M39029/16-166<br>-167<br>-168<br>-169<br>-170 | 81542-238<br>81542-23<br>81542-20<br>81542-16<br>81542-12 | Deutsch Engineered Connecting Devices<br><br>NAC E04.75/11-30-94 |
| M39029/16-167<br>-168<br>-169 | 316-2322-567<br>316-2020-568<br>316-1616-569 | Tri-Star Electronics, International, Inc.<br><br>NAC G04.89/11-30-94 |

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/17-171 | 81543-238 | Deutsch Engineered Connecting Devices |
| -172 | 81543-23 | |
| -173 | 81543-20 | |
| -174 | 81543-16 | NAC E04.75/11-30-94 |
| -175 | 81543-12 | |
| M39029/17-172 | 316-2322-572 | Tri-Star Electronics International, Inc. |
| -173 | 316-2020-573 | |
| -174 | 316-1616-574 | NAC G04.89/11-30-94 |
| M39029/18-176 | 81541-238 | Deutsch Engineered Connecting Devices |
| -177 | 81541-23 | |
| -178 | 81541-20 | |
| -179 | 81541-16 | NAC E04.75/11-30-94 |
| -180 | 81541-12 | |
| M39029/18-177 | 315-2322-567 | Tri-Star Electronics International, Inc. |
| -178 | 315-2020-568 | |
| -179 | 315-1616-569 | NAC G04.89/11-30-94 |
| M39029/22-191 | CTS-S22/22 | Deutsch Engineered Connecting Devices |
| -192 | CTS-S20/20 | |
| -193 | CTS-S16/16 | |
| -605 | CTS-S12/12 | NAC F04.84/08-31-93 |
| M39029/22-191 | 316-2222-191 | Tri-Star Electronics, International, Inc. |
| -192 | 316-2020-192 | |
| -193 | 316-1616-193 | NAC E04.81/08-31-93 |
| M39029/25-206 | 21-33114-42F | Amphenol Aerospace Bendix Connectors |
| M39029/26-207 | 21-33115-40F | NAC F04.5S/02-28-95 |
| M39029/27-210 | 21-33121-546 | Amphenol Aerospace Bendix Connectors |
| -402 | 21-33121-541 | 39029-155-78 |
| M39029/27-210 | 316-12CX-550 | Tri-Star Electronics International, Inc. |
| -402 | 316-12CX-551 | |
| -403 | 316-12CX-552 | 39029-218-84 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/28-211<br>-409 | 21-33122-546<br>21-33122-541 | Amphenol Aerospace<br>Bendix Connectors<br><br>39029-155-78 |
| M39029/28-211<br>-409<br>-414 | T3-4612-211LD<br>T3-4612-409LD<br>T3-4612-414LD | Amphenol Aerospace<br>Pyle-National Connectors<br><br>39029-378-85<br>39029-738-87 |
| M39029/28-211<br>-409<br>-410<br>-411<br>-413<br>-414<br>-415 | 6162-233-1277<br>6162-234-1277<br>6162-235-1277<br>6162-236-1277<br>6162-238-1277<br>6162-239-1277<br>6162-240-1277 | Deutsch Engineered<br>Connecting Devices<br><br>39029-221-84 |
| M39029/28-211<br>-409<br>-410 | 315-12CX-550<br>315-12CX-551<br>315-12CX-552 | Tri-Star Electronics<br>International, Inc.<br><br>39029-218-84 |
| M39029/28-211 | 602290-211 | Deutsch Ltd.<br><br>39029-398-88 |
| M39029/29-212<br>-213<br>-214<br>-215<br>-216 | 5000-029-0016<br>5000-029-0012<br>5000-029-0008<br>5000-029-0004<br>5000-029-0000 | Matrix Science<br>Connectors<br><br>NAC F04.61/05-31-93 |
| M39029/29-212<br>-213 | 0660-206-1631<br>0660-206-1282 | Deutsch Engineered<br>Connecting Devices<br><br>NAC K04.110/05-31-95 |
| M39029/29-212<br>-213<br>-214<br>-215<br>-216 | 030-3196-008<br>030-3197-007<br>030-3198-003<br>030-3199-004<br>030-3200-003 | ITT Cannon<br>(1)<br>NAC K04.70/05-31-95 |
| M39029/29-212<br>-213<br>-214<br>-215 | 541-110-1616<br>541-220-1212<br>541-220-0808<br>541-220-0404 | J-Tech<br><br>NAC A04.170/05-31-95 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/29-212 | 315-1616-091 or 315-1616-091L | Tri-Star Electronics International, Inc. |
| -213 | 915-1212-092 | |
| -214 | 915-0808-093 | |
| -215 | 915-0404-094 | NAC K04.72/05-31-93 |
| -216 | 915-0000-095 | |
| M39029/30-217 | 5100-033-1601 | Matrix Science Connectors |
| -218 | 5100-033-1602 | |
| -219 | 5100-033-0012 | |
| -220 | 5100-033-0008 | NAC F04061/05-31-93 |
| -221 | 5100-033-0004 | |
| -222 | 5100-033-0000 | |
| M39029/30-217 | 0662-212-1631 | Deutsch Engineered Connecting Devices |
| -218 | 0662-207-1631 | |
| -219 | 0662-207-1282 | |
| | | NAC K04.110/05-31-95 |
| M39029/30-217 | 031-3113-005 | ITT Cannon |
| -218 | 031-3114-008 | (1) |
| -219 | 031-3115-006 | NAC K04.70/05-31-95 |
| -220 | 031-3116-003 | |
| -221 | 031-3117-003 | |
| -222 | 031-3118-003 | |
| M39029/30-217 | 542-110-1616S | J-Tech |
| -218 | 542-110-1616 | |
| -219 | 542-220-1212 | NAC A04.170/05-31-95 |
| -220 | 542-220-0808 | |
| -221 | 542-220-0404 | |
| M39029/30-217 | 316-1616-117 or 316-1616-117L | Tri-Star Electronics International, Inc. |
| -218 | 316-1616-091 or 316-1616-091L | |
| -219 | 916-1212-092 | |
| -220 | 916-0808-093 | NAC K04.72/05-31-93 |
| -221 | 916-0404-094 | |
| -222 | 916-0000-095 | |
| M39029/31-223 | 10-807164-205 or LP-807164-205 | Amphenol Aerospace Bendix Connectors |
| -228 | 10-314980-16P or LP-314980-165 | |
| -229 | 10-807100-165 or LP-807100-165 | |
| -235 | 10-807100-125 or LP-807100-125 | NAC J04.80/11-30-93 |
| -240 | 10-314980-20P or LP-314980-205 | |
| -241 | 10-807100-205 or LP-807100-205 | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/31-228 | ZZL-4016-66LD | Amphenol Aerospace<br>Pyle-National Connectors<br><br>NAC G04.73t10-25-94 |
| -229 | ZZL-4016-36LD | |
| -234 | ZZL-4012-66LD | |
| -235 | ZZL-4012-36LD | |
| -240 | ZZL-4020-66LD | |
| -241 | ZZL-4020-36LD | |
| M39029/31-228 | 4160-203-1631 | **Deutsch Engineered Connecting Devices**<br><br>NAC 104.85/11-30-93 |
| -229 | 4160-204-1631 | |
| -240 | 0004-058-100 | |
| -241 | 4160-202-2031 | |
| M39029/31-228 | 030-9032-003 | ITT Cannon<br>(1)<br>NAC E04.79/11-30-93 |
| -240 | 030-9036-000 | |
| M39029/31-228 | 5000-255-0016 | Matrix Science<br>**Connectors**<br><br>NAC C04.163/11-30-93 |
| -240 | 5000-255-0020 | |
| M39029/31-223 | 317-2020-001 or 317-2020-O01L | Tri-Star Electronics International, Inc.<br><br>NAC 04.176/04-30-95<br>NAC J04.49/11-30-93 |
| -224 | 415-2020-0011 | |
| -225 | 015-2020-O01C | |
| -226 | 015-2020-O01A | |
| -227 | 015-2020-O01K | |
| -228 | 317-1616-086 or 317-1616-086L | |
| -229 | 315-1616-086 or 315-1616-086L | |
| -230 | 415-1616-0861 | |
| -231 | 015-1616-086C | |
| -232 | 015-1616-086A | |
| -233 | 015-1616-086K | |
| -234 | 317-1212-087 or 317-1212-087L | |
| -235 | 315-1212-087 or 315-1212-087L | |
| -236 | 415-1212-0871 . | |
| -237 | 015-1212-087C | |
| -238 | 015-1212-087A | |
| -239 | 015-1212-087K | |
| -240 | 317-2020-085 or 317-2020-085L | |
| -241 | 315-2020-085 or 315-2020-085L | |
| -448 | 317-2020-084 or 317-2020-084L | |
| M39029/32-242 | 10-807165-205 or LP-807165-205 | Amphenol Aerospace<br>Bendix Connectors<br><br>NAC J04.80/11-30-93 |
| -247 | 10-257982-16F | |
| -248 | 10-807103-165 or LP-807103-165 | |
| -254 | 10-807103-125 or LP-807103-125 | |
| -259 | 10-597820-355 or LP-597820-355 | |
| -259 | 10-257982-2OF or LP-257982-205 | |
| -260 | 10-807103-205 or LP-807103-205 | |
| -260 | LP-597815-35S | |



Source: https://assist.dla.mil -- Downloaded: 2026t0-26T13:21Z
Check the source to verify that this is the currentversion before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/32-247 | ZZL-4116-66LD | Amphenol Aerospace<br>Pyle-National Connectors<br><br>NAC G04.73/10-25-94 |
| -248 | ZZL-4116-36LD | |
| -253 | ZZL-4112-66LD | |
| -254 | ZZL-4112-36LD | |
| -259 | ZZL-4120-66LD | |
| -260 | ZZL-4120-36LD | |
| M39029/32-247 | 4162-201-1631 | Deutsch Engineered<br>Connecting Devices<br><br>NAC 104.85/+1-30-93 |
| -248 | 4162-202-1631 | |
| -259 | 0007-008-100 | |
| -260 | 4109-207-2000 | |
| 1439029132-247 | 031-9095-003 | ITT Cannon<br>(1)<br>NAC E04.79/11-30-93 |
| -259 | 031-9074-002 | |
| M39029/32-247 | 5100-401-0016 | Matrix Science<br>Connectors<br><br>NAC C04.163/11-30-93 |
| -259 | 5100-401-0020 | |
| M39029132-242 | 318-2020-001 or 318-2020-OO1L | Tri-Star Electronics<br>International, Inc.<br><br>NAC 04.176/04-30-95<br>NAC J04.49/11-30-93 |
| -243 | 416-2020-001I | |
| -244 | 016-2020-OO1C | |
| -245 | 016-2020-OO1A | |
| -246 | 016-2020-OO1K | |
| -247 | 318-1616-086 or 318-1616-086L | |
| -248 | 316-1616-086 or 316-1616-086L | |
| -249 | 416-1616-9021 | |
| -250 | 016-1616-902C | |
| -251 | 016-1616-902A | |
| -252 | 016-1616-902K | |
| -253 | 318-1212-087 or 318-1212-087L | |
| -254 | 316-1212-087 or 316-1212-087L | |
| -255 | 416-1212-9031 | |
| -256 | 016-1212-903C | |
| -257 | 016-1212-903A | |
| -258 | 016-1212-903K | |
| -259 | 318-2020-085 or 318-2020-085L | |
| -260 | 316-2020-085 or 316-2020-085L | |
| -449 | 318-2020-084 or 318-2020-084L | |
| M39029/33-262 | 10-807403-735 or LP-807403-735 | Amphenol Aerospace<br>Bendix Connectors<br><br>NAC G04.135/02-28-94 |
| -264 | 10-807401-735 or LP-807401-735 | |
| -266 | 10-807401-205 or LP-807401-205 | |
| -268 | 10-807003-165 or LP-807003-165 | |
| -270 | 10-807003-125 or LP-807003-125 | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/33-262<br>-264<br>-266 | 316-2328-513<br>316-2322-514<br>316-2020-515 | Tri-Star Electronics International, Inc.<br><br>NAC 104.95/02-28-94 |
| M39029/34-271<br>-272<br>-273<br>-440 | 2500-P4A20<br>2500-P6A20<br>2500-P6A16<br>MS2500-P2N2-61 | Continental Connector Corporation<br><br>39029-276-78<br>39029-719-80<br>39029-289-78 |
| M39029/34-271<br>-272<br>-273<br>-440 | MC220N-50<br>MC120N-50<br>MC116N-50<br>MC422N-50 | Positronic Industries Inc.<br>39029-1131-84<br>39029-1452-85 |
| M39029/34-272<br>-273 | 315-1620-519 Or 315-1620-519L<br>315-1616-520 or 315-1616-520L | Tri-Star Electronics International, Inc.<br><br>39029-1229-87 |
| M39029/34-271<br>-272<br>-273<br>-440 | 100-202729-50<br>100R-102OP95<br>100B-1016P95<br>100-202861-50 | Winchester "Electronics<br><br>39029-1225-84<br>39029-1094-79<br>39029-764-81<br>39029-291-78 |
| M39029/35-274<br>-275<br>-276<br>-441 | C2500-S4A20<br>C2500-S6A20<br>C2500-S6A16<br>MS2500-S2A22 | Continental Connector Corporation<br><br>39029-276-78<br>39029-719-80<br>39029-289-78 |
| M39029/35-274<br>-275<br>-276<br>-441 | FC220N2-50<br>FC120N2-50<br>FC116N2-50<br>FC422N2-50 | Positronic Industries<br><br>39029-1131-84 |
| M39029/35-275<br>-276 | 316-1620-519 or 316-1620-519L<br>316-1616-520 or 316-1616-520L | Tri-Star Electronics International, Inc.<br><br>39029-44-90 |



Source: https://assist.dla.mil -- Downloaded: 2026l0-26T13:21Z
Check the source to verify that this is the currentversion before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/35-274 | 100-202732-50 | Winchester Electronics |
| -275 | 100R-510200S95 | |
| -276 | 100B-51016S95 | 39029-1225-84 |
| -441 | 100-202862-50 | 39029-1094-79 |
| | | 39029-764-81 |
| | | 39029-291-78 |
| M39029/36-277 | 561-110-1620 | J-Tech |
| -278 | 561-110-1616 | |
| | | 39029-146-90 |
| M39029/36-277 | MP16Y20C300 | Packard-Hughes |
| -278 | MP16Y16C300 | |
| | | 39029-292-78 |
| M39029/36-277 | 315-1620-521 or 315-1620-521L | Tri-Star Electronics |
| -278 | 315-1616-522 or 315-1616-522L | International, Inc. |
| | | 39029-535-82 |
| M39029137-279 | 562-110-1620 | J-Tech |
| -280 | S62-110-1616 | |
| | | 39029-146-90 |
| M39029/37-279 | MS16Y20C300 | Packard-Hughes |
| -280 | MS16Y16C300 | |
| | | 39029-292-78 |
| M39029137-279 | 316-1620-S21 or 316-1620-521L | Tri-Star Electronics |
| -280 | 316-1616-522 or 316-1616-522L | International, Inc. |
| | | 39029-535-82 |
| M39029144-287 | 511-110-1622 | J-Tech |
| -288 | 511-110-1616 | |
| -289 | 511-120-1216 | NAC D04.161/08-31-94 |
| -290 | 511-220-1212 | |
| -291 | 511-220-0808 | |
| -292 | 511-220-0404 | |
| -293 | 511-220-0101 | |
| M39029/44-287 | 315-1622-09? or 215-1622-097L | Tri-Star Electronics |
| -288 | 315-1616-096 or 315-1616-096L | International, Inc. |
| -289 | 915-1216-125 | |
| -290 | 915-1212-098 | NAC F04.100/08-31-94 |
| -291 | 915-0808-099 | |
| -292 | 915-0404-100 | |
| -293 | 915-0000-101 | |



Source: https://assist.dla.mil -- Downloaded: 2026t0-26T13:21Z
Check the source to verify that this is the currentversion before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/45-294 | 512-110-1622 | J-Tech |
| -295 | 512-110-1616 | |
| -296 | 512-120-1216 | NAC D04.161/08-31-94 |
| -297 | 512-220-1212 | |
| -298 | 512-220-0808 | |
| -299 | 512-220-0404 | |
| -300 | 512-220-0101 | |
| M39029/45-294 | 316-1622-097 or 316-1622-097L | Tri-Star Electronics |
| -295 | 316-1616-096 or 316-1616-096L | International, Inc. |
| -296 | 916-1216-125 | |
| -297 | 916-1212-098 | NAC F04.100/08-31-94 |
| -298 | 916-0808-099 | |
| -299 | 916-0404-100 | |
| -300 | 916-0000-101 | |
| M39029/46-302 | 10-807402-735 or LP-807402-735 | Amphenol Aerospace |
| -304 | 10-807400-735 or LP-807400-735 | Bendix Connectors |
| -306 | 10-807400-205 or LP-807400-205 | |
| -308 | 10-807001-165 or LP-807001-165 | NAC G04.135/02-28-94 |
| -310 | 10-807001-225 or LP-807001-125 | |
| M39029/46-302 | 316-2328-561 | Tri-Star Electronics |
| -304 | 316-2322-562 | International, Inc. |
| | | NAC 104.95/02-28-94 |
| M39029/47-312 | 10-807018-735 or LP-807018-735 | Amphenol Aerospace |
| -314 | 10-807000-735 or LP-807000-735 | Bendix Connectors |
| -316 | 10-807000-205 or LP-807000-205 | |
| -337 | 10-807000-165 or LP-807000-165 | NAC G04.135/02-28-94 |
| -339 | 10-807000-125 or LP-807000-125 | |
| M39029/47-312 | 315-2328-561 | Tri-Star Electronics |
| -314 | 315-2322-562 | International, Inc. |
| | | NAC 104.95/2-28-94 |
| M39028/48-317 | 10-497100-6 | Amphenol Aerospace |
| -318 | 10-497102-6 | Bendix Connectors |
| -319 | 10-497222-6 | |
| -320 | 10-497100-4 | 39029-295-77 |
| -321 | 10-497102-4 | |
| -322 | 10-497222-4 | |
| -323 | 10-497100-3 | |
| -324 | 10-497102-3 | |
| -327 | 10-497100-43 | |
| -328 | 10-497102-43 | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/49-329 | 10-497101-6 | Amphenol Aerospace |
| -330 | 10-497223-6 | Bendix Connectors |
| -331 | 10-497101-4 | |
| -332 | 10-497233-4 | . 39029-295-77 |
| -333 | 10-497101-3 | |
| -335 | 10-497101-43 | |
| M39029/50-340 | 249-1825-001 | ITT Cannon (1) C70-73 |
| M39029/51-341 | 249-1826-000 | ITT Cannon (1) C70-73 |
| M39029/55-345 | 316-08CX-548 | Tri-Star Electronics International, Inc. 39029-63-88 |
| M39029/56-348 | 418-100-2200S-02 | Amphenol Ltd. |
| -351 | 418-100-2000S-02 | 39029-377-84 |
| M39029156-348 | 10-407035-725 | Amphenol Aerospace |
| 349 | 10-407035-235 or LP-407035-235 | Bendix Connector |
| -350 | 10-407035-225 or LP-407035-225 | |
| -351 | 10-407035-205 or LP-407035-205 | 39029-271-78 |
| -351 | 10-497403-205 | 39029-151-92 |
| -352 | 10-407035-165 or LP-407035-165 | |
| -353 | 10-407035-125 or LP-407035-125 | |
| M39029/56-348 | T3-4122-36LD | Amphenol Aerospace |
| -351 | T3-4120-36LD | Pyle-National Connectors |
| -352 | T3-4116-36LD | |
| -353 | T3-4112-36LD | 39029-894-79 |
| -527 | T3-411O-36LD | 39029-944-83 |
| | | 39029-378-85 |
| M39029/56-348 | 38943-22 | Deutsch Engineered |
| -351 | 38943-20 | Connecting Devices |
| -352 | 38943-16 | |
| -353 | 38943-12 ' | 39029-1054-82 |
| M39029/56-348 | 031-1147-007 or 031-1147-047 | ITT Cannon |
| -351 | 031-1250-001 | (1) |
| -352 | 031-1251-001 | 39029-273-78 |
| -353 | 031-1237-000 | 39029-1156-81 |
| | | 39029-78-92 |



Source: https://assist.dla.mil -- Downloaded: 202610-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT **DESIGNATION** | MANUFACTURER'S **DESIGNATION** | MANUFACTURER'S NAME **AND TEST REFERENCE** |
|---|---|---|
| M39029/56-348 | 5100-101-0122 | Matrix Science |
| **-351** | **5100-101-0120** | Connectors |
| -352 | 5100-101-0116 | |
| -353 | 5100-101-0112 | 39029-562-80 |
| M39029/56-348 | 8599-0906 | Framatome Connectors |
| -351 | 8599-0907 | |
| -352 | 8599-0908 | 39029-573-84 |
| -353 | 8599-0909 | |
| M39029156-348 | 316-2222-136 or 316-2222-136L | Tri-Star Electronics |
| -351 | 316-2020-139 or 316-2020-139L | International, Inc. |
| -349 | 316-2222-137 or 316-2222-137L | |
| -350 | 316-2222-138 or 316-2222-138L | 39029-1022-77 |
| -352 | 316-1616-140 or 316-1616-140L | 39029-238-82 |
| -353 | 316-1212-141 or 316-1212-141L | 39029-21-81 |
| -527 | 316-1010-231 | 39029-22-82 |
| M39029/57-354 | 204351-1 or 204351-2 | AMP Inc. (2) 39029-538-87 |
| 1439029/57-354 | 10-251416-725 or LP-251416-725 | Amphenol Aerospace |
| -355 | 10-251416-235 or LP-251416-235 | Bendix Connectors |
| -356 | 10-251416-225 or LP-251416-225 | |
| -357 | 10-497401-205 | 39029-271-78 |
| -357 | 10-251416-205 or LP-251416-205 | 39029-151-92 |
| -358 | 10-251416-165 or LP-251416-165 | |
| -359 | 10-251416-125 or LP-497093-125 | |
| M39029/57-354 | 38946-22 | Deutsch Engineered |
| -357 | 38946-20 | Connecting Devices |
| | | 39029-568-84 |
| M39029/57-354 | 031-1147-000 or 031-1147-046 | ITT Cannon |
| -355 | 031-1122-022 | (1) |
| -356 | 031-1125-022 | 39029-273-78 |
| -357 | 031-1124-020 | 39029-1156-81 |
| -358 | 031-1123-016 | 39029-78-92 |
| -359 | 031-1238-000 | |
| M39029/57-354 | 5100-101-0022 | Matrix Science |
| -357 | 5100-101-0020 | Connectors |
| -358 | 5100-101-0016 | |
| -359 | 5100-101-0012 | 39029-563-80 |


Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| 1439029157-354 | FC8522D | Positronic Industries<br>39029-680-87 |
| M39029/57-354<br>-357<br>-358<br>-359 | 8599-0910<br>8599-0911<br>8599-0912<br>8599-0913 | Framatome Connectors<br>39029-573-84 |
| M39029157-355<br>-356<br>-354<br>-357<br>-358<br>-359 | 316-2222-104 or 316-2222-104L<br>316-2222-105 or 316-2222-105L<br>316-2222-103 or 316-2222-103L<br>316-2020-106 or 316-202O-1O6L<br>316-1616-107 or 316-1616-107L<br>316-1212-108 or 316-1212-108L | Tri-Star Electronics International, Inc.<br>39029-238-82<br>39029-1023-77<br>39029-1022-77<br>39029-21-81<br>39029-22-82 |
| M39029/57-354 | E8901-354 | Texas Instruments<br>39029-298-92 |
| M39029/58-360 | 204370-2 or 204370-5 | AMP Inc.<br>(2)<br>39029-538-87 |
| M39029/58-360<br>-361<br>-362<br>-363<br>-364<br>-365 | 10-251415-725<br>10-251415-235 or LP-251415-725<br>10-251415-225 or LP-251415-225<br>10-251415-205 or LP-215415-205<br>10-251415-165 or LP-215415-165<br>1O-251415-12H or LP-215415-125 | Amphenol Aerospace Bendix Connectors<br>39029-271-78<br>39029-151-92 |
| M39029/58-360<br>-363<br>-364<br>-365<br>-528 | T3-4022-36LD<br>T3-4020-36LD<br>T3-4016-36LD<br>T3-4012-36LD<br>T3-401O-36LD | Amphenol Aerospace Pyle-National Connectors<br>39029-894-79<br>39029-944-83<br>39029-378-85 |
| M39029/58-360<br>-363<br>-364<br>-365 | 38941-22<br>38941-20<br>38941-16<br>38941-12 | Deutsch Engineered Connecting Devices<br>39029-1054-82 |



Source: https://assist.dla.mil -- Downloaded: 2026l0-26T13:21Z
Check the source to verify that this is the currentversion before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/58-360 | 030-2042-000 | ITT Cannon |
| -361 | 030-1993-022 | (1) |
| -362 | 030-1999-022 | 39029-273-78 |
| -363 | 030-1997-020 | 39029-1156-81- |
| -364 | 030-1995-016 | |
| -365 | 030-2155-000 | |
| -528 | 315-1010-231 | |
| M39029/58-360 | 5000-068-0022 | Matrix Science Connectors |
| -363 | 5000-068-0020 | |
| -364 | 5000-068-0016 | |
| -365 | 5000-068-0012 | 39029-562-80 |
| M39029/58-360 | MC8522D | Positronic Industries |
| | | 39029-680-87 |
| M39029/58-360 | 8599-0902 | Framatome Connectors |
| -363 | 8599-0903 | |
| -364 | 8599-0904 | 39029-573-04 |
| -365 | 8599-0905 | |
| M39029/58-360 | 315-2222-103 or 315-2222-103L | Tri-Star Electronics International, Inc. |
| -363 | 315-2020-106 or 315-202O-1O6L | |
| -361 | 315-2222-104 or 315-2222-104L | |
| -362 | 315-2222-105 or 315-2222-105L | 39029-1022-77 |
| -364 | 315-1616-107 or 315-16I6-107L | 39029-238-82 |
| -364 | 315-1616-707 or 315-1616-707L | 39029-21-81 |
| -365 | 315-1212-108 or 315-1212-108L | 39029-22-82 |
| -528 | 315-1010-231 | |
| M39029/58-360 | E8900-360 | Texas Instruments |
| | | 39029-298-92 |
| M39029/59-366 | 21-33101-21 | Amphenol Aerospace Bendix Connectors |
| | | 39029-288-78 |
| M39029/59-366 | 5700-012-0000 | Matrix Science Connectors |
| | | 39029-1164-83 |
| M39029/59-366 | 316-08CX-547 | Tri-Star Electronics International, Inc. |
| | | 39029-594-87 |



Source: https://assist.dla.mil -- Downloaded: 2026l0-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/60-367 | 21-33102-21 | Amphenol Aerospace Bendix Connectors<br>39029-288-78 |
| M39029/60-367 | 5600-019-0000 | Matrix Science Connectors<br>39029-1164-83 |
| M39029/60-367 | 315-08CX-547 | Tri-Star Electronics International, Inc.<br>39029-594-87 |
| M39029/63-368 | 205090-1 *or* 205090-2 | AMP Inc.<br>(2)<br>39029-538-87 |
| M39029/63-368 | DSC20W-1DJ5 | Burndy Corporation<br>39029-929-80 |
| M39029/63-368 | 2562-201-2031 | Deutsch Engineered Connecting Devices<br>39029-245-84 |
| M39029/63-368 | 126-20 | General Connector Corp.<br>39029-285-78 |
| M39029/63-368 | 031-1007-042 | ITT Cannon<br>(1,2,3)<br>39029-284-78 |
| M39029/63-368 | 5100-014-0020 | Matrix Science Connectors<br>39029-287-78 |
| M39029/63-368 | FC5020D | Positronic Industries<br>39029-694-79 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/63-368 | 8630-3022A | Framatome Connectors<br>39029-184-81 |
| M39029/63-368 | 318-2020-055 or 318-2020-055L | Tri-Star Electronics International, Inc.<br>39029-339-88 |
| M39029/64-369 | 205089-1 or 205089-2 | AMP Inc.<br>(2)<br>39029-538-87 |
| M39029/64-369 | DCM20W-1DJ5 | Burndy Corporation<br>39029-929-80 |
| M39029/64-369 | 2560-201-2031 | Deutsch Engineered Connecting Devices<br>39029-345-84 |
| M39029/64-369 | 25-43 | General Connector Corp.<br>39029-285-78 |
| M39029/64-369 | 330-S291-037 | ITT Cannon<br>(1,2,3)<br>39029-284-78 |
| M39029/64-369 | 5000-007-0020 | **Matrix Science Connectors**<br>39029-287-78 |
| M39029/64-369 | MC5020D | Positronic Industries Inc.<br>39029-694-79 |
| M39029/64-369 | 8630-3020A | Framatome Connectors<br>39029-184-81 |



Source: https://assist.dla.mil -- Downloaded: 202640-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/64-369 | 317-2020-055 or 317-2020-055L | Tri-Star Electronics International, Inc.<br><br>39029-339-88 |
| M39029/69-384<br>-385<br>-386 | C-21S1624LU<br>C-21S1620LU<br>C-21S1616LU | Packard-Hughes<br><br>NAC C04.98/08-17-94 |
| M39029/69-385<br>-386 | 316-1620-602<br>316-1616-602 | Tri-Star Electronics International, Inc.<br><br>NAC B04.171/07-31-94 |
| M39029/70-387<br>-388<br>-389 | C-21P1624LU<br>C-21P1620LU<br>c-21P1616LU | Packard-Hughes<br><br>NAC C04.98/08-17-94 |
| M39029/70-388<br>-389 | 315-1620-602<br>315-1616-602 | Tri-Star Electronics International, Inc.<br><br>NAC B04.171/07-31-94 |
| M39029/71-390<br>-392 | 10-407572-15<br>10-407572-35 | Amphenol Aerospace Bendix Connectors<br><br>39029-771-78 |
| 39029/71-390<br>-391<br>-392 | 315-22WW-912<br>-103<br>-127 | Tri-Star Electronics International, Inc.<br><br>39029-815-80 |
| M39029/72-393<br>-395<br>-524<br>-525<br>-526 | 10-407573-15<br>10-407573-35<br>10-497577-25<br>10-497577-35<br>10-497577-15 | Amphenol Aerospace Bendix Connectors<br><br>39029-771-78 |
| M39029/72-393<br>-394<br>-395<br>-524<br>-525<br>-526 | 316-22WW-912<br>316-22WW-103<br>316-22WW-127<br>316-22WW-157<br>316-22WW-345<br>316-22WW-038 | Tri-Star Electronics International, Inc.<br><br>39029-815-80<br>39029-691-83 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/73-397<br>-398 | 5700-011-0397<br>5700-011-0398 | Matrix Science Connectors<br><br>AFALD/PTSP Ltr 15 Nov 82 |
| M39029/73-396<br>-397<br>-398 | D-602-0107<br>D-602-0095<br>D-602-0105 | Raychem Corporation<br><br>TR1-6441-76039 19 Ott 79 |
| M39029/74-400<br>-401 | 5600-018-0400<br>5600-018-0401 | Matrix Science Connectors<br><br>AFALD Ltr 15 Nov 82 |
| M39029/74-399<br>-400<br>-401 | D-602-0106<br>D-602-0094<br>D-602-0104 | Raychem Corporation<br><br>TR1-6441-7039 19 Ott 79 |
| M39029/75-416<br>-417 | 21-33123-546<br>21-33123-541 | Amphenol Aerospace - Bendix Connectors<br><br>39029-1089-83 |
| M39029/75-416<br>-417<br>-422 | T3-4712-416LD<br>T3-4712-417LD<br>T3-4712-422LD | Amphenol Aerospace Pyle-National Connectors<br><br>39029-378-85<br>39029-738-87 |
| M39029/75-416<br>-417<br>-418<br>-419<br>-421<br>-422<br>-423 | 6162-217-1277<br>6162-218-1277<br>6162-219-1277<br>6162-220-1277<br>6162-222-1277<br>6161-223-1277<br>6162-224-1277 | Deutsch Engineered Connecting Devices<br><br>39029-221-84 |
| M39029/75-416 | 602272-416 | Deutsch Ltd.<br><br>39029-398-88 |
| M39025/75-416<br>-417 | 316-12CX-616<br>316-12CX-617 | Tri-Star Electronics **International, Inc.**<br><br>39029-302-83<br>39029-218-84 |


Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/76-424<br>-425 | 21-33122-563<br>21-33122-564 | Amphenol Aerospace<br>Bendix Connectors<br><br>39029-155-78 |
| M39029/76-424<br>-425<br>-426<br>-427 | 6162-229-1677<br>6162-230-1677<br>6162-231-1677<br>6162-232-1677 | Deutsch Engineered<br>Connecting Devices<br><br>39029-221-84 |
| M39029/76-424<br>-425<br>-426<br>-427 | 5600-020-0116<br>5600-020-0216<br>5600-020-0316<br>5600-020-0416 | **Matrix Science**<br>Connectors<br><br>39029-1224-85 |
| M39029/76-424 | 315-16CX-624 | Tri-Star Electronics<br>International, Inc.<br><br>39029-218-84 |
| M39029/77-428<br>-429 | 21-33123-563<br>21-33123-564 | Amphenol Aerospace<br>Bendix Connectors<br><br>39029-156-78 |
| M39029/77-428<br>-429<br>-430<br>-431 | 6162-213-1677<br>6162-214-1677<br>6162-215-1677<br>6162-216-1677 | Deutsch Engineered<br>Connecting Devices<br><br>39029-221-84 |
| M39029/77-428<br>-429<br>-430<br>-431 | 5700-013-0116<br>5700-013-0216<br>5700-013-0316<br>5700-013-0416 | Matrix Science<br>Connectors<br><br>39029-1224-85 |
| M39029/77-428 | 316-16CX-628 | Tri-Star Electronics<br>International, Inc.<br><br>39029-218-84 |
| M39029/78-432<br>-433 | 21-33121-563<br>21-33121-564 | Amphenol Aerospace<br>Bendix Connectors<br><br>39029-156-78 |


Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/78-432<br>-433<br>-434<br>-435 | 6162-253-1677<br>6162-254-1677<br>6162-255-1677<br>6162-256-1677 | Deutsch Engineered Connecting Devices<br><br>39029-221-84 |
| M39029/78-432<br>-433<br>-434<br>-435 | 5700-014-0116<br>5700-014-0216<br>5700-014-0316<br>5700-014-0416 | Matrix Science Connectors<br><br>39029-1224-85 |
| M39029/78-432 | 316-16CX-624 | Tri-Star Electronics International, Inc.<br><br>39029-218-84 |
| M39029/79-436<br>-437 | CSC16MO02<br>CSC16MO03 | Packard-Hughes<br><br>39029-286-77 |
| M39029/79-436<br>-437 | 315-16CX-612<br>315-16CX-613 | Tri-Star Electronics International, Inc.<br><br>39029-173-90 |
| M39029/80-438<br>-439 | CSC16FO02<br>CSC16FO03 | Packard-Hughes<br><br>39029-286-77 |
| M39029/80-438<br>-439 | 316-16CX-612<br>316-16CX-613 | Tri-Star Electronics International, Inc.<br><br>39029-173-90 |
| M39029/83-450<br>-451<br>-508 | 030-8008-800<br>030-8009-100<br>030-8085-700 | ITT Cannon<br>(1)<br>Crane 0781/12-8-81 |
| M39029/83-450<br>-451<br>-508 | 5000-391-2022<br>5000-391-2028<br>5000-391-2020 | Matrix Science Connectors<br><br>39029-837-93 |
| M39029/83-450<br>-451<br>-508 | GTP2022A0<br>GTP2028A0<br>GTP2020A0 | Packard-Hughes<br><br>Crane 0481/02-23-82 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029183-450 | 315-2022-915 or 315-2022-915L | Tri-Star Electronics International, Inc.<br><br>Crane 0383/11-17-83<br>Crane 0584/06-27-84 |
| -451 | 315-2028-915 or 315-2028-915L | |
| -508 | 315-2020-915 or 315-2020-915L | |
| M39029/84-452 | 031-8004-300 | ITT Cannon<br>(1)<br>Crane 0781/12-8-81 |
| -453 | 031-8004-400 | |
| -509 | 031-8005-700 | |
| M39029/04-452 | 5100-608-2022 | Matrix Science Connectors<br><br>39029-837-93 |
| -453 | 5100-608-2028 | |
| -509 | 5100-608-2020 | |
| M39029/84-452 | GTS2022A0 | Packard-Hughes<br><br>Crane 0481/02-23-82 |
| -453 | GTS2028A0 | |
| -509 | GTS2020A0 | |
| M39029/84-452 | 316-2022-915 or 316-2022-915L | Tri-Star Electronics International, Inc.<br><br>Crane 0383/11-17-83<br>Crane 0584/6-27-84 |
| -453 | 316-2028-915 or 316-2028-915L | |
| -509 | 316-2020-915 or 316-2020-915L | |
| 1439029/85-454 | 5000-042-4160 | Matrix Science Connectors<br><br>39029-952-81 |
| -455 | 5000-042-1160 | |
| -456 | 5000-042-2160 | |
| -457 | 5000-042-3160 | |
| -458 | 5000-042-4120 | |
| -459 | 5000-042-1120 | |
| -460 | 5000-042-2120 | |
| M39029/85-454 | PM091-1616-M16-015 | Precision Technology<br><br>39029-89-95 |
| -455 | PM091-1616-M14-015 | |
| -456 | PM091-1616-M15-015 | |
| -457 | PM091-1616-M17-415 | |
| -458 | PM092-1212-M16-015 | |
| -459 | PM092-1212-M14-015 | |
| -460 | PM092-1212-M15-015 | |
| -461 | PM092-1212-M17-415 | |
| M39029/85-454 | 015-1616-091K | Tri-Star Electronics International, Inc.<br><br>39029-319-85<br>39029-304-85<br>39029-592-83 |
| -457 | 415-1616-091I | |
| -455 | 015-1616-091A | |
| -456 | 015-1616-091C | |
| -450 | 015-1212-092K | |
| -459 | 015-1212-092A | |
| -460 | 015-1212-092C | |
| -461 | 415-1212-092I | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/86-462 | 5100-057-4162 | Matrix Science Connectors<br><br>39029-952-81 |
| -463 | 5100-057-1162 | |
| -464 | 5100-057-2162 | |
| -465 | 5100-057-3162 | |
| -466 | 5100-057-4120 | |
| -467 | 5100-057-1120 | |
| -468 | 5100-057-2120 | |
| -510 | 5100-057-4161 | |
| -511 | 5100-057-1161 | |
| -512 | 5100-057-2161 | |
| -513 | 5100-057-3161 | |
| M39029/86-462 | PM091-1616-M16-016 | precision Technology<br><br>39029-89-95 |
| -463 | PM091-1616-M14-016 | |
| -464 | PM091-1616-M15-016 | |
| -465 | PM091-1616-M17-416 | |
| -466 | PM092-1212-M16-016 | |
| -467 | PM092-1212-M14-016 | |
| -468 | PM092-1212-M15-016 | |
| -469 | PM092-1212-M17-416 | |
| -510 | PM117-1616-M16-016 | |
| -511 | PM117-1616-M14-016 | |
| -512 | PM117-1616-M15-016 | |
| -513 | PM117-1616-M17-416 | |
| M39029/86-462 | 016-1616-091K | Tri-Star Electronics International, Inc.<br><br>39029-319-85<br>39029-304-85<br>39029-592-83 |
| -463 | 016-1616-091A | |
| -464 | 016-1616-091C | |
| -465 | 416-1616-091I | |
| -466 | 016-1212-092K | |
| -467 | 016-1212-092A | |
| -468 | 016-1212-092C | |
| -469 | 416-1212-092I | |
| -510 | 016-1616-117K | |
| -511 | 016-1616-117A | |
| -512 | 016-1616-117C | |
| -513 | 416-1616-117I | |
| M39029/87-471 | T3-4022-1OR | Amphenol Aerospace Pyle-National Connectors<br><br>39029-112-84<br>39029-795-84 |
| -472 | T3-4022-1OP | |
| -475 | T3-402O-1OR | |
| -476 | T3-402O-1OP | |
| M39029/87-470 | PM103-2222-M16-O15 | Precision Technology<br><br>39029-34-94 |
| -471 | PM103-2222-M14-O15 | |
| -472 | PM103-2222-M15-O15 | |
| -473 | PM103-2222-M17-415 | |
| -474 | PM106-2O2O-M16-O15 | |
| -475 | PM106-2O2O-M14-O15 | |
| -476 | PM106-2020-M15-015 | |
| -477 | PM106-2O2O-M17-415 | |
| -478 | PM107-1616-M16-O15 | |



Source: https://assist.dla.mil -- Downloaded: 2026l0-26T13:21Z
Check the source to verify that this is the currentversion before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| -479 | PM107-1616-M14-O15 | Precision Technology (con't) |
| -480 | PM107-1616-M15-O15 | |
| -481 | PM107-1616-M17-415 | |
| M39029/87-470 | O15-2222-103K | Tri-Star Electronics International, Inc. |
| -471 | O15-2222-103A | |
| -472 | O15-2222-103C | |
| -473 | 415-2222-103I | 39029-319-85 |
| -474 | O15-202O-106K | 39029-592-83 |
| -475 | O15-202O-106A | 39029-304-85 |
| -476 | O15-202O-106C | 39029-319-85 |
| -417 | 415-2020-106I | |
| -478 | O15-1616-107K | |
| -479 | O15-1616-107A | |
| -480 | O15-1616-107C | |
| -481 | 415-1616-107I | |
| M39029/88-483 | T3-4122-1OR | Amphenol Aerospace Pyle-National Connectors |
| -484 | T3-4122-1OP | |
| -487 | T3-412O-1OR | 39029-112-84 |
| -488 | T3-412O-1OP | 39029-795-84 |
| M39029/88-482 | PM136-2222-M16-016 | Precision Technology |
| -483 | PM136-2222-M14-016 | |
| -484 | PM136-2222-M15-016 | 39029-34-94 |
| -485 | PM136-2222-M17-416 | |
| -486 | PM139-2020-M16-016 | |
| -487 | PM139-2020-M14-016 | |
| -488 | PM136-2020-M15-016 | |
| -489 | PM136-2020-M17-416 | |
| -490 | PM140-1616-M16-016 | |
| -491 | PM140-1616-M14-016 | |
| -492 | PM140-1616-M15-016 | |
| -493 | PM140-1616-M17-416 | |
| M39029188-482 | 016-2222-136K | Tri-Star Electronics International, Inc. |
| -483 | 016-2222-136A | |
| -484 | 016-2222-136C | |
| -485 | 416-2222-136I | 39029-319-85 |
| -486 | 016-2020-139K | 39029-304-85 |
| -487 | 016-2020-139A | 39029-592083 |
| -488 | 016-2020-139C | |
| -489 | 416-2020-139I | |
| -490 | 016-1616-140K | |
| -491 | 016-1616-140A | |
| -492 | 016-1616-140C | |
| -493 | 416-1616-1401 | |



Source: https://assist.dla.mil -- Downloaded: 202610-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/89-494 | PM103-2222-M16-O16 | Precision Technology<br><br>39029-34-94 |
| -495 | PM103-2222-M14-O16 | |
| -496 | PM103-2222-M15-O16 | |
| -497 | PM103-2222-M17-416 | |
| -498 | PM106-2020-M16-O16 | |
| -499 | PM106-2020-MI4-O16 | |
| -500 | PM106-2020-MI5-O16 | |
| -501 | PM106-2020-M17-416 | |
| -502 | PM107-1616-M16-O16 | |
| -503 | PM107-1616-M14-O16 | |
| -504 | PM107-1616-M15-O16 | |
| -505 | PM107-1616-M17-416 | |
| M39029/89-494 | O16-2222-103K | Tri-Star Electronics International, Inc.<br><br>39029-319-85<br>39029-304-85<br>39029-592-83 |
| -495 | O16-2222-103A | |
| -496 | O16-2222-103C | |
| -497 | 416-2222-1031 | |
| -498 | O16-2020-106K | |
| -499 | O16-2020-106A | |
| -500 | O16-2O2O-1O6C | |
| -501 | 416-2020-106I | |
| -502 | O16-1616-1O7K | |
| -503 | O16-1616-1O7A | |
| -504 | O16-1616-1O7C | |
| -505 | 416-1616-1071 | |
| M39029/90-529 | 21-33190-529 | Amphenol Aerospace Bendix Connectors<br><br>NAC D04.136/11-30-94 |
| M39029/90-529 | T3-46T08-LD | Amphenol Aerospace Pyle-National Connectors<br><br>NAC E04.138/11-30-94 |
| M39029/9O-529 | 602081-A | Deutsch Ltd.<br><br>NAC A04.166/11-04-93 |
| M39029/90-529 | 019912-2002 | Sabritec<br><br>NAC 04.173/11-04-92 |
| M39029/90-529 | 315-08CX-232 | Tri-Star Electronics International, Inc.<br><br>NAC B04.162/11-30-94 |



Source: https://assist.dla.mil -- Downloaded: 202610-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/90-529 | SPC8P-201 (3000-0081-201) | Trompeter Electronics<br>NAC C04.164/11-30-94 |
| M39029/91-530 | 21-33191-530 | Amphenol Aerospace<br>Bendix Connectors<br>NAC D04.136/11-30-94 |
| M39029/91-530 | T3-47T08-LD | Amphenol Aerospace<br>Pyle-National Connectors<br>NAC E04.138/11-30-94 |
| M39029/91-530 | 602091-A | Deutsch Ltd.<br>NAC A04.166/11-4-93 |
| M39029/91-530 | 019912-2003 | Sabritec<br>NAC 04.173/11-4-92 |
| M39029/91-530 | 316-08CX-232 | Tri-Star Electronics<br>NAC 604.162/11-30-94 |
| M39029/91-530 | SPC8S-201 (3000-0082-201) | Trompeter Electronics<br>NAC C04.164/11-30-94 |
| M39029/92-533 | SC10-1001 | Deutsch Relay Division<br>39029-1065-85 |
| M39029/92-531<br>-532<br>-533<br>-534<br>-535<br>-536 | CNS115900<br>CNS074900<br>CNS126900<br>CNS127900<br>CNS128900<br>CNS129900 | Precision Connector Design<br>39029-78-88 |
| M39029/92-533<br>-534<br>-535 | 316-1616-634 or 316-1616-634L<br>316-1620-634 or 316-1620-634L<br>316-1212-634 or 316-1212-634L | Tri-Star Electronics<br>International, Inc.<br>39029-1228-87 |



Source: https://assist.dla.mil -- Downloaded: 202640-26T13:21Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/93-597<br>-599<br>-539<br>-540 | 211901-5<br>208265-5<br>213122-5<br>213123-5 | AMP Inc.<br>(1)<br>39029-43-93 |
| M39029/93-597<br>-598<br>-539<br>-540 | 315-2222-306 or 315-2222-306L<br>315-2020-306 or 315-2222-306L<br>315-1616-306 or 315-1616-306L<br>315-1212-306 or 315-1212-306L | Tri-Star Electronics International, Inc.<br><br>39029-555-91 |
| M39029/94-601<br>-602<br>-603<br>-604 | 208264-4<br>208267-4<br>208270-4<br>208273-4 | **AMP Inc.**<br>(1)<br>39029-43-93 |
| M39029/94-601<br>-602<br>-603<br>-604 | 316-2222-306 or 316-2222-306L<br>316-2020-306 or 316-2222-306L<br>316-1616-306 or 316-1616-306L<br>316-1212-306 or 316-1212-306L | Tri-Star Electronics International, Inc.<br><br>39029-555-91 |
| M39029/101-553<br>-554 | 1662-213-2031<br>1662-213-1631 | Deutsch Engineered Connecting Devices<br><br>39029-338-88<br>39029-1130-86 |
| M39029/101-551<br>-552<br>-553<br>-554 | 316-2228-194<br>316-2222-194<br>316-2020-194<br>316-1616-194 | Tri-Star Electronics International, Inc.<br><br>39029-1226-87 |
| M39029/102-558<br><br>M39029/103-559 | 602177<br><br>602176 | Deutsch Ltd.<br><br>39029-398-88 |
| M39029/106-614<br>-615<br>-616<br>-617 | 1O-597O61-2X<br>1O-597O65-2X<br>1O-597O69-2X<br>1O-597O73-2X | Amphenol Aerospace Bendix Connectors<br><br>NAC A04.167/03-31-94 |
| M39029/106-614<br>-615<br>-616<br>-617 | 12333-22<br>12333-20<br>12333-16<br>12333-12 | Deutsch Engineered Connecting Devices<br><br>NAC A04.168/03-31-94 |



Source: https://assist.dla.mil -- Downloaded: 2026l0-26T13:21Z
Check the source to verify that this is the currentversion before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION | MANUFACTURER'S NAME AND TEST REFERENCE |
|---|---|---|
| M39029/107-620 | 10-597058-3X | Amphenol Aerospace Bendix Connectors<br><br>NAC A04.167/03-31-94 |
| -621 | 10-597064-2X | |
| -622 | 10-597068-2X | |
| -623 | 10-597072-2X | |
| M39029/107-620 | 12331-22 | Deutsch Engineered Connecting Devices<br><br>NAC A04.168/03-31-94 |
| -621 | 12331-20 | |
| -622 | 12331-16 | |
| -623 | 12331-12 | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| MANUFACTURER'S NAME AND ADDRESS | CAGE Number: |
|---|---|
| Office:<br>AMP Incorporated<br>470 Friendship Road<br>Harrisburg, PA 17111<br><br>Plant:<br>1. 1250 E. Main St.<br>Mount Joy, PA 17552<br><br>2. 45-C Parker Street<br>Irvine, CA 92718 | 00779 |
| Office:<br>Amphenol Aerospace<br>Bendix Connectors<br>40-60 Delaware Avenue<br>Sidney, NY 13838-1395<br><br>Plant:<br>Same as above | 77820 |
| Office:<br>Amphenol Aerospace<br>Pyle-National Connectors<br>40-60 Delaware Avenue<br>Sidney, NY. 13838<br><br>Plant:<br>same as above | 49367 |
| Office:<br>Amphenol, LTD<br>Thanet Way<br>Whistable, Kent, CT5 3JF England<br><br>Plant:<br>Same as above | K1100 |
| Office:<br>Burndy Corporation<br>Richards Avenue<br>Norwalk, CT 06856<br><br>Plant:<br>Same as above | 95267 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| MANUFACTURER'S NAME AND ADDRESS | CAGE Number: |
|---|---|
| Office:<br>Continental Connector Corporation<br>Subsidiary of PMC Corporation<br>52 LaFrance Avenue<br>Bloomfield, NJ 07003 | 05238 |
| Plant:<br>Same as above | |
| Office:<br>Deutsch Engineered Connecting Devices<br>36033 Whittier Avenue<br>Hemet, CA 92545 | 11139 |
| Plant:<br>same as above<br>and<br>Municipal Airport<br>Oceanside, CA 92054 | |
| Office:<br>Deutsch Relay Division<br>65 Daly Road<br>East Northport, L.I., NY 11731 | 99699 |
| Plant:<br>same as above | |
| Office:<br>Deutsch Ltd.<br>The Birches Industrial Estate<br>East Grinstead<br>West Sussex RH19 1RW<br>UNITED KINGDOM | OPE82 |
| Plant:<br>Deutsch Ltd.<br>4 Stanier Road<br>Castleham, St. Leonards-On-Sea<br>East Sussex<br>UNITED KINGDOM | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| MANUFACTURER'S NAME AND ADDRESS | CAGE Number; |
|---|---|
| Office:<br>Framatome Connectors France<br>Manufacturer Souriau Connectors<br>R.N. 23<br>72470 Champagne<br>FRANCE | F0323 |
| Plant:<br>same as above | |
| Office:<br>General Connector<br>A Wire-Pro Company<br>23 Front Street<br>Salem, NJ 08079 | 25330 |
| Plant:<br>**Same as above** | |
| Office:<br>G & H Technology Inc. .<br>750 West Ventura Blvd.<br>Camarillo, CA 90301 . | 99447 |
| Plant:<br>1639 llth St.<br>Santa Monica, CA 90404 | |
| Office:<br>ITT Cannon<br>666 East Dyer Road<br>P.O. *BOX* 929<br>Santa Ana, CA 92702 | 71468 |
| Plant:<br>1. same as above<br>2. ITT Electromechanical Component<br>AV. du Mal de Lattre de Tassigny<br>39105 Dole<br>FRANCE<br>3. El Cid<br>Carretera International<br>Kilometro 6.5, Parque Industrial<br>Nogales, Sonora MEXICO | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| MANUFACTURER'S NAME AND ADDRESS | CAGE Number: |
|---|---|
| Office:<br>J-Tech Inc.<br>14251 Franklin Avenue<br>Tustin, CA 92660 | OBW78 |
| Plant:<br>same as above | |
| Office:<br>Matrix Science Connectors<br>470 Friendship Road<br>P.O. BOX 3608<br>Harrisburg, PA 17105-3608 | 14283 |
| Plant:<br>45-C Parker Street<br>Irvine, CA 92718 | |
| Office:<br>Packard-Hughes Interconnect<br>17150 Von Karman Avenue<br>Irvine, CA 92713-9685 | 53669 |
| Plant:<br>Packard-Hughes Interconnect<br>Mexico S.A. de C.V.<br>14532 Boulevard Pacifico<br>Parque Industrial Pacifico<br>Tijuana, Baja California, Mexico | |
| Office<br>Positronic Industries, Inc.<br>423 North Campbell<br>Springfield, MO 65806 | 28198 |
| Plant:<br>same as above | |
| Office:<br>Precision Connector Designs Inc.<br>2 Technology Drive<br>Peabody, MA 01960 | 58982 |
| Plant:<br>same as above | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

| MANUFACTURER'S NAME AND ADDRESS | CAGE Number: |
|---|---|
| Office:<br>Precision Technology & Mfg., Inc.<br>3147 Durahart Street<br>Riverside, CA 92507<br><br>Plant:<br>same as above | OBA72 |
| Office:<br>Radian S.A.<br>Rue Velpeau, Z.I.N. °1<br>37110 Chateau-Renault<br>FRANCE<br><br>Plant:<br>same as above | F0987 |
| Office:<br>Raychem Corporation<br>300 Constitution Drive<br>Menlo Park, CA 94025<br><br>Plant:<br>same as above | 06090 |
| Office:<br>Sabritec<br>1733 Kaiser Ave.<br>Irvine, CA 92714<br><br>Plant:<br>same as above | 58795 |
| Office:<br>Texas Instruments, Inc.<br>34 Forest St.<br>Attleboro, MA 02703<br><br>Plant:<br>Texas Instruments, Inc.<br>111 Forbes Ave.<br>Mansfield, MA 02084 | 82647 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.

MANUFACTURER'S NAME AND ADDRESS | CAGE Number:

Office:

Tri-Star Electronics International, Inc.
2201 Rosecrans Avenue
El Segundo, CA 90245

55104

Plant:

same as above

Office:

Trompeter Electronics, Inc.
31186 La Baya Drive
P.O. Box 5069
Westlake Village, CA 91362-4047

14949

Plant:

same as above

Office:

Winchester Electronics
Division of Litton Industries, Inc.
400 Park Row
Watertown, CT 06795-0500

81312

Plant:

same as above

and

Winchester Electronics
Carretera International KM 6.5
Paque Industrial
Nogales, Sonora
MEXICO



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:21Z
Check the source to verify that this is the current version before use.