INCH-POUND

MIL-D-70430 (AR)
AMENDMENT 5
24 September 1996
SUPERSEDING
AMENDMENT 4
22 June 1994

MILITARY SPECIFICATION

DECELERATOR, RAM AIR, PARTS AND CONTAINER ASSEMBLY

This amendment forms a part of MIL-D-70430 (AR), dated 12 September 1983, and is approved for use by the U.S. Army Armament Research, Development and Engineering Center, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 3

* 3.4.1: Delete in its entirety and substitute the following:

"3.4.1 RAD integrity. The RAD Assembly Complete shall not display any broken threads nor opening of the weave around any stitch greater than 1/8 inch square after being inflated to peak pressure within a duration interval not to exceed 14.0 milliseconds by an inert gas which is exhausted by means of a solenoid valve from a lecture bottle (having an internal volume of 27.0 cu. in. minimum) pressurized to 490 + 10 psi."

3.5: Delete in its entirety.

PAGE 4

4.3.1, Parts Description: Delete "Scoop Assembly; Panel Assembly, Lower RAD; and Packing Container, RAD" in its entirety.

TABLE I: Delete "Scoop Assembly; Panel Assembly, Lower RAD; and Packing Container, RAD" in its entirety.

Source: https://assist.dla.mil - Downloaded: 2026-10-23T03:25Z
Check the source to verify that this is the current version before use.
DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

PAGE 7

TABLE I, under RAD Assembly, Complete: Delete "RAD Integrity" in its entirety.

PAGE 8

TABLE I: Under RAD Container Assembly, add "RAD Integrity 50 3.4.1 4.5.1".

Delete Thermal Shock in its entirety.

PAGE 10

4.4.2.1: Delete "Majors 102, 103, and 105".

Add Minor 203 "Major diameter .65% 3.4 Gage".

PAGE 11

4.4.2.2, Major 101: Add "(a)" next to .40%.

Add Note (a) to Notes block: "(a) Special inspection level, S-4, of MIL-STD-105."

PAGE 12

4.4.2.3:

Delete Major 101 in its entirety.

Delete Majors 102 and 104 in their entirety.

Delete Minor 201 and substitute "Major diameter .65%(a) 3.4 Gage".

Delete Minor 202 and substitute "Flatness .65%(a) 3.4 Gage".

Delete Minor 203.

Add "(a)" next to .40% (2 places).

Add Note (a) to Notes block: "(a) Special inspection level, S-4, of MIL-STD-105."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:25Z
Check the source to verify that this is the current version before use.

PAGE 13

4.4.2.4:

Major 102: Delete "from center".

Delete Minor 202 and 203 in their entirety.

Delete Minor 204 and substitute "Blend radius .65% 3.4 Gage".

Add Minor 205: "Notch .65% 3.4 Gage".

Add Minor 206: "Small hole diameters (of four-hole pattern) .65% 3.4 Gage".

Add Minor 207: "Small hole locations (of four-hole pattern) .65% 3.4 Gage".

Add Minor 208: "Center hole diameter .65% 3.4 Gage"

Add "(a)" next to .40% (2 places) and .65% (7 places).

Add Note (a) to Notes block: "(a) Special inspection level, S-4, of MIL-STD-105."

PAGE 14

4.4.2.5:

Major 101: Delete "100%" and substitute ".40%".

Add Major 102: "Rivets improper .40% 3.4 Gage".

PAGE 15

4.4.2.6:

Delete Minor 202 and substitute "Profile of scoop .65% 3.4 Gage".

Delete Minor 203.

Add "(a)" next to .65% (4 places).

Add Note (a) to Notes block: "(a) Five units per cutting die per 60,000 pieces."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:25Z
Check the source to verify that this is the current version before use.

PAGE 16

4.4.2.7:

Minor 201: Delete "Scoop length" and substitute "Centerline to outermost intersection of scoop (horizontal)".

Minor 202: Delete "Scoop width" and substitute "Centerline to outermost intersection of scoop (vertical)".

Add "(a)" next to .65% (3 places).

Add Note (a) to Notes block: "(a) Five units per cutting die per 60,000 pieces."

PAGE 17

Delete 4.4.2.8 in its entirety.

PAGE 18

Delete 4.4.2.9 in its entirety.

PAGE 19

4.4.2.10:

Delete Minor 202 and substitute "202 Notch .65% 3.4 Gage".

Delete Minors 203 and 204.

Add "(a)" next to .65% (4 places).

Add Note (a) to Notes block: "(a) Five units per cutting die per 20,000 pieces."

PAGE 20

4.4.2.11:

Delete Majors 101, 102, 103, 104, 105, 106 and 112 in their entirety.

Add Major 113: "Presence of RAD panel reinforcing .40% 3.4 Visual".

Add "(a)" next to .40% (5 places).

Add Note (a) to Notes block: "(a) Special inspection level, S-4, of MIL-STD-105."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:25Z
Check the source to verify that this is the current version before use.

PAGE 21

Delete 4.4.2.12 in its entirety.

PAGE 22

4.4.2.13:

Delete Critical 1 in its entirety.

Major 101: Delete "Visual" and substitute "Visual/Gage".

Add Major 102: "RAD integrity 32 3.4.1 4.5.1".

* Add Major 103: "Pinching of fabric .40% 3.4 Visual/Gage"

PAGE 23

* 4.5.1: Delete in its entirety and substitute the following:

"4.5.1 RAD integrity test. The RAD shall be removed from its container and inflated to a peak pressure, within a duration interval not to exceed 14.0 milliseconds, by an inert gas which is exhausted by means of solenoid valve from a lecture bottle (having an internal volume 27.0 cu. in. minimum) pressurized to 490 + 10 psi. In preparation for the test, it will be required to machine the center of the upper RAD plate (P/N 9333813) of the RAD Assembly Complete to accommodate the inflation input orifice (a 1/8 inch pipe fitting is normally sufficient). Pressure measurement of the lecture bottle shall be accomplished by means of suitable gage placed in the pneumatic circuit so as to allow direct exposure to the internal lecture bottle pressure. Measurement of the inflation interval of the RAD Assembly Complete shall be accomplished by means of a suitable piezoelectric transducer which is positioned along the axis of one lobe of the lower RAD panel (P/N 9345150), a distance of 2.0 + 0.5 inches from center, and coupled to a suitable oscilloscope with trace storage capacity.

A sample of 32 units per production lot shall be randomly selected and subjected to this test. Any assembly that fails to meet the requirements shall be considered a reject. A single failure shall result in an additional random sample of 64 assemblies pulled from the lot and tested. If no failures occur on the resample and test, the lot shall pass; if one or more failures occur, the lot shall be rejected. More than one failure on the initial test shall reject the lot."

Delete 4.5.2 in its entirety.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:25Z
Check the source to verify that this is the current version before use.

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1330-0400)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:25Z
Check the source to verify that this is the current version before use.