INCH-POUND

MIL-C-60315B (AR)
AMENDMENT 1
12 March 1992

MILITARY SPECIFICATION

CHARGE, PROPELLING, M67 FOR 105MM HOWITZER LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-C-60315B (AR) dated 9 September, 1991, and is approved for use by the US Army Armament Munitions and Chemical Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 8

4.3.2.3 Charge, assembly. Delete in its entirety and substitute new paragraph as included.

PAGE 11

4.3.3.3 Charge, propelling, assembly weight. Delete in its entirety.

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.3.2.3	Charge, Assembly	1 OF 1	9205472 or 9288695
			NEXT HIGHER ASSEMBLY

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical				
1	Missing or incorrect increments or incorrect propelling charge assembly weight.	100 % 1/	3.2	Scale
Major				
101	Incorrect sequence of increments.	100 %	3.2	Visual
102	Assembly damaged to the extent that propellant can escape.	100 %	3.2	Visual
Minor				
201	Increments insecurely tied at junctions.	Table II	3.2	Visual
202	Ties loose, broken or insecurely tied.	Table II	3.2	Visual
203	Marking missing or unidentifiable.	Table II	3.2	Visual
204	Evidence of poor workmanship.	Table II	3.5	Visual

NOTES:
1/ The defect shall be classed critical when the weight is in excess of 3 times that specified in 3.4. Major when the weight is in excess of that in 3.4 but not greater than 3 times. Compliance with 3.4 shall be determined by using the average weight of the empty bag assembly. If the defect is determined to be due to an incorrect propelling charge assembly weight, remove increment 5 by raising it off the scale without breaking the cord and replace it with a weight representing the average weight of increment 5. If the weight is incorrect, reject the charge. If the weight is correct and it can be determined that the off weight of increment 5 is caused by the lead foil (tare weight of bag) the charge shall be considered acceptable.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1315-AD74)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.