INCH-POUND

MIL-DTL-3628/151A
6 June 2000
SUPERSEDING
MIL-DTL-3628/151
15 November 1996

DETAIL SPECIFICATION SHEET

BADGE, IDENTIFICATION, CAREER COUNSELOR, ARMY

Inactive for new design after 13 January 1999.

This specification is approved for use by all Departments and Agencies of the Department of Defense.

The requirements for acquiring the product described herein shall consist of this specification sheet and the issue of MIL-DTL-3628 listed in that issue of the Department of Defense Index of Specifications and Standards (DoDISS) specified in the solicitation.

Dash No.
-1: Regular Size
-2: Miniature Size

MATERIAL: Red Brass or Nickel Silver

FINISH: Nickel Plated (Red Brass Only), Silver Plated, Oxidized, Relieved, Matte Finish and shall match TIOH Metal Finish Chip Number 14.

DIMENSIONS:

HEIGHT (overall):
-1: 1-7/8 inches (REF)
-2: 1-3/8 inches (REF)

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T19:50Z
Check the source to verify that this is the current version before use.

WIDTH (overall):
-1: 2-9/16 inches (REF)
-2: 1-7/8 inches (REF)
THICKNESS (at edge of scroll):
-1: 0.100 inch ± 0.005 inch
-2: 0.055 inch ± 0.005 inch

NOTES:

1. The term (REF) refers to the measurements taken from the Government furnished hub or die.

2. Piercing shall be as indicated.

3. A full forcer shall be used to bring up the design.

4. The attaching device shall be prong and wing-type clutch. Prongs shall be located on the reverse and configured as follows for both -1 and -2:

One prong shall be located on the vertical center line in the area of the eagle's head. One prong shall be located in the general area between the "L" and the "O" in "COUNSELOR." One prong shall be located in the general area between the "A" and the "R" in "CAREER."

CHANGES FROM PREVIOUS ISSUE: Marginal notations are not used in this revision to identify changes with respect to the previous issue due to the extent of the changes.

Custodian:
Army - IH

Preparing activity:
Army - IH

Review activities:
DLA - CT

(Project No. 8455-0015)

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T19:50Z
Check the source to verify that this is the current version before use.