MIL-B-43481E
AMENDMENT-2
17 March 1982
SUPERSEDING
AMENDMENT-1
12 November 1980

MILITARY SPECIFICATION

BOOTS, COMBAT, LEATHER, BLACK, DIRECT MOLDED SOLE

This amendment forms a part of Military Specification MIL-B-43481E, dated 31 May 1979, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 2

2.1, under STANDARDS MILITARY: ADD "MIL-STD-1188 - Commercial Packaging of Supplies and Equipment."

PAGE 3

* 2.2, under ASTM's Titles: Delete and substitute the following:

"D 518	- Rubber Deterioration - Surface Cracking.
D 573	- Rubber Deterioration - in an Air Oven.
D 1052	- Measuring Rubber Deterioration - Cut Growth Using Ross Flexing Apparatus.
D 1149	- Rubber Deterioration - Surface Ozone Cracking in a Chamber (Flat Specimen).
D 1630	- Rubber Property - Abrasion Resistance (NBS Abrader).
D 2240	- Rubber Property - Durometer Hardness."

PAGES 3 and 4

2.2: Delete all references to "NATIONAL MOTOR FREIGHT TRAFFIC ASSOCIATION, INC., AGENT" and "UNIFORM FREIGHT CLASSIFICATION COMMITTEE, AGENT".

PAGE 10

* 3.5, line 11: Delete "lastinng" and substitute "lasting".

FSC 8430

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:31Z
Check the source to verify that this is the current version before use.

PAGE 11

Add the following:

* "3.6 Lasts, markers and molds."

PAGE 13

* 3.7.3, last sentence: Delete "he" and substitute "The".

PAGE 15

3.7.6, lines 9 and 10: Delete "with a tack" and substitute "with 1 or 2 tacks".

PAGE 16

3.7.13, line 4: Delete "shall" and substitute "may".

3.7.13.1, line 1: Delete "of" and substitute "or under".

PAGE 17

3.7.13.2, first sentence: Delete and substitute:

"The heel biscuit may be one or two pieces and shall be placed in contact with the outersole biscuit so that during the molding operation the two knit together and the heel biscuit forms the bottom of wearing surface of the heel."

PAGE 19

4.3: Delete and substitute:

"4.3 First article inspection. When a first article is required (see 6.2), it shall be examined for the defects specified in 4.4.3.1.1 and tested for the characteristics specified in table VIII. The presence of any defect or failure of any test shall be cause for rejection of the first article."

PAGE 25

4.4.2.2.2, in defect column: Delete "Insole not scoured on the flesh side as required" and substitute: "Insole not fleshed and buffed on the flesh side as required."

PAGE 28

* 4.4.3.1.1, under Classification of Defects for "Vamp or counterpocket stitching at outersole junction", second defect : Delete "Minor X" and substitute "Major X".

Source: https://assist.dla.mil -- Downloaded: 202610-21T21:31Z
Check the source to verify that this is the current version before use.

PAGE 31

4.5: Delete and substitute:

"4.5 Methods of inspection."

PAGE 32

* 4.5.4.2, last sentence: Delete.

PAGE 33

5.1.2: Delete and substitute:

"5.1.2 Commercial. Boots shall be preserved in accordance with MIL-STD-1188."

* 5.2.1, line 5, after "PPP-B-636": Delete the period and insert: ", except that the liner joint may be secured in accordance with commercial practice."

PAGE 34

* 5.2.2, line 7, after "PPP-B-636": Delete the period and insert: ", except that the liner joint may be secured in accordance with commercial practice."

* 5.2.3: Delete and substitute:

"5.2.3 Commercial packing. Boots, preserved as specified in 5.1 shall be packed in accordance with MIL-STD-1188."

PAGE 35

5.3, line 2, after MIL-STD-129: Insert "or MIL-STD-1188, as applicable".

NOTE: The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the previous amendment.

Custodians:

Army - GL
Navy - NU
Air Force - 99

Preparing activity:

Army - GL

Project No. 8430-0307

Review activities:

Army - MD
Navy - MC
DLA - CT

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:31Z
Check the source to verify that this is the current version before use.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T21:31Z
Check the source to verify that this is the current version before use.