INCH-POUND

MIL-P-48655 (AR)
AMENDMENT 1
27 FEBRUARY 1990

MILITARY SPECIFICATION

PISTOL, SEMIAUTOMATIC, 9MM: M9

This Amendment forms a part of MIL-P-48655(AR), dated 19 December 1987, and is approved for use by the US Army Armament, Munitions and Chemical Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

2.1.1: Delete "MIL-I-6866 - Inspection, Penetrant, Method of".

PAGE 2

2.1.1: Add "MIL-STD-6866 - Inspection, Liquid Penetrant".

2.1.2: Add "B12913067 - Gage, Spanner".

PAGE 6

3.4.2, line 2: Delete "4.50 KG (9.9 lbs.)" and substitute "4.00 KG (8.82 lbs.)".

PAGE 9

Add as new paragraph 3.4.8.1:

"3.4.8.1 Slide capture mechanism function. At the conclusion of the reliability test, the slide capture mechanism shall be capable of preventing the rear half of a slide, which has been cut in half at the locking block slots, from separating from the pistol when one round of M882 ammunition is fired."

PAGE 12

4.5.2.1, line 3: Delete "4.5.3.1 and 4.5.3.2. " and substitute "4.5.3.1 and 4.5.3.2 except as noted in individual paragraphs below."

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:36Z
Check the source to verify that this is the current version before use.

PAGE 14

4.5.2.1.21: Add at the end of the paragraph: "This may be accomplished prior to testing per 4.5.3.1 and 4.5.3.2 provided that the rear sight is not repositioned after this inspection."

4.5.2.1.22: Add at the end of the paragraph "This may be performed prior to testing per 4.5.3.1 and 4.5.3.2."

4.5.2.1.23: Add at the end of the paragraph "This may be performed prior to testing per 4.5.3.1 and 4.5.3.2."

Add as new paragraph 4.5.2.1.24:

"4.5.2.1.24 Hammer pin/slide engagement. Gage the minimum engagement between the hammer pin head and the slide slot for compliance with drawing 9346412 using inspection equipment per drawing 12913067. This inspection shall be performed with the slide locked in the rearward position by the slide stop."

PAGE 17

4.5.3.5: Delete "Reliability testing" and substitute "Reliability and slide capture testing".

4.5.3.5.1: Delete in its entirety and substitute:

"4.5.3.5.1 Lot size. The reliability and slide capture test lot is the same lot and is hereafter referred to as the reliability test lot. The first five reliability test lots shall each consist of 500 pistols or a month's production, whichever is smaller. When five successive lots meet the reliability and slide capture requirements, the lot size shall be increased to 3,000 pistols or a month's production, whichever is smaller. When five successive lots of the increased lot size have met the reliability and slide capture requirements, the lot size shall be further increased to 6,000 pistols or a month's production, whichever is smaller. If rejection of a lot occurs at any time, the next smaller test lot size criteria shall be reinstated and the above procedures repeated in returning to the larger lot size. All changes to the reliability lot sizes must be approved by the government representative."

4.5.3.5.2, line 3: Delete "tested by the contractor for reliability using" and substitute "tested by the contractor for reliability and slide capture using".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:36Z
Check the source to verify that this is the current version before use.

4.5.3.5.2, line 7: Delete "Failure of the pistols shall be cause for rejection" and substitute "Failure of the pistols to meet the requirements in 3.4.8 and 3.4.8.1 shall be cause for rejection".

4.5.3.5.2, line 13: Delete "resubmitted for the reliability test." and substitute "resubmitted for the reliability and slide capture test."

PAGE 20

4.6.4, line 2: Delete "(9346444)" and substitute "(9346488)".

PAGE 22

4.6.7.1, Group IV: Delete "Slide (9346444)" and substitute "Slide (9346488)".

4.6.7.1, Group VI: Delete "Grip, left (9346450)" and substitute "Grip, left (9346489)".

PAGE 23

4.6.7.1, Group X: Delete "Pin, hammer (9346462)" and substitute "Pin, hammer (9346490)".

4.6.8: Delete "Reliability test" and substitute "Reliability and slide capture test".

4.6.8.4: Delete in its entirety and substitute:

"4.6.8.4 Inspection. Upon completion of the reliability test, the barrel and slide shall be magnetic particle inspected in accordance with MIL-STD-1949 and the receiver shall be dye penetrant inspected in accordance with MIL-STD-6866 (Type I, Method B, Sensitivity Level 3, Form d) to determine their compliance with Table I."

PAGE 24

Add as new paragraph 4.6.8.5:

"4.6.8.5 Slide capture test. Upon completion of the magnetic particle and dye penetrant inspection, the reliability pistols shall be tested for function of the slide capture mechanism (see 3.4.8.1). The slide from each of the three pistols shall be completely cut in half in the forward area of the locking block slot. Each pistol shall be fully assembled with the exception of the recoil spring and recoil spring guide. One M882 cartridge shall be inserted in the chamber and

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:36Z
Check the source to verify that this is the current version before use.

the severed halves of the slide shall be positioned on the pistol in the normal firing position. The pistol shall be fired. The firing shall be accomplished with the pistol held in a test fixture which allows firing from a safe position in the event that the slide separates from the pistol. Upon approval of the government representative, the reliability/slide capture weapons shall be scrapped."

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1005-A735)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:36Z
Check the source to verify that this is the current version before use.