MIL-P-63198(AR)
14 October 1977

MILITARY SPECIFICATION

PRIMER, STAB: PA505 PARTS FOR, AND LOADING, ASSEMBLING AND PACKING

This specification is approved for use by the U.S. Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification covers the parts for, and the loading, assembling and packing for one type of primer designated as Primer, Stab: PA505.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposal, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specification For

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-650 - Explosive: Sampling, Inspection and Testing
MIL-STD-1169 - Packaging, Packing and Marking For Shipment of Inert Ammunition Components

FSC: 1375

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

DRAWINGS (see 6.5)

U.S. Army Armament Research and Development Command

PRODUCT AND PACKAGING

9258182 - Box, Set-up, Packing, Ammunition, Inner for Small Explosive Components
9258183 - Box, Set-up, Packing, Ammunition, Outer for Small Explosive Components
9258184 - Box, Packing, Ammunition, for Small Explosive Components
9296892 - Primer, Stab, PA505

INSPECTION EQUIPMENT

8842964 - Adapter Ball
9275627 - Test Fixture
9275628 - Pin, Firing
9275629 - Guide, Pin, Firing
9275630 - Sleeve
9275631 - Pin, Support
9275632 - Base
9275633 - Plate, Witness

3. REQUIREMENTS

3.1 Materials. - Materials shall be in accordance with applicable drawings and specifications.

3.2 Primer. - The primer shall comply with all requirements specified on Drawing (Dwg.) 9296892, and associated drawings, and with all requirements specified in applicable specifications.

3.3 Moisture content.

3.3.1 Barium nitrate. - The moisture content of the barium nitrate at the time of loading the primer shall not exceed 0.50 percent when tested as specified in 4.5.1.

3.3.2 Lead azide. - The moisture content of the lead azide of the time of loading the primer shall not exceed 0.50 percent when tested as specified in 4.5.2.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

3.3.3 Priming mixture. - The moisture content of the priming mixture at the time of loading the primer shall not exceed 0.30 percent when tested as specified in 4.5.3.

3.4 Functioning.

3.4.1 Sensitivity and output. - The primer shall function on the first attempt and shall indent the specified lead disc for not less than 0.063 inch nor more than 0.183 inch and shall expand the diameter of the brass sleeve by not less than 0.006 nor more than 0.013 inch when tested as specified in 4.5.4.1.

3.4.2 Waterproofness. - The primer shall comply with the requirements of 3.4.1 after being submerged in water to a minimum depth of two (2) inches for not less than 48 hours, at a temperature of 75 degrees F plus or minus 5 degrees, when tested as specified in 4.5.4.2.

3.5 First article inspection. - This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

3.6 Workmanship. - All parts and assemblies shall be fabricated and loaded in a thorough, workmanlike manner. They shall be clean and free of burrs, chips, sharp edges, cracks, surface defects, dirt, grease, oil, rust, corrosion products, and other foreign matter. The cleaning method used shall not be injurious to any part nor shall the parts be contaminated by the cleaning agent. All required markings shall be neat and sharply defined.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibilities for inspection and standard quality assurance provisions. - Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of inspections. - The following types of inspection shall be conducted on this item.

a. First Article Inspection

b. Quality Conformance Inspection

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.3 First article inspection.

4.3.1 Submission. - The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated.

Part Description	Drawing	Quantity
Cup, Detonator	8798332	25
Primer, Stab, PA505	9296892	365

4.3.2 Inspections to be performed. - See MIL-A-48078 and Table I specified herein.

4.3.3 Rejection. - See MIL-A-48078.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-P-63198(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
	Primer, Stab, PA505				See Below
					NEXT HIGHER ASSEMBLY
					–
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Cup, Detonator (Dwg 8798332)				
	Examination for Defects	25	-	3.2	4.4.2.1
	Primer, Stab, PA505 (Dwg 9296892)				
	Examination for Defects	(a)	-	3.2	4.4.2.2
	Functioning - Sensitivity and Output	315	-	3.4.1	4.5.4.1
	Functioning - Waterproofness	50	-	3.4.2	4.5.4.2

NOTES:

(a) The sample shall consist of the primers to be functioned per 4.5.4.1 and 4.5.4.2.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection.

4.4.1 Inspection lot formation. - Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, inspection lots of primers shall contain:

a. Parts bearing the same lot interfix number from one manufacturer.

b. Lead azide from not more than one lot.

c. Priming mix from not more than one lot.

4.4.2 Examination. - See MIL-A-48078.

a. Sampling plans. - Unless otherwise specified in the Classification of Defects and Test tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63198(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.1	Cup, Detonator				8798332
					NEXT HIGHER ASSEMBLY
					9296892
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Cup cut, split or cracked		100.0%	3.2	Visual
Major	None defined				
Minor					
201	Evidence of poor workmanship		1.00%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63198(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.2	Assembly		9296892
			NEXT HIGHER ASSEMBLY —

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Cup cracked or split so that explosive is exposed or possibility of future leakage		100.0%	3.2	Visual
2	Disc punctured		100.0%	3.2	Visual
3	Caked explosive on exterior		100.0%	3.2	Visual
Major					
101	Length		0.40%	3.2	Gage
102	Diameter, Maximum (max)		0.40%	3.2	Gage
103	Paint on wrong end, both ends, missing, or improperly applied		0.40%	3.2	Visual
104	Disc seal missing or incomplete		0.40%	3.2	Visual
105	Functioning				
	Sensitivity and output		(a)	3.4.1	4.5.4.1
	Waterproofness		(b)	3.4.2	4.5.4.2
Minor					
201	Disc wrinkled or folded		0.65%	3.2	Visual
202	Assembly damaged (distorted or dented)		0.65%	3.2	Visual
203	Crimp not a full 360 degrees		0.65%	3.2	Visual
204	Evidence of poor workmanship		1.00%	3.6	Visual

NOTES:
(a) Sample as per 4.5.4.1.
(b) Sample as per 4.5.4.2.

Source: https://assist.dla.mil -- Downloaded: 2024-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63198(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.3	Box, Set-up, Inner, After Loading and Prior to Closing Slide Cover		9258182
			NEXT HIGHER ASSEMBLY —

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Filler and cushion assembly missing		100.0%	3.2	Visual
2	Filler and cushion assembly improperly assembled		100.0%	3.2	Visual
3	Stiffener missing		100.0%	3.2	Visual
4	Slide cover assembled reversed		100.0%	3.2	Visual
Major					
101	Release paper missing		0.40%	3.2	Visual
Minor					
201	Marking missing, incomplete or illegible		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.00%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.4	Box, Set-up, Outer, with Inner Set-up Boxes Assembled and Prior to Assembling Top				9258183
					NEXT HIGHER ASSEMBLY –
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Red surfaces on inner set-up boxes do not alternate on same side of outer set-up boxes		100.0%	3.2	Visual
2	Stiffeners not facing one direction		100.0%	3.2	Visual
Major	None defined				
Minor					
201	Marking missing, incomplete or illegible		0.65%	3.2	Visual
202	Box improperly taped		0.65%	3.2	Visual
203	Evidence of poor workmanship		1.00%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63198(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.5	Sealed Packed Barrier Bag, Prior to Packing In Box		9258183
			NEXT HIGHER ASSEMBLY —

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Waterproofness of barrier bag destroyed by rupture, puncture, or separation of heat seal		0.40%	3.2	Visual
102	Evidence of crushed box		0.40%	3.2	Visual
NOTE:	Package should be opened if there is evidence of crushing				
Minor					
201	Heat seal of barrier bag located so that one or more subsequent seals cannot be applied		0.65%	3.2	Visual
202	Marking of bag misleading or unidentifiable		0.65%	3.2	Visual
203	Evidence of poor workmanship		1.00%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.6	Box, Packing, Ammunition, Prior to Assembling Cover and Strapping	1 OF 1	9258184
			NEXT HIGHER ASSEMBLY: -

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Bags containing set-up boxes damaged		0.40%	3.2	Visual
102	Cushioning material incomplete or missing from around outer set-up boxes		0.40%	3.2	Visual
103	Marking missing, misleading or unidentifiable		0.40%	3.2	Visual
104	Contents loose within box		0.40%	3.2	Visual/Manual
Minor					
201	Evidence of poor workmanship		1.00%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63198(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.7	Box, Packing, Ammunition		9258184
			NEXT HIGHER ASSEMBLY: -

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Strapping missing, broken, loose or improperly fastened		0.40%	3.2	Visual/Manual
102	Box damaged		0.40%	3.2	Visual
103	Marking missing, incomplete or unidentifiable		0.40%	3.2	Visual
104	Wooden box cover nailed to box		0.40%	3.2	Visual
105	Metallic seal missing		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.00%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.4.3 Testing. - Testing is described in the First Article and Quality Conformance Inspection tables.

4.4.4 Inspection Equipment. - The inspection equipment required to perform the examinations and tests prescribed in this specification is identified, either directly or by reference, in the "Paragraph Reference/Inspection Method" column of the First Article or Quality Conformance Inspection tables herein. The contractor shall submit inspection equipment designs to the Government for approval in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and 6.2.

4.5 Test methods and procedures.

4.5.1 Moisture content of barium nitrate. - The moisture content of barium nitrate shall be determined at the time of loading. The moisture content of the barium nitrate shall be determined in accordance with MIL-STD-650, Method 101.5. The sample shall be selected from that quantity to be used to produce a primer lot.

4.5.2 Moisture content of lead azide. - The moisture content of lead azide shall be determined as specified in 4.5.1 except, that a two gram sample shall be used and the dish covered with a sheet of polytetrafluoroethylene. The sample shall be selected from that quantity to be used to produce a primer lot.

4.5.3 Moisture content of priming mixture. - The moisture content of the priming mixture shall be determined at the time of loading. A sample of 0.7 grams shall be selected. The sample shall be accurately weighed to the nearest milligram and dried to a constant weight at 60 degrees C plus or minus 5 degrees C, or in a desiccator containing anhydrous calcium chloride. The loss in weight shall be calculated as the percentage of moisture as follows:

$$\text{Percentage of Moisture} = \frac{100\ (A-B)}{A}$$

where:

A = The weight of the sample before drying.
B = The weight of the sample after drying.

4.5.4 Functioning.

4.5.4.1 Sensitivity and output. - Three hundred and fifteen (315) primers shall be selected from each lot and subjected to these tests. If three (3) or more primers fail to comply with the requirements specified, the lot shall be re-

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

jected. Test equipment and procedures shall be as specified on Dwgs. 8842964, 9275627, 9275628, 9275629, 9275630, 9275631, 9275632 and 9275633. The primer shall be assembled into the test fixture as specified on the applicable drawing. The specified weight shall be dropped from a height of nine (9) inches, maximum, onto the firing pin to function the primer. The height of the drop shall be measured from the top of the firing pin to the bottom of the weight ball. Any primer that fails to comply with the requirements specified in 3.4.1 shall be classed defective.

4.5.4.2 Waterproofness. - Following acceptance of the first article sample, one hundred and twenty-five (125) primers shall be selected from each lot for this test. If three (3) or more primers fail to comply with the specified requirements, the lot shall be rejected. All primers selected for the waterproofness test shall be conditioned as specified in 3.4.2, then removed and, within two (2) hours, shall be subjected to the functioning test as specified in 4.5.4.1.

4.5.5 Composition of priming mixture. - From each batch a sample of not less than six (6) grams shall be selected from that quantity of priming mixture to be used to produce a primer lot for this determination. The analysis shall be performed as specified in 4.5.5.1 to 4.5.5.5.

4.5.5.1 Barium nitrate. - Transfer an accurately weighed portion of approximately 0.5 grams of the dried sample (dried as per standard referenced in 4.5.1) to a tared medium porosity fritted glass crucible of 30 milliliter (ml.) capacity. Record the weight of crucible and sample as Weight A. Add 3 ml. of distilled water saturated with lead azide at a temperature of 5° ± 2°C. Swirl for 30 seconds, then apply suction. Repeat this procedure two times, making a total of three 3 ml. extractions. Using an eye dropper, transfer to the crucible enough alcohol to thoroughly wet the sample and wash the crucible walls. Aspirate until the odor of alcohol is no longer detectable and dry the crucible in an oven for 30 minutes at 60° ± 5°C. Cool in a desiccator and weigh. Record this weight as Weight B. Reserve the crucible and residue for the normal or basic lead styphnate determination. Correct for the percentage of normal or basic lead styphnate in the water extract as follows: Transfer the filtrate and washings quantitatively to a 100 ml. calibrated volumetric flask, washing the beaker thoroughly with distilled water and dilute to the mark. Using a calibrated pipette, transfer a 10 ml. aliquot of this solution

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

to a second 100 ml. calibrated volumetric flask and dilute to the mark with distilled water. Transfer a portion of this solution to a corex glass spectrophotometric cell (See 6.2) having a width of approximately 1 centimeter (cm) and determine its optical density at a wave length of 410 millimicrons. Use as reference a similar cell containing the same proportion of water saturated with lead azide and alcohol as the sample solution. Since the cell which holds the lead styphnate solution is not identical with the reference cell, correct the optical density obtained as described above for the difference in the amount of light which the two cells scatter and absorb. To do this, fill both cells with a solution of water and alcohol, and measure at a wave length of 410 millimicrons, the optical density of the cell which originally contained the normal lead styphnate solution. Calculate the percentage of normal lead styphnate in the filtrate on a dry basis as follows:

Normal lead styphnate found in barium nitrate filtrate, Percent $P_n = \frac{2.94\ (A-B)}{WD}$

Basic lead styphnate found in barium nitrate filtrate, Percent $P_b = \frac{4.48\ (A-B)}{WD}$

where:

A = Optical density of normal lead styphnate solution.
B = Optical density of water and alcohol solution.
D = Width of corex cell, cm.
W = Weight of dried sample.

Calculate the percentage of barium nitrate in the sample as follows:

Barium nitrate, percent = 100 (A-B) - (P_b or P_n)

where:

W = Weight of the dried sample.
A = Weight of crucible and sample.
B = Weight of the crucible and sample after extractions with water saturated with lead azide.
P_n = Percentage of normal lead styphnate found in barium nitrate filtrate.
P_b = Percentage of basic lead styphnate found in barium nitrate filtrate.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

4.5.5.2 Basic or normal lead styphnate. - The residue obtained in the determination of barium nitrate shall be extracted with the six-ml portions of ammonium acetate solution at about 25°C., (hot ammonium acetate shall not be used as it dissolves antimony sulfide to some extent) agitating each portion for about 30 seconds and allowing each portion to remain in contact with the residue for approximately 2 minutes. The residue shall be washed with water, saturated with antimony sulfide, until the washing coming through the crucible appears colorless. The filtrate and washing shall be quantitatively transferred to a 250-ml. calibrated volumetric flask, the beaker washed thoroughly with distilled water and diluted to the mark. Using a calibrated pipette, a 2-ml. aliquot of this solution shall be transferred to a 50-ml. calibrated volumetric flask in the case of basic lead styphnate, or a 2-ml. aliquot of the solution shall be transferred to a 100-ml. calibrated volumetric flask in the case of normal lead styphnate, and diluted to the mark with distilled water. A portion of this solution shall be transferred to a corex glass spectophotometric cell having a width of approximately one centimeter (cm.) and its optical density determined at a wave length of 410 millimicrons. As a reference, a similar cell containing ammonium acetate solution of the same concentration as the solution of the specimen shall be used. Since the cell which holds the basic lead styphnate is not identical with the reference cell, the optical density obtained shall be corrected as described above for the difference in the amount of light which the two cells scatter and absorb. This shall be done by filling both cells with ammonium acetate solution and measuring at a wave length of 410 millimicrons, the optical density of the cell which originally contained the lead styphnate solution. The percentage of normal or basic lead styphnate in the specimen shall be calculated as follows:

$$\text{Percentage basic lead styphnate} = \frac{28\ (A-B)}{WD} \pm P_b$$

$$\text{Percentage normal lead styphnate} = \frac{36.75\ (A-B)}{WD} \pm P_n$$

where:

A = Optical density of normal or basic lead styphnate.
B = Optical density of ammonium acetate solution.
D = Width of corex cell, cm.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

W = Weight of dried specimen.
P_b = Percent basic lead styphnate found in barium nitrate filtrate.
P_n = Percent normal lead styphnate found in barium nitrate filtrate.

4.5.5.3 Tetracene. - The wet residue obtained in the determination of basic lead styphnate shall be washed three times with alcohol, dried in an oven maintained at 60° ± 5°C., for 30 minutes, cooled in a desiccator and weighed. The dried residue in the crucible shall be transferred to a 125-ml. beaker with a stream of water, 25-ml. of water shall be added, and the contents of the beaker boiled on a hot plate for 5 minutes. The contents of the beaker shall be poured into the same crucible, and the residue in the crucible washed three times with boiling water and finally with alcohol. The crucible and contents shall be dried in an oven maintained at 60° ± 5°C. for 30 minutes, cooled in a desiccator and weighed. The percentage of tetracene in the specimen shall be calculated as follows:

$$\text{Tetracene, percent} = \frac{(C-D)\ 100}{W}$$

where:
C = Weight of crucible and residue after extraction with saturated ammonium acetate solution.
D = Weight of crucible and residue after treating with hot water.
W = Weight of the dried specimen.

4.5.5.4 Antimony sulfide. - The weight of the residue shall be calculated from the determination of tetracene to percentage antimony sulfide in the specimen as follows:

$$\text{Antimony sulfide, percent} = \frac{(D-E)\ 100}{W}$$

where:
D = Weight of crucible and specimen after treating with hot water.
E = Weight of crucible.
W = Weight of dried specimen.

4.5.5.5 Lead azide. - The lead azide content in the specimen shall be determined by subtracting from 100 the combined percentage of barium nitrate, basic or normal lead styphnate, tetracene and antimony sulfide.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

5. PREPARATION FOR DELIVERY

5.1 Preservation and packaging.

5.1.1 Level C. - The primers shall be preserved and packaged in accordance with Dwgs 9258182 and 9258183.

5.1.2 Level C. - Metal parts shall be packaged in accordance with MIL-STD-1169.

5.2 Packing.

5.2.1 Level C. - The primers, preserved and packaged as specified in 5.1.1, shall be packed in accordance with dwg 9258184.

5.2.2 Level C. - Metal parts, preserved and packaged as specified in 5.1.2, shall be packed in accordance with MIL-STD-1169.

5.3 Marking . - Marking shall be in accordance with Dwgs 9258182, 9258183, and 9258184. Packaging and packing containers for metal parts shall be marked in accordance with MIL-STD-1169.

5.4 Shipping. - When components from more than one lot are shipped at one time, each lot shall be kept separate, and the division between lots clearly indicated to prevent mixing of the lots in transit.

6. NOTES

6.1 Ordering data. - See MIL-A-48078(PA).

6.2 Submission of inspection equipment designs for approval. - (See MIL-A-48078). Submit equipment designs as required, to Commander: ARRADCOM, ATTN: DRDAR-QAA-I, Dover, New Jersey 07801.

6.3 Distribution of ammunition data cards. - Distribution of data cards shall include the following: Commander, ARRADCOM, ATTN: DRDAR-QAA-Q, Dover, New Jersey 07801.

6.4 Check test for possible deterioration. - The following test is designed to prevent primers that have deteriorated from being assembled into major ammunition items. The test

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.

shall be performed on primers from each lot which have been stored under normal conditions for more than two (2) years or under adverse conditions for any period of time. If the specification for the ammunition item into which primers are assembled does not require that the check test be performed, the Contracting Officer should insert in the contract a provision for the performance of the check test. The Contracting Officer will arrange for the contractor to be reimbursed for expense incurred in his performance of check tests for possible deterioration. Primers shall be selected from each lot for this test as per 6.4.1.

6.4.1 Sensitivity and output. - Three hundred and fifteen (315) primers shall be selected from each lot for these tests. The test shall be performed as specified in 4.5.4.1, using equipment in accordance with 4.4.4. Any primer that fails to comply with the requirements of 3.4.1 shall be classed defective. If four (4) or more primers are classed defective, the lot shall be rejected and not used in the loading operation.

6.5 Drawings. - Drawings listed in Section 2 of this specification under the heading U.S. Army Armanent Reasearch and Development Command (ARRADCOM) may also include drawings prepared by, and identified as, Edgewood Arsenal, Frankford Arsenal, Rock Island Arsenal or Picatinny Arsenal drawings. Technical data originally prepared by these activities are now under the cognizance of ARRADCOM.

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project Number: 1375-A-204

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:26Z
Check the source to verify that this is the current version before use.