ADOPTION NOTICE

SAE AMS10135, "ANGLE, BULB SECTION EXTRUDED" was adopted on 24 February 2004 for use by the Department of Defense (DoD). Proposed changes by DoD activities must be submitted to the DoD Adopting Activity: WR-ALC/TILCC, 420 Second Street, Suite 100, Robins AFB, GA 31098-1640. DoD activities, private sector and other Government agencies may purchase copies from the Society of Automotive Engineers, World Headquarters, 400 Commonwealth Drive, Warrendale, PA 15096-0001

SAE AMS10135 should be used instead of AND 10135, which was cancelled on 26 February 2004. The following information is provided for cross-reference purposes:

| AND 10135 | SAE AMS10135 |
|---|---|
| AND 10135-*[1] | SAE AMS10135-*[1] |

Note: *[1] represents the same dash number for AND and AMS PINs.

Custodians:
Air Force - 99

Adopting Activity:
Air Force - 84

Agent Activity:
Air Force - 99

(Project 9540-0188)

NOTE: The activities listed above were interested in this document as of the date of this document. Since organization and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at www.dodssp.daps.mil.

FSC 9540

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T16:23Z
Check the source to verify that this is the current version before use.