INCH-POUND

MIL-C-81703
NOTICE 2
10 December 2010
SUPERSEDING
NOTICE 1
30 September 1998

MILITARY SPECIFICATION

# CONNECTORS, ELECTRIC, CIRCULAR, MINIATURE, RACK AND PANEL OR PUSH-PULL COUPLING, ENVIRONMENT RESISTING

MIL-C-81703 and the following specification sheets associated with MIL-C-81703 are hereby canceled and superseded by the noted SAE International Aerospace Standard (AS):

| Document | Date | Cancellation Notice No. | Replacement | DoD Project No. |
|---|---|---|---|---|
| MIL-C-81703 | 21-Jul-1971 | 2 | SAE-AS81703 | 5935-2009-185 |
| Connectors, Solder Contact, Push-Pull Coupling, Series 1 | | | | |
| MS3130D | 21-Jul-1971 | 2 | SAE-AS31301 | 5935-2009-186 |
| MS3132D | 21-Jul-1971 | 2 | SAE-AS31321 | 5935-2009-187 |
| MS3134F | 21-Jul-1971 | 3 | SAE-AS31341 | 5935-2009-188 |
| MS3135D | 21-Jul-1971 | 2 | SAE-AS31351 | 5935-2009-189 |
| MS3137E | 21-Jul-1971 | 3 | SAE-AS31371 | 5935-2009-190 |
| MS3138D | 21-Jul-1971 | 4 | SAE-AS31381 | 5935-2009-191 |
| Connectors, Crimp Contact, Push-Pull Coupling, Series 2 | | | | |
| MS3140C | 21-Jul-1971 | 3 | SAE-AS31401 | 5935-2009-193 |
| MS3144C | 21-Jul-1971 | 3 | SAE-AS31441 | 5935-2009-194 |
| MS3147D | 21-Jul-1971 | 4 | SAE-AS31471 | 5935-2009-195 |
| MS3148D | 21-Jul-1971 | 4 | SAE-AS31481 | 5935-2009-196 |
| MS3445(AS) | 21-Jul-1971 | 3 | SAE-AS34451 | 5935-2009-197 |
| Connectors, Solder Contact, Push-Pull Coupling, Series 3 | | | | |
| MS3446(AS) | 21-Jul-1971 | 3 | SAE-AS34461 | 5935-2009-203 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T12:59Z
Check the source to verify that this is the current version before use.

| Document | Date | Cancellation Notice No. | Replacement | DoD Project No. |
|---|---|---|---|---|
| Connectors, Crimp Contact, Push-Pull Coupling, Series 3 | | | | |
| MS3146(AS) | 4-Feb-1972 | 2 | SAE-AS31461 | 5935-2009-199 |
| MS3149(AS) | 4-Feb-1972 | 2 | SAE-AS31491 | 5935-2009-200 |
| MS3466(AS) | 21-Jul-1971 | 3 | SAE-AS34661 | 5935-2009-198 |
| MS3467(AS) | 21-Jul-1971 | 3 | SAE-AS34671 | 5935-2009-205 |
| Connector Accessories | | | | |
| MS3182D | 21-Jul-1971 | 3 | SAE-AS31821 | 5935-2009-206 |
| Connectors Insert Arrangements | | | | |
| MS33698F(AS) | 21-Jul-1971 | 2 | SAE-AS33698 | 5935-2009-208 |
| MS33699F(AS) | 21-Jul-1971 | 1 | SAE-AS33699 | 5935-2009-209 |
| MS33700F(AS) | 21-Jul-1971 | 2 | SAE-AS33700 | 5935-2009-210 |
| MS33701G(AS) | 21-Jul-1971 | 2 | SAE-AS33701 | 5935-2009-211 |
| MS33702E(AS) | 21-Jul-1971 | 2 | SAE-AS33702 | 5935-2009-212 |
| MS33703F(AS) | 21-Jul-1971 | 2 | SAE-AS33703 | 5935-2009-213 |

CAUTION: The supersession information is valid as of the date of this notice and may be superseded by subsequent revisions of the superseding documents.

(Copies of SAE publications are available from www.sae.org or SAE International, 400 Commonwealth Drive, Warrendale, PA 15096-0001.)

Custodians:
Army – CR
Navy – AS
Air Force – 85
DLA – CC

Preparing activity:
Navy – AS
Project 5935-2009-185

Review activities:
Army – AR, AV, CR4, MI
Navy – EC
Air Force – 99



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T12:59Z
Check the source to verify that this is the current version before use.

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.daps.dla.mil.



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T12:59Z
Check the source to verify that this is the current version before use.