MIL-T-44243
30 September 1986
SUPERSEDING
(See 6.9)

MILITARY SPECIFICATION

TENT SECTIONS, TENT, EXTENDABLE, MODULAR, PERSONNEL (TEMPER)

This specification is approved for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This document covers the tent sections of an extendable frame supported tent.

1.2 Classification. Tent sections, liners, floors, vestibule, vestibule door, vestibule container and tent cover shall be classified as follows (see 6.2):

Items

1. - End section
2. - Window section (temperate)
3. - Door section (desert/tropical)
4. - Window section (desert/tropical)
5. - Door section (temperate)
6. - Tent fly (16 feet)
7. - Tent fly (8 feet)
8. - End section liner (temperate)
9. - End section liner (desert/tropical)
10. - Intermediate liner (temperate)

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: U.S. Army Natick Research, Development and Engineering Center, Natick, MA 01760-5014, by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

AMSC N/A FSC 8340

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

Items

11. - Intermediate liner (desert/tropical)
12. - Tent floor (single ply) 8 feet, 24 feet and 40 feet
13. - Tent floor (insulated)
14. - Vestibule w/door
15. - Vestibule floor (single ply)
16. - Vestibule floor (insulated)
17. - Partition
18. - Tent cover
19. - Vestibule container
20. - Tent pin container
21. - Modesty curtain
22. - Plenum, end wall, 16 feet
23. - Plenum, extendable, 16 feet
24. - Sliding blackout curtain
25. - Plenum, side entrance, 16 feet

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Documents. The following documents form a part of this document to the extent specified herein. Unless otherwise specified, the issues of these documents shall be those listed in the issue of the Department of Defense Index of Specifications and Standards (DODISS) and supplement thereto, cited in the solicitation.

SPECIFICATIONS

FEDERAL

TT-P-595	-	Preservative Coating, Canvas
DDD-L-20	-	Label: For Clothing, Equipage and Tentage (General Use)
PPP-B-601	-	Boxes, Wood, Cleated-Plywood
PPP-B-636	-	Boxes, Shipping, Fiberboard

STANDARDS

FEDERAL

FED-STD-751	-	Stitches, Seams and Stitchings

MILITARY

MIL-STD-105	-	Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-129	-	Marking for Shipment and Storage
MIL-STD-147	-	Palletized Unit Loads

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

DRAWINGS

U.S. ARMY NATICK RESEARCH, DEVELOPMENT AND ENGINEERING CENTER

5-4-3342	-	Hitch Pin Clip and Holder
5-4-3349	-	Tent Sections, Tent, Extendable, Modular, Personnel (Temper)
5-4-3350	-	End Section
5-4-3351	-	Door Section (Desert/Tropical)
5-4-3352	-	Window Section (Desert/Tropical)
5-4-3353	-	Tent Flies
5-4-3354	-	Screen Door
5-4-3355	-	Vent Flap
5-4-3356	-	Window Flap
5-4-3357	-	Beckets
5-4-3358	-	Erection Instructions
5-4-3359	-	Tent Cover
5-4-3360	-	Weather Seal Flaps
5-4-3361	-	Purlin Flaps
5-4-3362	-	Door Section (Temperate)
5-4-3363	-	Window Section (Temperate)
5-4-3364	-	End Section Liner (Temperate)
5-4-3365	-	End Section Liner (Desert/Tropical)
5-4-3366	-	Intermediate Liner (Temperate)
5-4-3367	-	Intermediate Liner (Desert/Tropical)
5-4-3368	-	Tent Floor (Single Ply)
5-4-3369	-	Tent Floor (Insulated)
5-4-3370	-	Vestibule
5-4-3371	-	Vestibule Door
5-4-3372	-	Vestibule Floor (Single Ply)
5-4-3373	-	Vestibule Floor (Insulated)
5-4-3374	-	Vestibule/Pin Container
5-4-3375	-	Adapter
5-4-3376	-	Adapter
5-4-3377	-	Vent Flap
5-4-3378	-	Window and Flap
5-4-3379	-	Sleeve
5-4-3380	-	Door/Window
5-4-3381	-	Stove Pipe Flap
5-4-3382	-	End Liner
5-4-3383	-	Door/Window Section Liner (Temperature)
5-4-3384	-	Door
5-4-3386	-	Stovepipe Shield Flap
5-4-3387	-	Door/Window Section Liner (Desert/Tropical)
5-4-3388	-	Vent Flap
5-4-3389	-	Flap
5-4-3390	-	Suspension Strap
5-4-3391	-	Partition

Source: https://assist.dla.mil -- Downloaded: 202610-22T00:55Z
Check the source to verify that this is the current version before use.

5-4-3613	-	Modesty Curtain
5-4-3614	-	Plenum, End Wall
5-4-3615	-	Body, End Wall
5-4-3616	-	Cover, Plenum
5-4-3617	-	Extension 12 Inch Dia, End Wall
5-4-3618	-	Plenum, Extendable, 16 Feet
5-4-3619	-	Body, Extendable
5-4-3620	-	Plenum, Side Entrance, 16 Feet
5-4-3621	-	Sliding Blackout Curtain
5-4-3981	-	Body, Side Entrance
5-4-3982	-	Exterior, 12 Inch Dia, Side Entrance
5-4-3983	-	Vestibule Door Cap
5-4-3984	-	Tent Floor, 24 Feet (Single Ply)
5-4-3985	-	Tent Floor, 40 Feet (Single Ply)

2.2 Other Government documents. The following other Government documents form a part of this document to the extent specified herein. Unless otherwise specified, the issues shall be those in effect on the date of solicitation.

DEPARTMENT OF THE ARMY FIELD MANUAL

FM 10-16 - General Repair of Tents, Canvas and Webbing

(Copies of documents required by manufacturers in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting activity.)

2.2 Other publications. The following documents form a part of this document to the extent specified herein. Unless otherwise specified, the issues of the documents which are DOD adopted shall be those listed in the issues of the DODISS specified in the solicitation. Unless otherwise specified, the issues of documents not listed in the DODISS shall be the issues of the nongovernment documents which are current on the date of the solicitation.

AMERICAN SOCIETY FOR TESTING AND MATERIALS (ASTM)

D 3951 - Standard Practice for Commercial Packaging

(Application for copies should be addressed to the American Society for Testing and Materials, 1916 Race Street, Philadelphia, PA 19103.)

(Technical society and technical association documents are generally available for reference from libraries. They are also distributed among technical groups and using Federal agencies.)

2.3 Order of precedence. In the event of a conflict between the text of this document and the references cited herein, the text of this document shall take precedence. Nothing in this document, however, shall supersede applicable laws and regulations unless a specific exemption has been obtained.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

3. REQUIREMENTS

3.1 First article. When specified, a sample shall be submitted to first article inspection (see 4.3, 6.2, and 6.3).

3.2 Materials and components. Materials (see 6.6) and components shall be as specified on the applicable drawings. Materials not definitely specified shall be of the quality normally used by the contractor provided that the complete item complies with all provisions of this document.

3.3 Construction. Construction shall conform to the drawings listed in section 2 and be as specified herein.

3.3.1 Stitching, machine.

3.3.1.1 Types of stitching. All stitch types, except bartacking, shall conform to FED-STD-751 as follows:

For all stitching except zig-zag stitching and stitching indicated by "Z" on drawings	- Type 301, 5 to 7 stitches per inch
For zig-zag stitching	- Type 304, 10 to 14 stitches per inch
For stitching indicated by "Z" on drawings	- Type 401, 5 to 7 stitches per inch - Chain portion of stitching shall not appear on outside of tent or cover
For bartacking	- Bartack, length as specified on drawings 1/8 inch in width (bight) and shall be free of thread breaks and loose stitching

3.3.1.2 Thread breaks. Thread breaks in stitching shall be overstitched not less than 1 inch at each break on stitch type 301; not less than 3/4 inch at each break on stitch type 304, and not less than 1-1/2 inches at each break on stitch type 401. Thread breaks in type 401 may be overstitched with stitch type 301. Thread breaks noted during inspection shall be repaired by overstitching the existing stitching starting from a distance of 1 inch before the break, across the defective area, to a distance of 1 inch beyond the break. The ends of repair stitching are not required to be backstitched.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

3.3.1.3 Stitching ends. The ends of type 301 stitching shall be overstitched not less than 1 inch except where ends are turned under in a hem or held down by other stitching. Where 301 stitching is performed automatically on stitch patterns such as box, box with cross-stitch, "W" stitching or straight line tacking, at least three tying, overlapping, or back stitches shall be used to secure the ends of stitching. The ends of type 304 stitching shall be firmly secured by back stitching or overstitching or by increasing the number of stitches per inch at the ends for a minimum of 1/4 inch.

3.3.1.4 Skipped stitches. Two or more consecutively skipped stitches occurring in types 301 or 304 stitching shall be overstitched not less than 1 inch. Any skipped stitches in type 401 stitching shall be overstitched not less than 1-1/2 inches. Skipped stitches in 401 stitching may be overstitched with type 301 stitching. Skipped stitches noted during inspection shall be repaired as specified for thread breaks (see 3.3.1.2).

3.3.1.5 Lubrication of thread. The addition of any lubrication to the polyester sewing thread prior to or during the sewing operations is prohibited.

3.3.2 Splicing of cloth. There shall be no splicing of roof, wall, fly or tent cover panels. Splicing of reinforcements and sod cloth sections will be permitted and, if performed, shall conform to the following requirements.

a. Eight feet or less in length - one splice permitted
More than 8 feet but not more than 12 feet in length - two splices permitted
More than 12 feet in length - three splices permitted

b. The shortest length of any spliced piece shall be not less than 2 feet

c. Pieces shall be joined as shown on Drawing 5-4-3352

3.3.3 Attachment of slide fasteners. Care shall be exercised to trim all thread ends to 1/2 inch or less and to maintain specified distances between edges of fabric attached to slide fastener tape so that there will be no interference with the operation of the slider.

3.3.4 Setting of grommets. Holes punched to receive the grommets shall be smaller than the outside diameter of the grommet barrel so that the barrel must be forced through the hole. The grommets shall be securely clinched without cutting the materials.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

3.3.5 Setting of end clips. Webbing shall be inserted the full depth of the clip. Clips shall be securely attached without cutting the webbing and the webbing shall be flat at the point of entry.

3.3.6 Wicking of sewing thread (cup test). There shall be no wicking of water through the tent stitching when the tent section is tested as specified in 4.5.1. The cup test is intended to insure that non-wicking thread has been utilized and that no lubrication has been added to the polyester thread prior to or during the sewing operation.

3.3.7 Cementing. Cementing shall be in accordance with the following procedure:

a. Surface preparation. Surfaces to be bonded shall be clean and dry prior to application of the adhesives. Coated cloth surfaces to be bonded shall be thoroughly cleaned by rubbing with toluene-wetted clean cloths or pads, which may contain a mild, bonded abrasive of 80, or finer, grit size or may be of a coarse weave (as for scouring). If abrading is exercised, there shall be no scuffing or abrading of the base cloth. Separate clean cloths and clean solvent shall be used for final cleaning wipes. Abrasive coated cloths or pads shall not be used directly on stitching at seams. Foam surfaces to be bonded to coated fabric need not be cleaned unless oiled or dust ladened.

b. Adhesive mixing. The ratio of the adhesive mixture shall be as specified on the drawings. Prior to extracting quantities of the base and accelerator to be mixed, any settlement shall be uniformly redispursed. Containers for mixing, transfer, and use shall be clean prior to each filling. Adhesive in the containers shall be covered during transit to work stations and during sustained periods of non-use to prevent loss of solvent by evaporation. After mixing, the adhesive shall be used only while sufficiently spreadable to obtain an even coat.

c. Adhesive application. Except for coated cloth-foam laminates, a minimum of two coats of mixed adhesive shall be evenly spread on the cleaned surfaces to be bonded. The first coat shall be dry to the touch before the application of the second coat. Prior to assembly, the adhesive coated surfaces shall not be allowed to be contaminated by a visible layer of dust or other foreign matter. Applied adhesive shall be free of heavy smears or excessively thick lap edges (resulting from insufficient spreading), thin starved areas, uncoated areas, or other defects characteristic of improper application. The second coat shall be dried as appropriate for the assembly method to be used; i.e., to a tacky (not wet) aggressive grab condition for the two-way, dry stick method; or to a low-tack (dry condition) for two-way stick, solvent reactivation method. Adhesive application on coated cloth-foam laminates shall be either in one coat application to each surface followed by two-way, dry stick assembly, or in one heavy coat application followed by wet tack assembly.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

d. Assembly. Assembly of components shall be made when the tack and grab of the adhesive coated surfaces are in a suitable range and a condition of either excess solvent in the adhesive layers or excessive drying or open time shall be avoided. Surfaces shall be joined in the locations specified on the drawings, applying adequate pressure and rolling or barring firmly to produce an adequate bond. Care shall be exercised to avoid finger contact in the adhesive coated areas along the edges of seams, patches, or other bonded parts. Precautions should be taken to prevent adhesive application, assembling or curing of an assembly at a temperature below 60°F. The assembled work shall not be moved too soon or in such a way as to result in edge lifting or decreasing strength of bond until the adhesive has set. Surfaces shall be assembled on the same day that they were coated, or a third coat of adhesive shall be applied to each surface. When surfaces have been assembled in an incorrect location, the adhesive bond may be immediately separated and reset at the proper location. To facilitate separation, toluene may be applied at the bond line by squirt can or atomizer and the component then peeled away as the adhesive softens. The excess toluene solvent shall be allowed to evaporate before resetting the surfaces. When incorrectly located parts are separated and the adhesive is not in an active condition or has transferred to the other surface, the affected surface shall be given an additional coat of adhesive before reassembling. Any adhesive residue shall not extend further than 1/2 inch beyond the edges of seams, strapping, splices, patches or other bonded parts.

3.3.8 Repairs to polyester fabric. All necessary repairs shall be effected in accordance with the Department of the Army Field Manual FM 10-16, except that handsewn patches, or cemented patches other than as specified herein, will not be acceptable. Cemented patches on holes, cuts, or tears not more than 1 inch in diameter or length, using cement per Minnesota Mining EC-8487 or equal (see 6.7), shall be permitted. A maximum of three cemented patches per tent shall be allowed without prior contracting officer authorization. Each patch shall be large enough to overlap the damaged area with a margin of at least 3/4 inch on all sides. Cemented patches shall be placed on the outside of the tent and shall not be permitted over seams or in hardware areas. All other repairs shall require authorization by the contracting officer. Repairs required as a result of failure of the cup test and when authorized by the contracting officer shall be performed by treating with a compound conforming to type I, class 1, shade olive drab of TT-P-595 prior to retesting.

3.3.9 Repairs to vinyl coated fabric. Repairs to holes, cuts or tears and repairs of burn-throughs resulting from the heat-sealing operation, when necessary, shall be effected as follows:

a. No more than one repair to holes, cuts, or tears shall be allowed per floor section.

b. No more than two repairs to burn-throughs shall be allowed per floor section.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

c. Repairs shall be accomplished by the application of heat-sealed or cemented patches.

d. For repairs of burn-throughs on panel lap seams, the width of the patch shall be such that the overlap on each side of the burn-through shall be equal to the width of seam. The maximum length of the patch shall not exceed the length of the sealing die plus the width of seam allowance at each end. All patches for repairs other than burn-throughs shall not exceed the size specified herein.

e. Patches shall be applied to the top side of the floor section and the patched area shall be smooth, i.e., with the torn or cut edges securely and completely sealed or cemented.

3.4 Marking. All markings and labels shall conform to DDD-L-20.

3.4.1 Special markings. The letters "US" and the item nomenclature on the tent sections, liner sections, tent flies, and vestibule and special marking on the tent cover and vestibule container shall conform to type IV, class 9 in the size characters and in the locations shown on the drawings. Class 9 markings shall be clearly legible after subjection to accelerated weathering.

3.4.2 Identification label. Identification labels shall conform to type VI, class 6 and shall be 3-1/2 inches by 5-1/2 inches minimum and a blank space of at least 1-1/4 inches shall be provided on the bottom of the label for the Department of Defense inspector's stamp. Identification labels shall be stitched to the tent components in the locations shown on the drawings.

3.4.3 Erection instruction label. Label of erection instructions shall conform to type VI, class 7 and shall be stitched to the cover in the location shown on Drawing 5-4-3359. The label shall be a proportionate copy of Drawing 5-4-3358 as reproduced from a glossy print of this drawing furnished by the contracting officer. The size of the label shall be, borderline to borderline, 30 ± 1/2 inches in the longer dimension, with a minimum 1/2 inch margin outside of the borderline on all sides.

3.5 Workmanship. Cloth components shall be clean and free of holes, cuts, tears, and cloth defects such as multiple floats or broken or missing yarns. Webbing and tape shall not have frayed or scalloped edges and rope components shall be free of cuts and breaks. Thread tension shall be maintained with seams properly sewed so that no runoffs, twists, pleats, or open seams shall result. Care shall be taken in sewing to see that no needle chews occur. All thread ends shall be trimmed to 1/2 inch or less. Metal components shall be free of burns, sharp edges, and corroded areas and shall not be broken or malformed. Heat welded seams shall be essentially free of wrinkles, pleats, and folds. A heat welded seam, regardless of its length, shall have not more than a total of two wrinkles, pleats, or folds.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in this document where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

4.1.1 Responsibility for compliance. All items must meet all requirements of sections 3 and 5. The inspection set forth in this document shall become a part of the contractor's overall inspection system or quality program. The absence of any inspection requirements in the document shall not relieve the contractor of the responsibility of assuring that all products or supplies submitted to the Government for acceptance comply with all requirements of the contract. Sampling in quality conformance does not authorize submission of known defective material, either indicated or actual, nor does it commit the Government to acceptance of defective material.

4.2 Classification of inspection. The inspection requirements specified herein are classified as follows:

a. First article inspection (see 4.3).
b. Quality conformance inspection (see 4.4).

4.3 First article inspection. When a first article is required, it shall be examined for defects listed in tables I and II and tested as specified in 4.5.1. The presence of any defect or failure of any test shall be cause for rejection of the first article.

4.4 Quality conformance inspection. Unless otherwise specified herein, sampling for inspection shall be performed in accordance with MIL-STD-105.

4.4.1 Component and material inspection. In accordance with 4.1, components and materials shall be inspected in accordance with all the requirements of referenced documents unless otherwise excluded, amended, modified, or qualified in this document or applicable purchase document.

4.4.2 In-process examination. Examination shall be made of the following fabrication operations to establish conformance with specified requirements.

a. There shall be no lubrication of polyester thread prior to or during sewing operations for compliance with 3.3.1.5.

b. Holes punched to receive grommets are in compliance with 3.3.4.

c. Webbing inserted to full depth of clip for compliance with 3.3.5.

Whenever nonconformance is noted, correction shall be made to the items affected and to the process.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

4.4.3 End item visual examination. The end item shall be examined for defects listed in table I. The lot size shall be expressed in units of end items of one item number only. The sample unit shall be one end item. The inspection level shall be I and the acceptable quality level (AQL), expressed in terms of defects per hundred units, shall be 10.0 for major defects, 25.0 for major and minor A combined defects, and 100.0 for total (major, minor A, and minor B combined) defects.

TABLE I. End item visual defects

Examine	Defect	Classification Major	Minor A	Minor B
Screening	Cut or tear:			
	- 1/4 inch or less in length			X
	- more than 1/4 inch in length but not more than 2 inches in length		X	
	- more than 2 inches in length	X		
Webbing; tie tapes	Edge frayed or scalloped			X
	Cut or tear			X
Cloth, except floor material	Cut, tear, or hole (including exposed drill hole) greater than 1/8 inch in length or diameter:			
	- on all tent sections, vestibules, or flies	X		
	- on covers, liners, partitions, modesty curtains, plenums, containers, or sod cloth		X	
	Cut, tear, or hole (including exposed drill hole) 1/8 inch or less in length or diameter:			
	- more than 20 holes:			
	- on all tent sections, vestibules, or flies	X		
	- on covers, liners, partitions, modesty curtains, plenums, containers, or sod cloth		X	
	- more than 10 but not more than 20 holes:			
	- on all tent sections, vestibules, or flies		X	
	- on covers, liners, partitions, modesty curtains, plenums, or sod cloth			X

Source: https://assist.dla.mil -- Downloaded: 202610-22T00:55Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Cloth, except floor material (cont'd)	- more than 5 but not more than 10 holes:			
	- on all tent sections, vestibules, or flies			X
	Untreated area on either side of cloth more than 1 inch in length or diameter		X	
	Broken or missing yarn; multiple floats, clearly visible at normal inspection distance of approximately 3 feet		X	
Cloth, coated for floor	Hole, cut, or tear; thin or weak place due to abrasion; exposed fabric; blister, tunnel or delamination of coating; crease or wrinkle	X		
	Lump or heavy coated area		X	
	Exposed adhesive (not overcoated)	X		
	Failure to dust exposed overcoating	X		
	Excessive dusting compound			X
Hardware and metal components	Broken	X		
	Malformed:			
	- fails to perform intended function	X		
	- but will perform intended function		X	
	Corroded area			X
	Burn or sharp edge which may cause injury in handling or damage to fabric	X		
Grommets	Improperly set, two or more teeth exposed (except where grommet is set as specified but is in an area of uneven thickness which prevents uniform clinching)			X
	Clinched loosely, allowing grommet to rotate around hole			X
	Clinched excessively tight; i.e., cutting cloth:			
	- on all tent sections, vestibules, or flies	X		
	- on covers		X	
	Insecurely clinched; i.e., grommets or washers become disengaged:			
	- on all tent sections, vestibules, or flies	X		
	- on covers		X	

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Grommets (cont'd)	Size #4 grommet sets with barrel inserted from outside instead of inside:			
	- on eave or ridge		X	
	- at any other location			X
	Roll of a grommet contains more than three scores (splits)			X
End clips	Improperly clinched, i.e., webbing not flat at point of entrance into clip			X
	Clinched excessively tight, cutting webbing or loosely clinched, i.e., clip becomes disengaged from webbing		X	
Rope and cord components, tent lines	Any cut or break:			
	- on ridge guy line		X	
	- on eave guy line		X	
	- on becket line		X	
	Eye splice omitted		X	
	Eye splice not as specified			X
	Free end not finished as specified			X
Seams and stitching	Open seam on stitch type 301:			
	- for more than 1/4 inch but not more than 1 inch			X
	- for more than 1 inch		X	
	Open seam on stitch type 401:			
	- one row of stitching open for 1 inch or less:			
	- on tent sections, liners, vestibules, floors, flies, or covers			X
	- one row of stitching open for more than 1 inch:			
	- on tent, vestibule, liner, floor, or fly sections		X	
	- on all other items			X
	- both rows of stitching open (not necessarily at the same location):			
	- on tent, vestibule, liner, floor, or fly sections	X		
	- on all other items		X	

Source: https://assist.dla.mil -- Downloaded: 202610-22T00:55Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Seams and stitching (cont'd)	NOTE: A seam shall be classified as open when one or more stitches joining a seam are broken, or when one or more skipped or run-off stitches occur. On double stitched seams, a seam shall be classified as open when either one or both sides of a seam are open.			
	Raw edges caught in stitching:			
	- more than 1 inch but not more than 3 inches			X
	- more than 3 inches		X	
	Thread breaks:			
	- overstitched less than 1-1/2 inches on stitch type 401			X
	Thread breaks: (cont'd)			
	- overstitched less than 1 inch on stitch type 301			X
	- overstitched less than 3/4 inch on stitch type 304			X
	NOTE: Thread breaks not overstitched shall be classified as open seams.			
	Needle chews resulting in cut, tear or hole (see cut, tear, or hole)			
	Skipped stitches:			
	- overstitched less than 1-1/2 inches on stitch type 401		X	
	- overstitched less than 1 inch on stitch type 301 or 304 (when two or more skipped stitches occur consecutively)		X	
	NOTE: Skipped stitches not overstitched shall be classified as open seams.			
	One or more required rows of stitching omitted (except on boxstitching)	X		

Source: https://assist.dla.mil -- Downloaded: 202610-22T00:55Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Boxstitching	Incomplete:			
	- one row of stitching omitted			X
	- two or more rows of stitching omitted		X	
	Less than specified length by more than 1/8 inch			X
Bartacking	Less than specified length by more than 1/8 inch			X
Stitching ends	Overstitched less than 1 inch on stitch type 301 (except where ends are held down by other stitching or turned under in a hem, or where stitching is performed automatically)		X	
	Secured with less than three tying, overlapping, or back stitches when automatic stitching is performed			X
Stitching ends	Secured with less than 1/4 inch of back stitching, overstitching, or an increased number of stitches per inch at the end of stitch type 304			X
Seams	Pleated:			
	- on all tent sections, liners, vestibules, floors, or flies		X	
	- on covers			X
Seam type	Wrong seam type	X		
Stitch type	Wrong stitch type	X		
Stitch tension	Loose, resulting in an exposed bobbin or top thread for more than 6 inches		X	
	Tight, as evidenced by puckering on fabric for more than 6 inches		X	

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Stitches per inch	Less than minimum specified (except on panel joining seams):			
	- one stitch			X
	- two or more stitches		X	
	Less than minimum specified on panel joining seams		X	
	More than maximum specified:			
	- one stitch			X
	- two or more stitches		X	
	NOTE: Variation in the number of stitches per inch, caused by the operator speeding up the machine and pulling the fabric in order to sew over heavy places or heavy seams or in turning corners, shall be classified as follows:			
	a. Within the minor "B" defect classification - no defect			
	b. Within the minor "A" defect classification - minor "B" defect			
Stitching gage	Not as specified		X	
Stitching margin	Larger than specified:			
	- for more than 2 inches but nor more than 4 inches			X
	- for more than 4 inches in length		X	
	Less than specified:			
	- for more than 2 inches but not more than 4 inches in length			X
	- for more than 4 inches in length		X	
Stitching	Chain portion of stitching shows on outside of tent sections or covers		X	
Mends, darns, or patches	Repairs not in accordance with Department of the Army Field Manual FM 10-16 or not authorized by the contracting officer (see 3.3.8)	X		

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Components and assembly	Any component part omitted, not assembled or fabricated of applicable referenced material	X		
Hems	Constructed with partial turnunder when double turnunder is required		X	
	Twisted or pleated			X
Reinforcements	Improperly applied, causing excessive fullness on reinforcements or reinforced parts	X		
Cloth splicing	Splice in roof, wall, fly, or tent cover panels	X		
	Spliced pieces not joined as shown on Drawing 5-4-3352			X
Slide fastener	Slider jams or fails to interlock chain	X		
	Any tape improperly assembled causing failure of chain to effect a smooth and secure closure	X		
Cementing, general	Puckers, loose edges, unadhered pocket, or tunnels		X	
	Excess adhesion in sags or lumps evident through outer layer of fabric		X	
	Adhesive exposed beyond the overcoated area on interior surface			X
Marking and labels	Omitted, incorrect, illegible, or misplaced			X
Cleanness	Grease or oil stains			X
	Thread ends not trimmed to 1/2 inch or less (except in slide fastener area)			X
	Thread ends not trimmed to 1/2 inch or less in slide fastener area		X	

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

4.4.4 End item dimensional examination. The end item shall be examined for the defects listed in table II. The lot size shall be expressed in units of end items of one item number only. The sample unit shall be one end item. The inspection level shall be S-3 and the AQL, expressed in terms of defects per hundred units, shall be 2.5 for major defects, 10.0 for major and minor A combined defects, and 100.0 for total (major, minor A and minor B combined) defects.

TABLE II. End item dimensional defects

Examine	Defect	Classification Major	Minor A	Minor B
Overall dimensions of end, window, or door sections; liners, floors, vestibules, vestibule doors, large or small flies	Smaller than specified dimensions less applicable minus tolerances indicated on drawings	X		
	Larger than specified dimensions and applicable plus tolerance indicated on drawings			X
Overall dimensions of all other items	Smaller than specified dimensions less applicable minus tolerance indicated on drawing, but not smaller than the specified dimensions less twice the applicable minus tolerance			X
	Smaller than specified dimensions less twice the applicable minus tolerance indicated on drawing		X	
	Larger than specified dimensions and applicable plus tolerance indicated on drawing			X
Location dimensions (unless otherwise specified)	Not within specified tolerance: - not exceeding twice the applicable tolerance			X
	- exceeding twice the applicable tolerance		X	
Webbing, tie tapes	Finished length less than specified by more than 1 inch			X
Grommets	Set beyond specified location by more than 1/2 inch		X	

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

TABLE II. End item dimensional defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Rope components, tent lines	Eye on footstop or line less than specified by more than 1/2 inch			X
	Finished length of guy line less than specified:			
	- by not more than 4 inches			X
	- by more than 4 inches but not more than 12 inches		X	
	- by more than 12 inches	X		
Beckets	Misplaced:			
	- by more than 1/4 inch but not more than 1/2 inch			X
	- by more than 1/2 inch		X	
	Length of loop more or less than specified by 1/2 inch or more		X	
Hems	Required to finish less than 3/4 inch or less in width, less than specified; hems required to finish more than 3/4 inch in width, less than specified by more than 1/4 inch		X	
Reinforcements	Finished dimensions less than specified by more than 1/2 inch			X
Sod cloths	Less than specified width by more than 1 inch			X
Ventilator opening	Misplaced by more than 1/2 inch			X
Tent cover flaps	Center line of flaps set off center of body by more than 3/4 inch			X

4.4.5 End item testing. End item units of sections, flies, and vestibules only (floors, liners, and covers or containers are excluded) shall be tested as specified in 4.5.1 for conformance to the wicking requirement in 3.3.6. The lot size shall be expressed in units of end items. The sample size shall be the number of end items indicated by inspection level S-2. Any test failure shall be cause for rejection of the lot.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

4.4.6 Packaging examination. The fully packaged end items shall be examined for the defects listed in table III. The lot size shall be expressed in units of shipping containers. The sample unit shall be one shipping container fully packaged. The inspection level shall be S-2 and the AQL, expressed in terms of defects per hundred units, shall be 2.5.

TABLE III. Packaging defects

Examine	Defect
Marking	Omitted; incorrect; illegible; of improper size, location, sequence, or method of application.
Materials	Any component missing, any component damaged.
Workmanship	Inadequate application of components, such as incomplete closure of container flaps, improper taping, loose strapping, or inadequate stapling. Bulged or distorted container.
Contents	Number per container is more or less than required.

4.4.7 Palletization examination. The fully packaged and palletized end items shall be examined for the defects listed in table IV. The lot size shall be expressed in units of palletized unit loads. The sample unit shall be one palletized unit load, fully packaged. The inspection level shall be S-1 and the AQL, expressed in terms of defects per hundred units, shall be 6.5.

TABLE IV. Palletization defects

Examine	Defect
Finished dimensions	Length, width, or height exceeds specified maximum requirement.
Palletization	Pallet pattern not as specified. Interlocking of loads not as specified. Load not bonded with required straps as specified.
Weight	Exceeds maximum load limits.
Marking	Omitted; incorrect; illegible; of improper size, location, sequence, or method of application.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

4.5 Methods of inspection.

4.5.1 Wicking test. The end item unit shall be tested once on a roof panel lap seam and once on a ridge reinforcement seam. The end item unit shall be laid over a 6 ± 1/8 inch diameter hoop so as to form a ± 1/4 inch deep depression with the seam to be tested running through the center of the depression. A 500-mL quantity of water at 77° ± 4°F shall be slowly poured into the depression and the under surface of the seam shall be observed. Any wicking of water along the sewing thread, identified by a discoloration or darkening of the thread within 5 minutes after water is poured, shall be considered a test failure. Water leakage through the needle holes or between the plies of the lapped seamed fabrics shall not be considered a failure.

5. PACKAGING

5.1 Preservation. Preservation shall be level A or Commercial, as specified (see 6.2).

5.1.1 Level A.

5.1.1.1 End section. One end section (with slide fasteners and window flaps closed) shall be folded to measure approximately 3 feet by 4 feet. All lines shall be placed within the folds of the item. The end section shall be unit packed within a close-fitting fiberboard container conforming to style FTC, grade V3c of PPP-B-636. The fiberboard container shall be closed as specified in the appendix of PPP-B-636.

5.1.1.2 Window section (temperate or desert/tropical). One window section (with slide fasteners and window flaps closed) shall be folded to measure approximately 3 feet by 4 feet. All lines shall be unit packed within the folds of the item and placed within a closed-fitting fiberboard container conforming to style FTC, grade V3c of PPP-B-636. The fiberboard container shall be closed as specified in the appendix of PPP-B-636.

5.1.1.3 Door section (temperate or desert/tropical). One door section (with slide fasteners closed) shall be folded to measure approximately 3 feet by 4 feet. All lines shall be unit packed within the folds of the item and placed within a close-fitting fiberboard container conforming to style FTC, grade V3c of PPP-B-636. The fiberboard shall be closed as specified in the appendix of PPP-B-636.

5.1.1.4 Tent fly (16 feet or 8 feet). One fly of one size shall be folded to measure approximately 3 feet by 4 feet. All lines shall be unit packed within the folds of the item and placed within a close-fitting fiberboard container conforming to style OPF, grade V3c of PPP-B-636. The fiberboard container shall be closed as specified in the appendix of PPP-B-636.

Source: https://assist.dla.mil -- Downloaded: 202610-22T00:55Z
Check the source to verify that this is the current version before use.

5.1.1.5 End section liner (temperate or desert/tropical). One end section liner shall be folded and unit packed as specified in 5.1.1.1.

5.1.1.6 Intermediate liner (temperate or desert/tropical). One intermediate liner shall be folded and unit packed as specified in 5.1.1.2.

5.1.1.7 Tent floor (single ply or insulated). One tent floor (single ply or insulated) shall be folded to measure 3 feet by 4 feet and shall be unit packed within a close-fitting fiberboard container conforming to style (OPF for single ply, and style FTC for insulated), grade V3c of PPP-B-636. The fiberboard container shall be closed as specified in the appendix of PPP-B-636.

5.1.1.8 Vestibule with door. One complete vestibule with door shall be folded to measure 3 feet by 4 feet and unit packed within a close-fitting fiberboard container conforming to style FTC, grade V3c of PPP-B-636. The fiberboard container shall be closed as specified in the appendix of PPP-B-636.

5.1.1.9 Vestibule floor (single ply or insulated). One vestibule floor shall be folded to measure 3 feet by 4 feet and unit packed within a close-fitting fiberboard container conforming to style (OPF for single ply, and style FTC for insulated), grade V3c of PPP-B-636. The fiberboard container shall be closed as specified in the appendix of PPP-B-636.

5.1.1.10 Partition. One partition shall be folded to measure approximately 3 feet by 4 feet and shall be unit packed within a close-fitting fiberboard container conforming to style OPF, grade V3c of PPP-B-636. The fiberboard container shall be closed as specified in the appendix of PPP-B-636.

5.1.1.11 Tent cover. One cover shall be folded to measure approximately 3 feet by 4 feet and shall be unit packed within a close-fitting fiberboard container conforming to style OPF, grade V3c of PPP-B-636. The fiberboard container shall be closed as specified in the appendix of PPP-B-636.

5.1.1.12 Vestibule container. Two vestibule containers shall be folded to measure approximately 3 feet by 4 feet and shall be unit packed within a close-fitting fiberboard container conforming to style OPF, grade V3c of PPP-B-636. The fiberboard container shall be closed as specified in the appendix of PPP-B-636.

5.1.1.13 Tent pin container. One tent pin container shall be folded to measure approximately 2 feet by 7 inches and shall be unit packed within a close-fitting fiberboard container conforming to style OPF, grade V3c of PPP-B-636. The fiberboard container shall be closed as specified in the appendix of PPP-B-636.

Source: https://assist.dla.mil -- Downloaded: 202640-22T00:55Z
Check the source to verify that this is the currentversion before use.

5.1.1.14 Modesty curtain. One modesty curtain, complete, shall be folded to measure approximately 3 feet by 4 feet and shall be unit packed within a close-fitting fiberboard container conforming to style OPF, grade V3c of PPP-B-636. The fiberboard container shall be closed as specified in the appendix of PPP-B-636.

5.1.1.15 Plenum (end wall, extendable or side entrance, 16 feet). One plenum shall be folded to measure approximately 3 feet by 4 feet and shall be unit packed within a close-fitting fiberboard container conforming to style OPF, grade V3c of PPP-P-636. The fiberboard container shall be closed as specified in the appendix of PPP-B-636.

5.1.1.16 Sliding blackout curtain. One blackout curtain shall be folded to measure approximately 3 feet by 4 feet and shall be unit packed within a close-fitting fiberboard container conforming to style OPF, grade V3c of PPP-B-636. The fiberboard container shall be closed as specified in the appendix of PPP-B-636.

5.1.2 Commercial. The tent components shall be preserved in accordance with ASTM D 3951.

5.2 Packing. Packing shall be level A, B, or Commercial as specified (see 6.2).

5.2.1 Level A packing.

5.2.1.1 Components (when procured separately). Thirty-two end sections, or 24 window sections, or 32 door sections, or 32 sixteen-foot tent flies, or 50 eight-foot flies, or 32 end section liners, or 48 intermediate liners, or 64 single-ply tent floors, or 10 insulated tent floors, or 40 vestibules with doors, or 100 single-ply vestibule floors, or 20 insulated vestibule floors, or 70 partitions, or 100 tent covers, or 180 vestibule containers, or 180 tent pin containers, or 50 modesty curtains, or 70 plenums, or 50 sliding blackout curtains, preserved as specified in 5.1, shall be packed in a close-fitting shipping container conforming to overseas-type, style A of PPP-B-601. Each container shall be provided with skids as specified in the container specification. Each container shall be closed and reinforced with steel strapping in accordance with the appendix of the container specification.

5.2.2 Level B packing.

5.2.2.1 Components (when procured separately). Sixteen end sections, or 12 window sections, or 16 door sections, or 16 sixteen-foot tent flies, or 25 eight-foot tent flies, or 16 end section liners, or 24 intermediate liners, or 32 single ply tent floors, or 5 insulated tent floors, or 20 vestibules with doors, or 50 single ply vestibule floors, or 10 insulated vestibule floors, or 35 partitions, or 50 tent covers, or 90 vestibule containers, or 90 tent pin

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

containers, or 25 modesty curtains, or 35 plenums, or 25sliding blackout curtains, preserved as specified in 5.1, shall be palletized in accordance with bonding means P or O, type 1a, type IV pallet size 40 by 48 inches of MIL-STD-147.

5.2.3 Commercial packing. The tent components, preserved as specified in 5.1, shall be packed in accordance with ASTM D 3951.

5.3 Marking. In addition to any special marking required by the contract or purchase order, unit packs, shipping containers and palletized unit loads shall be marked in accordance with MIL-STD-129 or ASTM D 3951, as applicable.

6. NOTES

6.1 Intended use. The tent sections which include liners, floors, flies and vestibule are designed to form an extendable frame supported tent for any general purpose use. The tent is variable in size and configuration depending on the number and variety of tent sections assembled together.

6.2 Ordering data. Acquisition documents should specify the following:

a. Title, number, and date of this document.
b. Items required, as applicable (see 1.2).
c. When a first article is required (see 3.1, 4.3, and 6.3).
d. Selection of applicable levels of preservation and packing (see 5.1 and 5.2).

6.3 First article. When a first article sample is required, it shall be inspected and approved under the appropriate provisions of FAR 52-209. The first article should be a preproduction sample. The contracting officer should specify the appropriate type of first article and the number of units to furnish. The contracting officer should include specific instructions in all acquisition documents regarding arrangements for inspection and approval of the first article.

6.4 Repair of leaking seams. A satisfactory method of applying the textile compound for the repair of leaking seams is as follows:

a. A suitable volume of textile compound conforming to type I, class 1, shade olive drab of TT-P-595 shall be thoroughly stirred and diluted with an equal volume of petroleum solvent (Stoddard solvent or equivalent). Thoroughly stir the mixture again before use.

b. Prior to application of the compound, the tent sections must be dry. Special attention must be taken to insure adequate ventilation and that proper fire prevention measures are taken since the compound is flammable.

Source: https://assist.dla.mil -- Downloaded: 202640-22T00:55Z
Check the source to verify that this is the currenversion before use.

c. Two coats of the textile compound shall then be applied to the seams (on the outside of the tent section only). A 4-inch wide stiff brush is recommended for use. The first coat shall be air dried for a minimum of 4 hours prior to application of the second coat. Elapsed time between coats may be reduced by providing a supply of hot air to evaporate the solvent more quickly. In this manner, a second coat may be applied as soon as the first coat is dry to the touch. After the application of the second coat, the treated tent section shall be allowed to air dry for a period of at least 24 hours.

6.4.1 Seams to be treated. Seams which have failed the test specified in 4.5.1 should be treated as follows:

a. Failure of panel lap seam - treat all panel lap seams.

b. Failure of purlin or header reinforcement stitching - treat all stitching on reinforcements.

6.5 Cementing of coated cloth. The following system has been used in preparing seams where chlorosulphonated polyethylene coated surfaces of coated cloths are to be adhered to chloroprene coated surfaces;

a. Abrade, by hand, the chlorosulphonated polyethylene surface only to the point of dullness and uniform roughness. Norton Company's Lighting Metalite Cloth-Aluminum Oxide 80-J or 3-M Company's Three-M-ite-Elek-tro-Cut Cloth J-wt Aluminum Oxide are satisfactory for use in abrading.

b. Wash the abraded chlorosulphonated polyethylene surface and the nonabraded chloroprene surface with clean cotton cloth swabs wet with toluene.

c. Allow each washed surface to dry at room temperature for 15 to 20 minutes.

d. Brush apply one coat of adhesive (see 3.3.7) to each washed surface.

e. Allow the adhesive to dry at room temperature for 15 to 20 minutes.

f. Brush apply a second coat of adhesive.

g. After 15 to 20 minutes drying, reactivate each adhesive with toluene.

h. Assemble immediately, smooth by hand, and then roll with a steel roller.

i. Cure the cemented assembly a minimum of 24 hours before movement.

6.6 Recycled material. It is encouraged that recycled material be used when practical as long as it meets the requirements of this document (see 3.2).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

6.7 Commercial product. The Minnesota Mining EC-847 adhesive coating has been found to meet the requirements for 3.3.8.

6.8 Subject term (key word) listing.

Floors
Liners
TEMPER
Tent cover
Tent sections

6.9 Supersession data. This document includes the requirements of LP/P. DES 2 80B, dated 29 February 1984.

Custodians:

Army - GL
Navy - NU
Air Force - 99

Preparing activity:

Army - GL

Project No. 8340-0485

Review activities:

Army - MD
Air Force - 82

User activity:

Navy - MC, MS

Source: https://assist.dla.mil -- Downloaded: 202610-22T00:55Z
Check the source to verify that this is the current version before use.

INSTRUCTIONS: In a continuing effort to make our standardization documents better, the DoD provides this form for use in submitting comments and suggestions for improvements. All users of military standardization documents are invited to provide suggestions. This form may be detached, folded along the lines indicated, taped along the loose edge *(DO NOT STAPLE)*, and mailed. In block 5, be as specific as possible about particular problem areas such as wording which required interpretation, was too rigid, restrictive, loose, ambiguous, or was incompatible, and give proposed wording changes which would alleviate the problems. Enter in block 6 any remarks not related to a specific paragraph of the document. If block 7 is filled out, an acknowledgement will be mailed to you within 30 days to let you know that your comments were received and are being considered.

NOTE: This form may not be used to request copies of documents, nor to request waivers, deviations, or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document*(s)* or to amend contractual requirements.

(Fold along this line)

(Fold along this line)

DEPARTMENT OF THE ARMY

U.S. ARMY NATICK RESEARCH, DEVELOPMENT
and ENGINEERING CENTER
ATTN: STRNC-ES
Natick, MA 01760-5014

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES

BUSINESS REPLY MAIL
FIRST CLASS PERMIT NO. 12062 WASHINGTON D. C.
POSTAGE WILL BE PAID BY THE DEPARTMENT OF THE ARMY

Commander
U.S. Army Natick Research, Development
and Engineering Center
ATTN: STRNC-ES
Natick, MA 01760-5014

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

(See Instructions – Reverse Side)

1. DOCUMENT NUMBER	2. DOCUMENT TITLE
MIL-T-44243	Tent Sections, Tent, Extendable, Modular Personnel, (Temper)

3a. NAME OF SUBMITTING ORGANIZATION	4. TYPE OF ORGANIZATION *(Mark one)*
	☐ VENDOR
b. ADDRESS *(Street, City, State, ZIP Code)*	☐ USER
	☐ MANUFACTURER
	☐ OTHER *(Specify)*: _____

5. PROBLEM AREAS

a. Paragraph Number and Wording:

b. Recommended Wording:

c. Reason/Rationale for Recommendation:

6. REMARKS

7a. NAME OF SUBMITTER *(Last, First, MI)* – Optional	b. WORK TELEPHONE NUMBER *(Include Area Code)* – Optional
c. MAILING ADDRESS *(Street, City, State, ZIP Code)* – Optional	8. DATE OF SUBMISSION *(YYMMDD)*

DD FORM 82 MAR 1426 NATICK OP1, Feb 86 PREVIOUS EDITION IS OBSOLETE

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:55Z
Check the source to verify that this is the current version before use.