INCH-POUND

MIL-T-44243A
23 November 1990
SUPERSEDING
MIL-T-44243
30 September 1986

MILITARY SPECIFICATION

TENT SECTIONS, TENT, EXTENDABLE, MODULAR, PERSONNEL (TEMPER)

This specification is approved for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This specification covers the tent sections of an extendable, modular, personnel, frame supported tent.

* 1.2 Classification. Tent sections, liners, floors, vestibule, vestibule door, vestibule container and tent cover shall be classified as follows (see 6.2):

Items

1. - End section
2. - Window section (temperate)
3. - Door section (desert/tropical)
4. - Window section (desert/tropical)
5. - Door section (temperate)
6. - Tent fly (16 feet)
7. - Tent fly (8 feet)
8. - End section liner (temperate)
9. - End section liner (desert/tropical)
10. - Intermediate liner (temperate)

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be used in improving this document should be addressed to: U.S. Army Natick Research, Development, and Engineering Center, Natick, MA 01760-5014 by using the Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

AMSC N/A FSC 8340

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 202610-22T00:54Z
Check the source to verify that this is the current version before use.

Items

11. - Intermediate liner (desert/tropical)
12. - Tent floor (single ply) 8 feet, 24 feet and 40 feet
13. - Tent floor (insulated)
14. - Vestibule w/door
15. - Vestibule floor (single ply)
16. - Vestibule floor (insulated)
17. - Partition
18. - Tent cover
19. - Vestibule container
20. - Tent pin container
21. - Modesty curtain
22. - Plenum, end wall, 16 feet
23. - Plenum, extendable, 16 feet
24. - Sliding blackout curtain
25. - Plenum, side entrance, 16 feet
26. - Vestibule door cap

2. APPLICABLE DOCUMENTS

2.1 Government documents.

* 2.1.1 Specifications, standards, and handbooks. The following specifications, standards, and handbooks form a part of this document to the extent specified herein. Unless otherwise specified, the issues of these documents are those listed in the issue of the Department of Defense Index of Specifications and Standards (DODISS) and supplement thereto, cited in the solicitation (see 6.2).

SPECIFICATIONS

FEDERAL

A-A-50083 - Bag, Plastic, Folded Garment
TT-P-595 - Preservative Coating, Canvas
DDD-L-20 - Label: For Clothing, Equipage, and Tentage, (General Use)
PPP-B-601 - Boxes, Wood, Cleated-Plywood
PPP-B-636 - Boxes, Shipping, Fiberboard
PPP-B-640 - Box, Fiberboard, Corrugated, Triple-Wall

STANDARDS

FEDERAL

FED-STD-191 - Textile Test Methods
FED-STD-751 - Stitches, Seams and Stitchings

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-129 - Marking for Shipment and Storage
MIL-STD-147 - Palletized Unit Loads
MIL-STD-731 - Quality of Wood Members for Containers and Pallets

(Unless otherwise indicated, copies of federal and military specifications, standards, and handbooks are available from the Standardization Documents Order Desk, Building 4D, 700 Robbins Avenue, Philadelphia, PA 19111-5094.)

* 2.1.2 Other Government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this document to the extent specified herein. Unless otherwise specified, the issues are those cited in the solicitation.

DEPARTMENT OF THE ARMY FIELD MANUAL

FM 10-16 - General Repair of Tents, Canvas and Webbing

(Copies of documents required by contractors in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting activity.)

DRAWINGS

U.S. ARMY NATICK RESEARCH, DEVELOPMENT, AND ENGINEERING CENTER

5-4-3342 - Hitch Pin Clip and Holder
5-4-3349 - Tent Sections, Tent, Extendable, Modular, Personnel (Temper)
5-4-3350 - End Section
5-4-3351 - Door Section (Desert/Tropical)
5-4-3352 - Window Section (Desert/Tropical)
5-4-3353 - Tent Flies
5-4-3354 - Screen Door
5-4-3355 - Vent Flap
5-4-3356 - Window Flap
5-4-3357 - Beckets
5-4-3358 - Erection Instructions
5-4-3359 - Tent Cover
5-4-3360 - Weather Seal Flaps
5-4-3361 - Purlin Flaps
5-4-3362 - Door Section (Temperate)
5-4-3363 - Window Section (Temperate)
5-4-3364 - End Section Liner (Temperate)
5-4-3365 - End Section Liner (Desert/Tropical)
5-4-3366 - Intermediate Liner (Temperate)

Source: https://assist.dla.mil -- Downloaded: 202610-22T00:54Z
Check the source to verify that this is the current version before use.

5-4-3367 - Intermediate Liner (Desert/Tropical)
5-4-3368 - Tent Floor (Single Ply)
5-4-3369 - Tent Floor (Insulated)
5-4-3370 - Vestibule
5-4-3371 - Vestibule Door
5-4-3372 - Vestibule Floor (Single Ply)
5-4-3373 - Vestibule Floor (Insulated)
5-4-3374 - Vestibule/Pin Container
5-4-3375 - Adapter
5-4-3376 - Adapter
5-4-3377 - Vent Flap
5-4-3378 - Window and Flap
5-4-3379 - Sleeve
5-4-3380 - Door/Window
5-4-3381 - Stove Pipe Flap
5-4-3382 - End Liner
5-4-3383 - Door/Window Section Liner (Temperate)
5-4-3384 - Door
5-4-3386 - Stovepipe Shield Flap
5-4-3387 - Door/Window Section Liner (Desert/Tropical)
5-4-3388 - Vent Flap
5-4-3389 - Flap
5-4-3390 - Suspension Strap
5-4-3391 - Partition
5-4-3613 - Modesty Curtain
5-4-3614 - Plenum, End Wall
5-4-3615 - Body, End Wall
5-4-3616 - Cover, Plenum
5-4-3617 - Extension 12 Inch Dia, End Wall
5-4-3618 - Plenum, Extendable, 16 Feet
5-4-3619 - Body, Extendable
5-4-3620 - Plenum, Side Entrance, 16 Feet
5-4-3621 - Sliding Blackout Curtain
5-4-3981 - Body, Side Entrance
5-4-3982 - Exterior, 12 Inch Dia, Side Entrance
5-4-3983 - Vestibule Door Cap
5-4-3984 - Tent Floor, 24 Feet (Single Ply)
5-4-3985 - Tent Floor, 40 Feet (Single Ply)

(Copies of drawings are available from the U.S. Army Natick Research, Development, and Engineering Center, ATTN: STRNC-UX, Natick, MA 01760-5014.)

* 2.2 Non-Government publications. The following documents form a part of this document to the extent specified herein. Unless otherwise specified, the issues of the documents which are DoD adopted are those listed in the issue of the DODISS cited in the solicitation. Unless otherwise specified, the issues of documents not listed in the DODISS are the issues of the documents cited in the solicitation (see 6.2).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

AMERICAN SOCIETY FOR TESTING AND MATERIALS (ASTM)

D 3574 - Standard Methods of Testing Flexible Cellular Materials - Slab, Bonded, and Molded Urethane Forms
D 3951 - Standard Practice for Commercial Packaging

(Application for copies should be addressed to the American Society for Testing and Materials, 1916 Race Street, Philadelphia, PA 19103-1187.)

(Non-Government standards and other publications are normally available from the organizations that prepare or distribute the documents. These documents also may be available in or through libraries or other informational services.)

2.3 Order of precedence. In the event of a conflict between the text of this document and the references cited herein, the text of this document takes precedence. Nothing in this document, however, supersedes applicable laws and regulations unless a specific exemption has been obtained.

3. REQUIREMENTS

3.1 First article. When specified (see 6.2), a sample shall be subjected to first article inspection (see 6.3) in accordance with 4.3.

* 3.2 Materials and components. Materials and components shall be as specified on the applicable drawings specified in 2.1.2. Materials not definitely specified shall be of the quality normally used by the contractor provided that the complete item complies with all provisions of this specification. It is encouraged that recycled material be used when practical as long as it meets the requirements of this specification.

* 3.2.1 Polyurethane foam. The polyurethane foam shall conform to the requirements specified on Drawing No. 5-4-3373 when tested as specified in 4.5.2.

3.3 Construction. Construction shall conform to the drawings listed in 2.1.2 and shall be as specified herein.

3.3.1 Stitching, machine.

* 3.3.1.1 Types of stitching. All stitch types, except bartacking, shall conform to FED-STD-751 as follows:

For all stitching except zig-zag stitching and stitching indicated by "Z" on drawings and for attachment of slide fasteners	- Type 301, 5 to 7 stitches per inch
For zig-zag stitching	- Type 304, 10 to 14 stitches per inch

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

For stitching indicated by "Z" on drawings and for attachment of slide fasteners	- Type 401, 5 to 7 stitches per inch - Chain portion of stitching shall not appear on outside of tent or cover
For bartacking	- Bartack, length as specified on drawings 1/8 inch in width (bight) and shall be free of thread breaks and loose stitching

3.3.1.2 Thread breaks. Thread breaks in stitching shall be overstitched not less than 1 inch at each break on stitch type 301, not less than 3/4 inch at each break on stitch type 304, and not less than 1-1/2 inches at each break on stitch type 401. Thread breaks in type 401 may be overstitched with stitch type 301. Thread breaks noted during inspection shall be repaired by overstitching the existing stitching starting from a distance of 1 inch before the break, across the defective area, to a distance of 1 inch before the break, across the defective area, to a distance of 1 inch beyond the break. The ends of repair stitching are not required to be backstitched.

3.3.1.3 Stitching ends. The ends of type 301 stitching shall be overstitched not less than 1 inch except where ends are turned under in a hem or held down by other stitching. Where 301 stitching is performed automatically on stitch patterns such as box, box with cross-stitch, "W" stitching or straight line tacking, at least three tying, overlapping, or back stitches shall be used to secure the ends of stitching. The ends of type 304 stitching shall be firmly secured by back stitching or overstitching or by increasing the number of stitches per inch at the ends for a minimum of 1/4 inch.

3.3.1.4 Skipped stitches. Two or more consecutively skipped stitches occurring in types 301 and 304 stitching shall be overstitched not less than 1 inch. Any skipped stitches in type 401 stitching shall be overstitched not less than 1-1/2 inches. Skipped stitches in type 401 stitching may be overstitched with type 301 stitching. Skipped stitches noted during inspection shall be repaired as specified for thread breaks (see 3.3.1.2).

3.3.1.5 Lubrication of thread. The addition of any lubrication to the polyester sewing thread prior to or during the sewing operations is prohibited (see 4.4.1.1).

* 3.3.2 Splicing of cloth. There shall be no splicing of roof, wall, fly, or tent cover panels. Splicing of reinforcements and sod cloth sections will be permitted and, if performed, shall conform to the following requirements:

a. Eight feet or less in length - one splice permitted
More than 8 feet but not more than 12 feet in length - two splices permitted
More than 12 feet in length - three splices permitted

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

b. The shortest length of any spliced piece shall be not less than 2 feet

c. Pieces shall be joined using seam type SSa-1 of FED-STD-751

* 3.3.2.1 Splicing of hook and loop fastener tape, reinforcement tapes, and reinforcement webbing. Splicing will be permitted and, if performed, the splicing shall conform to the following requirements:

a. Material shall be overlapped a minimum of 1 inch.
b. Material shall be spliced using a box stitch leaving a 1/8 inch margin from the edge of the item being spliced.
c. No more than one splice shall be permitted per continuous length of material.

3.3.3 Attachment of slide fasteners. Care shall be exercised to trim all thread ends to 1/2 inch or less and to maintain specified distances between edges of fabric attached to slide fastener tape so that there will be no interference with the operation of the slider.

3.3.4 Setting of grommets. Holes punched to receive the grommets shall be smaller than the outside diameter of the grommet barrel so that the barrel must be forced through the hole. The grommets shall be securely clinched without cutting the materials.

3.3.5 Setting of end clips. Webbing shall be inserted the full depth of the clip. Clips shall be securely attached without cutting the webbing, and the webbing shall be flat at the point of entry.

3.3.6 Wicking of sewing thread (cup test). There shall be no wicking of water through the tent stitching when the tent section is tested as specified in 4.5.1. The cup test is intended to ensure that non-wicking thread has been used and that no lubrication has been added to the polyester thread prior to or during the sewing operation (see 3.3.1.5).

3.3.7 Cementing. Cementing shall be in accordance with the following procedure:

a. Surface preparation. Surfaces to be bonded shall be clean and dry prior to application of the adhesives. Coated cloth surfaces to be bonded shall be thoroughly cleaned by rubbing with toluene-wetted clean cloths or pads, which may contain a mild, bonded abrasive of 80, or finer, grit size or may be of a coarse weave (as for scouring). If abrading is exercised, there shall be no scuffing or abrading of the base cloth. Separate clean cloths and clean solvent shall be used for final cleaning wipes. Abrasive coated cloths or pads shall not be used directly on stitching at seams. Foam surfaces to be bonded to coated fabric need not be cleaned unless covered with oil or dust.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

b. Adhesive mixing. The ratio of the adhesive mixture shall be as specified on the drawings. Prior to extracting quantities of the base and accelerator to be mixed, any settlement shall be uniformly redispersed. Containers for mixing, transfer, and use shall be clean prior to each filling. Adhesive in the containers shall be covered during transit to work stations and during sustained periods of non-use to prevent loss of solvent by evaporation. After mixing, the adhesive shall be used only while sufficiently spreadable to obtain an even coat.

c. Adhesive application. Except for coated cloth-foam laminates, a minimum of two coats of mixed adhesive shall be evenly spread on the cleaned surfaces to be bonded. The first coat shall be dry to the touch before the application of the second coat. Prior to assembly, the adhesive coated surfaces shall not be allowed to be contaminated by a visible layer of dust or other foreign matter. Applied adhesive shall be free of heavy smears or excessively thick lap edges (resulting from insufficient spreading), thin starved areas, uncoated areas, or other defects characteristic of improper application. The second coat shall be dried as appropriate for the assembly method to be used; i.e., to a tacky (not wet) aggressive grab condition for the two-way, dry stick method; or to a low-tack (dry condition) for two-way stick, solvent reactivation method. Adhesive application on coated cloth-foam laminates shall be either in one coat application in each surface followed by two-way, dry stick assembly, or in one heavy coat application followed by wet tack assembly.

d. Assembly. Assembly of components shall be made when the tack and grab of the adhesive coated surfaces are in a suitable range. Either excess solvent in the adhesive layers or excessive drying or open time shall be avoided. Surfaces shall be joined in the locations specified on the drawings, applying adequate pressure and rolling or barring firmly to produce an adequate bond. Care shall be exercised to avoid finger contact in the adhesive coated areas along the edges of seams, patches, or other bonded parts. Precautions should be taken to prevent adhesive application, assembling, or curing of an assembly at a temperature below 60°F. The assembled work shall not be moved too soon or in such a way as to result in edge lifting or decreasing strength of bond until the adhesive has set. Surfaces shall be assembled on the same day that they were coated, or a third coat of adhesive shall be applied to each surface. When surfaces have been assembled in an incorrect location, the adhesive bond may be immediately separated and reset at the proper location. To facilitate separation, toluene may be applied at the bond line by squirt can or atomizer and the component then peeled away as the adhesive softens. The excess toluene solvent shall be allowed to evaporate before resetting the surfaces. When incorrectly located parts are separated and the adhesive is not in an active condition or has transferred to the other surface, the affected surface shall be given an additional coat of adhesive before reassembling. Any adhesive residue shall not extend further than 1/2 inch beyond the edges of seams, strapping, splices, patches, or other bonded parts.

Source: https://assist.dla.mil -- Downloaded: 2026l0-22T00:54Z
Check the source to verify that this is the currentversion before use.

3.3.8 Repairs to polyester fabric. All necessary repairs shall be effected in accordance with the Department of the Army Field Manual FM 10-16, except that handsewn patches, or cemented patches other than as specified herein, will not be acceptable. Cemented patches on holes, cuts, or tears not more than 1 inch in diameter or length, using cement per Minnesota Mining EC-8487 or equal (see 6.6), shall be permitted. A maximum of three cemented patches per item shall be allowed without prior contracting officer authorization. Each patch shall be large enough to overlap the damaged area with a margin of at least 3/4 inch on all sides. Cemented patches shall be placed on the outside of the tent and shall not be permitted over seams or in hardware areas. All other repairs shall require authorization by the contracting officer. Repairs required as a result of failure of the cup test and when authorized by the contracting officer shall be performed by treating with a compound conforming to type I, class 1, shade Olive Drab of TT-P-595 prior to retesting.

* 3.3.9 Repairs to vinyl coated fabric. Repairs to holes, cuts, or tears and repairs of burn-throughs resulting from the heat-sealing operation, when necessary, shall be effected as follows:

a. No more than one repair to holes, cuts, or tears shall be allowed per cover or floor section.

b. No more than two repairs to burn-throughs shall be allowed per cover or floor section.

c. Repairs shall be accomplished by the application of heat-sealed or cemented patches.

d. For repairs of burn-throughs on panel lap seams, the width of the patch shall be such that the overlap on each side of the burn-through shall be equal to the width of seam. The maximum length of the patch shall not exceed the length of the sealing die plus the width of seam allowance at each end. All patches for repairs other than burn-throughs shall not exceed the size specified herein.

e. Patches shall be applied to the top side of the cover or floor section and the patched area shall be smooth, i.e., with the torn or cut edges securely and completely sealed or cemented.

3.4 Marking. All markings and labels shall conform to DDD-L-20.

3.4.1 Special markings. The letters "US" and the item nomenclature on the tent sections, liner sections, tent flies, and vestibule and special marking on the tent cover and vestibule container shall conform to type IV, class 9 in the size characters and in the locations shown on the drawings. Class 9 markings shall be clearly legible after subjection to accelerated weathering.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

* 3.4.2 Identification label. Identification labels shall conform to type VI, class 6, except the label shown on drawings 5-4-3369 and 5-4-3373 shall conform to type IV, class 6. Labels shall be 3-1/2 inches by 5-1/2 inches minimum and a blank space of at least 1-1/4 inches shall be provided on the bottom of the label for the Department of Defense inspector's stamp. Identification labels shall be stitched or marked as applicable to the tent components in the locations shown on the drawings.

* 3.4.3 Erection instruction label. Label of erection instructions shall conform to type VI, class 7 and shall be stitched to the cover in the location shown on Drawing 5-4-3359. The label shall be a proportionate copy of Drawing 5-4-3358 sheets 1 and 2, as reproduced from glossy prints of these drawings furnished by the contracting officer. The size of each label shall be, borderline to borderline, 15 inches ± 1/2 inch in the longer dimension, with a minimum 1/2 inch margin outside of the borderline on all sides.

3.5 Workmanship. Cloth components shall be clean and free of holes, cuts, tears, and cloth defects such as multiple floats or broken or missing yarns. Webbing and tape shall not have frayed or scalloped edges and rope components shall be free of cuts and breaks. Thread tension shall be maintained with seams properly sewed so that no run-offs, twists, pleats, or open seams shall result. Care shall be taken in sewing to see that no needle chews occur. All thread ends shall be trimmed to 1/2 inch or less. Metal components shall be free of burrs, sharp edges, and corroded areas and shall not be broken or malformed. Heat welded seams shall be essentially free of wrinkles, pleats, and folds. A heat welded seam, regardless of its length, shall have not more than a total of two wrinkles, pleats, or folds. The finished end item shall conform to the quality of product established by this specification and the occurrence of defects shall not exceed the applicable acceptable quality levels.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements (examinations and tests) as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in this specification where such inspections are deemed necessary to ensure supplies and services conform to prescribed requirements.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

4.1.1 Responsibility for compliance. All items shall meet all requirements of sections 3 and 5. The inspection set forth in this specification shall become a part of the contractor's overall inspection system or quality program. The absence of any inspection requirements in the specification shall not relieve the contractor of the responsibility of ensuring that all products or supplies submitted to the Government for acceptance comply with all requirements of the contract. Sampling inspection, as part of manufacturing operations, is an acceptable practice to ascertain conformance to requirements, however, this does not authorize submission of known defective material, either indicated or actual, nor does it commit the Government to accept defective material.

* 4.1.2 Responsibility for dimensional requirements. Unless otherwise specified in the contract or purchase order, the contractor is responsible for ensuring that all specified dimensions have been met. When dimensions cannot be examined on the end item, inspection shall be made at any point, or at all points in the manufacturing process necessary to assure compliance with all dimensional requirements.

4.2 Classification of inspections. The inspection requirements specified herein are classified as follows:

a. First article inspection (see 4.3).
b. Quality conformance inspection (see 4.4).

4.3 First article inspection. When a first article is required (see 3.1 and 6.2), it shall be examined for the defects listed in 4.4.3 and 4.4.4 and shall be tested for wicking as specified in 4.5.1. The presence of any defect or failure of any test shall be cause for rejection of the first article.

4.4 Quality conformance inspection. Unless otherwise specified herein, sampling for inspection shall be performed in accordance with MIL-STD-105.

4.4.1 Component and material inspection. In accordance with 4.1, components and materials shall be inspected in accordance with all the requirements of referenced documents unless otherwise excluded, amended, modified, or qualified in this specification or applicable purchase document.

4.4.1.1 Component and material certification. A certificate of compliance may be acceptable as evidence that the thread conforms to the requirement specified in 3.3.1.5.

4.4.2 In-process examination. Examination shall be made of the following fabrication operations to establish conformance with specified requirements.

a. Holes punched to receive grommets are in compliance with 3.3.4.

b. Webbing is inserted to full depth of clip for compliance with 3.3.5.

Source: https://assist.dla.mil -- Downloaded: 202610-22T00:54Z
Check the source to verify that this is the current version before use.

Whenever nonconformance is noted, correction shall be made to the items affected and to the process.

* 4.4.3 End item visual examination. The end item shall be examined for defects listed in table I. The lot size shall be expressed in units of end items of one item number only. The sample unit shall be one end item. The inspection level shall be I and the acceptable quality level (AQL), expressed in terms of defects per hundred units, shall be 10 for major defects, 25 for major and minor A combined defects, and 100 for total (major, minor A, and minor B combined) defects.

TABLE I. End item visual defects

Examine	Defect	Classification Major	Minor A	Minor B
Screening	Cut or tear:			
	- more than 2 inches in length	101		
	- more than 1/4 inch in length but not more than 2 inches in length		201	
	- 1/4 inch or less in length			301
Webbing; tie tapes	Edge frayed or scalloped			302
	Cut, torn, or caught in stitching			303
	Tie tape missing:			
	- more than one	102		
	- one			304
Cloth, except floor material	Cut, tear, or hole (including exposed drill hole) greater than 1/8 inch in length or diameter:			
	- on all tent sections, vestibules, or flies	103		
	- on covers, liners, partitions, modesty curtains, plenums, containers, or sod cloth		202	
	Cut, tear, or hole (including exposed drill hole) 1/8 inch or less in length or diameter:			
	- more than 20 holes:			
	- on all tent sections, vestibules, or flies	104		
	- on covers, liners, partitions, modesty curtains, plenums, containers, or sod cloth		203	

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Cloth, except floor material (cont'd)	- more than 10 but not more than 20 holes:			
	- on all tent sections, vestibules, or flies		204	
	- on covers, liners, partitions, modesty curtains, plenums, or sod cloth			305
	- more than 5 but not more than 10 holes:			
	- on all tent sections, vestibules, or flies			306
	Untreated area on either side of cloth more than 1 inch in length or diameter		205	
	Broken or missing yarn; multiple floats, clearly visible at normal inspection distance of approximately 3 feet		206	
Cloth, coated for floor	Hole, cut, or tear; thin or weak place due to abrasion; exposed fabric; blister, tunnel or delamination of coating; crease or wrinkle	105		
	Lump or heavy coated area		207	
	Exposed adhesive (not overcoated)	106		
	Failure to dust exposed overcoating	107		
	Excessive dusting compound			307
Hardware and metal components	Broken	108		
	Malformed:			
	- fails to perform intended function	109		
	- but will perform intended function		208	
	Corroded area			308
	Burr or sharp edge that may cause injury in handling or damage to fabric	110		
Grommets	Improperly set, two or more teeth exposed (except where grommet is set as specified but is in an area of uneven thickness which prevents uniform clinching)			309

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Grommets (cont'd)	Clinched loosely, allowing grommet to rotate around hole			310
	Clinched excessively tight; i.e., cutting cloth:			
	- on all tent sections, vestibules, or flies	111		
	- on covers		209	
	Insecurely clinched; i.e., grommets or washers become disengaged:			
	- on all tent sections, vestibules, or flies	112		
	- on covers		210	
	Size #4 grommet set with barrel inserted from outside instead of inside:			
	- on eave or ridge		211	
	- at any other location			311
	Roll of a grommet contains more than three scores (splits)			312
End clips	Improperly clinched, i.e., webbing not flat at point of entrance into clip			313
	Clinched excessively tight, cutting webbing or loosely clinched, i.e., clip becomes disengaged from webbing		212	
Rope and cord components, tent lines	Any cut or break:			
	- on ridge guy line		213	
	- on eave guy line		214	
	- on becket line		215	
	Eye splice omitted		216	
	Eye splice not as specified			314
	Free end not finished as specified			315
Seams and stitching	Open seam on stitch type 301:			
	- for more than 1/4 inch but not more than 1 inch			316
	- for more than 1 inch		217	

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Seams and stitching (cont'd)	Open seam on stitch type 401:			
	- one row of stitching open for 1 inch or less:			
	- on tent sections, liners, vestibules, floors, flies, or covers			317
	- one row of stitching open for more than 1 inch:			
	- on tent, vestibule, liner, floor, or fly sections		218	
	- on all other items			318
	- both rows of stitching open (not necessarily at the same location):			
	- on tent, vestibule, liner, floor, or fly sections	113		
	- on all other items		219	
	NOTE: A seam shall be classified as open when one or more stitches joining a seam are broken, or when one or more skipped or run-off stitches occur. On double stitched seams, a seam shall be classified as open when either one or both sides of a seam are open.			
	Raw edges caught in stitching:			
	- more than 1 inch but not more than 3 inches			319
	- more than 3 inches		220	
	Thread breaks:			
	- overstitched less than 1-1/2 inches on stitch type 401			320
	- overstitched less than 1 inch on stitch type 301			321
	- overstitched less than 3/4 inch on stitch type 304			322
	NOTE: Thread breaks not overstitched shall be classified as open seams.			

Source: https://assist.dla.mil -- Downloaded: 202610-22T00:54Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Seams and stitching (cont'd)	Needle chews resulting in cut, tear or hole (see cut, tear, or hole)			
	Skipped stitches:			
	- overstitched less than 1-1/2 inches on stitch type 401		221	
	- overstitched less than 1 inch on stitch type 301 or 304 (when two or more skipped stitches occur consecutively)		222	
	NOTE: Skipped stitches not overstitched shall be classified as open seams.			
	One or more required rows of stitching omitted (except on boxstitching)	114		
Boxstitching	Incomplete:			
	- one row of stitching omitted			323
	- two or more rows of stitching omitted		223	
	Less than specified length by more than 1/8 inch			324
Bartacking	Less than specified length by more than 1/8 inch			325
Stitching ends	Overstitched less than 1 inch on stitch type 301 (except where ends are held down by other stitching or turned under in a hem, or where stitching is performed automatically)		224	
	Secured with less than three tying, overlapping, or back stitches when automatic stitching is performed			326
	Secured with less than 1/4 inch of back stitching, overstitching, or an increased number of stitches per inch at the end of stitch type 304			327

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Seams	Pleated:			
	- on all tent sections, liners, vestibules, or flies		225	
	- on covers and floors			328
Seam type	Wrong seam type	115		
Stitch type	Wrong stitch type	116		
Stitch tension	Loose, resulting in an exposed bobbin or top thread for more than 6 inches		226	
	Tight, as evidenced by puckering on fabric for more than 6 inches		227	
Stitches per inch	Less than the minimum specified (except on panel joining seams):			
	- one stitch			329
	- two or more stitches		228	
	Less than the minimum specified on panel joining seams		229	
	More than the maximum specified:			
	- one stitch			330
	- two or more stitches		230	
	NOTE: Variation in the number of stitches per inch, caused by the operator speeding up the machine and pulling the fabric in order to sew over heavy places or heavy seams or in turning corners, shall be classified as follows:			
	a. Within the minor "B" defect classification - no defect			
	b. Within the minor "A" defect classification - minor "B" defect			
Stitching gage	Not as specified		231	

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Stitching margin	Larger than specified: 1/			
	- for more than 2 inches but not more than 4 inches			331
	- for more than 4 inches in length		232	
	Less than specified:			
	- for more than 2 inches but not more than 4 inches in length			332
	- for more than 4 inches in length		233	
Stitching	Chain portion of stitching shows on outside of tent sections or covers		234	
Mends, darns, or patches	Repairs not in accordance with Department of the Army Field Manual FM 10-16 or not authorized by the contracting officer (see 3.3.8)	117		
Component and assembly	Any component part omitted, not assembled or fabricated of applicable referenced material	118		
	Not assembled as specified	119		
Hems	Constructed with partial turnunder when double turnunder is required		235	
	Twisted or pleated			333
Reinforcements	Improperly applied, causing excessive fullness on reinforcements or reinforced parts	120		
Cloth splicing	Splice in roof, wall, fly, or tent cover panels	121		
	Splicing not as specified in 3.3.2			334
Slide fastener	Slider jams or fails to interlock chain	122		
	Any tape improperly assembled causing failure of chain to effect a smooth and secure closure	123		
	Thong omitted			335

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

TABLE I. End item visual defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Cementing, general	Puckers, loose edges, unadhered pocket, or tunnels		236	
	Excess adhesion resulting in sags or lumps evident through outer layer of fabric		237	
	Adhesive exposed beyond the overcoated area on interior surface			336
Marking and labels	Omitted, incorrect, illegible, or misplaced			337
Cleanness	Grease or oil stains			338
	Thread ends not trimmed to 1/2 inch or less (except in slide fastener area)			339
	Thread ends not trimmed to 1/2 inch or less in slide fastener area		238	

1/ Applicable to all seams except panel joining seam. For panel joining seam, stitching margin must exceed specified margin by more than 3/16 inch for more than 2 inches, but not more than 4 inches to be a minor B defect or more than 4 inches to be a minor A defect.

4.4.4 End item dimensional examination. The end item shall be examined for the defects listed in table II. The lot size shall be expressed in units of end items of one item number only. The sample unit shall be one end item. The inspection level shall be S-3 and the AQL, expressed in terms of defects per hundred units, shall be 2.5 for major defects, 10 for major and minor A combined defects, and 100 for total (major, minor A, and minor B combined) defects.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

TABLE II. End item dimensional defects

Examine	Defect	Classification Major	Minor A	Minor B
Overall dimensions of end, window, or door sections; liners, floors, vestibules, vestibule doors, larger or small flies	Smaller than specified dimensions less applicable minus tolerances indicated on drawings	101		
	Larger than specified dimensions and applicable plus tolerance indicated on drawings			301
Overall dimensions of all other items	Smaller than specified dimensions less applicable minus tolerance indicated on drawing, but not smaller than the specified dimensions less twice the applicable minus tolerance			302
	Smaller than specified dimensions less twice the applicable minus tolerance indicated on drawing		201	
	Larger than specified dimensions and applicable plus tolerance indicated on drawing			303
Location dimensions (unless otherwise specified)	Not within specified tolerance: - exceeding twice the applicable tolerance		202	
	- not exceeding twice the applicable tolerance			304
Webbing, tie tapes	Finished length less than specified by more than 1 inch			305
Grommets	Set beyond specified location by more than 1/2 inch		203	
	Number 4 eave and ridge grommet is set more or less than 1/2 inch from specified location	102		
Rope components, tent lines	Eye on footstop or line less than specified by more than 1/2 inch			306
	Finished length of guy line less than specified: - by not more than 4 inches			307
	- by more than 4 inches but not more than 12 inches		204	
	- by more than 12 inches	103		

Source: https://assist.dla.mil -- Downloaded: 202610-22T00:54Z
Check the source to verify that this is the currentversion before use.

TABLE II. End item dimensional defects (cont'd)

Examine	Defect	Classification Major	Minor A	Minor B
Beckets	Misplaced:			
	- by more than 1/4 inch but not more than 1/2 inch			308
	- by more than 1/2 inch		205	
	Length of loop more or less than specified by 1/2 inch or more		206	
Hems	Required to finish less than 3/4 inch or less in width, less than specified; hems required to finish more than 3/4 inch in width, less than specified by more than 1/4 inch		207	
Reinforcements	Finished dimensions less than specified by more than 1/2 inch			309
Sod cloths	Less than specified width by more than 1 inch			310
Ventilator opening	Misplaced by more than 1/2 inch			311
Tent cover flaps	Center line of flaps set off center of body by more than 3/4 inch			312

4.4.5 End item testing. End item units of sections, flies, and vestibules only (floors, liners, and covers of containers are excluded) shall be tested as specified in 4.5.1 for conformance to the wicking requirement in 3.3.6. The lot size shall be expressed in units of end items. The sample size shall be the number of end items indicated by inspection level S-2. Any test failure shall be cause for rejection of the lot.

4.4.6 Packaging examination. The fully packaged end items shall be examined for the defects listed below. The lot size shall be expressed in units of shipping containers. The sample unit shall be one shipping container fully packaged. The inspection level shall be S-2 and the AQL, expressed in terms of defects per hundred units, shall be 2.5.

Examine	Defect
Marking (exterior and interior)	Omitted; incorrect; illegible; of improper size, location, sequence, or method of application

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

Examine	Defect
Materials	Any component missing, damaged, or not as specified
Workmanship	Inadequate application of components, such as: Incomplete sealing or closure of flap, improper taping, loose strapping, or inadequate stapling Bulged or distorted container
Content	Number per container is more or less than required

* 4.4.7 Palletization examination. The fully packaged and palletized end items shall be examined for the defects listed below. The lot size shall be expressed in units of palletized unit loads. The sample unit shall be one palletized unit load, fully packaged. The inspection level shall be S-1 and the AQL, expressed in terms of defects per hundred units, shall be 6.5.

Examine	Defect
Finished dimensions	Length, width, or height exceeds specified maximum requirement
Palletization	Pallet pattern not as specified Load not bonded as specified
Weight	Exceeds maximum load limits
Marking	Omitted; incorrect; illegible; of improper size, location, sequence, or method of application

4.5 Methods of inspection.

4.5.1 Wicking test. The end item unit shall be tested once on a roof panel lap seam and once on a ridge reinforcement seam. The end item unit shall be laid over a 6 inch ±1/8 inch diameter hoop so as to form a ±1/4 inch deep depression with the seam to be tested running through the center of the depression. A 500-mL quantity of water at 77° ±4°F shall be slowly poured into the depression and the under surface of the seam shall be observed. Any wicking of water along the sewing thread, identified by a discoloration or darkening of the thread within 5 minutes after water is poured, shall be considered a test failure. Water leakage through the needle holes or between the plies of the lapped seamed fabrics shall not be considered a failure.

Source: https://assist.dla.mil -- Downloaded: 202640-22T00:54Z
Check the source to verify that this is the currentversion before use.

* 4.5.2 Polyurethane foam testing. The polyurethane foam shall be tested as specified in table III for compliance with the requirements specified in 3.2.1 Any nonconformance shall be cause for rejection of the lot of materials.

Table III. Polyurethane foam tests

Characteristic	Test method
Density	ASTM D 3574 (Test A)
Deflection:	
Indentation force at 25%	ASTM D 3574 (Test B_2)
Compression force at 50%	ASTM D 3574 (Test C)
Tear resistance	ASTM D 3574 (Test F)
Flame resistance after flame time:	
Original	FED-STD-191 (Method 5905)
After oven aging	ASTM D 3574 (Test K)
After steam autoclave	ASTM D 3574 (Test J)

* 5. PACKAGING

5.1 Preservation. Preservation shall be level A or Commercial, as specified (see 6.2).

5.1.1 Level A preservation. Each component shall be folded and/or rolled in a manner so as to achieve a compact unit. Each vestibule door cap shall be folded to approximately 15-1/2 by 11-1/2 inches and placed in a plastic bag conforming to A-A-50083. Each vestibule floor, vestibule container, pin container, door liner, window section liner, or blackout curtain shall be folded to approximately 23-1/2 by 19-1/2 inches and placed in a plastic bag conforming to A-A-50083.

5.1.2 Commercial preservation. Each component shall be preserved in accordance with ASTM D 3951.

5.2 Packing. Packing shall be level A, B, or Commercial, as specified (see 6.2).

5.2.1 Level A packing. Each component or quantity of components (see table V), preserved as specified in 5.1, shall be packed in a shipping container conforming to overseas type, style A, Grade B of PPP-B-601. Approximate inside dimensions of the box shall be as specified in table V. Each box shall be closed and strapped in accordance with the appendix of PPP-B-601.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

5.2.2 Level B packing. Each component or quantity of components (see table V), preserved as specified in 5.1, shall be packed in a shipping container conforming to style RSC-L, type CF (variety SW) or SF, class domestic, grade 275 of PPP-B-636. Approximate inside dimensions of the box shall be as specified in table V. Each box shall be closed in accordance with method II as specified in the appendix of PPP-B-636, except that the inspection shall be in accordance with 4.4.6.

5.2.2.1 Weather-resistant shipping container. When specified (see 6.2), the shipping container shall be a grade V3c, V3s, or V4s fiberboard box fabricated in accordance with PPP-B-636 and closed in accordance with the appendix of PPP-B-636, exept that the inspection shall be in accordance with 4.4.6.

5.2.2.2 For shipment to assembler. When bulk shipment to assembler is required, components of one type shall be packed in a triple-wall fiberboard container conforming to class 1, style G of PPP-B-640. The box shall be provided with 4-way entry built-up skids in accordance with PPP-B-601. The box shall be closed with a minimum of two plastic straps conforming to type II, III, or IV of ASTM D 3951 with nominal width and thickness of 1/2 by 0.020 inch or greater. Inside dimensions shall be approximately 47 inches in length, 39 inches in width, and 29 inches in depth. The quantity of each component per box shall be as specified in table IV.

TABLE IV. Packaging parameters

Item	Box style 1/	Box dimensions (inches)	Pallet pattern	Bulk quantity
Tent floor (in.)	FTC	49 by 39 by 5	83	4
Vestibule floor (in.)	FTC	40 by 23 by 5	89	10
End section	RSC-L	39 by 15 by 11	94	4
Door section	RSC-L	47 by 19 by 12	84	5
Window section	RSC-L	40 by 24 by 5.5	89	10
Tent fly (16 feet)	RSC-L	40 by 9 by 9	31	15
Tent fly (8 feet)	RSC-L	40 by 7 by 7	51	25
Tent cover	RSC-L	23 by 6 by 6	56	65

Source: https://assist.dla.mil -- Downloaded: 202610-22T00:54Z
Check the source to verify that this is the current version before use.

TABLE IV. Packaging parameters (cont'd)

Item	Box style 1/	Box dimensions (inches)	Pallet pattern	Bulk quantity
End section liner	RSC-L	39 by 9-1/2 by 9	31	15
Intermediate liner	RSC-L	38 by 8 by 6	50	30
Tent floor (8 foot single ply)	RSC-L	40 by 6 by 4-1/2	51	50
Vestibule and door	RSC-L	40 by 8 by 8	50	20
Partition	RSC-L	26 by 6 by 4-1/2	26	75
Modesty curtain	RSC-L	26 by 6 by 4-1/2	26	75
Plenum end wall	RSC-L	40 by 6 by 4	51	55
Plenum extendable	RSC-L	40 by 6 by 4	51	55
Plenum side entrance	RSC-L	40 by 6 by 4	51	55
10 vestibule floors	RSC-L	23-1/2 by 19-1/2 by 9	90	N/A
10 vestibule containers	RSC-L	23-1/2 by 19-1/2 by 9	90	N/A
10 pin containers	RSC-L	23-1/2 by 19-1/2 by 9	90	N/A
10 door liners	RSC-L	23-1/2 by 19-1/2 by 9	90	N/A
10 window section liners	RSC-L	23-1/2 by 19-1/2 by 9	90	N/A
10 blackout curtains	RSC-L	23-1/2 by 19-1/2 by 9	90	N/A
20 vestibule door caps	RSC-L	15-1/2 by 11-1/2 by 11	9	N/A

1/ Either end-loading or top-loading RSC boxes are acceptable. For an end-loading box, the largest dimension shall be depth. The flutes of the box and liner shall run parallel to the score line of the opening of the end-loading box (see PPP-B-636, figure 2). The height of the liner shall be the full inside width of the end-loading box.

5.2.3 Commercial packing. Components, preserved as specified in 5.1, shall be packed in accordance with ASTM D 3951.

5.3 Palletization. When specified (see 6.2), components, packed as specified in 5.2, shall be palletized on a 4-way entry pallet in accordance with load type I or Ia, as applicable, of MIL-STD-147. Pallet type shall be type I (4-way entry), type IV, or type V in accordance with MIL-STD-147.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

Pallets shall be fabricated from wood group I, II, III, or IV of MIL-STD-731. Each prepared load shall be bonded with primary and secondary straps in accordance with bonding means C and D or film bonding means F or G. Pallet pattern shall be as specified in table IV and shall be in accordance with the appendix of MIL-STD-147.

5.4 Marking. In addition to any special marking required by the contract or purchase order, unit packs, shipping containers, and unit loads shall be marked in accordance with MIL-STD-129 or ASTM D 3951, as applicable.

6. NOTES

(This section contains information of a general or explanatory nature that may be helpful but is not mandatory.)

6.1 Intended use. The tent sections including liners, floors, flies, and vestibule are designed to form an extendable frame supported tent for any general purpose use. The tent is variable in size and configuration depending on the number and variety of tent sections assembled together.

6.2 Ordering data. Acquisition documents must specify the following:

a. Title, number, and date of this document.
b. Items required, as applicable (see 1.2).
c. Issue of DODISS to be cited in the solicitation, and if required, the specific issue of individual documents referenced (see 2.1.1 and 2.2).
d. When a first article is required (see 3.1, 4.3, and 6.3).
e. Levels of preservation and packing (see 5.1 and 5.2).
f. When weather-resistant grade fiberboard shipping containers are required for level B parking (see 5.2.2.1).
g. When palletization is required (see 5.3).

6.3 First article. When a first article is required, it shall be inspected and approved under the appropriate provisions of Federal Acquisition Regulation FAR 52.209. The first article should be a preproduction sample. The contracting officer should specify the appropriate type of first article and the number of units to be furnished. The contracting officer should also include specific instructions in acquisition documents regarding arrangements for selection, inspection, and approval of the first article.

6.4 Repair of leaking seams. A satisfactory method of applying the textile compound for the repair of leaking seams is as follows:

a. A suitable volume of textile compound conforming to type I, class 1, shade Olive Drab of TT-P-595 shall be thoroughly stirred and diluted with an equal volume of petroleum solvent (Stoddard solvent or equivalent). Thoroughly stir the mixture again before use.

Source: https://assist.dla.mil -- Downloaded: 202640-22T00:54Z
Check the source to verify that this is the currentversion before use.

b. Prior to application of the compound, the tent sections must be dry. Special attention must be taken to ensure adequate ventilation and that proper fire prevention measures are taken since the compound is flammable.

c. Two coats of the textile compound shall then be applied to the seams (on the outside of the tent section only). A 4-inch wide stiff brush is recommended for use. The first coat shall be air dried for a minimum of 4 hours prior to application of the second coat. Elapsed time between coats may be reduced by providing a supply of hot air to evaporate the solvent more quickly. In this manner, a second coat may be applied as soon as the first coat is dry to the touch. After the application of the second coat, the treated tent section shall be allowed to air dry for a period of at least 24 hours.

6.4.1 Seams to be treated. Seams that have failed the test specified in 4.5.1 should be treated as follows:

a. Failure of panel lap seam - treat all panel lap seams.

b. Failure of purlin or header reinforcement stitching - treat all stitching on reinforcements.

6.5 Cementing of coated cloth. The following system has been used in preparing seams where chlorosulphonated polyethylene coated surfaces of coated cloths are to be adhered to chloroprene coated surfaces:

a. Abrade, by hand, the chlorosulphonated polyethylene surface only to the point of dullness and uniform roughness. Norton Company's Lighting Metalite Cloth-Aluminum Oxide 80-J or 3-M Company's Three-M-ite-Elek-tro-Cut Cloth J-wt Aluminum Oxide are satisfactory for use in abrading.

b. Wash the abraded chlorosulphonated polyethylene surface and the nonabraded chloroprene surface with clean cotton cloth swabs wet with toluene.

c. Allow each washed surface to dry at room temperature for 15 to 20 minutes.

d. Brush apply one coat of adhesive (see 3.3.7) to each washed surface.

e. Allow the adhesive to dry at room temperature for 15 to 20 minutes.

f. Brush apply a second coat of adhesive.

g. After 15 to 20 minutes drying, reactivate each adhesive with toluene.

h. Assemble immediately, smooth by hand, and then roll with a steel roller.

Source: https://assist.dla.mil -- Downloaded: 202610-22T00:54Z
Check the source to verify that this is the current version before use.

i. Cure the cemented assembly a minimum of 24 hours before movement.

* 6.6 Patch cement supply source. A source of supply for the patch cement specified in 3.3.8 is the Minnesota Mining & Mfg. Co., 3 M Center, St. Paul, Minnesota 55144.

6.7 Subject term (key word) listing.

Equipment, canvas
Floors
Frame support
Liners
Shelter

6.8 Changes from previous issue. The margins of this specification are marked with asterisks to indicate where changes (additions, modifications, corrections, deletions) from the previous issue were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous issue.

Custodians:

Army - GL
Navy - NU
Air Force - 99

Preparing activity:

Army - GL

(Project 8340-0523)

Review activities:

Army - MD
Air Force - 82
DLA - CT

User activities:

Navy - MC,
Air Force - 45

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS

1. The preparing activity must complete blocks 1, 2, 3, and 8. In block 1, both the document number and revision letter should be given.
2. The submitter of this form must complete blocks 4, 5, 6, and 7.
3. The preparing activity must provide a reply within 30 days from receipt of the form.

NOTE: This form may not be used to request copies of documents, nor to request waivers, or clarification of requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

I RECOMMEND A CHANGE:	1. DOCUMENT NUMBER	2. DOCUMENT DATE (YYMMDD)
	MIL-T-44243A	1990 November 23

3. DOCUMENT TITLE

Tent Sections, Tent, Extendable, Modular, Personnel (TEMPER)

4. NATURE OF CHANGE *(Identify paragraph number and include proposed rewrite, if possible. Attach extra sheets as needed.)*

5. REASON FOR RECOMMENDATION

6. SUBMITTER

a. NAME (Last, First, Middle Initial)	b. ORGANIZATION	
c. ADDRESS (Include Zip Code)	d. TELEPHONE (Include Area Code) (1) Commercial (2) AUTOVON (If applicable)	7. DATE SUBMITTED (YYMMDD)

8. PREPARING ACTIVITY

a. NAME	b. TELEPHONE (Include Area Code) (1) Commercial	(2) AUTOVON
U.S. Army Natick RD&E Center	508-651-4531	256-4531
c. ADDRESS (Include Zip Code) Commander, U.S. Army Natick RD&E Center ATTN: STRNC-UXT Natick, MA 01760-5017	IF YOU DO NOT RECEIVE A REPLY WITHIN 45 DAYS, CONTACT: Defense Quality and Standardization Office 5203 Leesburg Pike, Suite 1403, Falls Church, VA 22041-3466 Telephone (703) 756-2340 AUTOVON 289-2340	

DD Form 1426, OCT 89 NATICK OP, APR 90 *Previous editions are obsolete.* 198/290

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T00:54Z
Check the source to verify that this is the current version before use.