MILITARY SPECIFICATION

FUZE, PD, M936
LOADING, ASSEMBLING AND PACKING

This Specification is approved for use within the U.S. Army Armament Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This specification covers the requirements and quality assurance provisions for the loading, assembling and packing of the M936 Point Detonating Fuze.

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Specifications and standards. The following specifications and standards form a part of this specification to the extent specified herein. Unless otherwise specified, the issues of these documents shall be those listed in the issue of the Department of Defense Index of Specifications and Standards (DoDISS) and supplement thereto, cited in the solicitation.

MILITARY

MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specilfication for
MIL-P-60412 - Packaging, Packing and Marking for Shipment of Artillery Type and Rocket Fuzes, General Specification for

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes

MIL-STD-331 - Fuze and Fuze Components, Environmental and Performance Test for

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, U.S. Army Armament, Munitions and Chemical Command, Attn: AMSMC-QA, Dover, New Jersey 07801-5001 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

AMSC N/A FSC 1390
DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

2.1.2 Other Government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this specification to the extent specified herein. Unless otherwise specified, the issues shall be those in effect on the date of the solicitation.

DRAWINGS (See 6.5)

US ARMY ARMAMENT RESEARCH, DEVELOPMENT AND ENGINEERING CENTER (ARDEC)

PRODUCT DRAWINGS

9390425 - Fuze, PD, M936

(Copies of specifications, standards, handbooks, drawings, and publications required by manufacturers in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting officer.)

2.2 Order of precedence. In the event of a conflict between the text of this specification and the references cited herein, (except for associated detail specifications, specification sheets or MS standards), the text of this specification shall take precedence. Nothing in this specification, however, shall supersede applicable laws and regulations unless a specific exemption has been obtained.

3. REQUIREMENTS

3.1 Material. Materials and parts shall be in accordance with applicable drawings and specifications.

3.2 Fuze assembly. The PD, M936 fuze assemblies shall comply with all requirements specified on drawing (dwg.) 9390425 and with all requirements specified in applicable specifications.

3.3 Transportation vibration. The fuze assembly shall comply with the requirements of MIL-STD-331A, Test 119, Procedure 2, and of 3.4.1 and 3.4.2.

3.4 Ballistic Performance (Proving Ground).

3.4.1 Premature bursts. There shall be no premature bursts or metal parts failure in the mortar or in flight.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

3.4.2 Functioning. The fuze shall function on impact with the ground (as evidenced by cartridge high order functioning).

3.4.3 Arming safety. The fuze shall not function on impact against a 1/2" plywood screen positioned at a distance of 100 meters ± 1 meter.

3.5 Lead assembly output test. The lead assembly shall pierce a hole .220" minimum in diameter in a lead disc (dwg. 8816368).

3.6 Complete fuze leak test. The fuze shall have an air leakage rate no greater than 0.5 psi per 15 seconds.

3.7 First article. When specified in the contract or purchase order, a sample shall be subjected to first article inspection in accordance with the technical provisions herein. (see 4.3 and 6.2)

3.8 Workmanship. All parts and assemblies shall be fabricated in a thorough, workmanlike manner. They shall be free of burrs, sharp edges, cracks, dirt, rust and other foreign matter. The cleaning methods shall not be injurious to any part, nor shall the parts be contaminated by the cleaning agent. Exterior surface coatings shall be uniform and continuous except for a few light scratches not exposing base material. All required markings shall be neat and sharply defined.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.1.1 Responsibility for compliance. All items must meet all requirements of section 3 and 5. The inspection set forth in this specification shall become a part of the contractor's overall inspection system or quality program. The absence of any inspection requirements in the specification shall not relieve the contractor of the responsibility of assuring that all products or supplies

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

submitted to the Government for acceptance comply with all requirements of the contract. Sampling in quality conformance does not authorize submission of known defective material, either indicated or actual, nor does it commit the Government to acceptance of defective material.

4.2 Classification of inspections. The following types of inspection shall be conducted on this item:

a. First Article Inspection

b. Quality Conformance Inspection

4.3 First article inspection

4.3.1 Submission The contractor shall submitt a first article sample as designated by the Contracting Officer for evaluation in accordance with provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated.

Part description	Drawings	Quantity
Cup, Lead	9234684	10
Holder, Booster	9390421	10
Cup, Booster	9390422	10
Lead Assembly	9234683	50
Fuze, PD M936	9390425	191

4.3.2 Inspections to be performed. See MIL-A-48078 and Table I specified herein.

4.3.3 Rejection. See MIL-A-48078(AR).

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

TABLE I - First article inspection

CLASSIFICATION OF DEFECTS & TESTS MIL-F-70613 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
	M936, PD, Fuze and Components				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Cup, Lead (Dwg. 9234684)				
	Examination for Defects	10		3.2	4.4.2.1
	Lead Assembly (Dwg. 9234683)				
	Examination for Defects	50		3.2	4.4.2.2
	Lead Assembly Output Test	50		3.5	4.5.2
	Cup, Booster (Dwg. 9390422)				
	Examination for Defects	10		3.2	4.4.2.3
	Holder, Booster (Dwg. 9390421)				
	Examination for Defects	10		3.2	4.4.2.4
	Fuze, PD, M936 (Dwg. 9390425)				
	Examination for Defects	15		3.2	4.4.2.6
	Complete Fuze Leak Test	15		3.6	4.5.3
	Performance (PG Test) (See 6.4.2) (Dwg. 9390425)				
	Proving Ground Premature Bursts	164		3.4.1	4.5.4
	Proving Ground Functioning	124	(a)	3.4.2	4.5.4
	Proving Ground Arming Safety	12		3.4.3	4.5.5
	Transportation Vibration	10	(b)	3.3	4.5.1

NOTES:
(a) Three or more duds shall be cause for rejection.
(b) Two or more duds shall be cause for rejection.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection

4.4.1 Inspection lot formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, each inspection lot of fuzes shall contain:

a. Fuze components of one lot interfix number from one manufacturer.

b. Booster pellets of one lot interfix number from one manufacturer.

4.4.2 Examination. See MIL-A-48078. Unless otherwise specified in the Classification of Defects and Test Tables, sampling plans and procedures for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-70613 (AR)

PARAGRAPH	TITLE		SHEET	DRAWING NUMBER
4.4.2.1	Cup, Lead		1 OF 1	9234684
				NEXT HIGHER ASSEMBLY 9234683

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Thickness of base		0.40%	3.2	Gage
102	Inside diameter		0.40%	3.2	Gage
103	Outside diameter		0.40%	3.2	Gage
104	Outside flange diameter		0.40%	3.2	Gage
105	Thickness of flange		0.40%	3.2	Gage
106	Length from botton to base of flange		0.40%	3.2	Gage
107	Corner radii (two places)		0.40%	3.2	Gage
Minor					
201	Protective finish damaged		0.65%	3.2	Visual
202	Surface finish improper		0.65%	3.2	Visual
203	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

MIL-F-70613 (AR)

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.2	Lead Assembly				9234683
					NEXT HIGHER ASSEMBLY 9390425
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Overall length		0.40%	3.2	Gage
102	Outside diameter		0.40%	3.2	Gage
103	Charge depth improper		0.40%	3.2	Gage
104	Identification mark missing or improper		0.40%	3.2	Visual
105	Lead assembly output test	200	(a)	3.5	4.5.2
Minor					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES: (a) More than two (2) defects shall cause the lot to be rejected.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

MIL-F-70613 (AR)

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.3	Cup, Booster				9390422
					NEXT HIGHER ASSEMBLY 9390423
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Thickness of base		0.40%	3.2	Gage
102	Inside diameter		0.40%	3.2	Gage
103	Outside diameter		0.40%	3.2	Gage
104	Outside flange diameter		0.40%	3.2	Gage
105	Length from bottom to top of flange		0.40%	3.2	Gage
106	Corner radii (two places)		0.40%	3.2	Gage
Minor					
201	Surface finish improper		0.65%	3.2	Visual
202	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9390421
4.4.2.4	Holder, Booster				NEXT HIGHER ASSEMBLY 9390424
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Major diameter of holder		0.40%	3.2	Gage
102	Pitch diameter of holder		0.40%	3.2	Gage
103	Length of holder		0.40%	3.2	Gage
104	Inside diameter of holder		0.40%	3.2	Gage
105	Protective finish missing or improper		0.40%	3.2	Visual
Minor					
201	Inner radius at front face		0.65%	3.2	Gage
202	Location of spanner holes		0.65%	3.2	Visual
203	Diameter of spanner holes		0.65%	3.2	Gage
204	Depth of spanner holes		0.65%	3.2	Gage
205	Improper surface finish		0.65%	3.2	Visual
206	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-70613 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.5	Booster Cup Assembly				9390423
					NEXT HIGHER ASSEMBLY 9390425
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter		0.40%	3.2	Gage
102	Improper depth of booster charge		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-70613 (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.6	Fuze, PD, M936 (During and After Assembly)	1 OF 1	9390425
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Booster pellet missing, damaged or cracked		0.40%	3.2	Visual
102	Sealant missing from threads of booster cup		0.40%	3.2	Visual
103	Tape missing or improperly assembled		0.40%	3.2	Visual
104	Fuze improperly marked		0.40%	3.2	Visual
105	Label missing damaged or illegible		0.40%	3.2	Visual
106	Insufficient torque on booster cup		0.40%	3.2	Gage
107	Complete fuze leak test	20	(a)	3.6	4.5.3
Minor					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

(a) Two (2) more defects shall cause the lot to be rejected.

Source: https://assist.dla.mil - Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-70613 (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.7	Fuze, PD, M936, Destructive Lot Acceptance Testing	1 OF 1	9390425
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Transportation vibration test MIL-STD-331A, test no. 119, procedure 2 and premature burst during firing	10	100%	3.3	4.5.1
2	Premature burst in ballistic test	108	100%	3.4.1	4.5.4
3	Function in arming safety test	12	100%	3.4.3	4.5.5
Major					
101	Ballistic test SQ	88	(a)	3.4.2	4.5.4
102	Ballistic test delay	10	(b)	3.4.2	4.5.4
103	Transportation vibration firing phase non-function	10	(c)	3.4.2	4.5.1

NOTES: (a) Three (3) or more duds shall cause the lot to be rejected. After three (3) consecutive lots have been accepted according to this criteria, a special double sampling plan shall be used - see 4.5.4.1.3.

(b) Five (5) fuzes from the charge zero quantity shall be TV conditioned prior to ballistic test. Results for information only except for premature functioning.

(c) Two (2) or more duds shall cause the lot to be rejected.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

4.4.3 Inspection equipment. The inspection equipment required to perform the examination and tests prescribed herein is described in the Paragraph Reference/Inspection Method column in the tables starting with 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and 6.3 of this specification.

4.5 Methods of inspection

4.5.1 Transportation vibration. The test shall be performed on complete fuze assemblies (dwg. 9390425) in the unarmed position set SQ. The test shall be conducted in accordance with the procedures outlined in MIL-STD-331, Test 119, Procedure 2. Upon completion of the test, the fuzes shall not be disassembled but shall be x-rayed to determine if the fuze has armed, become unsafe in any way, or has been damaged so as to not function. If so, that condition shall be classed as a test failure, and the ballistic sample shall not be fired. If the x-rays indicate the fuzes safe and operable, then they shall be assembled to 60MM, M302 rounds and fired at Charge O set SQ, as detailed in 4.5.4.

4.5.2 Lead assembly output test. The test shall be performed on the lead assembly (dwg. 9234683). A fixture shall be used to hold the lead assembly in central contact with the lead disc (dwg. 8816368). A ball (dwg. 8816014) shall be dropped a distance of five (5) inches onto a firing pin (dwg. 9200012) - distance is measured from the bottom of the ball to the top of the firing pin. The firing pin shall strike and initiate an M98 detonator (dwg. 9243921) which in turn will function the lead assembly. Observation shall be made for compliance with requirements as defined in 3.6. Other suggested, but not mandatory, equipment which could be utilized in conjunction with this set-up are: holder (dwg. 8816367), bushing (dwg. 8827829) and base (dwg. 8802085). Government approval, of the test fixture to be used, is required.

4.5.3 Complete fuze leak test. This test shall be performed on complete fuzes (dwg. 9390425). A fixture shall be used which covers the entire outer surface of the fuze with as little clearance as possible. The test shall be conducted at ambient temperature using 3 $\pm$ 0.5 psi. Any sample which exhibits a pressure drop of more than 0.5 psi in 15 seconds minimum after stabilization shall be classed defective. A fixed volume of air shall be used so as to detect gross leaks. Equipment shall be as specified in 4.4.3.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

4.5.4 Performance test (proving ground ballistic).

4.5.4.1 Functioning test. The sample fuzes shall be assembled to 60mm, M302, series cartridges and fired from an appropriate mortar between 45° and 75° elevation. If any fuze fails to cause the shell to function high order, that fuze shall be classified as defective. If any fuze in either SQ or Delay setting mode causes the round to function prematurely, that fuze shall be classified as having critical defect. The proving ground shall utilize a geophonic sensing device to differentiate superquick and delay functionings at maximum charge.

4.5.4.1.1 SQ phase. The sample fuzes shall be divided into two (2) equal groups. The groups shall be fired at Charge 0 set SQ and maximum charge set SQ.

4.5.4.1.2 Delay phase. The sample fuzes shall be divided into two (2) equal groups. The groups shall be fired at Charge 0 set Delay and maximum charge set Delay, respectively. Sample fuzes required to be TV tested shall be conditioned in accordance with 4.5.1 except that the fuzes shall be set Delay after conditioning. This test is for informational purposes only and shall not be considered for lot acceptance purposes except for premature functions.

4.5.4.1.3 Double sample SQ. After three (3) consecutive lots have met the ballistic requirements of 4.4.2.5, a special double sample for the ballistic, SQ phase shall be employed. Forty-four (44) sample fuzes shall be fired in accordance with 4.5.4.1.1 If no (0) duds result, the lot shall be accepted. If two (2) or more duds are found, the lot shall be rejected. If one (1) dud results, another sample of forty-four (44) fuzes shall be fired. If more than one (1) additional dud results, the lot shall be rejected. If only the first sample is required, the Premature Burst sample size shall be reduced to sixty-four (64)".

4.5.5 Arming safety (proving ground). The fuzes shall be assembled to the inert filled M302 round set SQ and fired at Charge 0 from a 60mm mortar. They shall be fired against a 1/2 inch plywood screen set at a distance of 100 meters ±1 meter. A minimum muzzle velocity of 180 fps is required for every round. If any fuze functions when the muzzle velocity is equal to or greater than the requirement, the lot shall be rejected. If any fuze functions and the muzzle velocity is less than the requirement, the lot shall be referred. If a fuze does not function, but the muzzle velocity for that round is below the requirement, that sample shall be classed a "no-test" and a new sample shall be selected and tested.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

5. PACKAGING

5.1 Packaging, packing and marking. Packaging, packing and marking shall be in accordance with the requirements and inspection procedures specified in MIL-P-60412.

6. NOTES

6.1 Intended use. The M936 Fuze is intended for use on 60mm mortar ammunition.

6.2 Ordering data. See MIL-A-48078 (AR).

6.3 Submission of designs for approval. See 6.2.3 of MIL-A-48078 (AR). Submit equipment designs, as required, to Commander, AMCCOM, ATTN: AMSMC-QAT-I, Dover, NJ, 07801-5001.

6.4 Performance test summary.

6.4.1 Quality conformance test.

FUNCTIONING

Weapon	Cartridge	Charge	Fuze Setting	Quantity
60MM Mortar	60MM, WP, M302	0	SQ	44(a)
		0	Delay	5(b)
		4	SQ	44(a)
		4	Dealy	5(b)

(a) Quantity reduced to twenty-two (22) per test phase as required when employing special double sample.
(b) Results for information purposes only except for premature functionings. Charge zero quantity shall be TV conditioned prior to functioning test.

ARMING DELAY

Weapon	Cartridge	Charge	Fuze Setting	Quantity
60MM Mortar	M302 Inert	0	SQ	12

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

TRANSPORTATION VIBRATION

Weapon	Cartridge	Charge	Setting	Quantity
60MM Mortar	M302 WP	0	SQ	10

6.4.2 First article inspection test.

FUNCTIONING

Weapon	Cartridge	Charge	Setting	Quantity
60MM Mortar	M302 WP	0	SQ	62
		0	Delay	15(a)
		4	SQ	62
		4	Delay	15(a)

(a) Results for information only except for premature functioning. Five (5) fuzes of the charge zero quantity shall be TV conditioned prior to functioning test.

ARMING DELAY

Weapon	Cartridge	Charge	Setting	Quantity
60MM Mortar	M302 WP	0	SQ	12

TRANSPORTATION VIBRATION

Weapon	Cartridge	Charge	Setting	Quantity
60MM Mortar	M302 WP	0	SQ	10

6.5 Drawings. Drawings listed in Section 2 of this specification under the heading U.S. Army Armament Research, Development and Engineering Center (ARDEC) may also include drawings prepared by, and identified as, Edgewood Arsenal, Frankford Arsenal, Rock Island Arsenal or Picatinny Arsenal or ARRADCOM. Technical data originally prepared by these activities is now under the cognizance of ARDEC.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.

6.6 Subject term (key word) listing.

Booster cup assembly
Lead assembly
Leak test

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project No: 1390-A504)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:48Z
Check the source to verify that this is the current version before use.