INCH-POUND

MIL-S-63326 (AR)
AMENDMENT 5
17 APRIL 1989

SUPERSEDING
AMENDMENT 4
10 May 1988

MILITARY SPECIFICATION

SAFETY AND ARMING ASSEMBLIES
FOR
MINES: BLU 91/B AND BLU 92/B

This Amendment forms part of Military Specification MIL-P-63326(AR), dated 11 August 1981, and is approved for use within US Army Armament Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

2.1, Specification, Federal: Delete "QQ-S-465" and substitute "QQ-S-365".

PAGE 4

3.6.1, Under Temperature:

Delete "+70° + 10°F" and substitute "+70°F ± 10°F (Ambient)".
Delete "+140° + 5°F" and substitute "+145°F + 5°F".

3.6.2:

Delete "partucular" and substitute "particular".

Under Temperature:

Delete "+70° + 10°F" and substitute "Ambient".
Delete "+140° + 5°F" and substitute "+145°F + 5°F".

3.8: Delete "... than 0.015 ohm." and substitute "... than 0.15 ohm.".

PAGE 8

TABLE I: S&A Assembly and Components: Delete "Microminature" and substitute "Microminiature".

AMSC N/A

FSC 1345

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 11

TABLE I, S&A Assembly, Examination for Defects:
Delete "4.4.2.45(a)" and substitute "4.4.2.47(a)".

Note (a): Delete "4.4.2.41, 4.4.2.43, been performed" and substitute "4.4.2.41, 4.4.2.43 and 4.4.2.45 have been performed".

Note (b): Delete "70° ± 10°F" and substitute "Ambient".

PAGE 12

Note (a): Delete "4.4.2.42 and 4.4.2.41 been performed" and substitute "4.4.2.41, 4.4.2.42 and 4.4.2.44 have been performed".

Note (b): Delete "70° ± 10°F" and substitute "Ambient".

PAGE 16

4.4.2.2, Borerider:

Add the following Major Category:

"122, Chamfer on tines missing 0.40% 3.2 Visual".

PAGE 17

4.4.2.3, Spring Borerider:

Minor 201: Delete "3.10" and substitute "3.2".

PAGE 18

4.4.2.4, Interlock, Assembly:

* Major 101: Delete in its entirety.

Minor 201: Delete "3.2" and substitute "3.10".

PAGE 19

4.4.2.5, Pin, Interlock:

Minor 203: Delete in its entirety and substitute "Chamfers missing - 0.65% 3.2 Visual".

Source: https://assist.dla.mil -- Downloaded: 202640-23T02:39Z
Check the source to verify that this is the currentversion before use.

PAGE 21

4.4.2.7, Cup, Interlock:

* Add the following Major Category:

"109, Hardness test 0.40% 3.2 ASTM E-18"

Minor 203: Delete "3.2" and substitute "3.10".

PAGE 22

4.4.2.8, Slider Assembly:

* Major 102: Delete "Gage" and substitute "Visual".

* Major 103: Delete "Gage" and substitute "Visual".

Major 104: Delete in its entirety.

Major 106: After staked add "(-1 assy only)".

PAGE 23

4.4.2.9, Cup Slider:

Major 114: Delete "Depth of notch" and substitute "Length from notch to tabs".

PAGE 31

4.4.2.15, Flexible Cable Assembly:

Major 107: Delete "Gage" and substitute "Visual".

PAGE 32

4.4.2.16, Major 106: Delete "Gage" and substitute "Visual".

PAGE 33

4.4.2.17, Cable Flexible:

Major 107: Delete "Soldering poor or incorrect" and substitute "Solder coating poor or incorrect".

Add the following Major Category:

"115 Solderability 10-0-1 - 3.2 Visual".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 34

4.4.2.18, Clip Ground:

Note a: Delete "Accept D" and substitute "Accept 0".

PAGE 35

4.4.2.19, Actuator, Microminiature Piston:

Piston actuator function test: Delete "-60°" and substitute "-65°F".

Major 103: Delete "4.5.6.3" and substitute "4.5.3.3".

Major 104: Delete "4.5.6.3" and substitute "4.5.3.3".

Major 105: Delete "4.5.6.3" and substitute "4.5.3.3".

Major 106: Delete "4.5.6.1" and substitute "4.5.3.1".

Major 108: Delete "4.5.6.2" and substitute "4.5.3.2".

Minor 201: Delete "3.2" and substitute "3.10".

PAGE 36

4.4.2.20, MDF Assembly:

Major 107: Delete "4.5.8.2" and substitute "4.5.4.2".

Minor 201: Delete "3.2" and substitute "3.10".

PAGE 39

4.4.2.23, MDF, PBXN-5 Lead Sheathead:

Major 102: Delete "4.5.10" and substitute "4.5.6".

PAGE 40

4.4.2.24, Lower Housing Assembly:

Next Higher Assembly: Delete "9328693/9328743" and substitute "9328692/9328743".

Minor 201: Delete "3.2" and substitute "3.10".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 41

4.4.2.25, Housing, Lower, Sheet 1 of 4:

Major 106: Delete "(See E-E)" and substitute "(See G-G)".

Major 107: Delete "(See E-E)" and substitute "(See G-G)".

Number of sample units column: Delete "*".

NOTE: Delete in its entirety.

PAGE 42

4.4.2.25, Housing, Lower, Sheet 2 of 4:

Major 120: Delete in its entirety.

Major 121: Delete in its entirety.

Major 125: Add ", 2 places" after "hole".

Major 128: Add ", 2 places" after "hole".

Major 129: Add ", 2 places" after "hole".

Major 130: Delete "well" and substitute "wells (detonator and delay detonator).

Major 131: Add ", 2 places" after "hole".

Major 138: Delete "(a) - 3.2 4.5.4" and substitute "1/ - 3.2 4.5.1".

Add the following note:

"1/ Sampling and rejection shall be in accordance with MIL-T-12879".

PAGE 43

4.4.2.25, Housing, Lower, Sheet 3 of 4:

Note a: Delete in its entirety.

Source: https://assist.dla.mil -- Downloaded: 202610-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 44

4.4.2.25, Housing, Lower, Sheet 4 of 4:

Major 167: Delete in its entirety.

Add Major 175: "Location of interlock assembly notch 0.40% 3.2 Gage".

Add Major 176: "Width of interlock assembly notch 0.40% 3.2 Gage".

Minor 202: Delete in its entirety.

Minor 204: Delete "... notch incorrect" and substitute "... notch missing or incorrect".

PAGE 45

4.4.2.26, Upper Housing Assembly:

Minor 201: Delete "3.2" and substitute "3.10".

PAGE 46

4.4.2.27, Housing, Upper, Sheet 1 of 5:

Major 114: Delete "(Sec T-T, Sht. 3)" and substitute "(Sec T-T, Sht. 6)".

PAGE 47

4.4.2.27, Housing, Upper, Sheet 2 of 5:

Major 127: Delete "... cap counter bore, 2 places (Sht. 2)" and substitute "... cap flash hole, 2 places (Sht. 2)".

PAGE 48

4.4.2.27, Housing, Upper, Sheet 3 of 5:

Major 142: Delete "4.5.4" and substitute "4.5.1".

Major 143: Delete "(Sec S-3, Sht. 6)" and substitute "(Sec S-S, Sht. 6).

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

Major 144: Delete in its entirety.

Major 149: Delete "Distance ... section" and substitute "Distance from center of slider release pin cavity semicircular section to centerline of datum -A-".

PAGE 55

4.4.2.32, Pin, Shear Borerider:

Add the following Major Category:

"104, Head thickness, 0.40% 3.2 Gage".

PAGE 58

4.4.2.35, Cup, Centrifugal Lock:

Drawing Number: Delete "9328819" and substitute "9329819".

PAGE 59

4.4.2.36, MDF Spacer:

Major 102: Delete "Profile of side" and substitute "Profile incorrect".

Major 103: Delete in its entirety.

Major 104: Delete in its entirety.

PAGE 60

4.4.2.37, Spacer Actuator:

* Major 106: Delete "Diameter of cavity (Sec A-A)" and substitute "Depth of diameter located to DATUM A (Sec A-A)".

Minor 202: Delete "3.10" and substitute "3.2".

* Minor 203: Delete in its entirety.

PAGE 61

4.4.2.38, Shield:

Minor 201: Delete "Gage" and substitute "Visual".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 64

4.4.2.41, Safe & Arm Assembly (Prior to Assembling Borerider Shear Pin and Lock Plate):

Critical category:

Critical 1: Delete "1/" in its entirety.

Critical 2: Add "1/" after "binding".

Major category:

Major 102: Delete "... missing 0.40% 3.2 Visual/ Manual" and substitute "... missing 1/ 100% 3.2 Visual/Manual".

Notes:

Add the following note:

"1/ Major 102 shall be performed prior to critical 2".

PAGE 65

4.4.2.42, Safe & Arm Assembly:

Major 103: Delete "100%" and substitute "0.40%".

PAGE 66

4.4.2.43, Safe & Arm Assembly (Prior to Assembling Shield and Lock Plate).

Critical category: Delete "none defined" and add new Critical defect as follows:

"1 - Ball lock missing 100% 3.2 Gage".

Major 104: Delete "0.40%" and substitute "100%".

PAGE 67

4.4.2.44, Critical 1: Delete "Eyelet ground open circuit, detonator..." and substitute "Ground circuit open, detonator...".

PAGE 68

4.4.2.45, Critical 1: Delete "Eyelet ground open circuit, detonators..." and substitute "Ground circuit open, detonators..."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 69

4.4.2.46, Safe and Arm Assembly:

LAT of S&A ASSEMBLIES, NO. OF SAMPLE UNITS Column: Delete "*".

Transportation vibration, INSPECTION METHOD Column: Delete "4.5.15.3" and substitute "4.5.11.3".

Continuity - Resistance checks, REQUIREMENT Column: Delete "3.8" and substitute "3.2".

Arming, INSPECTION METHOD column: Delete "4.5.17" and substitute "4.5.13".

Main charge functioning: Add "2/" after "functioning".

SAMPLE SIZE Column: Add "1/" after "SIZE".

+70° + 5°F Column: Delete "+70° + 5°F" and substitute "AMBIENT".

PAGE 70

4.4.2.47, Safe & Arm Assembly:

LAT of S&A ASSEMBLIES, NO. OF SAMPLE UNITS Column: Delete "*".

Transportation vibration, INSPECTION METHOD Column: Delete "4.5.15.3" and substitute "4.5.11.3".

Continuity - Resistance checks, REQUIREMENT Column: Delete "3.8" and substitute "3.2".

Main charge functioning: Add "2/" after "functioning".

SAMPLE SIZE Column: Add "1/" after "SIZE".

+70° + 5°F Column: Delete "+70° + 5°F" and substitute "AMBIENT".

MDF functioning: Delete "4.5.14" and substitute "4.5.14.1".

Delay detonator, delay time: Delete "4.5.14" and substitute "4.5.14.2".

Main charge functioning: Delete "4.5.14" and substitute "4.5.14.2".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 73

4.5.9: Delete "Assemblies subjected to this test shall not be returned to the lot."

PAGE 74

* 4.5.14.2: Main charge lead explosive train functioning:

Delete "... The witness ring shall be 1-3/16 in I.D. x 1-1/2 in long x 3 in. O.D., cold drawn..." and substitute "... The witness ring shall be 1 3/16 in I.D. x 3/4 in long minimum x 2 1/2 in O.D. minimum, cold drawn...".

PAGE 75

4.5.18: Delete "4.5.18" and substitute "4.5.17".

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1345-A552)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.