NOTICE OF INACTIVATION FOR NEW DESIGN

NOT-MEASUREMENT SENSITIVE

MIL-DTL-11484/105D
NOTICE 1
20 January 1999

MILITARY SPECIFICATION

LAPEL BUTTON, AIR RESERVE FORCES MERITORIOUS SERVICE MEDAL

MIL-DTL-11484/105D, dated 27 September 1996, is inactive for new design and is no longer used, except for replacement purposes.

Custodians:
Army - IH
Air Force - 45

Preparing activity:
Army - IH

Review activities:
Air Force - 32, 82, 99
DLA - CT

AMSC N/A **FSC 8455**

DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T16:43Z
Check the source to verify that this is the current version before use.