INCH - POUND

MIL-F-20454D(AR)
18 December 1974
SUPERSEDING
MIL-F-20454C (AR)
3 May 1972

MILITARY SPECIFICATION

FUZE, TIME, M65A1
LOADING, ASSEMBLING AND PACKING

This specification is approved for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification covers the loading, assembling and packing for one type of fuze, designated as Fuze, Time, M65A1.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposal form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-P-223	- Powder, Black
MIL-P-663	- Powder, Fuze
MIL-P-12951	- Primer, Percussion, M39A1
MIL-P-46994	- Pellets, Boron Potassium Nitrate
MIL-A-48078	- Ammunition, Standard Quality Assurance Provisions, General Specification for

STANDARDS

MILITARY

MIL-STD-331	- Fuze and Fuze Components, Environmental and Performance Tests for
MIL-STD-1234	- Pyrotechnics: Sampling, Inspection and Testing

Beneficial comments, (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, U. S. ARDEC, ATTN: SMCAR-BAC-S, Picatinny Arsenal, New Jersey 07806-5000 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

AMSC/NA FSC: 1390

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

DRAWINGS

PICATINNY ARSENAL

9207568 - Fuze, Time, M65A1
9210427 - Container, Ammunition, Fiber, M322 for Fuze, Time M65A1
9210428 - Box, Packing, Ammunition, for Fuze, Time, M65A1

3. REQUIREMENTS

3.1 Material.-Materials shall be in accordance with the applicable drawings, standards and specifications.

3.2 Parts and Assemblies.-The parts and assemblies shall comply with all the requirements specified on drawing 9207568 and associated drawings and with all requirements specified in applicable specifications and standards.

3.3 Moisture Content

3.3.1 Ring Black Powder.-The moisture content of the ring black powder at the loading station at the time of loading the time train rings shall not exceed 0.70 percent.

3.3.2 Expelling Charge Black Powder.-The moisture content of expelling charge black powder at the loading station at the time of loading the charges into the fuze assemblies shall not exceed 0.70 percent.

3.4 Volatile Content of Boron Potassium Nitrate Pellets.-The volatile content of the Boron potassium pellets at the time of loading the charges into the fuze assemblies shall not exceed 0.75 percent.

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

3.5 Jolt and Jumble.–The fuze assemblies shall comply with the requirements of MIL-STD-331, tests 101.1 and 102.1.

3.6 Static Functioning and Uniformity of Burning Time.–The fuze assemblies shall function and shall burn between 11.86 and 12.66 seconds.

3.7 Proving Ground. (see 6.6)

3.7.1 Premature Burst.–There shall be no functioning of the fuze in the barrel of the mortar or within 200 yards horizontal range of the mortar.

3.7.2 Functioning and Uniformity of burning Time.–The fuze assemblies shall function and shall burn as specified in Table I.

TABLE I

Charge	Quadrant Elevation (degrees)	Burning Time (seconds)
2	68	11.68 - 13.18
4	45	11.80 - 13.30

3.8 Workmanship.–All parts and assemblies shall be loaded and assembled in a through, workmanlike manner, and all manufacturing, processing and assembling operations shall be correctly performed. The parts shall be free of burrs, sharp edges, cracks, dirt, grease, dust and other foreign matter. The cleaning method used shall not be injurious to any part, nor shall the parts be contaminated by the cleaning agent. All required markings shall be neat, legible and sharply defined.

3.9 First Article.–This specification makes provisions for a first article sample. Requirements for the delivery of a first article sample shall be as specified in the contract.

QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for Inspection and Standard Quality Assurance Provisions.–Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

4.2 Classification of Inspections.-The following types of inspection shall be conducted on this item:

a. First Article Inspection

b. Quality Conformance Inspection

4.3 First Article Inspection

4.3.1 Submission.-The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with the provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities indicated.

a. Twenty-five (25) each of the subassemblies depicted on drawings 9207556 and 9207554.

b. Sixty two (62) each loaded fuze assemblies.

c. Sixty (60) each loaded fuze assemblies (see 6.6)

The first article sample shall consist of parts and assemblies which have been produced by the contractor or furnished by a supplier, and which have been manufactured using the same production processes, procedures and equipment which will be used in fulfilling the contract. All parts and materials, including packaging and packing, shall be obtained from the same source of supply as will be used in regular production. Prior to submission, the contractor shall inspect the sample to the degree necessary to assure that it conforms to the requirements of the contract, and submit a record of this inspection with the sample, including statements of finding for materials, processes and tests. A sample containing known defects will not be submitted unless specifically authorized by the Contracting Officer. A first article sample, or portion thereof as directed by the Contracting Officer, shall also be submitted whenever there is a lapse in production for a period in excess of 90 days, or when a change occurs in manufacturing process, material used, drawing or specification such as to significantly effect product uniformity, as determined by the Government.

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

4.3.2 Inspection to be Performed.-The first article parts submitted in accordance with Paragraph 4.3.1 will be subjected by the Government to any or all of the applicable examinations and tests specified in 4.4.2 and 4.4.3 of this specification and to any or all of the requirement of the applicable drawings and specifications.

4.3.3 Rejection.-See MIL-A-48078

4.4 Quality Conformance Inspections

4.4.1 Inspection Lot Formation.-Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, inspection lots of M65A1 fuzes shall contain:

a. Percussion primers of one lot interfix number from one manufacturer.

b. Expelling charge black powder of one lot interfix number from one manufacturer.

c. Groove charge powder containing only one lot of fuze powder Type I from one manufacturer and slow burning black powder Type II from one lot from one manufacturer.

d. Metal parts of one lot interfix number from one manufacturer.

e. Pellet powder containing BKNO3 from one lot interfix number from one manufacturer.

4.4.2 Examination.-See MIL-A-48078

a. Sampling Plans.-Unless otherwise specified in the Classification Of Defects and Test Tables, sampling plans for Major and Minor Defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION
CLASSIFICATION OF DEFECTS AND TESTS

PARAGRAPH 4.4.2.1	TITLE Time Train Ring Assembly, Prior to Loading Powder Groove		SHEET OF 01 01		DRAWING NUMBER 9207554 / NEXT HIGHER ASSEMBLY 9207568
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined.				
MAJOR A 101	Moisture content of ring black powder	2 grams		3.3.1	4.5.3
MAJOR B 131	Powder groove not coated		0.40%	3.2	Visual
MINOR 201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION
CLASSIFICATION OF DEFECTS AND TESTS

PARAGRAPH 4.4.2.1	TITLE Time Train Ring Assembly, Prior to Loading Powder Groove		SHEET 01 OF 01		DRAWING NUMBER 9207554 / NEXT HIGHER ASSEMBLY 9207568
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL 0R 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined.				
MAJOR A 101	Moisture content of ring black powder	2 grams		3.3.1	4.5.3
MAJOR B 131	Powder groove not coated		0.40%	3.2	Visual
MINOR 201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:
7

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION
CLASSIFICATION OF DEFECTS AND TESTS

PARAGRAPH 4.4.2.3	TITLE Time Train Ring Assembly,		SHEET 01 OF 01		DRAWING NUMBER 9207554 / NEXT HIGHER ASSEMBLY 9207568
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined.				
MAJOR A					
101	Concentricity of undercut diameter with center hole diameter		0.40%	3.2	Gage
102	Pellet cracked, split or missing		0.40%	3.2	Visual
103	Stake or crimp missing in pellet cavity		0.40%	3.2	Visual
104	Vent closing disc punctured or missing		0.40%	3.2	Visual
105	Height of undercut		0.40%	3.2	Gage
MINOR					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION
CLASSIFICATION OF DEFECTS AND TESTS

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
4.4.2.4	**Body Assembly, Prior to Loading Expelling Charge**		01 01		9207556
					NEXT HIGHER ASSEMBLY 9207568
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL 0R 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined.				
MAJOR A					
101	Relay charge cover missing		0.40%	3.2	Visual
102	Moisture content of expelling charge black powder	2 grams		3.3.2	4.5.2
MAJOR B					
131	Excessive shellac on relay charge cover		0.40%	3.2	Visual
132	Shellac in relay charge hole		0.40%	3.2	Visual
MINOR					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

6

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION
CLASSIFICATION OF DEFECTS AND TESTS

PARAGRAPH 4.4.2.5	TITLE Body Assembly		SHEET 01 OF 01		DRAWING NUMBER 9207556
					NEXT HIGHER ASSEMBLY 9207556
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL 0R 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined.				
MAJOR A					
101	Primer missing or loose		0.40%	3.2	Visual/Manual
102	Primer flash hole obstructed or missing		0.40%	3.2	Visual
103	Expelling charge disc missing		0.40%	3.2	Visual
104	Expelling charge cover missing		0.40%	3.2	Visual
105	Expelling charge missing		0.40%	3.2	Visual/Manual
106	Body washer incorrectly positioned, loose or missing		0.40%	3.2	Visual/Manual
107	Weight of expelling charge	1 every 15 minutes		3.2	4.5.5
108	Volatile content on "E" pellet	2 grams		3.4	4.5.4
109	Body pellet split, cracked of missing		0.40%	3.2	Gage
MINOR					
201	Expelling charge retainer ring above flush		0.65%	3.2	Gage
202	Expelling charge retainer ring not staked		0.65%	3.2	Visual
203	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION
CLASSIFICATION OF DEFECTS AND TESTS

PARAGRAPH 4.4.2.6	TITLE Fuze, Time, M65A1		SHEET 01 OF 01		DRAWING NUMBER 9207568
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL					
1	Safety wire missing or broken		100%	3.2	Visual
SPECIAL					
A	Shear wire missing or broken		100%	3.2	Visual
MAJOR A					
101	Time train ring assembly missing		0.40%	3.2	Visual
MAJOR B					
131	Total length, maximum		0.40%	3.2	Gage
132	Shell threads damaged		0.40%	3.2	Visual
133	Head assembly loose		0.40%	3.2	Manual
MINOR					
201	Marking incomplete or incorrect		0.65%	3.2	Visual
202	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:
11

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION
CLASSIFICATION OF DEFECTS AND TESTS

PARAGRAPH 4.4.2.7	TITLE Fuze, Time, M65A1 Destructive Lot Acceptance Test		SHEET 01 OF 01		DRAWING NUMBER 9207568 NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL 0R 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined.				
1	Jolt Test and Jumble Test, MIL-STD-331, Test No. 101.1 and 102.1	12		3.5	4.5.1
2	Premature Burst	50		3.7.1	4.5.7.1.2
MAJOR A					
101	Static Functioning and Uniformity of burning time	50		3.6	4.5.6
102	Ballistic Functioning and Uniformity of burning times	50		3.7.2	4.5.7.1.2

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION
CLASSIFICATION OF DEFECTS AND TESTS

PARAGRAPH 4.4.2.8	TITLE Sealed Fiber Container		SHEET 01 OF 01		DRAWING NUMBER 9210427 NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL 0R 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined.				
MAJOR B					
131	Tape not in contact with container for full 360 degrees		0.40%	3.2	Visual
132	Container cut or damaged through all impregnated layers		0.40%	3.2	Visual/Manual
133	Metal end loose or distorted		0.40%	3.2	Visual/Manual
MINOR					
201	Contents loose		0.65%	3.2	Manual
202	Tear tab length excessively short		0.65%	3.2	Visual
203	Marking misleading or unidentifiable		0.65%	3,2	Visual
204	Tape color incorrect		0.65%	3.2	Visual
205	Cuts, scuffs, or gouges in outer layer		0.65%	3.2	Visual

NOTES:
13

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION
CLASSIFICATION OF DEFECTS AND TESTS

PARAGRAPH 4.4.2.9	TITLE Sealed Packing Box		SHEET 01 OF 01		DRAWING NUMBER 9210428 NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL 0R 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
CRITICAL	None defined.				
MAJOR B					
131	Box damaged to extent that contents are exposed or liable to become exposed		0.40%	3.2	Visual
132	Strapping missing, broken or loose		0.40%	3.2	Visual/Manual
133	Hardware missing, broken or loose		0.40%	3.2	Visual/Manual
MINOR					
201	Hardware or strapping improperly engaged or mislocated		0.65%	3.2	Visual
202	Car seal missing, unsealed or improperly positioned		0.65%	3.2	Visual
203	Contents loose		0.65%	3,2	Visual
204	Marking misleading or unidentifiable		0.65%	3.2	Visual/Manual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

4.4.3 Testing (see 6.6)

4.4.3.1 Proving Ground Tests

4.4.3.1.1 Beginning with the first lot produced and continuing until three consecutive lots have been found acceptable, a sample size of sixty (60) shall be randomly selected for this test. The lot shall be rejected if the requirements of 4.5.7.1.1 are not met.

4.4.3.1.2 After three consecutive lots have complied with the criteria specified in 4.4.3.1.1, the sample size shall be as specified in 4.4.2.7. The lot shall be rejected if the requirements of 4.5.7.1.2 are not met

4.4.4 Inspection Equipment.-The inspection equipment required to perform the examinations and tests prescribed herein is described in Paragraph Reference/ Inspection Method column in the tables starting with Paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and 6.3 herein.

4.5 Test Methods and Procedures

4.5.1 Jolt and Jumble Test.-The loaded fuze assemblies shall be subjected to the jolt test as specified in MIL-STD-331, Test 101.1. After completion of the jolt test, the fuzes shall not be disassembled but shall be subjected to the jumble test in accordance with MIL-STD-331, Test 102.1. The fuzes shall then be disassembled to determine compliance with the requirements of the test. As a minimum inspection requirement for Critical Defects, no pull wire shall be broken and no primer shall be initiated.

4.5.2 Moisture Content of Expelling Charge Black Powder.-A sample of two grams of black powder shall be selected from each sublot of powder used in each eight hours loading production for fuze assemblies. A composite sample shall not be used. If the moisture content of the sample exceeds 0.70 percent when tested as specified in MIL-P-223, and the loading has not started, that quantity of the material presented by the sample shall be rejected. If fuze assemblies have been loaded with material containing excessive moisture, the sublot together with all assemblies containing that sublot shall be rejected.

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

4.5.3 Moisture Content of Ring Black Powder.-A sample of two grams of black powder shall be selected from each sublot of powder used in each eight hours loading production for fuze assemblies. A composite sample shall not be used. If the moisture content of the sample exceeds 0.70 percent when tested as specified in MIL-P-663 and the loading has not started, that quantity of the material presented by the sample shall be rejected. If fuze assemblies have been loaded with material containing excessive moisture, the sublot together with all assemblies containing that sublot shall be rejected.

4.5.4 Volatile Content of Boron Potassium Nitrate Pellets.-A sample of two grams of boron potassium nitrate pellets shall be selected from the quantity of pellets used in each eight hours production of fuzes. If the volatile content of the sample exceeds 0.75 percent when tested in accordance with the procedure specified in Method 102.2.1 of MIL-STD-1234, the boron potassium nitrate pellets represented by the sample together with all assemblies containing these pellets shall be rejected.

4.5.5 Weight of Expelling Charge.-One fuze body shall be selected every fifteen (15) minutes during loading at the expelling charge loading station to verify meeting the applicable weight. If the weight of the black powder expelling charge in the sample selected does not meet the weight requirement, all fuze body assemblies loaded since the last 15 minute check shall be rejected. The rejected fuze body assemblies shall then be checked, weighed and black powder shall be added or removed from the fuze body assemblies so that they meet the expelling charge weight requirement.

4.5.6 Static Functioning and Uniformity of Burning Time.-the fuze assemblies just prior to the submission of this test shall be conditioned at 70^0 plus or minus 5^0 Fahrenheit for a minimum of six hours. The fuze assemblies shall be tested using static burning time fuze tester which can be read directly to at least the nearest 0.005 seconds. The torque applied to the test head adapters to seat the fuze ring shall not be greater than 610 inch pounds maximum or less than 590 inch pounds minimum. All static tests shall be conducted with the expelling charge present in the fuze assemblies. The lot shall be rejected if a total of two or more duds occur, or if the present defective for burning time as computed with the use of MIL-STD-414, Section B, Table B3, AQL of 1.5 percent exceeds the maximum allowable percent defective. The static burning times shall be corrected for barometric pressure (see 6.7).

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

4.5.7 Proving Ground (see 6.6)

4.5.7.1 The fuze assemblies shall be assembled to 60MM M83A1 Illuminating shells and conditioned prior to testing for a minimum of 24 hours at 70^0 plus a minimum 5^0 Fahrenheit. The assembled Cartridges shall be fired from a 60MM Mortar half at Charge 2 and the other half at Charge 4. All burning times shall be determined by infrared chronograph. All fuze burning times shall be reported to the nearest 0.01 seconds. When infrared chronograph times are lost in the ballistic acceptance test, no more than two stop watch times may be substituted for the lost chronograph times. The percent defective for burning times shall be computed with the use of MIL-STD-414, Section B, Table B3. The ballistic burning times shall be corrected for barometric pressure (see 6.7). The elevations for the mortar tube at Charge 2 shall be 68 degrees and at Charge 4 shall be 45 degrees. The proving ground shall include the mean and standard deviation for burning times in each charge zone in the ballistic acceptance summary reports.

4.5.7.1.1 Beginning with the first lot produced and continuing until three consecutive lots have been found acceptable the acceptance criteria shall be as follows:

Defect	Accept	Reject
Premature Burst	0	1
Duds	2	3
Percent defective at Charge 2	5.86	5.87
Percent defective at charge 4	5.86	5.87

4.5.7.1.2 After three consecutive lots have complied with the criteria specified in 4.5.7.1.1 the acceptance criteria shall be as follows.

Defect	Accept	Reject
Premature Burst	0	1
Duds	2	3
Percent defective at Charge 2	5.97	5.98
Percent defective at charge 4	5.97	5.98

If any production lot fails to meet the above dud criteria, testing shall revert to 4.5.7.1.1 until three consecutive lots have been accepted.

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

5. PREPARATION FOR DELIVERY

5.1 Preservation and Packaging

5.1.1 Level A.-The fuze assemblies shall be preserved and packaged as specified on drawing 9210427.

5.2 Packing

5.2.1 Level A.-the fiber container shall be packed as specified on drawing 9210428.

5.3 Marking. Marking shall be in accordance with drawings 9210427 and 9210428.

6. NOTES

6.1 Intended Use.-The parts and assemblies covered by this specification are intended for use on 60MM Illumination, M83A3 Cartridge.

6.2 Ordering Data.-See MIL-A-48078

6.3 Submission of Designs for Approval.-See MIL-A-48078. Submit equipment design, as required, to Commander, U.S. Army ARDEC, ATTN: SMCAR-QAT-B, Picatinny Arsenal, N. J. 07806-5000.

6.4 Submission of First Article Samples.-Instruction as to the location of the evaluation of the first article samples shall be obtained from the Contracting Officer. Upon receipt of such request, the Contracting Officer shall advise Picatinny Arsenal and instructions will be issued accordingly. All Inquiries shall be forwarded to: Commander, U.S. Army ARDEC, ATTN: SMCAR-QAT-B, Picatinny Arsenal, N. J. 07806-5000.

6.5 Check Test for Deterioration of Percussion Primer.-If the total elapsed time between the acceptance of any percussion primer lot and assembly of that lot into fuze lots exceeds two (2) years, or if the percussion primer have been subjected to adverse conditions, however brief, at any time since previous tests, the percussion primer lot shall be check-tested as specified in MIL-P-12951 immediately prior to assembly into fuzes. This test shall be conducted at Government expense without cost to the supplier who loaded the percussion primer or the supplier assembling the percussion primer into the fuze, and shall not constitute a basis for rejection against either supplier, except where deterioration has occurred as a direct result of carelessness in handling, storage, etc., while the percussion primer lot is under the jurisdiction of either contractor.

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

6.6 Deletion of Requirements.–The requirements of paragraphs 3.7, 4.3.1c, 4.4.3, 4.4.2.7, (Defects 2 and 102 only) and 4.5.7 are not applicable when the contractor for the M65A1 Time Fuze is also the contractor for the Cartridge, 60MM, Illuminating M83A3.

6.7 Barometric Correction for Static and Ballistic Fuze Burning Times.–All fuze assembly static and ballistic burning time values observed during acceptance testing shall be corrected to standard pressure conditions by use of the following formula:

$$TC = \frac{To\ (B)^{05}}{5.48}$$

where:

TC = Time of burning in seconds, corrected to standard pressure conditions (30 inches of Mercury)

To = Actual observed burning time in seconds

$B^{0.5}$ = Square root of barometric pressure in inches of mercury at the time of the static or ballistic acceptance test.

The corrected fuze burning times shall be reported in the Static Ballistic Acceptance Test Reports and shall be used to determine conformance to the requirements. In addition, the barometric pressure during the time of testing shall be reported on the official reports.

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

6.8 Proving Ground Summary

FIRST ARTICLE TEST

WEAPON	CARTRIDGE	ZONE	ELEVATION	NO. TESTED
60MM Mortar	M83A3 Illum	2	68 Degrees	30
		4	45 Degrees	30

ACCEPTANCE CRITERIA

Defect	Accept	Reject
Premature Burst	0	1
Duds	2	3
Percent defective at Charge 2	5.86	5.87
Percent defective at Charge 4	5.86	5.87

QUALITY CONFORMANCE TEST

FIRST THREE CONSECUTIVE ACCEPTABLE LOTS

WEAPON	CARTRIDGE	ZONE	ELEVATION	NO. TESTED
60MM Mortar	M83A3 Illum	2	68 Degrees	30
		4	45 Degrees	30

ACCEPTANCE CRITERIA

Defect	Accept	Reject
Premature Burst	0	1
Duds	2	3
Percent defective at Charge 2	5.86	5.87
Percent defective at Charge 4	5.86	5.87

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

SUBSEQUENT LOTS

WEAPON	CARTRIDGE	ZONE	ELEVATION	NO. TESTED
60MM Mortar	M83A3 Illum	2	68 Degrees	30
		4	45 Degrees	30

ACCEPTANCE CRITERIA

Defect	Accept	Reject
Premature Burst	0	1
Duds	2	3
Percent defective at Charge 2	5.97	5.98
Percent defective at Charge 4	5.97	5.98

Custodian:
ARMY-AR

Preparing Activity:
ARMY-AR

Project Number: 1390-A-069

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS

1. The preparing activity must complete blocks 1, 2, 3, and 8. In block 1, both the document number and revision letter should be given.
2. The submitter of this form must complete blocks 4, 5, 6, and 7.
3. The preparing activity must provide a reply within 30 days from receipt of the form.

NOTE: This form may not be used to request copies of documents, nor to request waivers, or clarification of requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

I RECOMMEND A CHANGE:	1. DOCUMENT NUMBER	2. DOCUMENT DATE (YYMMDD)
	MIL-F-20454D(AR)	18 DECEMBER 1974

3. DOCUMENT TITLE: FUZE, TIME, M65A1 LOADING, ASSEMBLING AND PACKING

4. NATURE OF CHANGE *(Identify paragraph number and include proposed rewrite, if possible. Attach extra sheets if needed.)*

5. REASON FOR RECOMMENDATION

6. SUBMITTER

a. NAME (Last, First, Middle Initial)	b. ORGANIZATION	
c. ADDRESS (Include Zip Code)	d. TELEPHONE (Include Area Code) (1) Commercial (2) AUTOVON (If applicable)	7. DATE SUBMITTED (YYMMDD)

8. PREPARING ACTIVITY

a. NAME	b. TELEPHONE (Include Area Code)	
U.S ARMY ARDEC STANDARDIZATION OFFICE	(1) Commercial 201-724-6671	(2) AUTOVON DSN-880-6671
c. ADDRESS (Include Zip Code) ATTN: SMACA-BAC-S PICATINNY ARSENAL, NJ 07806-5000	IF YOU DO NOT RECEIVE A REPLY WITHIN 45 DAYS, CONTACT: Defense Quality and Standardization Office 5203 Leesburg Pike, Suite 1403, Falls Church, VA 22041-3466 Telephone (703) 756-2340 AUTOVON 289-2340	

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T07:51Z
Check the source to verify that this is the current version before use.