MILITARY SPECIFICATION

Impregnation of Metal Castings

Page 6

Delete from paragraph 4.4.4.5 at line 4: "Diffusion rate in cubic feet per square inch per hour =.

Add the following to paragraph 4.4.4.5 at line 4: "Diffusion rate in cubic feet per square inch per hour =

$$\frac{7.9V(R_2-R_1)}{A} \times 10^{-5}$$

Custodians:
Army - MR
Navy - SH
Air Force - 11

/AREA MFFP/

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T02:29Z
Check the source to verify that this is the current version before use.