WITHDRAWAL OF ADOPTION NOTICE

The Department of Defense has determined it no longer has an interest in ANSI-Z1.1,1.2,1.3, "Guide for Quality Control Charts, Control Chart Method of Analyzing Data, Control Chart of Method of Controlling Quality During Production", and is hereby withdrawing its adoption of this document as of 03 June 2009.

Custodians:
Army - AR
Air Force - 05
DLA - DH

Adopting Activity:
Army - AR

Reviewer Activities:
Army - CR

NOTE: The activities above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at http://assist.daps.dla.mil.

AREA QCIC

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T15:04Z
Check the source to verify that this is the current version before use.