MILITARY SPECIFICATION

PROJECTILE, 155MM, TEST, NON-HAZ, M718/M741 TYPES LOADING, ASSEMBLING AND PACKING OF

This specification is approved for use by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification contains requirements not normally covered by the drawings and provides quality assurance provisions for the fabrication of parts, assembly, and packing for the Projectile, 155MM, Test, Non-Haz, M718/M741 Types.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposals, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-A-48078	Ammunition, Standard Quality Assurance Provisions, General Specifications for
MIL-P-48749	Projectile, 155MM, HE, M483A1, Loading, Assembling, and Packing
MIL-P-63238	Projectile, 155MM, AT M718/M741 Loading, Assembling and Packing
MIL-S-45743	Soldering, Manual Type, High Reliability Electrical and Electronic Equipment.

FSC: 1320

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

STANDARDS

MILITARY

MIL-STD-105	Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-453	Inspection, Radiographic
MIL-STD-1235	Single and Multi-Level Continuous Sampling Procedures and Tables for Inspection by Attributes

DRAWINGS

ARMAMENT RESEARCH AND DEVELOPMENT COMMAND

9277852	Projectile, 155MM, AT, M718
9278014	Projectile, 155MM, AT, M741
9317597	Projectile, 155MM Test, Non-Haz, M718 Type
9317598	Projectile, 155MM Test, Non-Haz, M741 Type
8837839	Pallet, Projectile, 155MM, HE and GB, Hollow Base Type
9317605	Mine, Test, Non-Haz (M718)
9317608	Mine, Test, Non-Haz (M741)

(Copies of specifications, standards, drawings and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the Contracting Officer).

2.2 Other publications. The following documents form a part of this specification to the extent specified herein. Unless otherwise indicated, the issue in effect on the date of invitation for bids or request for proposal shall apply.

Code of Federal Regulations, Title 49 - Transportation Parts 100-199

ASTM Destignation D792 - "Specific Gravity and Density of Plastics by Displacement, Method A-1.

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:27Z
Check the source to verify that this is the current version before use.

(The Code of Federal Regulations is available from the Superintendent of Documents, US Government Printing Office, Washington, DC 20402. Orders should specify "49 CFR 100-199 (latest revision)". American Society for Testing and Material (ASTM) Standards for test methods are generally available in reference libraries. They are also distributed among technical groups and certain federal agencies).

3. REQUIREMENTS

3.1 Material. Materials shall be in accordance with the applicable drawings and specifications.

3.2 Projectile. The projectile assembly, mines, and components shall comply with all requirements specified on drawings 9317597 and 9317598, all associated drawings, and with all requirements of the applicable specifications.

3.3 S&A assembly. The S&A assembly (9317620) shall be in the full safe condition and have all safety features in the proper position as evidenced by the following:

a. Both centrifugal locks overlapping the slider.

b. G-weight and ball bearing in the safe position.

c. G-weight lock engaged.

d. Set-back pin engaged.

The firing pin of the S&A shall not extend more than .093 inch beyond the housing. There shall be no main output leads or M5 propellant present and there shall be evidence of the length of solder in the dummy center lead. There shall be no damage to the MDF; i.e. no cracks in the lead sheathing, or neck down (reduction in diameter) below 75% of the original diameter, anywhere along the length of the MDF.

3.4 Soldering of the flexprint to the electronic assembly terminals. Soldering of the terminals shall comply with MIL-S-45743.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

3.5 M-S plate to electronic assembly interface. The M-S plate shall mate with the cover flange of the electronic assembly around the entire circumference. Gaps shall not exceed .010 inch under hand pressure.

3.6 Non-hazardous mine S&A and explosive loading verification. The color coded non-hazardous mine shall show evidence of the S&A assembly in the full safe condition as evidenced by the following:

a. Both centrifugal locks overlapping the slider.

b. G-weight and ball bearing in the safe position.

The color coded non-hazardous mine shall also show evidence of proper explosive loading as evidenced by the following:

a. Length of solder in the S&A dummy center lead.

b. Lead shot in the booster simulant and main charge simulant.

3.7 Controls on the use of adhesives. The contractor shall develop a documented operational procedure for utilization of raw materials and processes to be used, details associated with intended use, such as proper handling, dispensing, mixing, curing cycles, pot life, etc., cleaning agents, safety precautions, special ventilation, drying or other processes, and any other information of a similar nature that is considered necessary for the particular adhesive in use. This procedure shall be updated whenever a change is made such that the original assurance of product quality is not affected. Submission of this procedure shall be in accordance with Data Item Description DI-T-5372 (Tailored)

3.8 Documentation of plan for safety in handling and processing of munitions. Prior to loading, the contractor shall document a detailed plan of the procedures to be employed during handling of the munition. This documentation shall describe, as a minimum, the procedures to be employed to assure that:

(1) The various types of electronic assemblies and mines shall remain segregated at all times.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

(2) Markings on electronic assemblies, mine assemblies, and projectiles are consistent, and handling of the items shall be controlled to prevent intermixing.

(3) The temperature of the electronic assemblies, mines, or projectile does not exceed 165°F at any time during processing or storage, and the time at 165°F shall not exceed one (1) hour. In no case shall continuous storage of the items be at a temperature above 100°F for a period exceeding 30 days.

(4) High explosive (HE) munition items shall remain segregated from non-hazardous munitions at all times, and identification of HE & non-hazardous munitions shall be strictly maintained.

Submission of the plan shall be in accordance with Data Item Description DI-T-5372 (Tailored).

3.9 Data requirements. The contractor shall generate data in accordance with the requirements of the data item descriptions cited in paragraph 6.8.

3.10 First article inspection. This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

3.11 Workmanship. All parts and assemblies shall be fabricated, loaded and assembled in a thorough workmanlike manner. They shall be free of burrs, sharp edges, cracks, dirt, grease, rust, and other foreign matter that may impair proper functioning. The cleaning method used shall not be injurious to any part, nor shall the parts be contaminated by the cleaning agents. All required marking and stamping shall be neat and sharply defined.

Inert boosters and main charges may contain surface defects. Breakage on outside edge of inert main charge, not exceeding 1/4 sq. inch in area, and/or 1/4 inch in depth, and not exceeding four (4) per side, is acceptable.

4. QUALITY ASSURANCE PROVISIONS

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:27Z
Check the source to verify that this is the current version before use.

4.1 Responsibility for inspection and standard quality assurance provisions. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of inspections. The following types of inspection shall be conducted on this item:

a. First Article Inspection

b. Quality Conformance Inspection

4.3 First article inspection. (Ref. MIL-P-63238)

4.3.1 Submission. The contractor shall submit a first article sample, as designated by the Contracting Officer, for evaluation in accordance with the provisions of para. 4.3.2. The first article sample shall consist of the following items in the sample quantities indicated.

Part Description	Drawing	Quantity
Booster, Simulant	9277763	5
Main Charge, Simulant	9277743	5
*Projectile, 155MM, Test, Non-Haz, M718 Type (see 6.4)	9317597	6

*See MIL-P-63238

4.3.2 Inspections to be performed. The first article parts submitted in accordance with paragraph 4.3.1, will be subjected by the Government to any or all the requirements of the applicable drawings, and to the inspections and tests of Table 1. The projectiles shall be forwarded to a Government Proving Ground designated by the Contracting Officer for the ballistic functioning test.

4.3.3 Rejection. See MIL-A-48078

The first article sample shall be rejected if any assembly or projectile fails to comply with any of the examinations or tests specified in this specification, or any of the requirements of the

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

applicable drawing. In addition, the first article sample shall be rejected if the ballistic test results reveal any one of the defects listed in MIL-P-63238.

In the event of rejection, the Government reserves the right to require the contractor to take corrective action and submit a new first article quantity. Until the first article quantity is accepted, the contractor is not to proceed with regular production unless otherwise directed by the Contracting Officer.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

TABLE I: FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
	Projectile, 155MM, Test, Non-Haz, M718/M741 Type		9317597/9317598
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Booster Simulant (Dwg. 9277763)				
	Examination for defects	5		3.2	4.4.2.5
	Main Charge, Simulant (Dwg. 9277743)				
	Examination for defects	5		3.2	4.4.2.6
	Projectile, 155MM, Test, Non-Haz, M718 (Dwg. 9317597)				
	Examination for defects *	6		3.2	4.4.2.17
	Radiographic examination	6		3.6	4.5.5
	Ballistic tests	6			MIL-P-63238

NOTES:

* All applicable paragraphs for mine and projectile assembly apply.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection

4.4.1 Inspection lot formation. Projectiles specified herein are non-hazardous test projectiles containing representative parts of M718/M741 HE projectiles. Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, inspection lots of projectiles shall contain:

a. Projectile metal parts assemblies of one lot interfix number from one manufacturer and drawn from as accepted lot of representative parts used in the assembly of one lot of HE projectiles (per MIL-P-63238).

b. Charge assembly propellant from one lot interfix number only.

c. Projectiles of one model designation only.

d. Non-hazardous S&A's from one lot interfix number from one manufacturer and bearing the same manufacturers identification symbol, year and month code and lot sequence number as the S&A lot used in one lot of HE projectiles (per MIL-P-63238).

e. Electronic Assy's from one lot interfix number from one manufacturer and drawn from an accepted lot of representative parts used in the assembly of one lot of HE projectiles (per MIL-P-63238).

Maximum lot size shall be no more than one (1) month production. (30 calender day period)

The non-hazardous test projectiles shall be identified with a different lot interfix number, however, the manufacturers identification symbol, year and month code and lot sequence number shall be the same as the lot of HE projectiles which the test rounds represent.

4.4.2 Examination. See MIL-A-48078.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Test Tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105 Inspection Level II. Equivalent continuous sampling plans in accordance with MIL-STD-1235 may be utilized. The choice of the plan shall be subject to approval from the procuring activity. In any case, inspection for critical defects shall be maintained at 100%.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.1	S&A Assembly				9317620
					NEXT HIGHER ASSEMBLY
					9317605/9317608
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Safety features improperly positioned		100%	3.3	X-ray 4.5.1
2	Clearing charge propellant not removed		100%	3.3	Visual
3	Main charge leads not removed		100%	3.3	Visual
4	Center lead not inert slug (no evidence of solder in slug)		100%	3.3	Visual/X-ray
Major					
101	MDF Damaged		100%	3.3	Visual/x-ray
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES: 1. Data Item Description DI-R-1721 applies - report required when critical defects are found. Immediate notification of technical agency required for critical defects.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.2	Electronic and Primer Assembly (M718)	1 OF 1	9277881-1, -2
			NEXT HIGHER ASSEMBLY: 9317605

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Primer missing or improperly installed (improper color showing)		100%	3.2	Visual
102	Bushing missing or improperly installed		100%	3.2	Visual
103	Adhesive present on primer		100%	3.2	Visual
104	Height to top of primer		0.40%	3.2	Gage/Note 1
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:
1. Gage shall not damage primer surface or apply unnecessary pressure.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.3	Electronic and Primer Assembly (M741)				9278012-1, -2
					NEXT HIGHER ASSEMBLY
					9317608
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Primer missing or improperly installed (improper color showing)		100%	3.2	Visual
102	Bushing missing or improperly installed		100%	3.2	Visual
103	Adhesive present on primer		100%	3.2	Visual
104	Height to top of primer		0.40%	3.2	Gage/Note 1
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

1. Gage shall not damage primer surface or apply unnecessary pressure.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.4	Battery Check and Insulator Test Point Installation				9317592
					NEXT HIGHER ASSEMBLY
					9317605/9317608
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Battery cell(s) active (See note 1)		100%	3.2	See Dwg. 9317592
102	Test points not resealed		100%	3.2	Visual
103	Test point insulator missing		100%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES: 1. Data Item Description DI-R-1721 applies for this defect. Submission of the report shall be whenever defects are found. Immediately notify technical agency.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.5	Booster Simulant	1 OF 1	9277763
			NEXT HIGHER ASSEMBLY: 9317605/9317608

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter	See 4.4.3.6		3.2	Gage
102	Inside diameter	See 4.4.3.6		3.2	Gage
103	True position ID to OD	See 4.4.3.6		3.2	Gage
104	Length	See 4.4.3.6		3.2	Gage
105	Material				Certification
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.6	Main Charge Simulant				9277743
					NEXT HIGHER ASSEMBLY 9317605/9317608
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter	See 4.4.3.6		3.2	Gage
102	Inside diameter	See 4.4.3.6		3.2	Gage
103	True position OD to ID	See 4.4.3.6		3.2	Gage
104	Spherical Radius two sides	See 4.4.3.6		3.2	Gage
105	Length	See 4.4.3.6		3.2	Gage
106	Thickness	See 4.4.3.6		3.2	Gage
107	Material				Certification
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER 9317608
4.4.2.7	Mine, Test, Non-Haz (during assembly) (M741)				NEXT HIGHER ASSEMBLY 9317598
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	S&A shield over detonators missing, or damaged		100%	3.2	Visual
2	S&A firing pin in partially or fully armed position (See note 1)		100%	3.3	Gage
3	Incorrect electronic assembly part number for the mine identified as M741		100%	3.8	Visual
4	Test, Non-Haz Mine not identifiable prior to loading		100%	3.8	Visual
5	Booster and/or main charge not inert		100%	3.2	Visual
Major					
101	Flex cable twisted or improperly soldered (Ref. note 2 of dwg. prior to potting)		0.40%	3.2/3.4	Visual
102	S&A firing pin tip not visible above S&A housing, or evidence of tip damage		0.40%	3.2	Visual
103	Damage to MDF		0.40%	3.2	Visual

NOTES:
1. Firing pin extends more than .093 inch beyond housing. Gaging technique shall not touch firing pin tip if below the maximum extension.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 9317608
4.4.2.7 (cont)	Mine, Test, Non-Haz (during assembly) (M741)				NEXT HIGHER ASSEMBLY 9317598
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major					
104	Detonator resistance improper (after soldering to electronic assy)		100%	3.2	Ohmmeter (Note 2)
105	Potting missing or improperly applied		0.40%	3.2	Visual
106	Insulator missing		100%	3.2	Visual
107	Clearing charge cup with collar improperly assembled (Ref note 2 of dwg.)		0.40%	3.2	Visual
108	Plate not seated on cover flange (360° around)		0.40%	3.5	Visual/Gage
109	O-ring missing (ref note 2 of dwg)		100%	3.5	Visual
110	Adhesives improperly applied (See note 2 of dwg)	See 4.4.3.1		3.2/3.7	Visual
111	Plate missing (See note 2 of dwg)		0.40%	3.2	Visual
112	Impact lens or cover missing (See note 2 of dwg)		0.40%	3.2	Visual
113	Retaining ring not flush or below flush Note 2)		0.40%	3.2	Visual/Gage
114	Mine pre-load/retaining ring torque improper	See 4.4.3.2		3.2	4.5.2
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES: 2. Less than one (1) milliampere current to be applied to detonators.
3. Data Item Description DI-R-1721 applies to the critical defects, supply report whenever defects are found. Immediate notification of technical agency required for critical defects.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
4.4.2.8	Mine, Test, Non-Haz (during assembly) (M718)				9317605
					NEXT HIGHER ASSEMBLY 9277852
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	S&A shield over detonators missing, or damaged		100%	3.2	Visual
2	S&A firing pin in partially or fully armed position (See note 1)		100%	3.3	Gage
3	Incorrect electronic assembly part number for the mine identified as M718		100%	3.8	Visual
4	Test, Non-Haz, Mine not identifiable prior to loading		100%	3.8	Visual
5	Booster and/or main charge not inert		100%	3.2	Visual
Major					
101	Flex cable twisted or improperly soldered (ref Note 2 of Dwg, prior to potting)		0.40%	3.2/3.4	Visual
102	S&A firing pin tip not visible above S&A housing, or evidence of tip damage		0.40%	3.2	Visual
103	Damage to MDF		0.40%	3.3	Visual

NOTES: 1. Firing pin extending .093 inch beyond housing. Gaging technique shall not touch firing pin tip if below the maximum extension.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.4.2.8	Mine, Test, Non-Haz (during assembly) (M718)				9317605
					NEXT HIGHER ASSEMBLY 9277852
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major					
104	Detonator resistance improper (after soldering to electronic assy)		100%	3.2	Ohmmeter (Note 2)
105	Potting missing or improperly applied		0.40%	3.2	Visual
106	Insulator missing		100%	3.2	Visual
107	Clearing charge cup with collar improperly assembled (Ref note 2 of dwg.)		0.40%	3.2	Visual
108	Plate not seated on cover flange (360° around)		100%	3.5	Visual/Gage
109	O-ring missing (ref note 2 of dwg)		100%	3.2	Visual
110	Adhesives improperly applied (See note 2 of dwg)	See 4.4.3.1		3.2/3.7	Visual
111	Plate missing (See note 2 of dwg)		0.40%	3.2	Visual
112	Impact lens or cover missing (See note 2 of dwg)		0.40%	3.2	Visual
113	Retaining ring not flush or below flush (Note 2)		0.40%	3.2	Visual
114	Mine pre-load/retaining ring torque improper	See 4.4.3.2		3.2	4.5.2
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES: 2. Less than one (1) milliampere current to be applied to detonators.
3. Data item description DI-R-1721 applies to the critical defects; submit whenever defects are found. Immediate notification of technical agency required for critical defects.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.9	Projectile, 155MM, M718/M741 Metal Parts (Prior to Loading Mines)	1 OF 1	9282848
			NEXT HIGHER ASSEMBLY: 9277852/9317598

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Rust or foreign matter on projectile interior walls, threads, or base end		0.40%	3.2	Visual
102	Threads damaged on projectile ogive or base ends		0.40%	3.2	Visual
103	Base threads damaged		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH 4.4.2.10	TITLE Projectile, 155MM, Test, Non-Haz, M741 Type (Prior to Inserting Mines into Projectile)		SHEET 1 OF 1		DRAWING NUMBER 9317598 NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Incorrect (M718 Non-Haz) or unidentified mine(s) to be assembled into projectile designated M741, or projectile not identified (note 1)		100%	3.8	Visual
2	HE mine to be assembled into projectile		100%	3.8	Visual
3	Correlation of mine color code and explosive loading of mine		100%	3.6	Visual/x-ray 4.5.5
Major					
101	Key or any spherical pad missing from any mine		100%	3.2	Visual
102	Pusher plate missing		100%	3.2	Visual
103	Improper number of -1 and -2 mines		100%	3.2	Visual
104	Keyway Mark missing or improperly located		100%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES: 1. Data Item Description DI-R-1721 applies for the critical defects. Submission of report shall be whenever defects are found. Immediate notification of technical agency required for critical defects.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.11	Projectile, 155MM, Test, Non-Haz M741 Type (After Inserting Mines & Prior to assembling base)	1 OF 1	9317598
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Mine stack preload improper	See 4.4.3.3		3.2	4.5.2
102	Shim thickness improper	See 4.4.3.3		3.2	Gage
103	Evidence of grease on base or projectile threads		0.40%	3.2	Visual
104	Sealant missing from base threads		0.40%	3.2	Visual
105	Base O-ring missing		0.40%	3.2	Visual
Minor	None defined				

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.12	Projectile, 155MM, Test, Non-Haz, M741 Type (Prior to assembling lifting plug)	1 OF 1	9317598
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Base improperly torqued	See 4.4.3.4	100%	3.2	4.5.2
102	Gap between body and base improper		100%	3.2	Gage
103	Expulsion charge assembly missing, damaged, or cup improperly staked		100%	3.2	Visual/Manual
104	Air test	See note 1	100%	3.2	Air Tester/4.5.3
105	Fuze thread in ogive damaged, incomplete or contains foreign matter		100%	3.2	Visual
106	Projectile zone weight incorrect		100%	3.2	Scale
107	Zone stenciling or zone punch mark incorrect or inadequate		100%	3.2	Visual
108	Explusion charge assembly not accepted	See 4.4.3.7			Ammo Data Card
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES: 1. 100% test. Verify production test or sample following 100% production test to MIL-STD-105 level II. Reject lot if one (1) defective found. Use approved equipment.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
4.4.2.13	Projectile, 155MM, Test, Non-Haz, M741 Type				9317598
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Nomenclature on body, letter in triangle and stamped number on base not consistent		100%	3.2	Visual
2	"M" missing from body		100%	3.2	Visual
Major					
101	Grease missing from lifting plug threads (prior to installing)		0.40%	3.2	Visual
102	Lifting plug improper		0.40%	3.2	Visual
103	Lifting plug torque improper	See 4.4.3.5		3.2	Torquewrench
104	Lifting plug gasket missing		0.40%	3.2	Visual
105	Max. diameter forward of grommet improper (Applicable after retouching paint)		100%	3.2	Gage
106	Stamped letter "A" missing from base		100%	3.2	Visual
107	Rotating band damaged (Applicable if grommet has been removed		0.40%	3.2	Visual
108	Obturator missing or damaged (Applicable if grommet has been removed)		0.40%	3.2	Visual

NOTES: 1. Data item description DI-R-1721 applies for all critical defects. Submission of the report shall be whenever defects are found. Immediate notification of technical agency required for critical defects.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.4.2.13 (cont)	Projectile, 155MM, Test, Non-Haz, M741 Type				9317598
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Protective coating with a total of bare areas in excess of 1/4 inch		0.65%	3.2	Visual
202	Marking missing or unidentifiable (Other than critical defect 1 above)		0.65%	3.2	Visual
203	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.14	Projectile, 155MM, Test, Non-Haz, M718 Type (Prior to inserting mines into projectile)	1 OF 1	9317597
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Incorrect (M741 Non-Haz) or unidentified mine(s) to be assembled into projectile		100%	3.8	Visual
2	HE mine to be assembled into projectile		100%	3.8	Visual
3	Correlation of mine color code and explosive loadingof mine		100%	3.6	Visual/x-ray 4.5.5
Major					
101	Key or any spherical pad missing from any mine		100%	3.2	Visual
102	Pusher plate missing		100%	3.2	Visual
103	Proper number of -1 and -2 mines		100%	3.2	Visual
104	Keyway Mark missing or improperly located		100%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES: Data Item Description DI-R-1721 applies for critical defects. Submit report whenever defects are found. Immediate notification of technical agency required for critical defects.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.15	Projectile, 155MM, Test, Non-Haz, M718 Type (After inserting Mines & Prior to assembling base)				9317597
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Mine stack preload improper	See 4.4.3.3		3.2	4.5.2
102	Shim thickness improper	See 4.4.3.3		3.2	Gage
103	Evidence of grease on body or base threads		0.40%	3.2	Visual
104	Adhesive missing from base threads		0.40%	3.2	Visual
105	Base O-ring missing		0.40%	3.2	Visual
Minor	None defined				

NOTES:

DRDAR-QA For 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.16	Projectile, 155MM, Test, Non-Haz, M718 Type (Prior to assembling lifting plug)	1 OF 1	9317597
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Base improperly torqued	See 4.4.3.4	100%	3.2	4.5.2
102	Gap between body and base improper		100%	3.2	Gage
103	Expulsion charge assembly missing, damaged, or cup improperly staked		100%	3.2	Visual/Manual
104	Air test	See note 1	100%	3.2	Air Tester/4.5.3
105	Fuze thread in ogive damaged, incomplete or containing foreign matter.		100%	3.2	Visual
106	Projectile zone weight incorrect		100%	3.2	Scale
107	Zone stenciling and/or zone punch marks incorrect or inadequate		100%	3.2	Visual
108	Expulsion charge assembly not accepted	See 4.4.3.7			Ammo Data Card
Minor					
201	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES: 1. 100% test. Verify production test or sample following 100% production test to MIL-STD-105 level II. Reject lot if one (1) defective found. Use approved equipment.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
4.4.2.17	Projectile, 155MM, Test, Non-Haz, M718 Type				9317597
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Nomenclature on body, letter in triangle and stamped number on base not consistent		100%	3.2	Visual
2	"M" missing from body		100%	3.2	Visual
Major					
101	Grease missing from lifting plug threads (prior to installing)		0.40%	3.2	Visual
102	Lifting plug improper		0.40%	3.2	Visual
103	Lifting plug torque improper	See 4.4.3.5		3.2	Torque wrench
104	Lifting plug gasket missing		0.40%	3.2	Visual
105	Max. diameter forward of grommet improper (Applicable after retouching paint)		100%	3.2	Gage
106	Stamped letter "A" missing from base		100%	3.2	Visual
107	Rotating band damaged (Applicable if grommet has been removed		0.40%	3.2	Visual
108	Obturator missing or damaged (Applicable if grommet has been removed)		0.40%	3.2	Visual

NOTES: 1. Data item description DI-R-1721 applies for all critical defects. Submission of the report shall be whenever defects are found. Immediate notification of technical agency required for critical defects.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.4.2.17	Projectile, 155MM, Test, Non-Haz, M718 Type				9317597
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Protective coating with a total of bare areas in excess of 1/4 inch		0.65%	3.2	Visual
202	Marking missing or unidentifiable (Other than critical defect 1 above)		0.65%	3.2	Visual
203	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-63430(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.18	Pallet (loaded)				8837839
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Projectile lifting plug missing		0.40%	3.2	Visual
102	Projectile grommet assembly missing, damaged, or improperly assembled		0.40%	3.2	Visual
103	Board broken or split		0.40%	3.2	Visual
104	Projectile(s) of different zones on the same pallet		0.40%	3.2	Visual
105	DOT symbol missing or unidentifiable		0.40%	3.2	Visual
Minor					
201	Strap width incorrect		0.65%	3.2	Visual/gage
202	Strapping improperly assembled		0.65%	3.2	Visual
203	Marking missing, incorrect or unidentifiable		0.65%	3.2	Visual

NOTES:

DRDAR-QA Form 360 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

4.4.3 Testing. Testing is described in the First Article and Quality Conformance Inspection Tables.

4.4.3.1 Adhesive application. At the start of each days production, and after each four (4) hours during production, and at the end of each shift, a verification of proper adhesive application shall be made, following the procedure generated by the contractor (see 3.7). The procedure shall assure that the proper amount of adhesive has been and is being dispensed and properly applied. The method shall assure that adhesive is not migrating to the S&A assembly. Additionally, all other process controls delineated in para. 3.7 shall be verified, at least once each shift. Evidence of inadequate adhesive or migration of adhesive to the S&A during any of the verification checks shall result in rejection of that quantity of mines assembled since the last acceptable check. If the adhesive application does not comply with all requirements at the start of production the Contractor shall not proceed with production until corrective action has been taken and all requirements met.

4.4.3.2 Mine preload and retaining ring torque. At the start of assembly of each group of the non-hazardous test mines and at the completion of the assembly of each group or end of shift, the mine preload and retaining ring torque shall be verified. The contractor shall supply for approval, a plan detailing the method to be used to verify these forces (see 6.6). The contractor shall not proceed with assembly until verification is achieved. Failure of last unit in the group or at the end of the shift shall result in 100% screening of all units in the group produced since the initial acceptance.

4.4.3.3 Mine stack preload and shim thickness measurement. At the start of assembly of each group of non-hazardous test projectiles and at the completion of the assembly of each group or end of shift, the mine stack preload force and shim thickness measurements shall be verified. The contractor shall supply, for approval, a plan detailing the methods to be used to verify these requirements (see 6.6). The contractor shall not proceed with assembly until verification is achieved. Failure of the last unit in the group or at the end of the shift shall result in 100% screening of all projectiles in the group produced since the initial acceptance.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

4.4.3.4 Base torque. The contractor shall supply for approval, a plan detailing the method to be used to verify the base torque (see 6.6). The contractor shall not proceed with production until the proper torque has been demonstrated.

4.4.3.5 Lifting plug torque. At the start of each assembly of non-hazardous test rounds the lifting plug torque shall be verified. The contractor shall submit for approval, a plan detailing the method to be used to verify the torque (see 6.6). The contractor shall not proceed with production until the proper torque has been demonstrated.

4.4.3.6 Dimensional control of main charge and booster simulants (see dwg 9277763 and 9277743). The dimensions specified in paragraphs 4.4.2.5 and 4.4.2.6 for the booster and main charge simulants shall be checked by randomly selecting three (3) samples from the quantity produced by each press during a period not to exceed four (4) hours. The samples shall be allowed to cool and become dimensionally stable prior to inspecting. The quantity represented by the samples shall be identified and not used in production until the dimensional inspections are completed. If any one (1) sample fails to comply with the dimensional requirements, the quantity of parts represented by the sample shall be subjected to 100% inspection. The contractor and technical agency shall determine the amount of time required for cooling and supply this information to the resident Government inspector. The above inspection shall also be performed each time a new lot of explosive material is used.

4.4.3.7 Expulsion charge assembly

4.4.3.7.1 Charge loading assembly, prior to fastening cover and insertion in cup (Dwg 9272020). The charge shall be inspected and tested for the titled specified requirements in accordance with MIL-P-48749.

4.4.3.7.2 Expulsion charge assembly (Dwg 9272019). The assembly shall be inspected for the titled specified requirements in accordance with MIL-P-48749.

4.4.3.7.3 Cover, expulsion charge (Dwg 9272022). The cover shall be inspected for the titled specified requirements in accordance with MIL-P-48749.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.

4.4.4 Inspection equipment. The inspection equipment required to perform the examinations and tests prescribed herein is described in the "Paragraph Reference/Inspection Method" column in the tables starting with paragraph 4.4.2.1. The contractor shall submit inspection equipment designs for approval in accordance with the terms of the contract. See section 6 of MIL-A-48078 and 6.3 herein.

4.5 Test methods and procedures

4.5.1 S&A x-ray examination. S&A assemblies shall be examined for presence and position of the safety features and explosive loading (See para. 3.3). The quality of the x-ray shall be such to permit ready identification of the presence and location of the parts and identification of the dummy center lead. Rotation of the part may be necessary and is permitted. Any assembly having a safety feature missing or out of position or containing improper explosive loading shall be immediately removed from the lot and marked or tagged to prevent the assembly from entering subsequent operations. The cognizant technical agency shall be immediately notified. Data item description DI-R-1721 applies to this paragraph.

4.5.2 Preload and torque measurements. Preload and torque measurements shall be performed in accordance with the plans submitted in accordance with paragraphs 4.4.3.2, 4.4.3.3, 4.4.3.4, and 4.4.3.5 as applicable.

4.5.3 Air pressure test of projectile. The assembled projectile, with lifting plug, shall be placed in a chamber, and a pre-determined volume of air shall be delivered to produce fifteen plus one (15 + 1) pounds per square inch (psi) pressure between the outside of the projectile and the interior of the chamber. After initial stabilization of the pressure the projectile shall withstand the external pressure (15 + 1 psi) for fifteen (15) seconds minimum without exhibiting more than a 0.1 psi drop in pressure. Any projectile failing this test shall be rejected, suitably marked, and removed from the lot. All equipment used in this test shall be capable of performing the test accurately and consistently. Equipment shall be calibrated at intervals to be approved by the technical agency. If it is found that the gage is out of calibration in such a direction that the test pressure was actually lower than that specified on the drawing, projectiles tested since the last satisfactory calibration shall be retested, after the error has been corrected. All test and calibration instructions, equipment and procedures shall be approved in accordance with 4.4.4.

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:27Z
Check the source to verify that this is the current version before use.

4.5.4 Projectile weight determination. The projectile, without lifting plug, gasket, and grommet assembly shall be weighed, using equipment of suitable range and accuracy. The zone weight shall be marked in the specified location on the projectile and this marking shall be verified as being proper for the weight zone indicated by the equipment.

4.5.5 Radiographic examination of test mines. Mines shall be radiographed at the load plant before insertion of the mines into the projectile. Projectiles shall be radiographed at the proving ground before test firing (see MIL-P-63238). The radiographs of mines shall be taken with the beam focused perpendicular to the center axis 90° from the keyway slot. The location of the g-weight, ball, and slider shall be visible in the radiographs. The booster simulant and main charge simulant shall show evidence of the lead shot. The mine radiographs shall be identifiable to the projectile, as well as indicate the location of the individual mine in the projectile. These radiographs may be retained for inspection upon request or forwarded to ARRADCOM, ATTN: DRDAR-QAA-M. Any indication of a missing or out-of-line slider, g-weight or ball in any S&A, or the absence of the lead shot in the booster or main charge simulants in any mine shall result in that mine being clearly marked and removed from the lot, and the Contracting Officer and Technical Agency shall be immediately notified.

NOTE: Radiographic equipment, operations and procedures shall be qualified in accordance with MIl-STD-453. In addition, the photographic density of the film used shall be of a quality which will produce a sharp definition of internal structure.

5. PREPARATION FOR DELIVERY

5.1 Packing (Level A). The projectiles shall be packed in accordance with Dwg. 8837839.

5.2 Marking. Marking shall be in accordance with Dwg. 8837839.

5.3 Shipping. When projectiles from more than one lot are shipped at one time, each lot shall be kept separate and the division between lots clearly indicated to prevent mixing of the lots in transit.

6. NOTES

6.1 Intended use. Not applicable.

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:27Z
Check the source to verify that this is the current version before use.

6.2 Ordering data. See MIL-A-48078.

6.3 Submission of designs for approval. See 6.2.3 of MIL-A-48078. Submit equipment designs, as required, to Commander, ARRADCOM, ATTN: DRDAR-QAA-I, Dover, New Jersey 07801.

6.4 Submission of test data and data cards. In addition to the normal distribution of records, when the projectiles are procured by the US Army Armament Material Readiness Command, one (1) copy of all ballistic data and ammunition data cards shall be forwarded to: Commander, ARRADCOM, ATTN: DRDAR-QAA-M, Dover, New Jersey 07801.

6.5 Drawings. Drawings listed in section 2 of this specification under the heading US Army Armament Research and Development Command (ARRADCOM), may also include drawings prepared by, and identified as, Edgewood Arsenal, Frankford Arsenal, Rock Island Arsenal or Picatinny Arsenal drawings. Technical data originally prepared by these activities are now under the cognizance of ARRADCOM.

6.6 Data requirements. Deliverable data required by the specifications are cited in the following paragraphs:

Paragraph	Data Requirement	Applicable DID No.
3.7	Plan for control in use of adhesives	DI-T-5372 (Tailored)
3.8	Safety Plans	DI-T-5372 (Tailored)
4.4.2.1, 4.4.2.4, 4.4.2.7, 4.4.2.8, 4.4.2.10, 4.4.2.13, 4.4.2.14, 4.4.2.17	Quality Inspect Defect Reports	DI-R-1721
4.4.3.2, 4.4.3.3, 4.4.3.4, 4.4.3.5	Plans for Verification of Preload forces and Torques	DI-T-5372 (Tailored)
6.4	Ammunition Data Card	DI-L-1410

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project No.: 1320-A568

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:27Z
Check the source to verify that this is the current version before use.