|INCH-POUND|
MIL-S-81220A(AS)
15 February 1991
SUPERSEDING
MIL-S-81220(WP)
23 February 1965

MILITARY SPECIFICATION

SHELTER, EXPEDITIONARY AIRFIELD WEAPONS READY, SERVICE

This specification is approved for use by the Naval Air Systems Command Department of the Navy, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This specification establishes the requirements for the procurement of one type of expeditionary airfield weapons ready service shelter. The shelter is constructed of folding arches and purlings covered with a polyester coated canvas. An electrical system for lighting and power outlets is included.

2. APPLICABLE DOCUMENTS.

2.1 Government Documents.

2.1.1 Specification and standards. The following specifications and standards form a part of this document to the extent specified herein. Unless otherwise specified, the issues of these documents are those listed in the issue of the Department of Defense Index of Specifications and Standards (DODISS) and supplement thereto, cited in the solicitation (see 6.2).

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Naval Air Engineering Center, Systems Engineering and Standardization Department (Code 53), Lakehurst, NJ 08733-5100, by using the Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or letter.

AMSC N/A FSC 8340

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:34Z
Check the source to verify that this is the current version before use.

SPECIFICATION

FEDERAL

V-F-106	-	Fastener, Slide Interlocking
QQ-A-200	-	Aluminum alloy 6162, Bar, Rod, Shapes, Tubes and Wire Extruded
V-T-285	-	Thread, Polyester
CCC-C-285	-	Cloth, Osnaburg, Cotton
CCC-C-467	-	Cloth, Burlap, Jute (or Kenaf)
T-C-571	-	Cords, Cotton; General and Special Purpose, Sash and Venetian Blind
QQ-A-601	-	Aluminum Alloy Sand Casting
PPP-B-601	-	Boxes, Wood, Cleated-Plywood
QQ-S-766	-	Steel, Stainless and Heat Resisting, Alloys, Plate, Sheet and Strip
T-T-911	-	Twine, Fibrous Jute

MILITARY

MIL-R-3390	-	Rings, Dee
MIL-W-4088	-	Webbing, Textile, Woven Nylon
MIL-G-16491	-	Grommet, Metallic
MIL-C-20696	-	Cloth, Coated, Polyester or Nylon, Waterproof
MIL-R-30500	-	Rope, Polyester
MIL-T-43566	-	Tape, Textile, Cotton or Polyester, General Purpose Natural or in Colors
MIL-C-43627	-	Cloth, Duck, Cotton, Plied Yarns, Fire, Water, Weather and Mildew Resistant Treated, LightDry Finish

STANDARDS

FEDERAL

FED-STD-595	-	Colors
FED-STD-751	-	Stitches, Seams and Stitching

MILITARY

MIL-STD-105	-	Sampling Procedures and Tables for Inspection by Attribute
MIL-STD-129	-	Marking for Shipment and Storage
MS51925	-	Ring, DEE-Medium

(Unless otherwise indicated, copies of federal and military specifications, and standards, are available from the Standardization Documents Order Desk, Building 4D, 700 Robbins Avenue, Philadelphia, PA 19111-5094.)

2.1.2 Other Government Documents. The following other Government documents form a part of this specification to the extents specified herein. Unless otherwise specified, the issues shall be those in effect on the date of the solicitation:

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:34Z
Check the source to verify that this is the current version before use.

DATA LISTS

NAVAL AIR SYSTEMS COMMAND (30003)

DL1522AS100 - Shelter SubAssembly
DL2482856 - EAF Ready Service Weapon Shelter
DL2483036 - Electrical System Carrying Case
DL2483070 - Lighting System

PUBLICATION

NAVAL AIR SYSTEMS COMMAND (NAVAIR)

19-1-86 - Operation Instructions and Intermediate maintenance with Illustrated Parts Breakdown for the Expeditionary Airfield (EAF) Weapons Ready Service Shelter and handling System P/N 2482836.

2.2 Other Publications. The following documents form a part of this document to the extent specified herein. Unless otherwise specified, the issues of the documents which are DOD adopted shall be those listed in the DODISS specified in the solicitation. Unless otherwise specified, the issues of the documents not listed in the DODISS shall be the issue or the nongovernment documents which are current on the date of the solicitation.

AMERICAN SOCIETY FOR TESTING AND MATERIALS (ASTM)

D 3951 - Standard Practice for Commercial Packaging

(Application for copies should be Addressed to ASTM 1916 Race Street, Philadelphia, PA 19103)

(Non-Government standards and other publications are normally available from the organizations that prepare or distribute the documents. These documents also may be available in or through libraries or other informational services.)

2.3 Order of Precedence. In the event of a conflict between the text of this document and the references cited herein, the text of this document shall take precedence. Nothing in this document, however, shall supersede applicable laws and regulations unless a specific exemption has been obtained.

3. REQUIREMENTS

3.1 First Article. When specified in the contract or purchase order, a sample shall be subjected to first article inspection (see 4.3, 6.2). Until the first article has, to the Government's satisfaction, successfully completed all first article inspection requirements, no work on any other units shall be authorized.

3.2 Design, Materials and Construction. Design, materials and construction shall be in accordance with the drawings listed on NAVAIR Data List DL1522AS100, associated Data Lists and as specified herein.

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:34Z
Check the source to verify that this is the current version before use.

3.3 Construction. The construction of the shelter shall conform to the drawings listed herein.

3.3.1 Stitching, Machine.

3.3.1.1 Types of Stitching. All stitch types, except bartacking, shall conform to FED-STD-751, as indicated on applicable drawings.

3.3.1.2 Type 301 Stitching. All 301 type stitches shall contain between 5 and 7 stitches per inch. Ends of all stitching shall be backstitched or overstitched 1 inch minimum except when caught in other stitching or turned under in a hem. Thread tension shall be maintained s that there will be no loose stitching resulting in puckering of the materials sewn. The lock shall be embedded in the materials sewn.

3.3.1.2.1 Repairs of Type 301 Stitching. Repair of type 301 stitches shall be as follows:

a. When thread breaks or bobbin run-outs occur during sewing, the stitching shall be repaired by restarting the stitching a minimum of 1 inch back of the end of the stitching.

b. Thread breaks or two or more consecutive skipped or run-off stitches noted during inspection of the item (in-process or end item) shall be repaired by overstitching. The stitching shall start a minimum of 1 inch in back of the defective area (1/2 inch on box-x) and continue a minimum of 1 inch beyond the defective area on to the existing stitching. Loose or excessively tight stitching shall be repaired by removing the defective stitching without damaging the materials, and restitching in the same manner described above.

3.3.1.3 Type 401 Stitching. Thread tension shall be maintained so that there will be no loose stitching. Both ends of all seams or stitching produced with 401 stitch type, when not turned under in a hem or held down by other stitching, shall have a 1/2 to 3/4 inch chain extending beyond each end. The looper shall be in accordance with 3.4.1.2.1A and 3.4.2.1.1B. Repairs may be made using 301 stitch type.

3.3.1.4 Type 304 Zig-Zag Stitching. Type 304 stitching shall contain between 10 and 14 stitches per inch. Thread tension shall be maintained so that there will be no loose or excessively tight stitching. Repairs shall be in accordance with 3.4.1.2.1A and 3.4.1.2.1B except that the stitching shall overstitch the defective stitching area a minimum of three stitches onto the existing stitching.

3.3.1.5 Bartacking. Bartacking shall be 3/4 inch plus or minus 1/16 inch in length, 1/8 inch plus or minus 1/16 inch in width (bight) and shall contain 28 stitches. Bartacks shall be free of thread breaks and loose stitching.

3.3.2 Automatic Stitching Machines. Automatic stitching machines may be used to perform any of the required stitch patterns provided the requirements of the stitch pattern, stitches per inch, size and type of thread are met, and at least three or more tying, overlapping or backstitches are used to secure the end of the stitching.

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:34Z
Check the source to verify that this is the current version before use.

3.3.3 Thread Ends. All thread ends that are visible on the finished item shall be trimmed to a length of not more than 1/4 inch.

3.3.4 Lubrication of thread. There shall be no lubrication of the thread by any means prior to or during the sewing process (see 4.4.1.1).

3.3.5 Needle Holes. Each row of stitching on the seam attaching the roof blanket portion of the end cover to the end wall portion of the end cover shall be overcoated with the sealant specified in 3.3.13 so as to effectively seal all needle holes.

3.3.5.1 Wicking of Stitching Threads. There shall be no wicking of water through any stitching when tested in accordance with the requirements of 4.3.1.1. The cup test is intended to insure that nonwicking thread has been utilized and that no lubrication has been added to the thread prior to or during the sewing operation.

3.3.6 Stitching Margins. Unless otherwise specified, all stitching margins shall be 1/8 inch plus or minus 1/16 inch.

3.3.7 Attachment of Slide Fasteners. Care shall be exercised to trim all thread ends and maintain specified distances between edges of fabric attached to slide fastener tape so that there will be no interference with the operation of the slider.

3.3.8 Setting of Grommets. Holes punched to receive grommets shall be smaller than the outside diameter of the grommet barrel so that the barrel must be forced through the hole. The grommets shall be securely clinched without cutting the materials.

3.3.9 Searing. The ends of all straps, ropes and cords shall be seared in order to prevent fraying.

3.3.10 Panel Joining. All panel joining seams shall run lengthwise with a minimum cloth width of 60 inches. Unless otherwise specified all seams shall be cemented. Adjoining panels shall overlap 2-1/2 ± 1/2 inches. All cemented seams shall be smooth and fully adhere throughout their lengths and shall be free of puckers, airpockets and tunnels. There shall be no smearing or unsightly spreading of the adhesive and care should be exercised to insure the surrounding areas are kept free and clean of excess adhesive. Stains or fabric discoloration shall not show 1/2 inch beyond the cemented area. Cemented areas shall be dusted with a fine white talc or other finely divided material that does not support mildew growth.

3.4 Workmanship. A shelter manufactured to this specification shall be free from dust, dirt, metal filings, loose threads, moisture, weld splashes, chips, torn or loose stitching or seams or any other evidence of inferior workmanship. Necessary precautions shall be taken during manufacture and assembly to insure these conditions.

4. QUALITY ASSURANCE PROVISIONS.

4.1 Responsibility for Inspection. Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:34Z
Check the source to verify that this is the current version before use.

4.4 Tests

pection requirements as specified herein. Except as otherwise specified in the tract or purchase order, the contractor may use his own or any other facilities table for the performance of the inspection requirements specified herein, ess disapproved by the Government. The Government reserves the right to perform of the inspections set forth in this document where such inspections are deemed essary to assure that supplies and services conform to prescribed requirements.

.1.1 Responsibility for Compliance. All items must meet all requirements of tions 3 and 5. The inspection set forth in this document shall become a part of contractor's overall inspection system or quality program. The absence of any pection requirements in this document shall not relieve the contractor of the ponsibility of assuring that all services and supplies submitted to the ernment for acceptance comply with all the requirements of the contract. ıpling in quality conformance does not authorize submission of known defective erial, either indicated or actual, nor does it commit the Government to eptance of defective material.

1.1.2 Responsibility for Dimensional Requirements. Unless otherwise specified the contract or purchase order, the contractor is responsible for assuring that l specified dimensions have been met. When dimensions cannot be examined on the l item, inspection shall be made at any point, or at all points in the ıufacturing process necessary to assure compliance with all dimensional ıuirements.

4.2 Classification of Inspection. The inspection requirements specified herein e classified as follows:

a. First article inspection (see 4.3).
b. Quality conformance inspection (see 4.4).

4.3 First Article Inspection. When a first article is specified in the contract purchase order, it shall be subjected to the test and inspection procedures of bi 11 and paragraphs 4.3.1 thru 4.3.5. The presence of any defect or failure to ss any test shall be cause for rejection of the first article.

4.3.1 Leak Test Requirements. The end covers, the roof blanket and a randomly lected case shall be subjected to the leak test outlined in paragraph 4.3.1.1. o seams from each piece shall be tested, one a cemented seam and the other a itched seam. In the event of any piece not having a cemented seam two randomly lected stitched seams shall be tested.

4.3.1.1 Leak Test Procedures. Suspend the area to be tested between two ıpports (boxes, wooden horses) so as to allow both sides of the fabric to be ewed. The area to be tested shall than be cupped into a hoop 6 to 7 inches in ameter, e.g., an embroidery hoop, with the seam running through the center of the oop. Pour into the cupped area approximately one pint of room temperature water. llow to stand for five minutes. At the end of five minutes examine the seam over ıe entire test area. Evidence of any moisture or seepage through the stitching, loth or commented seam shall constitute rejection.

4.3.2 Framework Functional Setup. The entire shelter framework, P/N 2470259, nall be erected in accordance with the latest revision of NAVAIR Technical Manual

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:34Z
Check the source to verify that this is the current version before use.

19-1-86. There shall be not selective fitting or parts and only those tools provided in the tool kit roll assembly and the ladder may be used in the erection process. All hinges shall operate smoothly and all pins capable of locking in place without the use of excessive force (light to moderate tapping of the pins with the hammer provided in the tool kit is considered acceptable). Failure of any component to perform its' intended function or assemble in its' intended fashion shall constitute rejection.

4.3.3 Electrical System Functional Test. The entire electrical system, P/N2483070, shall be assembled in accordance with the latest revision of NAVAIR Technical Manual 19-1-86. With the circuit breakers in the off position, the main power cable shall be connected to a 120 volt, 60Hz electrical power supply in a manner approved by local electrical building codes. At this point it shall be verified that there is no electrical power reaching either of the chandeliers or the auxiliary junction box and that no ground fault exist at the main junction box. Next, the circuit breakers shall be flipped to the on position. At this point is shall be verified that all six lamps on the chandeliers operate properly and that the auxiliary junction box, as well as the two auxiliary outlets on the main junction box, are providing 120 volt, 60 Hz electrical power.

4.3.4 Canvas Component Functional Test. The shelter framework shall be covered with the two end covers and the roof blanket in accordance with the latest revision of NAVAIR Technical Manual 19-1-86. It shall be verified that all tie down straps function properly and are correctly located for attachment to respective arch assemblies. All hem ropes, draw ropes and rope locks used in attaching roof blanket and end covers shall be checked for proper fit and function. Male and female spars shall be checked for assembly and fit in the end cover door pockets. Door draw ropes shall be checked for proper operation by raising and lowering each door. Slide fasteners shall be checked for proper operation by raising and lowering each through it's full range of travel. All guy lines, hold down ropes and tie-down ropes shall be attached to their respective arches and purlins in order to verify quantity as well as proper location of respective canvas openings. A sample of each guy line, hold down rope and draw rope shall be checked for proper length. Failure of any component used in securing the canvas to the framework or the framework to the ground from performing its intended function shall constitute rejection.

4.3.5 Completeness. Verify The presence of the items in the quantities listed below.

P/N	QTY.	ITEM
2643204	34	GROUND ANCHOR
2643205	34	WIRE ASSY.
2482796	1	ARCH SPACER ASSY.
2483309	1	ROOF BLANKET REPAIR KIT
2643209	1	STAKE ROLL ASSY.
2643208	2	TOOL KIT ROLL ASSY.
2483043	2	HEATER DUCT BLOCK-OUT PLUGS
2482807	1	SHIPPING COVER
2482808	1	SHIPPING COVER
2482810	4	PURLIN CARRYING CASES
2482811	1	VERTICAL TUBE CARRYING CASE
2482812	2	ARCH CARRYING CASES
2482813	1	LADDER CASE

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:34Z
Check the source to verify that this is the current version before use.

4.4 Quality Conformance Inspection. Units selected for quality conformance testing shall be subjected to the inspection requirements of Table III and the test requirements of paragraphs: 4.3.1.1, 4.3.3 and 4.3.5.

4.4.1 Sampling Lot Size. Unless otherwise specified the sampling lot size for quality conformance inspection shall be in accordance with MIL-STD-105.

4.4.2 Acceptable Quality Levels. The end item shall be examined for defects in accordance with Table II. The inspection level shall be II and the acceptable quality levels (AQL's), expressed in terms of defects per hundred units, shall be 15.0 for major and 40.0 for major and minor combined.

TABLE II. CLASSIFICATION OF DEFECTS.

EXAMINE	DEFECT	CLASSIFICATION MAJOR	CLASSIFICATION MINOR
Cloth, coated	Hole (except drill hole) cut or tear	X	
	Exposed drill hole; i.e., not covered by attached parts.	X	
	Scratch or abrasion mark.	X	
	Any uncoated area, delamination of coating, area where coating noticeably thinner or area of tackiness.	X	
Webbing	Edge frayed or scalloped.		X
Seams, Cemented	Any panel joining seam not overlapped a minimum of 1-7/8".	X	
	Any panel joining seams not securely bonded or containing puckers, air pockets or tunnels.	X	
	Adhesive does not extend a minimum of 1/2" beyond the edges of panel joining seams, both sides of cloth.		X
	Any unsightly spreading of adhesive beyond the 1/2" area on either side of seam, or staining or discoloration of tent fabric due to adhesive outside of seamed area.		X
	Failure to dust cemented seam.	X	
	Excessive dusting of cemented seam.		X

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:34Z
Check the source to verify that this is the current version before use.

TABLE II. CLASSIFICATION OF DEFECTS.(Continued)

EXAMINE	DEFECT	CLASSIFICATION MAJOR	CLASSIFICATION MINOR
Seams, Stitched and Stitching	Any open seams except run-offs.	X	
	Run-offs		
	- more than 1/2" but not more than 1".		X
	- more than 1".	X	
NOTE:	A seam shall be classified as open when one or more stitches joining a seam are broken or when two or more consecutive skipped stitches or run-offs occur. On double stitched seams the seam shall be considered open when either one or both sides of the seam are open.		
Boxstitching	Open seam, or one row of stitching omitted.		X
	More than one row of stitching omitted.	X	
Seams	Badly twisted or pleated:		
	- two or less.		X
	- more than two.	X	
Raw Edges	When securely caught in stitching:		
	- more than 1" but not more than 3".		X
	- more than 3".	X	
Seam and Stitch Type	Wrong seam or stitch type.	X	
Stitch Tension	Loose, resulting in a loosely exposed top or bottom (bobbin or looper) thread.		X
	Tight, resulting in excessive tightness or puckering of fabric.	X	
Stitches Per Inch	One stitch less than the minimum specified.		X
	Two or more stitches less than the minimum specified.	X	
	Two or more stitches in excess of the maximum specified.		X

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:34Z
Check the source to verify that this is the current version before use.

TABLE II. CLASSIFICATION OF DEFECTS.(Continued)

EXAMINE	DEFECT	CLASSIFICATION MAJOR	CLASSIFICATION MINOR
NOTE:	Variation in the number of stitches per inch caused by operators speeding up the machine and pulling the fabric in order to sew over heavy seams or heavy places or turning corners shall be classified as follows:		
	A. Within the major defect classification. B. Within the minor defect classification. No defect.		X
Stitching Margins	Not as specified.		X
Bartacks	One or more missing or not as specified.		X
Thread Breaks	Overstitched less than 1" on type 401 stitches.		X
	Overstitched less than 1" on type 301 stitches.		X
	Overstitched less than 1/4" on type 304 stitches.		
NOTE:	Thread breaks not overstitched on each side of break or ends not backstitched as specified shall be classified as open seams.		
Stitching Ends	Not backstitched.	X	
	Stitch type 301 backstitched less than 1".		X
	Stitch type 304 backstitched less than 1/4".	X	
Needle Chews	Needle chews resulting in a cut tear or hole.	X	
Uncoated Stitches	Any stitched area not overcoated with sealant.	X	
Components and Assembly	Any component part omitted (unless otherwise classified herein).	X	
	Any component part not fabricated from specified material.	X	

Source: https://assist.dla.mil -- Downloaded: 202610-26T04:34Z
Check the source to verify that this is the current version before use.

TABLE II. CLASSIFICATION OF DEFECTS.(Continued)

EXAMINE	DEFECT	CLASSIFICATION MAJOR	CLASSIFICATION MINOR
	Hem ropes misplaced, failing to extend from No. 4 grommets atends of hem.	X	
	Rope locks not extending from far side as required in detail. A Dwg. No. 2482800 and detail W Dwg. No. 2482786.	X	
Tie Down Flaps	Tie Down Flaps not properly aligned.		X
Hems	Badly twisted or pleated: - two or less.		X
	- more than two.	X	
	Constructed with partial turnunder, when double turnunder is required.	X	
Reinforcements	Improperly applied, causing excessive fullness on reinforcement or reinforced parts.		X
	Not securely stitched to reinforced parts on all sides, or not securely caught in seams or stitching of reinforced parts.		X
"S" Hooks	"S" Hooks not secured to tarp straps.		X
Patches	Any patches	X	
Marking	Omitted, incorrect or illegible.	X	
	Misplaced.		X
Cleaniness	Noticeable grease or oil stains.		X
Rope and Cord Components	Cut or abrasion.	X	
	Splice or knot omitted, or not as specified.	X	
Hardware	Broken or malformed, protective finish omitted or incorrect, corroded area, burrs or sharp edges.	X	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:34Z
Check the source to verify that this is the current version before use.

of one class only, packaged as specified

TABLE II. CLASSIFICATION OF DEFECTS.(Continued)

EXAMINE	DEFECT	CLASSIFICATION MAJOR	CLASSIFICATION MINOR
	Missing.	X	
	Operating parts do not function as intended.	X	
Grommets	Improperly set; two or more teeth exposed inside or barrel, clinched loosely causing grommet to rotate around hole.		X
	Clinched excessively tight, cutting fabric or insecurely clinched, i.e., grommet or washer become disengaged.	X	
Spar Pockets	Not formed and stitched to door as specified.	X	
Staple Rivets	Not securely set or neatly headed.	X	
Weather Flaps	Not centered on slide fastener by more than 1/2" in either direction.	X	
Buckles	Reversed, failing to effect a secure fastening of flaps.	X	
Toggles and loops	Out of alignment with on another failing to effect a smooth and secure closure.		X
Grommet Flaps	Off center of grommets by more than 1/8" in any direction.		X
Heater Duct Sleeve	Not properly located or attached to wrong side of cloth.		X

NOTE: Since there are no critical examination items the column has been omitted.

5. PACKAGING.

5.1 Preservation. Preservation shall be level A or commercial as specified (see 6.2).

5.1.1 Level A. All shelter components shall be free from dirt, dust, grease, moisture or any other unsightly foreign matter. Each component shall then be carefully stored in the appropriate covers/cases and quantities as specified by Table I, WP004 00 of NAVAIR Technical Manual 19-1-86. In instances where items

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:34Z
Check the source to verify that this is the current version before use.

must be folded, care shall be taken to ensure that all attached hardware shall be positioned in such a manner so as not to stress or tear at the cloth or seams. All covers or cases shall be securely tied so as to insure that internal components will not slide out or work themselves fr000 The lid to the electrical system carrying case shall be securely fastened with the latches provided.

5.1.2 Commercial. Each tent shall be preserved in accordance with ASTM D-3951.

5.2 Packing. Packing shall be level A, B or commercial as specified (see 6.2).

5.2.1 level A Packing. All components required for one shelter, preserved in accordance with 5.1.1, shall be packed within a snug fitting, wood-cleated, plywood shipping container conforming to overseas type I, style A or J of PPP-B-601. Each container shall be provided with skids fabricated as specified in PPP-B-601. Cushioning shall be applied as necessary to immobilize the contents and prevent abrasions. Each shipping container shall be closed and strapped with flat steel strapping in accordance with container specification.

5.2.2 Level B. Packing.

5.2.2.1 Complete Assembly. All components required for one shelter, preserved as specified in 5.1, shall be packed as specified in 5.2.1 except that the shipping container shall be domestic type.

5.2.2.2 Canvas Items Only. When purchased separately as spares, end covers, roof blankets, shipping covers, carrying cases, stake roll and tool kit roll assemblies, preserved as specified in 5.1.1 shall be individually wrapped and sewn in cotton osnaburg cloth conforming to Class 2 of CCC-C-429, or burlap cloth conforming to Class 3 of CCC-C-467. The cloth wrapping shall be securely hand sewn with type I or II, 16 ply cotton twine conforming to T-T-911, with approximately one stitch to the inch and every third stitch overhand knotted. Alternately the bottom and side may be machine sewn. A minimum of five inches of wrapping material shall be gathered on each of the four corners and securely sewn into ears for handles.

5.2.3 Commercial Packing. All the components required for one shelter, preserved as specified in 5.1.2, shall be packed in accordance with ASTM D-3951.

5.3 Marking. In addition to any special marking required by the contract or purchase order, shipping containers shall be marked in accordance with MIL-STD-129 or ASTM D-3951 as applicable.

6. NOTES.

(This section contains information of a general or explanatory nature that may be helpful, but is not mandatory.)

6.1 Intended Use. The shelter was designed for use by Marine Corps aviation units to assemble, checkout and store air launched weapons at expeditionary airfields.

Source: https://assist.dla.mil -- Downloaded: 2026t0-26T04:34Z
Check the source to verify that this is the currentversion before use.

6.2 Acquisition Requirements. Acquisition documents must specify the following:

a. Title, number, and date of the specification.

b. Issue of DODISS to be cited in the solicitation, and if required, the specific issue of individual documents referenced (see 2.1).

c. Wether or not first article sample is required.

d. Number of units which will constitute the first article sample.

e. Information pertinent to the site of first article testing (see 4.2.1).

f. Level of preservation and packaging required (see Section 5 and 6.3).

* 6.3 Data Requirements. The following Data Item Descriptions (DID's) must be listed, as applicable, on the Contract Data Requirements List (DD Form 1423) when this specification is applied on a contract, in order to obtain the data, except where DOD FAR Supplement 27.475-1 exempts the requirement for a DD Form 1423.

Referenced Paragraph	DID Number	DID Title	Suggested Tailoring
4.2	DI-T-2072/ DI-MISC-80653	Test Reports	Wherever possible, use the contractor's standard test report format.

The above DID's were those cleared as of the date of this specification. The current issue of DOD 5010.12-L, Acquisition Management Systems and Data Requirements Control List (AMSDL), must be researched to ensure that only current, cleared DID's are cited on the DD Form 1423.

6.4 Criteria for Selection of Proper Level of Preservation, Packaging, and Packing. - The attention of the contracting officer is invited to the Quality Assurance Provisions and options delineated in Specification MIL-P-116 and to the following paragraphs:

For Level A. - This level shall be used for those items which are to be shipped to indeterminate destinations or stored under indeterminate conditions for redistribution anywhere.

For Level B. - This level shall be used only when it is definitely known that the item will be held in covered storage in overseas locations for six months or less or in domestic locations for an indefinite period.

For Level C. - This level shall be used only when it is definitely known that the packaged item is to be shipped to domestic installations for immediate use at the first receiving activity.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:34Z
Check the source to verify that this is the current version before use.

6.5 First Article. When first article inspection is required, the contracting officer should provide specific guidance to offerors whether the item(s) should be a preproduction sample, a first article sample, a first production item, a sample selected from the first production items, a standard production item from the contractor's current inventory (see 3.1), and the number of items to be tested as specified in 4.3. The contracting officer should also include specific instructions in acquisition documents regarding arrangements for examinations, approval of first article test results, and disposition for first articles. Invitations for bids should provide that the Government reserves the right to waive the requirement for samples for first article inspection to those bidders offering a product which has been previously acquired or tested by the Government, and that bidders offering such products, who wish to rely on such production or test, must furnish evidence with the bid that prior Government approval is presently appropriate for the pending contract. Bidders should not submit alternate bids unless specifically requested to do in the solicitation..

6.6 Subject Term (key word) Listing.

Field tent
Mobile tent
Rigid walled tent with lights

6.7 Changes From Previous Issue. Marginal notations are not used in this revision to identify changes with respect to the previous issue due to the extensiveness of the changes.

Custodian:
Navy-AS

User Activities:
Navy-MC

Preparing Activity:
Navy-AS
(Project No. 8340-N527)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:34Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS

1. The preparing activity must complete blocks 1, 2, 3, and 8. In block 1, both the document number and revision letter should be given.
2. The submitter of this form must complete blocks 4, 5, 6, and 7.
3. The preparing activity must provide a reply within 30 days from receipt of the form.

NOTE: This form may not be used to request copies of documents, nor to request waivers, or clarification of requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

I RECOMMEND A CHANGE:	1. DOCUMENT NUMBER MIL-S-81220A(AS)	2. DOCUMENT DATE (YYMMDD) 15 FEBRUARY 1991

3. DOCUMENT TITLE
Shelter, Expeditionary, Airfield Weapons Ready Service

4. NATURE OF CHANGE *(Identify paragraph number and include proposed rewrite, if possible. Attach extra sheets as needed.)*

5. REASON FOR RECOMMENDATION

6. SUBMITTER

a. NAME (Last, First, Middle Initial)	b. ORGANIZATION	
c. ADDRESS (Include Zip Code)	d. TELEPHONE (Include Area Code) (1) Commercial (2) AUTOVON (If applicable)	7. DATE SUBMITTED (YYMMDD)

8. PREPARING ACTIVITY

a. NAME Commanding Officer val Air Engineering Center	b. TELEPHONE (Include Area Code) (1) Commercial: (908) 323-7709 (2) AUTOVON: 624-7709
c. ADDRESS (Include Zip Code) SESD Code 53 Lakehurst, NJ 08733-5100	IF YOU DO NOT RECEIVE A REPLY WITHIN 45 DAYS, CONTACT: Defense Quality and Standardization Office 5203 Leesburg Pike, Suite 1403, Falls Church, VA 22041-3466 Telephone (703) 756-2340 AUTOVON 289-2340

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T04:34Z
Check the source to verify that this is the current version before use.