MILITARY SPECIFICATION

ELBOW ASSEMBLY, PASSIVE: 11733401

This amendment forms a part of Military Specification MIL-E-48441A (MU) dated 31 December 1975.

PAGE 1

Paragraph 1.1, Delete and substitute:

"1.1 This specification covers a modular unit of the Tank Commander's M36E1 Periscope or the Tank Gunner's M32E1, M32CE1 and M35E1 Periscope, herein after referred to as Elbow Assembly (see 6.1)."

Paragraph 2.1, SPECIFICATIONS: Add "MIL-O-13830 Optical Components For Fire Control Instruments; General Specification Governing The Manufacture, Assembly And Inspection Of".

Paragraph 2.1, DRAWINGS: Delete "F11746721 Boot, Objective
C11746729 Holder, Eyepiece 10" Collimator
D11746730 Eyepiece Assembly 10" Collimator".

PAGE 3

Paragraph 3.6.1.2, line 2: Delete "and 3.6.1.2.2".

PAGE 4

Paragraph 3.6.1.2.1, Delete and substitute:

"3.6.1.2.1 On axis.-The objective system shall resolve 40, 150 and 300 line pairs per millimeter on axis."

Delete Paragraph 3.6.1.2.2 in its entirety.

FSC 1240

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:26Z
Check the source to verify that this is the current version before use.

PAGE 6

Paragraph 3.6.5.1, Delete and substitute:

"3.6.5.1 Vibration "A".-This requirement shall be met with the image intensifier tube and reticle projector lamp emergized by the application of +24 ± 6.0 VDC to the contact for the regulator and the reticle projector lamp (Reference Drawing F11733401). Vibration shall be applied along each of three mutually perpendicular axes of the elbow assembly. The vibration shall be sinusoidal as follows:

a. At a frequency of 5 Hertz (Hz), the acceleration shall be .5G ± 10%.

b. During a frequency sweep of 5 to 9 Hz, increase acceleration linearly from .5G to 1.5 G's ± 10%.

c. During a frequency sweep of 9 to 500 Hz, maintain constant acceleration of 1.5 G's ± 10%.

d. During frequency sweep of 500 to 9 Hz, maintain constant acceleration of 1.5 G's ± 10%.

e. During a frequency sweep of 9 to 5 Hz, decrease acceleration linearly from 1.5 G's to .5G ± 10%.

f. At 5 Hz, the acceleration shall be .5G ± 10%.

The frequency of applied vibration shall be swept logarithmically in 15 minute ± 1 minute sweep cycles for a total of two hours per axis. There shall be no failure or flicker of light emission from the image intensifier tube nor the reticle projector lamp during vibration and the elbow assembly shall show no evidence of physical failure subsequent to vibration. Following the vibration test, the elbow assembly shall meet the requirements of 3.2, 3.6 through 3.6.4.10 inclusive and 3.6.6 through 3.8 inclusive."

PAGE 7

Paragraph 3.6.5.2, Delete and substitute:

"3.6.5.2 Vibration "B".-This requirement shall be met with the image intensifier tube and reticle projector lamp energized by the application of +24 ± 6.0 VDC to Contact 11733497

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:26Z
Check the source to verify that this is the current version before use.

(Reference Drawing F11733401). Vibration shall be applied along each of three mutually perpendicular axes of the elbow assembly. The vibration shall be sinusoidal as follows:

a. At a frequency of 5 Hertz (Hz), the acceleration shall be 1.0 G ± 10%.

b. During a frequency sweep of 5 to 500 Hz, maintain constant acceleration of 1.0 G ± 10%.

c. During a frequency sweep of 500 to 5 Hz, maintain constant acceleration of 1.0 G ± 10%.

d. At 5 Hz, the acceleration shall be 1.0 G ± 10%.

The frequency of applied vibration shall be swept logarithmically in 15 minute ± 1 minute sweep cycles for a total of 15 minutes ± 1 minute along each of the three mutually perpendicular axes (total vibration time 45 minutes ± 3 minutes). There shall be no failure or flicker of light emission from the image intensifier tube nor the reticle projector lamp during vibration and the elbow assembly shall show no evidence of physical failure subsequent to vibration. Following the vibration test, the elbow assembly shall meet the requirements of 3.2, 3.6 through 3.6.4.10 inclusive and 3.6.6 through 3.8 inclusive."

Paragraph 3.6.5.3, Delete and substitute:

"3.6.5.3 Shock.-This requirement shall be met with the image intensifier tube and reticle projector lamp energized by the application of +24 ± 6.0 VDC to Contact 11733497 (Reference Drawing F11733401). The elbow assembly shall be subjected to 24 cumulative shocks consisting of three each of 35 G's ± 10%, then 20 G's ± 10% applied in each direction along each of the two mutually perpendicular horizontal axes (all four sides). The shock pulse shall have a half sine wave with a time duration of 3 ± .2 milliseconds. The elbow assembly shall also be subjected to six cumulative shocks consisting of three each at 35 G's ± 10%, then 20 G's ± 10% applied in one direction along the vertical axis (normal operating position of elbow assembly only). The shock pulse shall have a half sine wave with a time duration of 18 ± 3 milliseconds. Subsequent to shock, there shall be no failure or flicker of light emission from the image tube nor the reticle projector lamp. The elbow assembly shall also show no evidence of physical failure. Following the shock test the elbow assembly shall meet the requirements of 3.2, 3.6 through 3.6.4.10 inclusive and 3.6.6 through 3.8 inclusive.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:26Z
Check the source to verify that this is the current version before use.

PAGE 10

Paragraph 4.3.2.1.1, lines 2 and 3: Delete "image intensifier tube".

TABLE I: Delete characteristic 302 in its entirety.

PAGE 14

Paragraph 4.5.2.3.2, Delete and substitute:

"4.5.2.3.2 Performance.-Special test equipment to determine performance of the elbow assembly shall conform.to the requirements of Drawing F11746736 (Test Set-up for M35 Elbow), Drawing F11746724 (Holder, eyepiece) and drawings pertaining thereto."

Paragraph 4.6.2.1, Delete and substitute:

"4.6.2.1 Resolution-objective system-on axis.-Perform this test utilizing a resolving power chart on a wall target and an auxiliary telescope having a magnification of at least 50 power (50X) and a numerical aperture of at least .65. The resolving power chart shall represent the angular subtense for line pairs per millimeter specified in 3.6.1.2.1 and shall contain four line sets as shown in Figure I of MIL-O-13830. The test method and procedure shall be in compliance with the "Resolution Test" specified in MIL-O-13830. The limits of resolution shall be within the value specified in 3.6.1.2.1, as determined by viewing through the auxiliary telescope."

PAGE 15

Delete Paragragh 4.6.2.2 in its entirety.

PAGE 18

Paragraph 4.6.5.2, line 21: Delete "M32E1, M35E1 and M36E1." and substitute "M32E1, M32CE1, M35E1 and M36E1."

PAGE 19

Paragraph 4.6.5.5.1, line 21: Delete "M32E1, M35E1 and M36E1." and substitute "M32E1, M32CE1, M35E1 and M36E1."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:26Z
Check the source to verify that this is the current version before use.

PAGE 20

Paragraph 4.6.6.5.2, line 12: Delete "M32E1, M35E1 and M36E1." and substitute "M32E1, M32CE1, M35E1 and M36E1."

PAGE 28

Paragraph 6.1, line 3: Delete "Periscope: M32E1 and M35E1" and substitute "Periscope: M32E1, M32CE1 and M35E1".

Custodian:
ARMY-AR

Preparing Acitivity:
ARMY-AR

Project No. 1240-A725

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:26Z
Check the source to verify that this is the current version before use.